

COMPETITIVE QUOTE

FOR ASBESTOS ABATEMENT

**Fort Dodge City Hall
Priority 5.0 Renovation**

**Prepared For:
City of Fort Dodge
819 1st Avenue South
Fort Dodge, IA 50501**

Prepared By:



**9550 Hickman Rd, Suite 105
Clive, IA 50325**

February 16, 2021

CERTIFICATION

PROJECT MANUAL

for

Specifications for Asbestos Abatement

Fort Dodge City Hall

Priority 5.0 Renovation

Specifications Prepared By:

A handwritten signature in cursive script, reading "Jacob Huxford", is written over a horizontal line.

Jacob Huxford
Impact7G, Inc.

Accredited by the State of Iowa for Asbestos Project Design
License #20-3983 Expires 02-12-2021

This document is the property of Impact7G, Inc. and shall not be reproduced in any format without written permission.

TABLE OF CONTENTS

ASBESTOS ABATEMENT Priority 5.0 Renovation 819 1st Avenue South Fort Dodge, IA 50501

CERTIFICATION
TABLE OF CONTENTS
NOTICE TO BIDDERS AND NOTICE OF PUBLIC HEARING
INSTRUCTION TO BIDDERS
PROPOSAL
SPECIAL PROVISIONS – GENERAL REQUIREMENTS

DRAWINGS

Site Plans from ACM Inspection Reports

APPENDICES

Appendix 1 - Asbestos Containing Materials Inspection Report
Appendix 2 - Asbestos Diagrams and Field Forms
Appendix 3 - Iowa DNR 10-Day Notification Form

NOTICE TO BIDDERS

ASBESTOS ABATEMENT PRIORITY 5.0 RENOVATION 819 1ST AVENUE SOUTH FORT DODGE, IA 50501

Time and Place for Filing Sealed Proposals: Sealed bids for the work consisting of asbestos abatement as stated below must be filed before 2:00 P.M. on Friday, February 26, 2021, in the clerk's office of the City of Fort Dodge, 819 First Avenue South, Fort Dodge, IA 50501. Bidder must provide acknowledgement of addenda, if issued. The proposal shall be sealed in an envelope, properly identified as the Proposal with the project title and the name and address of the bidder and delivered at or before the time and at the place provided in the Notice and Instruction to Bidders. It is the sole responsibility of the bidder to see that its proposal is delivered prior to the time for opening bids, along with the appropriate bid security sealed in the separate envelope identified as Bid Security, if required, and attached to the outside of the bid proposal envelope. Any proposal received after the scheduled time for the receiving of proposals will be returned to the bidder unopened and will not be considered. Bidder shall include verification of license to remove asbestos meeting the requirements of Iowa Code, Chapter 88B.

Time and Place Sealed Proposals Will be Opened and Considered: Sealed proposals will be opened, and bids tabulated at 2:00 P.M. on Friday, February 26, 2021, in the office of the City of Fort Dodge reserves the right to reject any and all bids.

Time for Commencement and Completion of Work: Work on the improvement shall commence upon approval of the contract by The City of Fort Dodge, and as stated in the Notice to Proceed. The contractor shall have the project complete by March 31, 2021 (30 days after the Notice to Proceed).

Contract Documents: The document governing the asbestos abatement which have been made a part of this Notice and the proposed contract are on file with the City of Fort Dodge, at 819 First Avenue South, Fort Dodge, IA 50501; phone 515-573-3426. This document can be obtained from Impact7G at 9550 Hickman Rd, Suite 105, Clive, IA 50325; phone 515-473-6256 or via email from info@impact7g.com.

Sales Tax Exemption Certificates. The bidder shall not include sales tax in the bid. The City of Fort Dodge will distribute tax exemption certificates and authorization letters to the Contractor and all subcontractors who are identified. The Contractor and subcontractor may make copies of the tax exemption certificates and provide a copy to each supplier providing construction materials. These tax exemption certificates and authorization letters are applicable only for this specific project under the Contract.

PROJECT DESCRIPTION: The work includes removal and disposal of Asbestos Containing Materials (ACMs) from the Fort Dodge City Hall located at 819 First Avenue South, Fort Dodge, IA 50501. City Hall is undergoing a major renovation, which is broken into two constructions phases (5.0). Specifications for asbestos removal includes nonfriable ACMs. All materials removed from the property shall be done in accordance with local, state, and federal regulations.

*****END OF SECTION*****

INSTRUCTIONS TO BIDDERS

ASBESTOS ABATEMENT Priority 5.0 Renovation 819 1st Avenue South Fort Dodge, IA 50501

Contractors must read this document in its entirety and comply with all requirements. Please be certain that all documents have been completed properly, as failure to complete and sign all documents and to comply with the requirements listing within this document can cause your bid not to be read.

I. SUBMISSION OF THE PROPOSAL AND IDENTITY OF BIDDER

A. The proposal shall be sealed in an envelope, properly identified as the Proposal with the project title and the name and address of the bidder, and deposited with the Jurisdiction at or before the time and at the place provided in the Notice to Bidders. It is the sole responsibility of the bidder to see that its proposal is delivered to the Jurisdiction prior to the time for opening bids, along with the appropriate bid security sealed in the separate envelope identified as Bid Security and attached to the outside of the bid proposal envelope. Any proposal received after the scheduled time for the receiving of proposals will be returned to the bidder unopened and will not be considered.

B. The following documents shall be completed, signed and returned in the Proposal envelope. The bid cannot be read if any of these documents are omitted from the Proposal envelope.

1. PROPOSAL – Complete each of the following parts:

- Part B – Acknowledgment of Addenda, if any have been issued;
- Part C – Bid Items, Quantities and Prices
- Part F – Identity of Bidder;

Sign the proposal. The signature on the proposal and all proposal attachments must be an original signature in ink signed by the same individual who is the Company Owner or an authorized Officer of the Company; copies, facsimiles, or electronic signatures will not be accepted.

The following documents must be submitted as printed. No alterations, additions, or deletions are permitted. If the Bidder notes a requirement in the contract documents which the Bidder believes will require a conditioned or unsolicited alternate bid, the Bidder must immediately notify Bryce Davis, of the City of Fort Dodge in writing. The City will issue any necessary interpretation by an addendum.

C. Bidder shall include verification of license to remove asbestos meeting the requirements of Iowa Code, Chapter 88B.

II. PROSECUTION AND PROGRESS OF THE WORK

A. The work is located in the City of Fort Dodge.

Work shall commence upon approval of the contract by the Council, and as stated in the Notice to Proceed. All work under the Contract must be substantially complete on or before March 31, 2021.

B. The City of Fort Dodge, in accordance with Title VI of the Civil Rights Act of 1964, 78 Stat. 252, 42U.S.C. 2000d to 2000d-4 and title 49 Code of Federal Regulations, Department of Transportation, Subtitle A, Office of the Secretary, Part 21, Nondiscrimination in Federally-assisted programs of the Department of Transportation issued pursuant to such Act, hereby notifies all bidders that it will affirmatively insure that in any contract entered into pursuant to this advertisement, minority business enterprises will be afforded full opportunity to submit bids in response to this invitation and will not be discriminated against on the grounds of race, color, or national origin in consideration for an award.

C. Once Contractor has mobilized to begin construction, Contractor shall remain on-site until Project is substantially complete as determined by the City of Fort Dodge or their Consultant.

III. TAXES

A. The City of Fort Dodge will issue a sales tax exemption certificate to the Contractor for all materials purchased on the project. The City will issue the appropriate exemption certificates and authorization letters to the Contractor and all subcontractors completing work on the project. Tax exemption certificates are applicable only for the specific project for which the tax exemption certificate is issued.

B. The Contractor shall provide a listing to the City identifying all appropriate subcontractors qualified for use of the tax exemption certificate. The Contractor and subcontractors may make copies of the certificate and provide to each supplier providing construction material a copy of the tax exemption certificate.

C. Income Tax:

a. Successful Bidder is subject to payment of Iowa income tax on income from this work in amounts prescribed by law.

b. If successful bidder is a non-Iowa partnership, individual or association, he shall furnish evidence prior to execution of contract that bond or securities have been posted with the Iowa Department of Revenue in the amount required by law.

******END OF SECTION******

PROPOSAL

**ASBESTOS ABATEMENT
Priority 5.0 Renovation
819 1st Avenue South
Fort Dodge, IA 50501**

PROPOSAL: PART A – SCOPE

City of Fort Dodge, hereinafter called “CITY”, has need for a permitted contractor to complete the work comprising the below referenced improvement. The undersigned Bidder hereby proposes to complete the work as specified in the contract documents, at the prices hereinafter provided in Part C of the Proposal, for the following described improvements:

PROJECT DESCRIPTION: The work includes removal and disposal of Asbestos Containing Materials (ACMs) from the Fort Dodge City Hall located at 819 First Avenue South, Fort Dodge, IA 50501. City Hall is undergoing a major renovation, which is broken into two constructions phases (5.0). Specifications for asbestos removal includes nonfriable ACMs. All materials removed from the property shall be done in accordance with local, state, and federal regulations.

PROPOSAL: PART B – ACKNOWLEDGMENT OF ADDENDA

The Bidder hereby acknowledges that all addenda become a part of the contract documents when issued, and that each such addendum has been received and utilized in the preparation of this bid. The Bidder hereby acknowledges receipt of the following addenda by inserting the number of each addendum in the blanks below:

ADDENDUM NUMBER _____ ADDENDUM NUMBER _____
ADDENDUM NUMBER _____ ADDENDUM NUMBER _____

PROPOSAL: PART C – BID ITEMS AND QUANTITIES

This is a **LUMP SUM PRICE CONTRACT**. The bidder must provide the Lump Sum Price of Asbestos Abatement. The Quantities shown on the Proposal Attachment: Part C – Bid Items and quantities are approximate only but are considered sufficiently adequate for the purpose of comparing bids. CITY shall use the Total Bid Price of each Bid Item for comparison of bids.

PROPOSAL: PART D – GENERAL

The Bidder hereby acknowledges that the CITY, in advertising for bids for this project, reserves the right to:

1. Reject any or all bids. Award of the contract, if any, to be to the lowest responsible, responsive bidder; and
2. Reject any or all alternates in determining the items to be included in the contract. Designation of the lowest responsible, responsive bidder to be based on comparison of the total bid only, not including any alternates; and
3. Make such alterations in the contract documents or in the proposal quantities as it determines necessary in accordance with the contract documents after execution of the contract. Such alterations shall not be considered a waiver of any conditions of the contract documents, and shall not invalidate any of the provisions thereof; and

The Bidder hereby agrees to:

1. Commence the work upon written Notice to Proceed, and
2. Complete the project by March 31, 2021 (30 days after the Notice to Proceed).

PROPOSAL: PART E – NON-COLLUSION AFFIDAVIT

The Bidder hereby certifies:

1. That this proposal is not affected by, contingent on, or dependent on any other proposal submitted for any improvement with CITY; and
2. That no individual employed by the Bidder has employed any person to solicit or procure the work on this project, nor will any employee of the Bidder make any payment or agreement for payment of any compensation in connection with the procurement of this project; and
3. That no part of the bid price received by the Bidder was or will be paid to any person, corporation, firm, association, or other organization for soliciting the bid, other than the payment of their normal compensation to persons regularly employed by the Bidder whose services in connection with the construction of the project were in the regular course of their duties for the Bidder; and
4. That this proposal is genuine and not collusive or sham; that the Bidder has not colluded, conspired, connived or agreed, directly or indirectly, with any bidder or person, to submit a sham bid or to refrain from bidding, and has not in any manner, directly or indirectly, sought, by agreement or collusion, or communication or conference, with any person, to fix the bid price of the Bidder or of any other bidder, and that all statements in this proposal are true; and
5. That the individual(s) executing this proposal have the authority to execute this proposal on behalf of the Bidder.

PROPOSAL: PART F – IDENTITY OF BIDDER

The bidder shall indicate whether the bid is Submitted by a/an:

- Individual,
Sole Proprietorship
- Partnership
- Corporation
- Limited Liability Company
- Joint-venture; all parties must
join-in and execute all documents
- Other

Bidder

Signature

By _____

Name (Print/Type)

Title

Street Address

City, State, Zip Code

Telephone Number

**Type or print the name and title of the
company's owner, president, CEO, etc. if
a different person than entered above**

Name

Title

NOTE: The signature on this proposal must be an original signature in ink by the same individual who is the Company Owner or authorized Officer of the Copy; copies, facsimiles, or electronic signatures will not be accepted.

PROPOSAL ATTACHMENT: PART C – BID ITEMS AND QUANTITIES

This is a **LUMP SUM PRICE CONTRACT**. The bidder must provide the Total Bid Price. The Quantities shown on the Proposal Attachment: Part C – Bid Items and quantities are approximate only but are considered sufficiently adequate for the purpose of comparing bids. CITY shall use the Total Bid Price for comparison of bids.

Materials and quantities are approximate only but are considered adequate for the purpose of this Project Design. The contractor is responsible for verification of all materials and quantities listed below. No additions to the contract will be allowed for additional ACMs discovered that amount to less than ten percent (10%) of each material listed below. If additional amounts greater than ten percent (10%) are identified, contractor is to stop work and notify the CITY and/or CITY’S consultant immediately.

If suspect ACMs are discovered during the abatement process that are not listed below, contractor is to stop work and notify the CITY and/or CITY’S consultant immediately. No compensation for removal of suspect ACMs without prior authorization by CITY and/or CITY’s consultant will be approved. All materials and quantities are subject to revision by the CITY.

BASE BID PRICE BREAKDOWN INFORMATION

ITEM	DESCRIPTION	TOTAL BID PRICE
1	Asbestos Abatement and Disposal – 819 1 st Avenue South (Priority 5.0 Renovation)	\$
TOTAL AMOUNT BID		\$


ASBESTOS CONTAINING MATERIAL LIST

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location, Room	Est. Quantity
19JH031938	Tile Cove Base	Misc	N	Gray	2 nd	Economic Development – Kitchen – e211J	10 LF
19JH031940	Floor Tile Mastic	Misc	N	Black	2 nd	Economic Development – Kitchen – e211J	45 SF
19JH031945	Wall Adhesive	Misc	N	Black	2 nd	Economic Development – Waiting Room – e211A	975 SF

NOTE: IT IS UNDERSTOOD THAT THE QUANTITIES OF ACMS DOCUMENTED WITHIN THIS PROJECT MANUAL ARE ESTIMATED FOR THE PURPOSE OF THIS BID. ALL QUANTITIES SHALL BE VERIFIED BY CONTRACTOR PRIOR TO SUBMISSION OF BID.

Bidder Name

APPENDIX 1 – Asbestos Diagrams and Field Forms



PERSONNEL DECONTAMINATION UNIT

CERTIFICATION OF VISUAL INSPECTION

BUILDING _____

LOCATION _____

CONTRACTOR CERTIFICATION OF VISUAL INSPECTION

The contractor hereby certifies that he has visually inspected the work area (all surfaces including pipes, beams, ledges, walls, ceiling and floor, Decontamination Unit, sheet plastic, etc.) and has found no dust, debris or residue to the best of his knowledge.

by: _____
Signature Date

Print Name

Print Title

OWNER'S REPRESENTATIVE CERTIFICATION OF VISUAL INSPECTION

The owner's representative hereby certifies that he has visually inspected the work area (all surfaces including pipes, beams, ledges, walls, ceiling and floor, Decontamination Unit, sheet plastic, etc.) and has found no dust, debris or residue to the best of his knowledge.

by: _____
Signature Date

Print Name

Print Title

WASTE SHIPMENT RECORD

G E N E R A T O R	1. Work site name and mailing address		Owner's name	Owner's telephone number	
	2. Operator's name and address			Operator's telephone number	
				Waste Generator Number	
	3. Waste disposal site (WDS) name, mailing address, and physical site location			WDS telephone number	
	4. Name and address of responsible agency				
	5. Description of materials		6. Containers	7. Total Quantity m ³ (yd ³)	
Asbestos, ID # NA 2212, PACKAGING GROUP 111					
8. Special handling instructions and additional information					
9. OPERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and government regulations.					
Printed/typed name and title		Signature		Month Day Year	
T R A N S P O R T E R	10. Transporter 1 (Acknowledgment of receipt of materials)				
	Printed/typed name and title		Signature		Month Day Year
	Address & telephone number				
	11. Transporter 2 (Acknowledgment of receipt of materials)				
Printed/typed name and title		Signature		Month Day Year	
Address & telephone number					
D I S P O S E A L	12. Discrepancy indication space				
	13. Waste disposal site owner or operator: Certification of receipt of asbestos materials covered by this manifest except as noted in item 12.				
	Printed/typed name & title		Signature		Month Day Year

**APPENDIX 2 – Iowa Department of
Natural Resources Asbestos Notification**



ASBESTOS NOTIFICATION OF DEMOLITION AND RENOVATION

DNR USE ONLY			
CON 10-15	County #:		
Date:		Initials:	
<input type="checkbox"/> Check/Money Order <input type="checkbox"/> Credit Card <input type="checkbox"/> Cash			

This notice must be postmarked at least ten (10) working days before beginning the activity. All applicable information must be included.

Notification Fee: Effective beginning January 15, 2016, each required **Original** or **Annual** notification must be accompanied by the fee required by 567 IAC 30.3(1).

567 IAC 30.3(1) Payment of fees established. Beginning on January 15, 2016, the owner or operator of a site subject to the national emission standard for hazardous air pollutants (NESHAP) for asbestos notifications adopted by reference in paragraph 23.1(3)"a," shall submit a fee with each required original or each annual notification for each demolition or renovation, including abatement.

Fees are **not** required for the following:

- a. Notifications when the total amount of asbestos to be removed or disturbed is less than 260 linear feet, less than 160 square feet, and less than 35 cubic feet of facility components and is below the reporting thresholds as defined in 40 CFR 61.145 as amended on January 16, 1991;
- b. Notifications of training fires as required in 567—paragraph 23.2(3)"g";
- c. Controlled burning of demolished buildings as required in 567—paragraph 23.2(3)"j";
- d. Revised, canceled, and courtesy notifications. A revision to a previously submitted courtesy notification due to applicability of the notification requirements in 567—paragraph 23.1(3)"a" is considered an original notification and is subject to the fee requirements of subrule 30.3(1).

Each required fee is \$100 payable to "Iowa Department of Natural Resources" in the form of a check, money order, credit card or cash. Please do not send cash in the mail.

Owner or Operator Name Paying Fee: _____ Phone #: _____

\$100 Fee Enclosed Contact for Credit Card Payment or State Agency

1. Type of Notification

- Original (Fee) Revised Cancelled Courtesy Annual (Fee)

2. Type of Operation

(Each Type of Operation requiring an original notification must be accompanied by a separate \$100 fee.)

- Abatement Demolition
- Renovation Ordered Demolition
- Emergency Renovation

3. Is Asbestos Present?

- Yes No – Abatement has already occurred
- No – Asbestos found is under NESHAP limits

4. Scheduled Dates asbestos removal (MM/DD/YY) Start: _____ Stop: _____

5. Scheduled Dates Demo/Renovation (MM/DD/YY) Start: _____ Stop: _____

6. Facility Description (Include building name, number and floor or room number.)

Building Name: _____

Address: _____ County: _____

City: _____ State: _____ Zip: _____

Site Location (floor or room number(s)): _____

Building Size: _____ No of floors: _____ Year Constructed: _____

Present Use: _____ Prior Use: _____

7. Facility Information (Identify owner, and operator)

Owner Name: _____

Address: _____

City: _____ State: _____ Zip: _____

Contact: _____ Phone: _____

Operator (if different from owner): _____
Address: _____
City: _____ **State:** _____ **Zip:** _____
Contact: _____ **Phone:** _____

8. Asbestos Abatement Contractor (if applicable)

Contractor Name: _____ **IA Permit Number:** _____
Address: _____
City: _____ **State:** _____ **Zip:** _____
Contact: _____ **Phone:** _____

9. Demolition Contractor (if applicable)

(if ordered demolition)

Contractor Name: _____ **IA Permit Number:** _____
Address: _____
City: _____ **State:** _____ **Zip:** _____
Contact: _____ **Phone:** _____

10. Asbestos Inspector (required unless an Ordered Demolition or Emergency Renovation)

Name of Inspector: _____ **IA License Number:** _____
Date Inspected: _____ **Phone:** _____

11a. Approximate Amount of Asbestos (for Abatement purposes only)	Regulated Asbestos-Containing Material (RACM) to be Removed	Nonfriable Asbestos-Containing Material Not To Be Removed (Category I and II)
Total Surface Area (Sq. Ft.) (Also see 11b.)		
Facility Component(s) (Cu. Ft.)		
Pipes (Linear Ft.)		

11b. Quantity in Sq. Ft. the Total Surface Area of RACM to be removed from 11a (check all that apply)
Do not include Pipes or Facility Components

- Floor Materials _____ Ceiling Materials _____ Roofing Materials _____
 Interior Wall Systems _____ Spray-on Materials _____ Asbestos Cement Board _____
 Window Glaze/Caulk _____ Other: _____

12. Procedure, including analytical method, if appropriate, used to detect the presence of asbestos materials.

- Polarized Light Microscopy (PLM) Other: _____

13. Description of work practices and engineering controls to be used to prevent asbestos emissions
(check all that apply)

- Adequately Wet Materials Glove Bag Seal in Leak Tight Containers Encapsulate
 Negative Air Containment Seal in Leak Tight Wrapping Mini-enclosure
 Lined Containers Other: _____

14. Description of planned demolition or renovation work (check all that apply)

- Backhoe Bulldozer Hand Removal
 Implosion Other: _____

15. Waste Transporter #1

Name: _____
Address: _____
City: _____ **State:** _____ **Zip:** _____
Contact: _____ **Phone:** _____

Waste Transporter #2 (if applicable)

Name: _____

Address: _____
City: _____ State: _____ Zip: _____
Contact: _____ Phone: _____

16. Waste Disposal Site #1

Name: _____
Address: _____
City: _____ State: _____ Zip: _____
Phone: _____

Waste Disposal Site #2 (if applicable)

Name: _____
Address: _____
City: _____ State: _____ Zip: _____
Phone: _____

17. If Demolition Ordered by a Government Agency, Identify the Agency and Attach a Copy of the Order

Name of Responsible Official: _____
Title: _____ Phone: _____
Authority: _____
Date of Order (MM/DD/YY): _____

18. If Emergency Renovation, Please Complete this Section

Date Emergency (MM/DD/YY): _____ Time of Emergency: _____
Description of the emergency of sudden event: _____

Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:

19. Description of procedures to be followed if there is an unexpected asbestos fiber release:

STOP WORK AND CALL A CERTIFIED ASBESTOS CONTRACTOR AND THE DNR I agree

20. Certification (required if asbestos is present)

I certify that an individual trained in the provisions of regulation 40 CFR Part 61, Subpart M (Asbestos NESHAP) will be onsite during the demolition or renovation and evidence that the required training has been accomplished by this person will be available for inspection during normal business hours.

_____	_____	_____
Name (Print)	Title	Date
_____	_____	_____
Signature of Owner/Operator	Company/Organization	

21. I certify to the best of my knowledge that the above information is true and correct

_____	_____	_____
Name (Print)	Title	Date
_____	_____	_____
Signature of Owner/Operator	Company/Organization	

MAIL TO: Iowa DNR- Air Quality
502 E 9th St
Des Moines IA 50319
515-725-8200

INSTRUCTIONS
ASBESTOS NOTIFICATION OF DEMOLITION AND RENOVATION FORM

GENERAL INFORMATION

The Asbestos NESHAP, 40 CFR 61.145 and 567 IAC 23.1(3), requires written notification of demolition or renovation activities in facilities. In most cases, a facility includes all types of structures except single family homes and apartment buildings having no more than four units. The enclosed form must be used to fulfill this requirement. Only complete notification forms will be accepted.

The notification should be typewritten or neatly printed and postmarked or delivered no later than ten days prior to the beginning of either the asbestos removal activity (Section IV) or demolition activity (in Section V) whichever is applicable.

INSTRUCTIONS

1. **Type of Notification:** Check "Original" if the notification is a first time or original notification, "Revised" if the notification is a revision of a prior notification, or "Canceled" if the activity has been canceled. Check "Courtesy" if you would like to make DNR aware of a non-regulated project. Check "Annual" for projects in accordance with 40 CFR Part 61, Subpart M 61.145(a)(4)(iii).
2. **Type of Operation:** Check as appropriate for facility abatement, demolition, renovation, ordered demolitions, or emergency renovations. A notification for renovation is required only if asbestos was removed or still present but not being disturbed. However, if asbestos has been or will be removed, then a separate abatement notification form should be submitted by the appropriate part.
3. **Is Asbestos Present?** Answer "Yes," "No – Abatement has already occurred," or "No – Asbestos found is under NESHAP limits."
4. **Scheduled Dates of Asbestos Removal (MM-DD-YY):** Enter scheduled dates (month/day/year) for asbestos removal work. Asbestos removal work includes any activity, including site preparation, which may break up, dislodge or disturb asbestos material.
5. **Scheduled Dates of Demolition/Renovation (MM-DD-YY):** Enter scheduled dates (month/day/year) for beginning and ending the planned demolition or renovation project.
6. **Facility Description:** Provide the following information on the areas being renovated or demolished:

Building Address :	Physical location of site
Site Location (floor or room number)	Enter specific location
Building Size:	The building size in square feet.
No. of Floors:	Enter the number of floors including basement, if applicable.
Year Constructed:	Enter year the facility was originally constructed.
Present Use/Prior Use:	Describe the primary use of the facility or enter the following codes: AC – Apartment Complex, B – Boat/Ship, BR – Bridge, CH – Church, C – Commercial, F – Fire Damaged, G – Government, H – Hospital, I – Industrial, M – Miscellaneous, MG – Manufacturing, N – Nursing Home, O – Office, P – Public Building, R – Residence, S - School, U – University/College, V - Vacant
7. **Facility Information:** Enter the names, addresses, contact persons and telephone numbers of the following:
 - Owner:** Legal owner of the site at which asbestos is being removed or demolition planned.
 - Operator:** General contractor, or any other person who leases, operates, controls or supervises the site.

If known, the name of the site supervisor should be entered as the contact person for the notification. If additional parties share responsibility for the site, demolition activity, renovation or ACM removal, include complete information (including name, address, contact person and telephone number) on additional sheets submitted with the form.
8. **Asbestos Abatement Contractor:** If notification is being submitted for asbestos removal enter the name of contractor hired to remove asbestos, contractor permit number, address, contact, and phone number.
9. **Demolition Contractor:** If notification is being submitted for demolition or renovation enter the name of contractor hired, permit number, address, contact, and phone number.
10. **Asbestos Inspector:** Enter the individual who conducted the asbestos inspection prior to demolition/renovation, the inspector license number, date inspected and telephone number.
11. **a) Approximate Amount of Asbestos Including:** (1) Regulated ACM to be removed (including nonfriable ACM to be sanded, ground or abraded); and (2) Category I and Category II nonfriable asbestos containing material not to be removed. For both renovations and demolitions, enter the amount of RACM to be removed by entering a number in the appropriate box. If applicable, enter the amount of nonfriable ACM not to be removed during a demolition or renovation.

Category I nonfriable material includes packing, gaskets, resilient floor covering and asphalt roofing materials. Category II nonfriable material includes any material, excluding Category I materials, that when dry, cannot be crumbled, pulverized or reduced to powder by hand pressure, or mechanical forces expected to operate on the material during the demolition or renovation activity. All Category II materials must be removed prior to demolition.

Complete the volume from facility component(s) if asbestos-containing materials have been removed from facility components and the volume is known.

b) Quantify in Sq. Ft. the Total Surface Area of RACM to be removed from 11a. Check the type of RACM to be removed and enter the square feet for each material. (Total 11b square feet should equal 11a square feet of RACM to be removed.) **Facility Components and Pipes are not included in 11b.**

12. **Asbestos Testing Procedure:** Check the appropriate box for the procedure that was used to determine asbestos content.
13. **Description of Work Practices and Engineering Controls to Prevent Asbestos Emissions:** Check the appropriate box(s) for work practices that will be employed to prevent asbestos emissions.
14. **Description of Planned Demolition or Renovation Work:** Check the appropriate box(s) that describe the renovation/ demolition technique(s) to be used.
15. **Waste Transporter(s):** Enter the name(s), addresses(s), contact person(s) and telephone number(s) of the person(s) or company(ies) responsible for transporting ACM from the removal site to the waste disposal site. If the removal contractor or owner is the waste transporter, state "same as owner" or "same as removal contractor."
16. **Waste Disposal Site:** Identify the waste disposal site, including the complete name, location, and telephone number of the facility. If ACM is to be disposed of at more than one site, provide complete information on an additional sheet submitted with the form.
17. **If Demolition Ordered by a Government Agency, Please Identify the Agency below:** Provide the name of the responsible official, title and agency, authority under which the order was issued and the date of the order. A copy of the order from the government agency must be attached to this form.
18. **Emergency Renovation Information:** Provide the date and time of the emergency, a description of the event and a description of unsafe conditions, equipment damage or financial burden resulting from the event. The information should be detailed enough to evaluate whether a renovation falls within the emergency exemption.
19. **Description of Procedures to be Followed in the Event that Unexpected Asbestos Fiber Release:** Provide adequate information to demonstrate that appropriate actions have been considered and can be implemented to control asbestos emissions adequately, including at a minimum, conformance with applicable work practice standards. Attach an additional sheet of paper if needed and submit with this form.
20. **Certification:** This is required if asbestos is present, i.e. abatements and ordered demolitions. Include signature, date, printed name, title, and company to certify that training provisions required by the asbestos NESHAP regulation will be followed.
21. **Information provided in notification is true and correct:** This is required for all notifications. Include signature, date, printed name, title, and company to certify the information provided is true and correct to the best of your knowledge.

APPENDIX 3 – ACM and LBP Inspection Reports

**ASBESTOS CONTAINING MATERIAL &
LEAD-BASED PAINT INSPECTION**



**Fort Dodge City Hall
819 First Avenue South
Fort Dodge, Iowa 50501**

Prepared for:

**City of Fort Dodge
819 First Avenue South
Fort Dodge, Iowa 50501**

Prepared by:



**9550 Hickman Road, Suite 105
Clive, Iowa 50325
Impact7G, Inc.**

April 11, 2019



ASBESTOS CONTAINING MATERIAL INSPECTION & LEAD-BASED PAINT INSPECTION

**Fort Dodge City Hall
819 First Avenue South
Fort Dodge, Iowa 50501**

Inspected/Prepared by:

A handwritten signature in black ink, appearing to read "Tyler Silverthorn", written over a horizontal line.

Tyler Silverthorn
Environmental Specialist
LBP Inspector/Risk Assessor: #LEAD-INSP10031

Inspected by:

A handwritten signature in black ink, appearing to read "Jacob Huxford", written over a horizontal line.

Jacob Huxford
Environmental Specialist
Iowa Certified Asbestos Inspector: 19-1795

Reviewed by:

A handwritten signature in black ink, appearing to read "Jon Reis", written over a horizontal line.

Jon Reis
Senior Project Manager/QAQC
Iowa Certified Asbestos Inspector: 18-0950
LBP Inspector/Risk Assessor: #LEAD-INSP10006

TABLE OF CONTENTS

1.0	EXECUTIVE SUMMARY	1
2.0	INTRODUCTION.....	4
3.0	PROPERTY DESCRIPTION	5
4.0	INSPECTION LIMITATIONS	5
5.0	INSPECTION ACTIVITIES.....	5
6.0	OPERATIONS & MAINTENANCE PROGRAM RECOMMEDATIONS.....	21
7.0	CONCLUSIONS / RECOMMENDATIONS	25
8.0	CONDITIONS & LIMITATIONS	26

LIST OF TABLES

- Table 1 – Asbestos Containing Material Summary
- Table 2 – Lead-Based Paint Summary
- Table 3 – Asbestos Containing Material Samples List
- Table 4 – Non-Asbestos Containing Material Samples List

APPENDICES

- APPENDIX A - Qualifications
- APPENDIX B - Laboratory Reports / Chain of Custody Documentation
- APPENDIX C - Photographs
- APPENDIX D - Sample Location Map(s)
- APPENDIX E – LBP Results

1.0 EXECUTIVE SUMMARY

Impact7G, Inc. (Impact7G), completed an Asbestos Containing Material (ACM) and Lead-Based Paint (LBP) Inspection on March 18th-22nd, 2019 of the existing building located at 819 First Avenue South, Fort Dodge, Iowa 50501 (Property). The purpose of this Inspection is to document the presence of ACM and LBP within the building and assist the City of Fort Dodge (Client) in facilitating renovation activities.

The following tables indicate that ACM and LBP currently exist in this Property, as of the date of this report.

Table 1 – Asbestos Containing Materials Summary

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location, Room
19JH031938	Tile Cove Base	Misc	N	Gray	2 nd	Economic Development – Kitchen – e211J
19JH031940	Floor Tile Mastic	Misc	N	Black	2 nd	Economic Development – Kitchen – e211J
19JH031945	Wall Adhesive	Misc	N	Black	2 nd	Economic Development – Waiting Room – e211A
19JH031972	Drywall Joint Compound	Misc	N	White	2 nd	Inspections/Engineering – Lobby – e205A
19JH031980	12" x 12" Floor Tile	Misc	N	Cream w/ Tan Streaks	2 nd	Inspections/Engineering – e205B
19JH031991	Sink Undercoat	Misc	N	Black	2 nd	Human Resources – Kitchen – e203A
19JH031993	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – Storage – e203F
19JH031997	Ceiling Tile	Misc	N	White	2 nd	Human Resources – Storage – e203F
19JH0319108	Sink Undercoat	Misc	N	White	1 st	Storage – e147
19JH0319113	12" x 12" Floor Tile	Misc	N	Brown	1 st	Breakroom – e143A and Conference Room (David) – e143B
19JH0319114	Floor Tile Mastic	Misc	N	Black	1 st	Breakroom – e143A and Conference Room (David) – e143B
19JH0319117	Wall Mastic	Misc	N	Brown	1 st	Breakroom – e143A
19JH0319118	Floor Tile	Misc	N	Maroon	1 st	Breakroom – e143A
19JH0319120	Floor Tile	Misc	N	Green	1 st	Breakroom – e143A
19JH0319121	Floor Tile	Misc	N	Black	1 st	Breakroom – e143A
19JH0319126	Wall Mastic	Misc	N	Black	1 st	Breakroom – e143A
19JH0319175	Wall Panel Mastic	Misc	N	Black	1 st	City Administrator – Storage/Attorney (Ryan) – e135
19JH0319229 ABC	Pipe Insulation	TSI	Y	White	1 st	Electrical Room – e158
19JH0319232 ABC	Mudded Joints	TSI	Y	White	1 st	Electrical Room – e158
19JH0319261	Pipe Wrap (tar like)	Misc	N	Black	B	Storage e13A

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location, Room
19JH0403337	Drywall Joint Compound	Misc	N	White	2 nd	Engineering/Inspections – e205C
19JH0403340	Drywall Joint Compound	Misc	N	White	2 nd	Engineering/Inspections – e205E
19JH0403342	Ceiling Tile	Misc	N	White	2 nd	Human Resources – e203A
19JH0403343	Ceiling Tile	Misc	N	White	2 nd	Human Resources – e203B
19JH0403344	Ceiling Tile	Misc	N	White	2 nd	Human Resources – e203E
19JH0403346	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – e203A
19JH0403349	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – e203E
19JH0403352	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – e203B

Material Type – Surf=Surfacing, TSI=Thermal System Insulation, Misc=Miscellaneous

Asbestos was identified in thirty-two (32) bulk samples taken from the Property. ACMs included tile cove base, floor tile mastic, wall adhesive/mastic, drywall joint compound, 12” x 12” Floor Tile(s), sink undercoats, ceiling tile(s), floor tile(s), pipe insulation, mudded joints, and pipe wrap. The sample location of each material is listed in the table above. If during renovation activities additional areas are discovered, they should be treated as ACM.

Table 2 – Lead-Based Paint Summary

See following pages

LBP was identified in two hundred and sixty-six (266) samples taken from the property. These components include walls, ceilings, window components, ladders, baseboards, shoe molding, door components, stair tread, pipes, jail components, radiators, floors, crown molding, sink tile, wall tile, shelves, shelving components, work bench components, and cabinet components. The location of each LBP sample is listed in the table above and shown on the Sample Location Maps in Appendix D.

1.1 Recommendations

Impact7G recommends the abatement of all ACM located within the inspection area if those building materials are to be disturbed during future renovation or demolition activities. All abatement work shall be completed in accordance with local, state, and federal regulations. A visual inspection is recommended upon completion of abatement work to document that all ACMs within the scope of abatement have been removed. While abatement/removal of LBP components is not required by the Iowa Department Natural Resources (IDNR) prior to demolition, Iowa Occupational Safety and Health (IOSH) may require additional personal protective equipment (PPE) be used if these materials are left in the structure during demolition.

Based on the presence of LBP throughout the Property, lead-safe work practices should be utilized during renovation activities. Options for mitigating lead hazards in abatement by removal, enclosure, or encapsulation, or series of interim controls to manage LBP in place. In general, interim control options will likely be less expensive than abatement control options but will require the development of a management plan. Abatement control options do not require such a plan. Impact7G recommends that the identified LBP components be remediated in accordance with applicable Federal, State and Local Regulations.

Table 2: Fort Dodge City Hall - Positive XRF Results

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1	3/18/2019 11:27	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	9.16	12.5	10.1	22.6
2	3/18/2019 11:27	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	9.21	16.4	11.5	27.9
3	3/18/2019 11:28	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	10	19	12.3	31.3
4	3/18/2019 11:28	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	10	6.1	4.7	10.8
5	3/18/2019 11:28	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Inspections Large Office	Positive	10	18.1	11.9	30
25	3/18/2019 11:34	mg/cm ²	Window Frame	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	9.97	15	11	26
30	3/18/2019 11:44	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Lobby	Positive	10	12.4	10.2	22.6
31	3/18/2019 11:44	mg/cm ²	Roof Access Ladder	Metal	D	Deteriorated	Black	Friction	2	Inspections Lobby	Positive	1.3	2	0.9	2.9
32	3/18/2019 11:45	mg/cm ²	Wall Behind Ladder	Plaster	D	Deteriorated	Black	Cracking	2	Inspections Lobby	Positive	2.12	12.3	10.4	22.7
33	3/18/2019 11:45	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Lobby	Positive	8.86	12.4	9.8	22.2
49	3/18/2019 11:58	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Brown	Cracking	2	Inspections Office 2	Positive	3.11	1.4	0.3	1.7
50	3/18/2019 11:59	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Brown	Cracking	2	Inspections Office 2	Positive	2.69	0.8	0.2	1
72	3/18/2019 12:12	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Yellow	Cracking	2	Inspections Office 1	Positive	5.26	1.8	0.8	2.6
74	3/18/2019 12:14	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Office 1	Positive	7.81	12.1	15.8	27.9
90	3/18/2019 12:29	mg/cm ²	Window Casing/Header	Wood	D	Intact	Black		2	Elevator Lobby	Positive	4.99	0.9	0.1	1
102	3/18/2019 12:38	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Elevator Lobby	Positive	10	11.1	9.1	20.2
103	3/18/2019 12:39	mg/cm ²	Wall Above Drop Ceiling	Plaster	B/C/D	Deteriorated	Green	Cracking	2	Elevator Lobby	Positive	10	14.2	10	24.2
107	3/18/2019 12:45	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Spiral Staircase	Positive	5.69	15.2	11.2	26.4
108	3/18/2019 12:45	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	2	Spiral Staircase	Positive	5.75	15.2	11.3	26.5
109	3/18/2019 12:46	mg/cm ²	Baseboard	Wood	C/D	Deteriorated	Beige	Impact	2	Spiral Staircase	Positive	7.02	3.8	2.3	6.1
110	3/18/2019 12:46	mg/cm ²	Shoe Molding	Wood	C/D	Deteriorated	Beige	Impact	2	Spiral Staircase	Positive	5.24	5.7	3.4	9.1
111	3/18/2019 12:47	mg/cm ²	Door Threshold	Concrete	A	Deteriorated	White	Friction	2	Spiral Staircase	Positive	1.97	1.8	0.7	2.5
114	3/18/2019 12:48	mg/cm ²	Stair Tread	Metal	All	Intact	Red		2	Spiral Staircase	Positive	1.72	2.3	1.2	3.5
117	3/18/2019 12:51	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Spiral Staircase	Positive	7.32	14.4	10.4	24.8
119	3/18/2019 12:53	mg/cm ²	Wall	Concrete	A	Intact	Beige		2	Spiral Staircase	Positive	6.97	19	12.4	31.4
127	3/18/2019 13:01	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Green		2	Vending Area	Positive	10	11.5	9.6	21.1
129	3/18/2019 13:01	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	Beige		2	Vending Area	Positive	10	20.6	12.6	33.2
130	3/18/2019 13:01	mg/cm ²	Ceiling Frame Above Drop Ceiling	Wood	All	Intact	Brown		2	Vending Area	Positive	4.23	0.6	0.4	1
131	3/18/2019 13:07	mg/cm ²	Wall	Plaster	A	Intact	Brown		2	Conference Room	Positive	5.42	0.5	0.5	1
133	3/18/2019 13:09	mg/cm ²	Wall	Plaster	C	Intact	Brown		2	Conference Room	Positive	6.92	0.4	0.6	1
172	3/18/2019 13:39	mg/cm ²	Column Base Trim	Plaster	All	Intact	Beige		2	E/W Hallway	Positive	10	23.2	21.1	44.3
241	3/18/2019 14:34	mg/cm ²	Wall Above Drop Ceiling	Plaster	A	Deteriorated	Green	Cracking	2	Human Rights Office 2	Positive	1.69	0.5	0.5	1
263	3/18/2019 14:48	mg/cm ²	Vault Casing/Header	Metal	D	Intact	White		2	Purchasing Hall	Positive	3.48	14.8	11.2	26
264	3/18/2019 14:48	mg/cm ²	Vault Door	Metal	D	Intact	White	Friction/Impact	2	Purchasing Hall	Positive	3.39	18.4	12.6	31
265	3/18/2019 14:50	mg/cm ²	Vault Door Jamb	Metal	D	Deteriorated	Grey	Friction	2	Purchasing Hall	Positive	1.29	1.6	0.5	2.1
279	3/18/2019 15:03	mg/cm ²	Wall	Plaster	D	Intact	Blue		2	Purchasing Office	Positive	4.07	0.4	0.6	1
294	3/18/2019 15:33	mg/cm ²	Wall	Concrete	A	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	6.03	2.3	1.3	3.6
295	3/18/2019 15:33	mg/cm ²	Wall	Concrete	B	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	4.92	1.5	0.4	1.9
296	3/18/2019 15:35	mg/cm ²	Wall	Concrete	C	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	4.51	2.8	1.4	4.2
297	3/18/2019 15:35	mg/cm ²	Wall	Concrete	D	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	5.03	1.9	0.9	2.8
301	3/18/2019 16:33	mg/cm ²	Window Jamb	Wood	All	Deteriorated	White	Chipping	2	Econ. Devel. SW Storage	Positive	2.06	24.4	21.8	46.2
302	3/18/2019 16:33	mg/cm ²	Window Exterior Stop	Wood	All	Deteriorated	White	Chipping	2	Econ. Devel. SW Storage	Positive	2.2	29.2	24.9	54.1
306	3/18/2019 16:34	mg/cm ²	Pipe	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	4.71	1.4	0.4	1.8
309	3/18/2019 16:35	mg/cm ²	Door Casing/Header	Metal	A	Deteriorated	Grey	Impact	2	Econ. Devel. SW Storage	Positive	2.35	2.2	1.2	3.4
310	3/18/2019 16:35	mg/cm ²	Door Jamb	Metal	A	Deteriorated	Grey	Friction	2	Econ. Devel. SW Storage	Positive	2.13	2.3	1.1	3.4
311	3/18/2019 16:36	mg/cm ²	Door	Metal	A	Deteriorated	Grey	Friction/Impact	2	Econ. Devel. SW Storage	Positive	2.62	3.4	2.1	5.5
312	3/18/2019 16:36	mg/cm ²	Vent Frame	Metal	A	Intact	Grey		2	Econ. Devel. SW Storage	Positive	3.98	2.7	1.3	4
323	3/18/2019 16:38	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	5.21	3.8	2.7	6.5
323	3/18/2019 16:49	mg/cm ²	Door Casing/Header	Metal	C	Deteriorated	White	Impact	2	Econ. Devel. Office 10	Positive	5.07	2.2	1.1	3.3
340	3/18/2019 16:59	mg/cm ²	Door Frame	Metal	A	Intact	White		2	Econ. Devel. S Hall	Positive	7.9	3.6	1.9	5.5
342	3/18/2019 17:00	mg/cm ²	Door Casing/Header	Metal	C	Intact	White		2	Econ. Devel. S Hall	Positive	7.84	8.1	5.3	13.4
343	3/18/2019 17:00	mg/cm ²	Door Jamb	Metal	C	Deteriorated	Grey	Friction	2	Econ. Devel. S Hall	Positive	1.92	4.2	3	7.2
344	3/18/2019 17:00	mg/cm ²	Door	Metal	C	Deteriorated	White	Friction/Impact	2	Econ. Devel. S Hall	Positive	7.96	4.5	2.9	7.4
345	3/18/2019 17:00	mg/cm ²	Door Threshold	Metal	C	Deteriorated	Grey	Friction	2	Econ. Devel. S Hall	Positive	2.66	0.7	0.3	1
347	3/18/2019 17:05	mg/cm ²	Wall	Plaster	A	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Positive	5.22	7	5.8	12.8
348	3/18/2019 17:05	mg/cm ²	Wall	Plaster	D	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Positive	4.31	8.4	6.4	14.8
349	3/18/2019 17:06	mg/cm ²	Cell Door	Metal	All	Deteriorated	Grey	Friction/Impact	2	Econ. Devel. Jail	Positive	2.78	4.9	3	7.9
350	3/18/2019 17:06	mg/cm ²	Cell Door Frame	Metal	All	Deteriorated	Grey	Friction	2	Econ. Devel. Jail	Positive	2.43	4.6	2.6	7.2
351	3/18/2019 17:07	mg/cm ²	Locking Cabinet	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.15	4.5	3.4	7.9

Table 2: Fort Dodge City Hall - Positive XRF Results (continued)

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
353	3/18/2019 17:08	mg/cm ²	Cell Walls	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.72	4.5	2.7	7.2
354	3/18/2019 17:09	mg/cm ²	Bed Frame	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.26	5.6	4.3	9.9
356	3/18/2019 17:14	mg/cm ²	Wall	Plaster	B	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Positive	4.52	10.8	5.5	16.3
357	3/18/2019 17:14	mg/cm ²	Radiator	Metal	B	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	3.35	4.5	3	7.5
359	3/18/2019 17:15	mg/cm ²	Window Jamb	Wood	All	Deteriorated	White	Chipping	2	Econ. Devel. Jail	Positive	2.28	36	30.1	66.1
361	3/18/2019 17:16	mg/cm ²	Outer Cell Wall	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.69	7.8	6.7	14.5
363	3/18/2019 17:19	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Office 9	Positive	4.84	12.2	10.5	22.7
379	3/18/2019 17:53	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. W Hall	Positive	5.14	1.3	0.3	1.6
392	3/19/2019 10:36	mg/cm ²	Wall Above Drop Ceiling	Plaster	A	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Positive	4.72	0.6	0.4	1
393	3/19/2019 10:42	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Positive	3.57	0.5	0.5	1
394	3/19/2019 10:42	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Positive	5.57	0.9	1.3	2.2
397	3/19/2019 10:49	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Econ. Devel. Office 6	Positive	10	5	3.6	8.6
408	3/19/2019 10:49	mg/cm ²	Wall	Plaster	D	Intact	Beige		2	Econ. Devel. Office 6	Positive	10	3.7	2.7	6.4
409	3/19/2019 10:53	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 6	Positive	4.54	3.3	1.4	4.7
412	3/19/2019 11:07	mg/cm ²	Wall	Plaster	B	Intact	Beige		2	Econ. Devel. Office 8	Positive	10	4.2	2.7	6.9
413	3/19/2019 11:07	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Econ. Devel. Office 8	Positive	10	2.4	1.2	3.6
421	3/19/2019 11:13	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 8	Positive	2.98	3.6	2.4	6
425	3/19/2019 11:20	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. Office 5	Positive	10	4	2.7	6.7
437	3/19/2019 11:43	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 5	Positive	6.07	2.9	1.3	4.2
439	3/19/2019 11:45	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Blue		2	Econ. Devel. Office 5	Positive	6.99	3	1.4	4.4
440	3/19/2019 11:46	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	White		2	Econ. Devel. Office 5	Positive	10	3.3	2.3	5.6
473	3/19/2019 12:15	mg/cm ²	Window Inside Stop	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Kitchen	Positive	8.41	0.4	0.6	1
517	3/19/2019 12:38	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Green	Cracking	2	Econ. Devel. Office 3	Positive	1.82	0.23	0.77	1
521	3/19/2019 12:43	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	2	Econ. Devel. Office 3a	Positive	6.97	0.4	0.6	1
564	3/19/2019 13:06	mg/cm ²	Safe Frame	Metal	C	Deteriorated	Brown	Friction	2	Econ. Devel. N Hall	Positive	1.43	2.3	1.1	3.4
565	3/19/2019 13:06	mg/cm ²	Safe Door	Metal	C	Deteriorated	Brown	Friction/Impact	2	Econ. Devel. N Hall	Positive	1.35	1.2	0.2	1.4
575	3/19/2019 13:12	mg/cm ²	Column	Plaster	C	Intact	White		2	Econ. Devel. N Hall	Positive	4.46	0.4	0.6	1
587	3/19/2019 13:25	mg/cm ²	Vault Door Casing/Header	Metal	B	Deteriorated	Grey	Cracking	2	Econ. Devel. Vault Hall	Positive	2.07	12.8	11.2	24
588	3/19/2019 13:25	mg/cm ²	Vault Door Jamb	Metal	B	Deteriorated	Green	Friction	2	Econ. Devel. Vault Hall	Positive	1.31	1.4	0.3	1.7
589	3/19/2019 13:25	mg/cm ²	Vault Door	Metal	B	Deteriorated	Grey	Friction/Impact	2	Econ. Devel. Vault Hall	Positive	1.83	22.1	14.2	36.3
602	3/19/2019 13:33	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. Office 1	Positive	2.91	0.8	0.7	1
605	3/19/2019 13:34	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 1	Positive	10	2.8	1.1	3.9
614	3/19/2019 13:42	mg/cm ²	Wall	Plaster	C	Intact	White		2	Lobby W Hall	Positive	5.9	2.1	0.9	3
615	3/19/2019 13:42	mg/cm ²	Wall	Plaster	D	Intact	Grey		2	Lobby W Hall	Positive	6.46	2.2	1.1	3.3
616	3/19/2019 13:43	mg/cm ²	Wall Near Stairway	Plaster	A	Intact	White		2	Lobby W Hall	Positive	5.25	2.7	1.5	4.2
617	3/19/2019 13:43	mg/cm ²	Wall Near Stairway	Plaster	B	Deteriorated	White	Cracking	2	Lobby W Hall	Positive	6.36	2	0.9	2.9
618	3/19/2019 13:44	mg/cm ²	Radiator	Metal	A	Deteriorated	White	Chipping	2	Lobby W Hall	Positive	7.09	2	1	3
619	3/19/2019 13:44	mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	Dark Brown	Chipping	2	Lobby W Hall	Positive	5.11	1.5	0.4	1.9
626	3/19/2019 13:47	mg/cm ²	Outer Door Casing/Header	Metal	C	Intact	White		2	Lobby W Hall	Positive	4.08	3.7	1.7	5.4
646	3/19/2019 13:56	mg/cm ²	Baseboard	Wood	All	Deteriorated	Beige	Chipping	2	Lobby W Hall Closet	Positive	2.19	0.8	1.1	1.9
660	3/19/2019 14:09	mg/cm ²	Radiator	Metal	C	Intact	Grey		2	Womens Restroom	Positive	2.42	1.5	0.6	2.1
671	3/19/2019 14:12	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Womens Restroom	Positive	2.81	0.08	0.92	1
673	3/19/2019 14:15	mg/cm ²	Wall	Plaster	A	Intact	Grey		2	Central Staircase	Positive	5.79	0.3	0.7	1
685	3/19/2019 14:22	mg/cm ²	Arched Ceiling	Plaster	All	Intact	White		2	Central Staircase	Positive	10	2.3	1	3.3
686	3/19/2019 14:23	mg/cm ²	Ceiling Molding	Plaster	All	Intact	White		2	Central Staircase	Positive	10	1.2	0.4	1.6
694	3/19/2019 14:32	mg/cm ²	Wall	Plaster	C	Intact	White		2	Server Room	Positive	5.94	0.28	0.72	1
724	3/19/2019 15:11	mg/cm ²	Window Trough	Metal	B	Intact	Brown		1/2	Storage 1	Positive	4.76	0.3	0.7	1
732	3/19/2019 15:15	mg/cm ²	Wall	Plaster	D	Intact	White		1/2	SW Stair/Outside Storage 1	Positive	5.82	2.7	1.6	4.3
746	3/19/2019 15:20	mg/cm ²	Wall	Plaster	D	Intact	White		1/2	SW Stairway to Main Floor	Positive	3.47	0.5	0.5	1
803	3/19/2019 15:56	mg/cm ²	Wall Above Drop Ceiling	Plaster	B	Deteriorated	Beige	Cracking	1	Conference 1	Positive	9.64	3.9	2.6	6.5
805	3/19/2019 15:57	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Yellow	Cracking	1	Conference 1	Positive	7.77	4.2	3.1	7.3
814	3/19/2019 16:03	mg/cm ²	Vault Door Casing/Header	Metal	B	Intact	Beige		1	Conference 1	Positive	5.2	12.1	10.8	22.9
815	3/19/2019 16:03	mg/cm ²	Vault Door Jamb	Metal	B	Deteriorated	Green	Friction	1	Conference 1	Positive	1.25	1.4	0.3	1.7
816	3/19/2019 16:03	mg/cm ²	Vault Door	Metal	B	Deteriorated	Beige	Friction/Impact	1	Conference 1	Positive	3.54	14.8	11.7	26.5
872	3/19/2019 16:49	mg/cm ²	Wall	Plaster	B	Intact	Green		1	Storage 4 Restroom	Positive	4.78	0.4	0.6	1
878	3/19/2019 16:50	mg/cm ²	Sink Tile	Ceramic	B	Deteriorated	White	Cracking	1	Storage 4 Restroom	Positive	2.68	5.2	3.3	8.5
896	3/19/2019 16:58	mg/cm ²	Wall	Plaster	C	Deteriorated	Orange	Cracking	1	Conference 3	Positive	6.14	0.2	0.8	1
898	3/19/2019 16:59	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Conference 3	Positive	10	1	0.2	1.2
952	3/19/2019 17:36	mg/cm ²	Wall	Plaster	A	Intact	Yellow		1	Admin Restroom	Positive	10	3.3	1.4	4.7

Table 2: Fort Dodge City Hall - Positive XRF Results (continued)

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
953	3/19/2019 17:36	mg/cm ²	Wall	Plaster	B	Intact	Yellow		1	Admin Restroom	Positive	10	2.9	1.4	4.3
954	3/19/2019 17:36	mg/cm ²	Wall	Plaster	C	Intact	Yellow		1	Admin Restroom	Positive	6.14	0.5	0.5	1
955	3/19/2019 17:37	mg/cm ²	Wall	Plaster	D	Intact	Yellow		1	Admin Restroom	Positive	8.87	2.2	1.1	3.3
958	3/19/2019 17:37	mg/cm ²	Radiator	Metal	D	Intact	Brown		1	Admin Restroom	Positive	2.55	1.1	0.2	1.3
965	3/19/2019 17:39	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Admin Restroom	Positive	6.7	4.4	2.9	7.3
988	3/19/2019 17:56	mg/cm ²	Vault Door Casing/Header	Metal	B	Intact	Beige		1	Admin Vault Hall	Positive	6.03	14.6	11.7	26.3
989	3/19/2019 17:56	mg/cm ²	Vault Door Jamb	Metal	B	Deteriorated	Green	Friction	1	Admin Vault Hall	Positive	1.39	1.9	0.8	2.7
990	3/19/2019 17:56	mg/cm ²	Vault Door	Metal	B	Deteriorated	Beige	Friction/Impact	1	Admin Vault Hall	Positive	5.99	17.4	12.1	29.5
995	3/19/2019 17:58	mg/cm ²	Wall	Concrete	D	Intact	White		1	Admin Vault	Positive	2.07	0.4	0.6	1
1037	3/19/2019 18:29	mg/cm ²	Wall	Plaster	B	Intact	Grey		1	Lobby W Hall	Positive	7.88	1.7	0.6	2.3
1038	3/19/2019 18:30	mg/cm ²	Wall	Plaster	D	Intact	Grey		1	Lobby W Hall	Positive	10	1.2	0.2	1.4
1039	3/19/2019 18:32	mg/cm ²	Column Frame	Plaster	All	Intact	White		1	Lobby W Hall	Positive	10	1.2	0.3	1.5
1046	3/19/2019 18:35	mg/cm ²	Hose Case Casing	Wood	B	Intact	Stain		1	Lobby W Hall	Positive	1.19	0.7	0.3	1
1049	3/19/2019 18:35	mg/cm ²	Wall	Plaster	C	Intact	Grey		1	Lobby W Hall	Positive	10	7.4	4.6	12
1052	3/19/2019 18:37	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Lobby W Hall	Positive	10	0.4	0.6	1
1053	3/19/2019 18:38	mg/cm ²	Crown Molding	Plaster	All	Intact	White		1	Lobby W Hall	Positive	10	1.2	0.5	1.7
1069	3/19/2019 18:47	mg/cm ²	Wall	Plaster	B	Intact	White		1	SW Stairway Hall	Positive	5.72	2.6	1.4	4
1072	3/19/2019 18:47	mg/cm ²	Radiator	Metal	A	Deteriorated	White	Chipping	1	SW Stairway Hall	Positive	5.15	1	0.2	1.2
1090	3/19/2019 18:51	mg/cm ²	Stair Lower Wall	Wood	D	Intact	White		1	SW Stairway	Positive	4.04	2.5	1.3	3.8
1162	3/20/2019 8:18	mg/cm ²	Wall Tile	Ceramic	D	Intact	Grey		1	Lobby Hall	Positive	3.17	4.7	3.2	7.9
1164	3/20/2019 8:22	mg/cm ²	Wall	Plaster	B	Intact	Grey		1	Foyer	Positive	10	3.4	2.3	5.7
1165	3/20/2019 8:22	mg/cm ²	Wall	Plaster	D	Intact	Grey		1	Foyer	Positive	6.21	2.6	1.5	4.1
1172	3/20/2019 8:27	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Front Entry	Positive	10	7.9	4.6	12.5
1173	3/20/2019 8:27	mg/cm ²	Crown Molding	Plaster	All	Intact	White		1	Front Entry	Positive	10	5.3	3.7	9
1196	3/20/2019 8:45	mg/cm ²	Radiator	Metal	A/B	Intact	Brown		1	Park and Rec Office 2	Positive	6.59	2.8	1.4	4.2
1214	3/20/2019 8:54	mg/cm ²	Radiator	Metal	A	Intact	Brown		1	Park and Rec Office 1	Positive	10	7.1	4.8	11.9
1241	3/20/2019 9:08	mg/cm ²	Door Jamb	Metal	B	Intact	Beige	Friction	1	Park and Rec Vault	Positive	2.4	1.5	0.5	2
1242	3/20/2019 9:08	mg/cm ²	Door	Metal	B	Intact	Black	Friction/Impact	1	Park and Rec Vault	Positive	2.23	17.7	12.8	30.5
1250	3/20/2019 9:10	mg/cm ²	Vault Door Casing/Header	Metal	D	Intact	Black		1	Park and Rec W Hall	Positive	2.11	16.7	12.4	29.1
1276	3/20/2019 9:24	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	1	Park and Rec Storage	Positive	1.7	4.8	3.7	8.5
1293	3/20/2019 9:41	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Chipping	1	Council Chambers Restroom	Positive	1.27	0.19	0.81	1
1314	3/20/2019 10:03	mg/cm ²	Vault Door Casing/Header	Metal	B	Intact	Brown		1	Billing Main Office	Positive	5.98	14.4	11.7	26.1
1315	3/20/2019 10:03	mg/cm ²	Vault Door	Metal	B	Intact	Brown	Friction/Impact	1	Billing Main Office	Positive	4.9	17.3	12.9	30.2
1316	3/20/2019 10:03	mg/cm ²	Vault Door Jamb	Metal	B	Intact	Green	Friction	1	Billing Main Office	Positive	1.32	1.5	0.4	1.9
1317	3/20/2019 10:03	mg/cm ²	Vault Door Threshold	Metal	B	Deteriorated	Green	Friction	1	Billing Main Office	Positive	1.55	0.7	0.3	1
1318	3/20/2019 10:04	mg/cm ²	Wall	Concrete	A	Intact	White		1	Billing Vault	Positive	5.46	0.16	0.84	1
1324	3/20/2019 10:23	mg/cm ²	Wall	Plaster	A	Intact	White		1	SW Entry Hall	Positive	4.56	3.9	1.9	5.8
1325	3/20/2019 10:23	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	1	SW Entry Hall	Positive	3.59	4.5	3.1	7.6
1326	3/20/2019 10:23	mg/cm ²	Wall	Plaster	C	Intact	White		1	SW Entry Hall	Positive	3.91	4.9	3.5	8.4
1328	3/20/2019 10:24	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	SW Entry Hall	Positive	8.95	13.9	10.8	24.7
1345	3/20/2019 10:28	mg/cm ²	Door Slop	Wood	C	Deteriorated	Brown	Impact	1	SW Entry Hall	Positive	2.97	26	23.8	49.8
1353	3/20/2019 10:33	mg/cm ²	Wood Beam	Wood	B	Intact	White		1	SW Entry	Positive	4.75	14.1	10.1	24.2
1355	3/20/2019 10:35	mg/cm ²	Door Casing/Header	Wood	A	Intact	Brown		1	SW Entry	Positive	2.27	32.7	28.3	61
1356	3/20/2019 10:36	mg/cm ²	Door Transom Sash	Wood	A	Intact	White		1	SW Entry	Positive	2.36	39.3	31.8	71.1
1357	3/20/2019 10:36	mg/cm ²	Door Transom Jamb	Wood	A	Deteriorated	Brown	Cracking	1	SW Entry	Positive	2.62	30.1	26.1	56.2
1379	3/20/2019 10:57	mg/cm ²	Window Sash	Wood	C	Deteriorated	White	Cracking	1	SW Entry Storage 2	Positive	2.11	2.8	1.6	4.4
1412	3/20/2019 11:27	mg/cm ²	Wall	Wood	A	Deteriorated	White	Cracking	1	SW Basement Entry Hall	Positive	3.22	2	0.8	2.8
1413	3/20/2019 11:27	mg/cm ²	Wall	Plaster	B	Intact	White		1	SW Basement Entry Hall	Positive	5.71	2.4	1.2	3.6
1414	3/20/2019 11:27	mg/cm ²	Wall	Plaster	C	Intact	White		1	SW Basement Entry Hall	Positive	4.69	1.2	0.2	1.4
1415	3/20/2019 11:27	mg/cm ²	Wall	Plaster	D	Intact	White		1	SW Basement Entry Hall	Positive	4.72	1.7	0.6	2.3
1420	3/20/2019 11:30	mg/cm ²	Closet Door	Wood	A	Deteriorated	White	Friction/Impact	1	SW Basement Entry Hall	Positive	3.64	3	1.9	4.9
1452	3/20/2019 11:54	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	1	SW Map Room	Positive	3.15	5.1	3.3	8.4
1453	3/20/2019 11:54	mg/cm ²	Wall	Wood	A	Deteriorated	Brown	Cracking	1	SW Map Room	Positive	3.05	3.9	2.6	6.5
1456	3/20/2019 11:55	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	1	SW Map Room	Positive	3.42	5.7	3.9	9.6
1457	3/20/2019 11:55	mg/cm ²	Wall	Plaster	C	Deteriorated	Brown	Cracking	1	SW Map Room	Positive	3.09	12	10.1	22.1
1458	3/20/2019 11:55	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	1	SW Map Room	Positive	3.56	6.4	4.3	10.7
1459	3/20/2019 11:55	mg/cm ²	Wall	Plaster	D	Deteriorated	Brown	Cracking	1	SW Map Room	Positive	3.58	4.8	3.3	8.1
1461	3/20/2019 11:56	mg/cm ²	Radiator	Metal	A	Deteriorated	Grey	Chipping	1	SW Map Room	Positive	4.84	4.5	3	7.5
1463	3/20/2019 11:57	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	SW Map Room	Positive	4.59	0.9	1.2	2.1

Table 2: Fort Dodge City Hall - Positive XRF Results (continued)

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1471	3/20/2019 12:43	mg/cm ²	Wall	Plaster	B	Deteriorated	Grey	Cracking	Basement E14	Basement E14	Positive	1.99	0.5	0.5	1
1472	3/20/2019 12:44	mg/cm ²	Wall	Plaster	C	Deteriorated	Grey	Cracking	Basement E14	Basement E14	Positive	1.89	0.5	0.5	1
1509	3/20/2019 13:04	mg/cm ²	Pipe	Metal	-	Intact	Yellow		Basement E13B	Basement E13B	Positive	1.93	2	0.7	2.7
1533	3/20/2019 13:15	mg/cm ²	Pipe	Metal	C	Deteriorated	White	Chipping	Basement E13A	Basement E13A	Positive	1.24	1.3	0.3	1.6
1552	3/20/2019 13:30	mg/cm ²	Window Sash	Wood	D	Deteriorated	Brown	Friction/Impact	Basement E13	Basement E13	Positive	1.47	2	0.9	2.9
1566	3/20/2019 13:42	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement E04	Basement E04	Positive	10	10.4	5.6	16
1586	3/20/2019 13:51	mg/cm ²	Drive in Wall Stripe	Concrete	-	Deteriorated	Yellow	Impact	Basement E04	Basement E04	Positive	3.24	3.4	2.3	5.7
1595	3/20/2019 13:58	mg/cm ²	Window Sill	Concrete	D	Deteriorated	White	Chewable	Basement E12	Basement E12	Positive	1.34	1.1	0.1	1.2
1615	3/20/2019 14:08	mg/cm ²	Stud Cross Member	Wood	B	Deteriorated	Yellow	Chipping	Basement E11	Basement E11	Positive	1.61	4.2	2	6.2
1616	3/20/2019 14:10	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	White	Cracking	Basement E11	Basement E11	Positive	1.62	1.6	0.5	2.1
1617	3/20/2019 14:10	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	Green	Cracking	Basement E11	Basement E11	Positive	1.33	2.1	0.8	2.9
1619	3/20/2019 14:16	mg/cm ²	Wall	Wood	A	Deteriorated	White	Cracking	Basement E10	Basement E10	Positive	3.12	1.1	0.1	1.2
1621	3/20/2019 14:17	mg/cm ²	Wall	Wood	B	Deteriorated	White	Cracking	Basement E10	Basement E10	Positive	2.97	0.9	0.1	1
1622	3/20/2019 14:17	mg/cm ²	Wall	Wood	B	Deteriorated	Green	Cracking	Basement E10	Basement E10	Positive	2.49	1.8	0.7	2.5
1623	3/20/2019 14:17	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement E10	Basement E10	Positive	3.76	1.1	0.2	1.3
1624	3/20/2019 14:18	mg/cm ²	Wall	Plaster	C	Deteriorated	Green	Cracking	Basement E10	Basement E10	Positive	3.6	0.8	0.2	1
1625	3/20/2019 14:18	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E10	Basement E10	Positive	4.22	1.3	0.3	1.6
1626	3/20/2019 14:18	mg/cm ²	Wall	Plaster	D	Deteriorated	Green	Cracking	Basement E10	Basement E10	Positive	2.99	1.3	0.3	1.6
1627	3/20/2019 14:19	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement E10	Basement E10	Positive	3.69	1.2	0.2	1.4
1641	3/20/2019 14:33	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	Basement E09 Restroom	Basement E09 Restroom	Positive	6.82	5.4	4.3	9.7
1642	3/20/2019 14:33	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	Basement E09 Restroom	Basement E09 Restroom	Positive	5.59	3.9	2.1	6
1643	3/20/2019 14:33	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	Basement E09 Restroom	Basement E09 Restroom	Positive	6.91	10.4	5.8	16.2
1644	3/20/2019 14:33	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	Basement E09 Restroom	Basement E09 Restroom	Positive	5.96	6.3	4.8	11.1
1646	3/20/2019 14:34	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	Basement E09 Restroom	Basement E09 Restroom	Positive	4.71	7.5	6	13.5
1647	3/20/2019 14:34	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement E09 Restroom	Basement E09 Restroom	Positive	2.41	7.7	6.1	13.8
1657	3/20/2019 14:45	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement E08	Basement E08	Positive	4.64	0.4	0.6	1
1660	3/20/2019 14:46	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E08	Basement E08	Positive	2.93	0.9	0.1	1
1665	3/20/2019 14:47	mg/cm ²	Window Sill	Ceramic	A	Deteriorated	White	Chewable	Basement E08	Basement E08	Positive	2.16	3.1	1.7	4.8
1666	3/20/2019 14:47	mg/cm ²	Bench Top	Wood	-	Deteriorated	Blue	Friction	Basement E08	Basement E08	Positive	2.29	1.2	0.2	1.4
1667	3/20/2019 14:47	mg/cm ²	Bench Frame	Wood	-	Deteriorated	Blue	Chipping	Basement E08	Basement E08	Positive	1.72	0.9	0.1	1
1670	3/20/2019 14:48	mg/cm ²	Shelf Frame	Wood	D	Deteriorated	White	Cracking	Basement E08	Basement E08	Positive	2.3	0.7	0.3	1
1677	3/20/2019 14:50	mg/cm ²	Sink	Metal	D	Deteriorated	White	Cracking	Basement E08	Basement E08	Positive	1.91	36.6	32.1	68.7
1683	3/20/2019 14:53	mg/cm ²	Cabinet Face	Wood	B	Deteriorated	White	Impact	Basement E08	Basement E08	Positive	2.2	0.8	0.2	1
1684	3/20/2019 14:53	mg/cm ²	Cabinet Door	Wood	B	Deteriorated	White	Friction/Impact	Basement E08	Basement E08	Positive	2.08	1	0.1	1.1
1690	3/20/2019 15:00	mg/cm ²	Shelf	Plaster	C	Deteriorated	White	Cracking	Basement E006	Basement E006	Positive	1.86	1	0.2	1.2
1703	3/20/2019 15:04	mg/cm ²	Shelf Frame	Wood	D	Deteriorated	White	Cracking	Basement E006	Basement E006	Positive	1.67	0.9	0.3	1.2
1704	3/20/2019 15:04	mg/cm ²	Shelf	Wood	D	Deteriorated	White	Friction	Basement E006	Basement E006	Positive	2.01	1.2	0.2	1.4
1706	3/20/2019 15:04	mg/cm ²	Work Bench Face	Wood	D	Deteriorated	White	Impact	Basement E006	Basement E006	Positive	1.26	0.7	0.3	1
1708	3/20/2019 15:05	mg/cm ²	Work Bench Shelf	Wood	D	Deteriorated	White	Friction	Basement E006	Basement E006	Positive	1.2	0.8	0.2	1
1709	3/20/2019 15:05	mg/cm ²	Hanger Board	Wood	B	Deteriorated	White	Cracking	Basement E006	Basement E006	Positive	3.52	4.3	3.1	7.4
1711	3/20/2019 15:07	mg/cm ²	Wall	Plaster	B	Deteriorated	Brown	Cracking	Basement E005	Basement E005	Positive	2.25	2.1	0.7	2.8
1712	3/20/2019 15:07	mg/cm ²	Wall	Plaster	C	Deteriorated	Brown	Cracking	Basement E005	Basement E005	Positive	1.93	1.6	0.5	2.1
1751	3/22/2019 9:55	mg/cm ²	Wall	Plaster	A	Intact	Blue		Basement E Stairway to Front Entry	Basement E Stairway to Front Entry	Positive	3.27	1.4	0.3	1.7
1753	3/22/2019 9:55	mg/cm ²	Wall	Plaster	B	Intact	Blue		Basement E Stairway to Front Entry	Basement E Stairway to Front Entry	Positive	2.35	1.1	0.1	1.2
1756	3/22/2019 9:57	mg/cm ²	Wall	Plaster	D	Intact	Blue		Basement E Stairway to Front Entry	Basement E Stairway to Front Entry	Positive	2.5	0.9	0.1	1
1761	3/22/2019 10:04	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement E01A	Basement E01A	Positive	4.58	1.1	0.1	1.2
1762	3/22/2019 10:04	mg/cm ²	Wall	Plaster	A	Deteriorated	Blue	Cracking	Basement E01A	Basement E01A	Positive	4.44	1.4	0.4	1.8
1766	3/22/2019 10:05	mg/cm ²	Wall	Plaster	C	Deteriorated	Blue	Cracking	Basement E01A	Basement E01A	Positive	3.72	3.3	1.5	4.8
1774	3/22/2019 10:07	mg/cm ²	Floor Stripe	Concrete	All	Deteriorated	Yellow	Friction	Basement E01A	Basement E01A	Positive	2.1	3.1	1.7	4.8
1776	3/22/2019 10:08	mg/cm ²	Column	Plaster	All	Deteriorated	Blue	Cracking	Basement E01A	Basement E01A	Positive	3.33	1.5	0.5	2
1794	3/22/2019 10:11	mg/cm ²	Floor Drain	Wood	-	Deteriorated	Yellow	Chipping	Basement E01A	Basement E01A	Positive	1.64	1.5	0.4	1.9
1798	3/22/2019 10:14	mg/cm ²	Work Bench Frame	Wood	All	Deteriorated	Blue	Cracking	Basement E01A	Basement E01A	Positive	2.55	2.9	1.8	4.7
1799	3/22/2019 10:14	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement E01A	Basement E01A	Positive	5.46	4.2	2.3	6.5
1806	3/22/2019 10:15	mg/cm ²	Work Bench	Wood	All	Deteriorated	Blue	Friction	Basement E01A	Basement E01A	Positive	2.5	1.5	0.4	1.9
1809	3/22/2019 10:17	mg/cm ²	Shelf Frame	Wood	C	Deteriorated	Blue	Cracking	Basement E01A	Basement E01A	Positive	2.22	1.1	0.1	1.2
1815	3/22/2019 10:20	mg/cm ²	Ceiling	Concrete	All	Deteriorated	Brown	Cracking	Basement E01 Vault	Basement E01 Vault	Positive	1.8	0.5	0.5	1
1824	3/22/2019 10:25	mg/cm ²	Wall	Plaster	A	Deteriorated	Green	Cracking	Basement E01D	Basement E01D	Positive	1.37	0.9	0.1	1
1828	3/22/2019 10:27	mg/cm ²	Wall	Plaster	C	Deteriorated	Green	Cracking	Basement E01D	Basement E01D	Positive	1.44	0.9	0.1	1
1830	3/22/2019 10:28	mg/cm ²	Wall	Plaster	D	Deteriorated	Green	Cracking	Basement E01D	Basement E01D	Positive	1.32	1.5	0.4	1.9

Table 2: Fort Dodge City Hall - Positive XRF Results (continued)

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1831	3/22/2019 10:28	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	Basement	E01D	Positive	2.26	0.8	0.4	1.2
1832	3/22/2019 10:30	mg/cm ²	Hanger Board	Wood	All	Deteriorated	Beige	Cracking	Basement	E01D	Positive	2.07	0.8	0.2	1
1833	3/22/2019 10:35	mg/cm ²	Wall	Plaster	A	Deteriorated	Brown	Cracking	Basement	E01C	Positive	7.4	4.9	3.1	8
1834	3/22/2019 10:35	mg/cm ²	Wall	Plaster	B	Deteriorated	Brown	Cracking	Basement	E01C	Positive	8.05	6.7	4.4	11.1
1835	3/22/2019 10:35	mg/cm ²	Wall	Plaster	C	Deteriorated	Brown	Cracking	Basement	E01C	Positive	3.15	2	0.9	2.9
1836	3/22/2019 10:36	mg/cm ²	Wall	Plaster	D	Deteriorated	Brown	Cracking	Basement	E01C	Positive	8.31	6.3	4.6	10.9
1838	3/22/2019 10:36	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	E01C	Positive	9.26	4.8	3.3	8.1
1839	3/22/2019 10:36	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement	E01C	Positive	1.67	2.2	1	3.2
1852	3/22/2019 10:38	mg/cm ²	Sink	Metal	B	Intact	White		Basement	E01C	Positive	1.55	3.8	2.5	6.3
1853	3/22/2019 10:39	mg/cm ²	Pipe	Metal	All	Deteriorated	Grey	Chipping	Basement	E01C	Positive	1.95	13.1	10.8	23.9
1855	3/22/2019 10:41	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	E01B	Positive	5	10.9	9.6	20.5
1856	3/22/2019 10:41	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement	E01B	Positive	5.31	9.4	8.2	17.6
1857	3/22/2019 10:41	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement	E01B	Positive	6.82	15.1	11.5	26.6
1859	3/22/2019 10:42	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	E01B	Positive	4.87	9.5	8	17.5
1860	3/22/2019 10:42	mg/cm ²	Radiator	Metal	All	Intact	White		Basement	E01B	Positive	2.57	6.2	3.5	9.7
1870	3/22/2019 10:49	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	Grey	Cracking	Basement	E02B	Positive	1.28	1.5	0.4	1.9
1871	3/22/2019 10:49	mg/cm ²	Shelf	Wood	A	Deteriorated	Grey	Friction	Basement	E02B	Positive	1.25	1.2	0.2	1.4
1877	3/22/2019 10:54	mg/cm ²	Work Bench	Wood	D	Deteriorated	Green	Friction	Basement	E02A	Positive	1.26	0.6	0.4	1
1879	3/22/2019 10:54	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement	E02A	Positive	1.29	0.9	0.1	1
1881	3/22/2019 10:54	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement	E02A	Positive	5.25	5.5	3.4	8.9
1883	3/22/2019 10:55	mg/cm ²	Cabinet Face	Wood	B	Deteriorated	Blue	Impact	Basement	E02A	Positive	2.02	2.1	1.1	3.2
1884	3/22/2019 10:55	mg/cm ²	Cabinet Door	Wood	B	Deteriorated	Blue	Friction/Impact	Basement	E02A	Positive	1.56	1.1	0.1	1.2
1891	3/22/2019 10:56	mg/cm ²	Door Threshold	Concrete	C	Deteriorated	Yellow	Friction	Basement	E02A	Positive	10	2.3	1.3	3.6
1892	3/22/2019 11:01	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement	E02	Positive	2.57	0.4	0.6	1
1897	3/22/2019 11:03	mg/cm ²	Radiator	Metal	-	Deteriorated	White	Chipping	Basement	E02	Positive	2.75	0.8	0.2	1
1900	3/22/2019 11:03	mg/cm ²	Steps	Concrete	All	Deteriorated	Yellow	Impact	Basement	E02	Positive	10	2.1	1.1	3.2
1903	3/22/2019 11:04	mg/cm ²	Overhead Door Frame	Wood	C	Deteriorated	White	Cracking	Basement	E02	Positive	1.94	0.7	0.3	1
1904	3/22/2019 11:04	mg/cm ²	A/C Unit Casing	Wood	A	Deteriorated	Blue	Chipping	Basement	E02	Positive	1.29	0.6	0.4	1
1920	3/22/2019 11:14	mg/cm ²	Wall	Concrete	C	Deteriorated	Blue	Cracking	Basement	E03B	Positive	1.82	1.4	0.4	1.8
1921	3/22/2019 11:14	mg/cm ²	Wall	Concrete	D	Deteriorated	Blue	Cracking	Basement	E03B	Positive	1.33	1.3	0.3	1.6

If areas of ACM and LBP components will remain, Impact7G recommends establishing an Operations & Maintenance (O&M) program. The O&M program should at a minimum consist of training, cleaning, work practices, monitoring, and recordkeeping to maintain these materials in good condition. Additional details on establishing an O&M program are discussed in Section 6.0 of this report.

This report is designed to aid the building owner, architect, construction manager, general contractor, and/or remediation contractor in locating LBP. This report is not to be used as abatement specifications, as it does not contain needed components to serve as such.

2.0 INTRODUCTION

A. Property Information

Location:

Fort Dodge City Hall
819 First Avenue South
Fort Dodge, Iowa 50501

Contact Person:

Mr. Ryan Meahl
City of Fort Dodge
819 First Avenue South
Fort Dodge, Iowa 50501

B. Personnel

Project Manager/QC/QA: Jon Reis

State of Iowa Lead License LEAD-INSP10006

State of Iowa Asbestos License 18-0950

ACM Inspector: Jacob Huxford State of Iowa Lead License 19-1795

LBP Inspector: Tyler Silverthorn State of Iowa Lead License LEAD- INSP10031

C. Sampling Plan

The scope of this ACM & LBP Inspection included the interior of the structure located on the Property.

Impact7G completed an ACM Inspection in accordance with OSHA Regulation 1926.1101 and EPA 40 CFR Part 763 (AHERA). All samples collected in the field were analyzed by Impact7G's in-house laboratory. The samples were analyzed via the polarized light microscopy (PLM) method for asbestos content. When required, samples were further analyzed via the transmission electron microscopy (TEM) method or PLM 400 Point Count analysis method.

The LBP Inspection was based on Iowa Administrative Code (IAC) *Chapter 70 – Lead-Based Paint Activities*. These guidelines, and additional EPA guidelines, specify using an X-Ray Fluorescence (XRF) analyzer to detect LBP on all coated surfaces within the structure.

D. Regulation Review

The U.S. EPA qualifies asbestos containing materials (ACM) as materials with an asbestos content greater than 1%. According to Iowa OSHA, ACM is any material found to contain asbestos, regardless of its concentration, and shall be regulated as hazardous waste. The following definitions are taken from Section 61.141 of Subpart M, Part 61 of Title 40: Protection of Environment of the Code of Federal Regulations (CFR).

- “Category I nonfriable asbestos-containing material (ACM)” is defined as asbestos-containing packings, gaskets, resilient floor covering, and asphalt roofing products containing more than 1% asbestos as determined using the method specified in appendix E, subpart E, 40 CFR part 763, section 1, Polarized Light Microscopy (PLM).
- “Category II nonfriable ACM” is defined as any material, excluding Category I nonfriable ACM, containing more than 1% asbestos as determined using the methods specified in Appendix E, Subpart E, 40 CFR Part 763, Section 1, PLM that, when dry, **cannot** be crumbled, pulverized, or reduced to powder by hand pressure.

- “Friable asbestos material” is defined as any material containing more than 1% asbestos as determined using the methods specified in appendix E, subpart E, 40 CFR part 763, section 1, PLM that when dry, **can** be crumbled, pulverized, or reduced to powder by hand pressure. If the asbestos content is less than 10% as determined by a method other than point counting by PLM, verify the asbestos content by point counting using PLM.

Lead-Based Paint (LBP) is defined as paint or other surface coatings that contain lead greater than or equal to 1.0 milligram per square centimeter (mg/cm²) or greater than 0.5 percent (%) by weight. LBP is present on any surface that is tested and found to contain lead above these levels, and on any surface like a surface tested in the same room equivalent that has a similar painting history and that is found to be LBP.

3.0 PROPERTY DESCRIPTION

The Property consists of a 2-story commercial building currently utilized as the City of Fort Dodge City Hall.

4.0 INSPECTION LIMITATIONS

An Inspection limitation, for the purpose of this report, is any action or task that is limited from the original scope work. The overall reason for any limitation is the protection of Impact7G personnel. Examples of limitations can range from a lack of accessibility to an area of the Property, unsafe work areas, collecting additional samples, etc.

The following limitations were encountered during this ACM and LBP Inspection.

- No roof or exterior samples were collected during this ACM and LBP Inspection. Discreet sampling methods were used.

No additional limitations were encountered during this ACM and LBP Inspection.

5.0 INSPECTION ACTIVITIES

5.1 Asbestos Containing Material Sampling

Iowa certified asbestos inspectors from Impact7G collected three-hundred and sixty-three (363) samples between March 18th and 21st, 2019 and April 3rd, 2019. The samples were collected from various building components located throughout the building’s interior. Upon completion of bulk sampling activities, samples were sent to a certified laboratory under chain of custody for analysis by polarized light microscopy (PLM).

Materials that are “suspected” to contain asbestos are divided into the following three categories:

1. **Surfacing materials** are materials that are sprayed or troweled on for acoustical, decorative, or fireproofing purposes. Examples are textured ceilings or drywall, exterior stucco and structural steel fireproofing;
2. **Thermal System Insulation (TSI)** is insulation used to inhibit heat transfer from pipes, boilers, tanks, ducts, and various other components of hot and cold-water systems and

HVAC systems. Examples are hard cementitious “mud” type insulation on pipes, boilers and flues; and,

3. **Miscellaneous** materials are mostly non-friable products and materials such as floor tile, drywall, ceiling tile and roofing felt.

The following tables show samples positively identified by the laboratory to be asbestos containing materials (ACM) and samples that were analyzed as non-ACM. The complete analytical results can be found in Appendix B.

Table 3 – Asbestos Containing Materials Sample List

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content	Est. Quantity
19JH031938	Tile Cove Base	Misc	N	Gray	2nd	Economic Development – Kitchen – e211J	2% Chrysotile	10 LF
19JH031940	Floor Tile Mastic	Misc	N	Black	2nd	Economic Development – Kitchen – e211J	10% Chrysotile	70 SF
19JH031945	Wall Adhesive	Misc	N	Black	2nd	Economic Development – Waiting Room – e211A	2% Chrysotile	4,650 – Throughout 2nd Floor
19JH031972	Drywall Joint Compound	Misc	N	White	2nd	Inspections/Engineering – Lobby – e205A	<1% Chrysotile	1,200 SF
19JH031980	12" x 12" Floor Tile	Misc	N	Cream w/ Tan Streaks	2nd	Inspections/Engineering – e205B	2% Chrysotile	1,100 SF
19JH031991	Sink Undercoat	Misc	N	Black	2nd	Human Resources – Kitchen – e203A	2% Chrysotile	1 Sink
19JH031993	Drywall Joint Compound	Misc	N	White	2nd	Human Resources – Storage – e203F	<1% Chrysotile	1,600 SF
19JH031997	Ceiling Tile	Misc	N	White	2nd	Human Resources – Storage – e203F	<1% Amosite	950 SF
19JH0319108	Sink Undercoat	Misc	N	White	1st	Storage – e147	2% Chrysotile	1 Sink
19JH0319113	12" x 12" Floor Tile	Misc	N	Brown	1st	Breakroom – e143A and Conference Room (David) – e143B	3% Chrysotile	625 SF
19JH0319114	Floor Tile Mastic	Misc	N	Black	1st	Breakroom – e143A	2% Chrysotile	Same as 19JH0319113
19JH0319117	Wall Mastic	Misc	N	Brown	1st	Breakroom – e143A	2% Chrysotile	180 SF
19JH0319118	Floor Tile	Misc	N	Maroon	1st	Breakroom – e143A	3% Chrysotile	Same as 19JH0319113
19JH0319120	Floor Tile	Misc	N	Green	1st	Breakroom – e143A	3% Chrysotile	Same as 19JH0319113
19JH0319121	Floor Tile	Misc	N	Black	1st	Breakroom – e143A	3% Chrysotile	Same as 19JH0319113
19JH0319126	Wall Mastic	Misc	N	Black	1st	Breakroom – e143A	2% Chrysotile	Same as 19JH0319113
19JH0319175	Wall Panel Mastic	Misc	N	Black	1st	City Administrator – Storage/Attorney (Ryan) – e135	2% Chrysotile	1,250 – Throughout 1st Floor
19JH0319229 ABC	Pipe Insulation	TSI	Y	White	1st	Electrical Room – e158	65% Chrysotile	65 LF

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content	Est. Quantity
19JH0319232 ABC	Mudded Joints	TSI	Y	White	1 st	Electrical Room – e158	55% Chrysotile	10 Fittings
19JH0319261	Pipe Wrap (tar like)	Misc	N	Black	B	Storage e13A	4% Chrysotile	6 LF
19JH0403337	Drywall Joint Compound	Misc	N	White	2 nd	Engineering/Inspections – e205C	<1% Chrysotile	Same as 19JH031972
19JH0403340	Drywall Joint Compound	Misc	N	White	2 nd	Engineering/Inspections – e205E	<1% Chrysotile	Same as 19JH031972
19JH0403342	Ceiling Tile	Misc	N	White	2 nd	Human Resources – e203A	<1% Amosite 2% Chrysotile	Same as 19JH031997
19JH0403343	Ceiling Tile	Misc	N	White	2 nd	Human Resources – e203B	<1% Amosite 2% Chrysotile	Same as 19JH031997
19JH0403344	Ceiling Tile	Misc	N	White	2 nd	Human Resources – e203E	<1% Amosite 2% Chrysotile	Same as 19JH031997
19JH0403346	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – e203A	<1% Chrysotile	Same as 19JH031993
19JH0403349	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – e203E	<1% Chrysotile	Same as 19JH031993
19JH0403352	Drywall Joint Compound	Misc	N	White	2 nd	Human Resources – e203B	<1% Chrysotile	Same as 19JH031993

Material Type – Surf=Surfacing, TSI=Thermal System Insulation, Misc=Miscellaneous / **Est. Quantity** – SF=Square foot, LF=Linear foot, EA=Each

Asbestos Containing Material (ACM) is defined as any material containing more than one percent (1%) asbestos. Although building materials containing less than <1% asbestos are not classified ACM by the EPA, they may still be regulated as asbestos by Iowa OSHA and should be treated as such. Twenty (20) bulk material sample was analyzed greater than 1%. Eight (8) of the remaining building material samples were detected with a concentration of <1%. **Due to positive stop analysis, sample numbers 19JH0319229B, 19JH0319229C, 19JH0319232B, and 19JH0319232C were not analyzed.** ACMs include tile cove base, floor tile mastic, wall adhesive/mastic, drywall joint compound, 12" x 12" Floor Tile(s), sink undercoats, ceiling tile(s), floor tile(s), pipe insulation, mudded joints, and pipe wrap. If during renovation activities additional areas of identified ACM are discovered, they should be abated accordingly. Laboratory analytical reports are provided in Appendix B.

Table 4 – Non-Asbestos Containing Material Sample List

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH031901	Wall Plaster	Surf	N	Gray	2 nd	Jail – e211U	ND
19JH031902	Wall Skim Coat	Surf	N	Gray	2 nd	Jail – e211U	ND
19JH031903	Caulk	Misc	N	Gray	2 nd	Jail – e211U	ND
19JH031904	Ceiling Plaster	Surf	N	Gray	2 nd	Former Jail – e211T	ND
19JH031905	Ceiling Skim Coat	Surf	N	Gray	2 nd	Former Jail – e211T	ND
19JH031906	Felt Paper	Misc	N	Gray	2 nd	Former Jail – e211T	ND
19JH031907	Ceiling Plaster	Surf	N	White	2 nd	Former Jail – e211T	ND
19JH031908	Felt Paper	Misc	N	Gray	2 nd	Former Jail – e211T	ND
19JH031909	Tar Paper	Misc	N	Black	2 nd	Former Jail – e211T	ND
19JH031910	Ceiling Tile	Misc	N	Gray	2 nd	Economic Development – e211R	ND
19JH031911	Wall Plaster	Surf	N	Gray	2 nd	Former Jail – e211T	ND
19JH031912	Wall Skim Coat	Surf	N	Gray	2 nd	Former Jail – e211T	ND
19JH031913	Duct Insulation	Misc	N	Yellow	2 nd	Former Jail – e211T	ND
19JH031914	Duct Insulation Wrap	Misc	N	Silver	2 nd	Former Jail – e211T	ND
19JH031915	Duct Seam Tape	Misc	N	Gray/Silver	2 nd	Former Jail – e211T	ND
19JH031916	Cove Base	Misc	N	Gray	2 nd	Economic Development – Back Hall – e211Q	ND
19JH031917	Cove Base Mastic	Misc	N	Gold	2 nd	Economic Development – Back Hall – e211Q	ND
19JH031918	Carpet Mastic	Misc	N	Gold	2 nd	Economic Development – Back Hall – e211Q	ND
19JH031919	Drywall	Misc	N	White	2 nd	Economic Development – e211R	ND
19JH031920	Drywall Joint Compound	Misc	N	White	2 nd	Economic Development – e211R	ND
19JH031921	Drywall Tape	Misc	N	Cream	2 nd	Economic Development – e211R	ND
19JH031922	Drywall	Misc	N	White	2 nd	Economic Development – Hall – e211L	ND
19JH031923	Drywall Joint Compound	Misc	N	White	2 nd	Economic Development – Hall – e211L	ND
19JH031924	Drywall Tape	Misc	N	Cream	2 nd	Economic Development – Hall – e211L	ND
19JH031925	Corkboard	Misc	N	Brown	2 nd	Economic Development – e211O	ND
19JH031926	Corkboard Adhesive	Misc	N	Yellow	2 nd	Economic Development – e211O	ND
19JH031927	Floor Leveler	Misc	N	Gray	2 nd	Economic Development – Hall – e211L	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH031928	Carpet Adhesive	Misc	N	Yellow	2nd	Economic Development – Hall – e211L	ND
19JH031929	Wall Plaster	Surf	N	Gray	2nd	Economic Development – e211M	ND
19JH031930	Wall Skim Coat	Surf	N	Gray	2nd	Economic Development – e211M	ND
19JH031931	Countertop	Misc	N	Cream	2nd	Economic Development – Kitchen – e211J	ND
19JH031932	Countertop Adhesive	Misc	N	Gold	2nd	Economic Development – Kitchen – e211J	ND
19JH031933	Sink Undercoat	Misc	N	Gray	2nd	Economic Development – Kitchen – e211J	ND
19JH031934	Caulk	Misc	N	White	2nd	Economic Development – Kitchen – e211J	ND
19JH031935	Caulk	Misc	N	White	2nd	Economic Development – Kitchen – e211J	ND
19JH031936	Duct Insulation	Misc	N	Yellow	2nd	Economic Development – Kitchen – e211J	ND
19JH031937	Duct Wrap	Misc	N	Silver	2nd	Economic Development – Kitchen – e211J	ND
19JH031939	Cove Base Mastic	Misc	N	Gold	2nd	Economic Development – Kitchen – e211J	ND
19JH031941	Ceiling Tile	Misc	N	Yellow	2nd	Economic Development – Waiting Room – e211A	ND
19JH031942	Wall Insulation	Misc	N	Brown	2nd	Economic Development – Waiting Room – e211A	ND
19JH031943	Insulation Paper	Misc	N	Black	2nd	Economic Development – Waiting Room – e211A	ND
19JH031944	Window Caulk	Misc	N	Brown	2nd	Economic Development – e211F	ND
19JH031946	Carpet Adhesive	Misc	N	Dark Brown	2nd	Economic Development – Waiting Room – e211A	ND
19JH031947	Duct Insulation	Misc	N	Pink	2nd	Economic Development – e211C	ND
19JH031948	Duct Wrap	Misc	N	Silver	2nd	Economic Development – e211C	ND
19JH031949	Ceiling Insulation	Misc	N	Brown	2nd	Economic Development – e211C	ND
19JH031950	Ceiling Skim Coat	Surf	N	Pink/Gray	2nd	Economic Development – e211C	ND
19JH031951	Ceiling Plaster	Surf	N	Gray	2nd	Economic Development – e211C	ND
19JH031952	12" x 12" Floor Tile	Misc	N	Gray	2nd	Lobby Back Hall – e210	ND
19JH031953	Floor Tile Adhesive	Misc	N	Pink	2nd	Lobby Back Hall – e210	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH031954	Floor Tile Adhesive	Misc	N	White	2nd	Lobby Back Hall – e210	ND
19JH031955	Concrete Joint Compound	Misc	N	Gray	2nd	Lobby Back Hall – e210	ND
19JH031956	Wall Plaster	Surf	N	Gray	2nd	Janitors Closet	ND
19JH031957	Wall Skim Coat	Surf	N	Gray	2nd	Janitors Closet	ND
19JH031958	Gypsum Adhesive	Misc	N	White	2nd	Lobby – e201A	ND
19JH031959	Marble Baseboard Adhesive	Misc	N	Yellow	2nd	Lobby – e201A	ND
19JH031960	Cove Base	Misc	N	Brown	2nd	Lobby – e201A	ND
19JH031961	Cove Base Mastic	Misc	N	Tan	2nd	Lobby – e201A	ND
19JH031962	Cove Base Mastic	Misc	N	Yellow	2nd	Lobby – e201A	ND
19JH031963	Flooring	Misc	N	Gray	2nd	Elevator Lobby – e202	ND
19JH031964	Flooring Adhesive	Misc	N	Brown	2nd	Elevator Lobby – e202	ND
19JH031965	Caulk	Misc	N	White	2nd	Elevator Lobby – e202	ND
19JH031966	Caulk	Misc	N	Black	2nd	Elevator Lobby – e202	ND
19JH031967	Expansion Joint Foam	Misc	N	Gray	2nd	Elevator Lobby – e202	ND
19JH031968	Cove Base	Misc	N	Black	2nd	Inspections/Engineering – Lobby – e205A	ND
19JH031969	Cove Base Mastic	Misc	N	Yellow	2nd	Inspections/Engineering – Lobby – e205A	ND
19JH031970	Cove Base Mastic	Misc	N	Gold	2nd	Inspections/Engineering – Lobby – e205A	ND
19JH031971	Drywall	Misc	N	White	2nd	Inspections/Engineering – Lobby – e205A	ND
19JH031973	Drywall Tape	Misc	N	Cream	2nd	Inspections/Engineering – Lobby – e205A	ND
19JH031974	Ceiling Tile	Misc	N	Gray	2nd	Inspections/Engineering – Lobby – e205A	ND
19JH031975	Carpet Mastic	Misc	N	Black/Yellow	2nd	Inspections/Engineering – e205E	ND
19JH031976	Cove Base	Misc	N	Gray	2nd	Inspections/Engineering – e205E	ND
19JH031977	Cove Base Mastic	Misc	N	Brown	2nd	Inspections/Engineering – e205E	ND
19JH031978	Cove Base	Misc	N	Brown	2nd	Inspections/Engineering – e205C	ND
19JH031979	Cove Base Mastic	Misc	N	Gold	2nd	Inspections/Engineering – e205C	ND
19JH031981	Floor Tile Mastic	Misc	N	Black	2nd	Inspections/Engineering – e205B	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH031982	Ceiling Plaster	Surf	N	Gray	2nd	Inspections/Engineering – e205B	ND
19JH031983	Ceiling Skim Coat	Surf	N	Gray	2nd	Inspections/Engineering – e205B	ND
19JH031984	Wall Plaster	Surf	N	Gray	2nd	Inspections/Engineering – e205B	ND
19JH031985	Wall Skim Coat	Surf	N	Gray	2nd	Inspections/Engineering – e205B	ND
19JH031986	Countertop	Misc	N	Black	2nd	Human Resources – Kitchen – e203A	ND
19JH031987	Countertop Adhesive	Misc	N	Yellow	2nd	Human Resources – Kitchen – e203A	ND
19JH031988	Cove Base	Misc	N	Gray	2nd	Human Resources – Kitchen – e203A	ND
19JH031989	Cove Base Mastic	Misc	N	Yellow	2nd	Human Resources – Kitchen – e203A	ND
19JH031990	Carpet Mastic	Misc	N	Yellow	2nd	Human Resources – Kitchen – e203A	ND
19JH031992	Drywall	Misc	N	White	2nd	Human Resources – Storage – e203F	ND
19JH031994	Drywall Tape	Misc	N	Cream	2nd	Human Resources – Storage – e203F	ND
19JH031995	Cove Base	Misc	N	Black	2nd	Human Resources – Storage – e203F	ND
19JH031996	Cove Base Mastic	Misc	N	Gold	2nd	Human Resources – Storage – e203F	ND
19JH031998	Carpet mastic	Misc	N	Yellow/Green	2nd	Purchasing – e203D	ND
19JH031999	12" x 12" Floor Tile	Misc	N	Cream	2nd	IT – e207	ND
19JH0319100	Floor Tile Mastic	Misc	N	Brown/Yellow	2nd	IT – e207	ND
19JH0319101	Ceiling Tile	Misc	N	White	2nd	IT – e207	ND
19JH0319102 ABC	Ceiling Texture	Surf	N	White	1st	Storage – e147, e145, e146	ND
19JH0319103	Fire Caulk	Misc	N	Red	1st	Storage – e147	ND
19JH0319104	Drywall	Misc	N	White	1st	Storage – e147	ND
19JH0319105	Drywall Joint Compound	Misc	N	White	1st	Storage – e147	ND
19JH0319106	Drywall Tape	Misc	N	White	1st	Storage – e147	ND
19JH0319107	Carpet Mastic	Misc	N	Yellow	1st	Storage – e147	ND
19JH0319109	Countertop	Misc	N	Brown	1st	Storage – e147	ND
19JH0319110	Countertop Adhesive	Misc	N	Yellow	1st	Storage – e147	ND
19JH0319111	Countertop	Misc	N	Brown	1st	Breakroom – e143A	ND
19JH0319112	Countertop Adhesive	Misc	N	Yellow	1st	Breakroom – e143A	ND
19JH0319115	Carpet Mastic	Misc	N	Yellow	1st	Breakroom – e143A	ND
19JH0319116	Carpet Pad	Misc	N	Black	1st	Breakroom – e143A	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319119	Floor Tile Mastic	Misc	N	Black	1st	Breakroom – e143A	ND
19JH0319122	Flooring	Misc	N	Gray	1st	Breakroom – e143A	ND
19JH0319123	Wall Plaster	Surf	N	Gray	1st	Breakroom Vault – e144	ND
19JH0319124	Duct Insulation	Misc	N	Yellow	1st	Breakroom – e143A	ND
19JH0319125	Duct Wrap	Misc	N	Silver	1st	Breakroom – e143A	ND
19JH0319127	Ceiling Tile	Misc	N	White	1st	Breakroom – e143A	ND
19JH0319128	Wall Skim Coat	Surf	N	Gray	1st	Breakroom – e143A	ND
19JH0319129	Caulk	Misc	N	Yellow	1st	Conference Room (David) – e143B	ND
19JH0319130	Felt Paper	Misc	N	Black	1st	Breakroom Vault – e144	ND
19JH0319131	Plaster	Surf	N	White	1st	Breakroom Vault – e144	ND
19JH0319132	Felt Paper	Misc	N	Black	1st	Breakroom Vault – e144	ND
19JH0319133	Ceiling Plaster	Surf	N	Gray	1st	Breakroom Vault – e144	ND
19JH0319134	Ceiling Skim Coat	Surf	N	Gray	1st	Breakroom Vault – e144	ND
19JH0319135 ABC	Wall Texture	Surf	Y	White	1st	Temp Billing & Break/Kitchenette – e140A & e139	ND
19JH0319136	Duct Seam Tape	Misc	N	Gray	1st	Break/Kitchenette – e140A	ND
19JH0319137	Ceramic Tile Mastic	Misc	N	Yellow	1st	Toilet – e140B	ND
19JH0319138	Wall Adhesive	Misc	N	Yellow	1st	Temp Billing – e139	ND
19JH0319139	Floor Leveling Compound	Misc	N	Tan	1st	Temp Billing – e139	ND
19JH0319140	Carpet Mastic	Misc	N	Yellow	1st	Temp Billing – e139	ND
19JH0319141	12" x 12" Floor Tile	Misc	N	Tan	1st	Temp Billing – e139	ND
19JH0319142	Floor Tile Mastic	Misc	N	Black	1st	Temp Billing – e139	ND
19JH0319143	Wall Skim Coat	Misc	N	Gray	1st	Temp Billing – e139	ND
19JH0319144	Wall Plaster	Misc	N	Gray	1st	Temp Billing – e139	ND
19JH0319145	1' x 1' Ceiling Tile	Misc	N	Brown	1st	Temp Billing – e139	ND
19JH0319146 ABC	Ceiling Texter (on tiles)	Surf	N	White	1st	Temp Billing – e139	ND
19JH0319147	Ceiling Tile Mastic	Misc	N	Brown	1st	Temp Billing – e139	ND
19JH0319148	Window Glazing	Misc	N	Black	1st	Temp Billing – e139	ND
19JH0319149	Caulk	Misc	N	Brown	1st	Temp Billing – e139	ND
19JH0319150	Cove Base	Misc	N	Brown	1st	Temp Billing – e139	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319151	Cove Base Mastic	Misc	N	Black	1st	Temp Billing – e139	ND
19JH0319152	Caulk	Misc	N	White	1st	Temp Billing – e139	ND
19JH0319153	Ceiling Tile	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319154	Gypsum Block	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319155	Wall Skim Coat	Surf	N	Gray	1st	City Administrator – Reception – e130	ND
19JH0319156	Wall Plaster	Surf	N	Gray	1st	City Administrator – Reception – e130	ND
19JH0319157	Caulk	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319158	Marble Adhesive	Misc	N	White	1st	City Administrator – Toilet – e138	ND
19JH0319159	Cove Base	Misc	N	Gray	1st	City Administrator – Toilet – e138	ND
19JH0319160	Cove Base Mastic	Misc	N	Yellow	1st	City Administrator – Toilet – e138	ND
19JH0319161	Linoleum Flooring	Misc	N	Brown	1st	City Administrator – Toilet – e138	ND
19JH0319162	Linoleum Flooring Adhesive	Misc	N	Yellow	1st	City Administrator – Toilet – e138	ND
19JH0319163	Linoleum Flooring Adhesive	Misc	N	Brown	1st	City Administrator – Toilet – e138	ND
19JH0319164	Carpet Adhesive	Misc	N	Yellow	1st	City Administrator – Toilet – e138	ND
19JH0319165	Drywall	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319166	Drywall Joint Compound	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319167	Drywall Tape	Misc	N	Cream	1st	City Administrator – Reception – e130	ND
19JH0319168	Ceiling Plaster	Surf	N	Gray	1st	City Administrator – Reception – e130	ND
19JH0319169	Ceiling Skim Coat	Surf	N	Gray	1st	City Administrator – Reception – e130	ND
19JH0319170	Ceiling Tile	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319171	Gypsum Block	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319172	Wall Plaster	Surf	N	Gray	1st	City Administrator – Reception – e130	ND
19JH0319173	Gypsum Block Grout	Misc	N	Gray	1st	City Administrator – Reception – e130	ND
19JH0319174	Wall Paper	Misc	N	Yellow	1st	City Administrator – Reception – e130	ND
19JH0319176	Floor Leveler	Misc	N	White	1st	City Administrator – Reception – e130	ND
19JH0319177	Drywall	Misc	N	White	1st	City Administrator – Storage/Attorney (Ryan) – e135	ND
19JH0319178	Drywall Joint Compound	Misc	N	White	1st	Billing Storage – e124	ND
19JH0319179	Drywall Tape	Misc	N	White	1st	Billing Storage – e124	ND
19JH0319180	Caulk	Misc	N	Cream	1st	Billing Storage – e124	ND
19JH0319180	Caulk	Misc	N	Tan	1st	Billing Storage – e124	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319181	Wall Mastic (behind baseboard)	Misc	N	Black	1st	Billing Storage – e124	ND
19JH0319182	Cove Base	Misc	N	Brown	1st	Billing Storage – e124	ND
19JH0319183	Cove Base Mastic	Misc	N	Yellow	1st	Billing Storage – e124	ND
19JH0319184	Cove Base Mastic	Misc	N	Clear	1st	Billing Storage – e124	ND
19JH0319185	Pipe Insulation	Misc	N	Yellow	1st	Billing Workroom – e123	ND
19JH0319186	Pipe Wrap	Misc	N	White	1st	Billing Workroom – e123	ND
19JH0319187	Carpet Adhesive	Misc	N	Gray	1st	Billing Storage – e124	ND
19JH0319188	Floor Leveler	Misc	N	Gray	1st	Billing Storage – e124	ND
19JH0319189	Wall Insulation	Misc	N	Yellow	1st	Billing Storage – e124	ND
19JH0319190	Insulation Paper	Misc	N	Brown	1st	Billing Storage – e124	ND
19JH0319191	Ceiling Tile	Misc	N	Gray	1st	Billing Storage – e124	ND
19JH0319192	Duct Caulk	Misc	N	Gray	1st	Billing Storage – e124	ND
19JH0319193	Duct Insulation	Misc	N	Brown	1st	Billing Storage – e124	ND
19JH0319194	Duct Wrap	Misc	N	Silver	1st	Billing Storage – e124	ND
19JH0319195	Ceiling Tile	Misc	N	White	1st	Billing Storage – e124	ND
19JH0319196	Wall Insulation	Misc	N	Brown	1st	Billing Workroom – e123	ND
19JH0319197	Insulation Paper	Misc	N	Black	1st	Billing Workroom – e123	ND
19JH0319198	Ceiling Plaster	Surf	N	Gray	1st	Billing Workroom – e123	ND
19JH0319199	Ceiling Skim Coat	Surf	N	Gray	1st	Billing Workroom – e123	ND
19JH0319200	Duct Tape	Misc	N	Silver	1st	Billing Storage – e124	ND
19JH0319201	Window Caulk	Misc	N	Brown	1st	Billing – e120	ND
19JH0319202	Caulk	Misc	N	White	1st	Billing – e120	ND
19JH0319203	Ceiling Tile	Misc	N	White	1st	Billing Office – e122	ND
19JH0319204	Countertop	Misc	N	Tan	1st	Parks and Rec – Waiting – e100A	ND
19JH0319205	Countertop Adhesive	Misc	N	Pink	1st	Parks and Rec – Waiting – e100A	ND
19JH0319206	Caulk	Misc	N	Tan	1st	Parks and Rec – Waiting – e100A	ND
19JH0319207	Back Splash Adhesive	Misc	N	Yellow	1st	Parks and Rec – Waiting – e100A	ND
19JH0319208	Floor Leveler	Misc	N	Gray	1st	Parks and Rec – Waiting – e100A	ND
19JH0319209	Cove Base	Misc	N	Brown	1st	Parks and Rec – Storage – e100B	ND
19JH0319210	Cove Base Mastic	Misc	N	Yellow	1st	Parks and Rec – Storage – e100B	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319211	Cove Base Mastic	Misc	N	Clear	1st	Parks and Rec – Storage – e100B	ND
19JH0319212	Drywall	Misc	N	White	1st	Parks and Rec – Storage – e100B	ND
19JH0319213	Drywall Joint Compound	Misc	N	White	1st	Parks and Rec – Storage – e100B	ND
19JH0319214	Drywall Tape	Misc	N	Cream	1st	Parks and Rec – Storage – e100B	ND
19JH0319215	Ceiling Plaster	Surf	N	Gray	1st	Parks and Rec – Storage – e100B	ND
19JH0319216	Felt Paper	Misc	N	Black	1st	Parks and Rec – Storage – e100B	ND
19JH0319217	12" x 12" Floor Tile	Misc	N	Gray	1st	Parks and Rec – Toilet – e100D	ND
19JH0319218	Floor Tile Adhesive	Misc	N	Pink	1st	Parks and Rec – Toilet – e100D	ND
19JH0319219	Caulk	Misc	N	White	1st	Parks and Rec – Toilet – e100D	ND
19JH0319220	Wall Plaster	Surf	N	Gray	1st	Parks and Rec – Vault – e100L	ND
19JH0319221	Wall Skim Coat	Surf	N	Gray	1st	Parks and Rec – Vault – e100L	ND
19JH0319222	1' x 1' Ceiling Tile	Misc	N	Brown	1st	Parks and Rec – Copy – 100H	ND
19JH0319223	Ceiling Tile Mastic	Misc	N	Brown	1st	Parks and Rec – Copy – 100H	ND
19JH0319224	Ceramic Tile Grout	Misc	N	White	1st	Lobby – e101	ND
19JH0319225	Ceramic Tile Adhesive	Misc	N	Yellow	1st	Lobby – e101	ND
19JH0319226	Marble Grout	Misc	N	White	1st	Vestibule – e101B	ND
19JH0319227	Tar	Misc	N	Black	1st	Electrical – e158	ND
19JH0319228 ABC	Pipe Wrap	TSI	N	White	1st	Electrical – e158	ND
19JH0319230	Pipe Wrap	Misc	N	White	1st	Electrical – e158	ND
19JH0319231	Pipe Insulation	Misc	N	Yellow	1st	Electrical – e158	ND
19JH0319233	Wall Plaster	Surf	N	Gray	1st	Map Room – e154	ND
19JH0319234	Wall Skim Coat	Surf	N	Gray	1st	Map Room – e154	ND
19JH0319235	Pipe Insulation	Misc	N	Yellow	1st	Map Room – e154	ND
19JH0319236	Pipe Wrap	Misc	N	White	1st	Map Room – e154	ND
19JH0319237	Wall Plaster	Surf	N	Gray	B	Stair – e14	ND
19JH0319238	Wall Skim Coat	Surf	N	Gray	B	Stair – e14	ND
19JH0319239	Ceiling Plaster	Surf	N	Gray	B	Stair – e14	ND
19JH0319240	Ceiling Skim Coat	Surf	N	White	B	Stair – e14	ND
19JH0319241	Pipe Insulation	Misc	N	Yellow	B	Boiler Room – e13	ND
19JH0319242	Pipe Wrap	Misc	N	White	B	Boiler Room – e13	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319243	End Cap Caulk	Misc	N	White	B	Boiler Room – e13	ND
19JH0319244	Pipe Insulation	Misc	N	Yellow	B	Boiler Room – e13	ND
19JH0319245	Pipe Wrap	Misc	N	White	B	Boiler Room – e13	ND
19JH0319246	Pipe Insulation	Misc	N	Yellow	B	Boiler Room – e13	ND
19JH0319247	Pipe Wrap	Misc	N	White	B	Boiler Room – e13	ND
19JH0319248	Seam Caulk	Misc	N	White	B	Boiler Room – e13	ND
19JH0319249	Pipe Insulation	Misc	N	Yellow	B	Boiler Room – e13	ND
19JH0319250	Pipe Wrap	Misc	N	White	B	Boiler Room – e13	ND
19JH0319251	Cardboard Duct	Misc	N	Brown/Black	B	Boiler Room – e13	ND
19JH0319252	Ceiling Plaster	Surf	N	Gray	B	Boiler Room – e13	ND
19JH0319253	Ceiling Skim Coat	Surf	N	Gray	B	Boiler Room – e13	ND
19JH0319254	Plaster	Misc	N	White	B	Boiler Room – e13	ND
19JH0319255	Felt Paper	Misc	N	Black	B	Boiler Room – e13	ND
19JH0319256	Tar Paper	Misc	N	Black	B	Boiler Room – e13	ND
19JH0319257	Plaster (tar soaked)	Misc	N	Black	B	Boiler Room – e13	ND
19JH0319258	Duct Insulation	Misc	N	Yellow	B	Boiler Room – e13	ND
19JH0319259	Duct Wrap	Misc	N	Silver	B	Boiler Room – e13	ND
19JH0319260	Duct Tape	Misc	N	Silver	B	Boiler Room – e13	ND
19JH0319262	Tar Paper	Misc	N	Black	B	Storage – e13B	ND
19JH0319263	Tar (man hole cover)	Misc	N	Black	B	Storage – e13B	ND
19JH0319264	Fire Caulk	Misc	N	Red	B	Boiler Room – e13	ND
19JH0319265	Caulk	Misc	N	Silver	B	Boiler Room – e13	ND
19JH0319266	Wall Plaster	Surf	N	Gray	B	Electrical Department – e12	ND
19JH0319267	Wall Skim Coat	Surf	N	Gray	B	Electrical Department – e12	ND
19JH0319268	Ceiling Plaster	Surf	N	Gray	B	Electrical Department – e12	ND
19JH0319269	Ceiling Skim Coat	Surf	N	Gray	B	Electrical Department – e12	ND
19JH0319270	Plaster	Misc	N	White	B	Electrical Department – e12	ND
19JH0319271	Felt Paper	Misc	N	Black	B	Electrical Department – e12	ND
19JH0319272	Tar Paper	Misc	N	Black	B	Electrical Department – e12	ND
19JH0319273	Pipe Insulation	Misc	N	Yellow	B	Electrical Department – e12	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319274	Pipe Wrap	Misc	N	White	B	Electrical Department – e12	ND
19JH0319275	Tar	Misc	N	Black	B	Electrical Department – e12	ND
19JH0319276	Concrete/Grout	Misc	N	Gray	B	Electrical Department – e12	ND
19JH0319277	Caulk	Misc	N	White	B	Hall – e07	ND
19JH0319278	Corkboard	Misc	N	Brown	B	Hall – e07	ND
19JH0319279	Marble Wall Adhesive	Misc	N	White	B	Men's Restroom – e09	ND
19JH0319280	Marble Wall Adhesive	Misc	N	White	B	Men's Restroom – e09	ND
19JH0319281	Marble Sill Adhesive	Misc	N	White	B	Men's Restroom – e09	ND
19JH0319282	Terrazzo Floor	Misc	N	Gray	B	Men's Restroom – e09	ND
19JH0319283	Wall Plaster	Surf	N	Gray	B	Office – e006	ND
19JH0319284	Ceiling Tile	Misc	N	Gray	B	Office – e006	ND
19JH0319285	Duct Insulation	Misc	N	Yellow	B	Storage – e005	ND
19JH0319286	Duct Wrap	Misc	N	White	B	Storage – e005	ND
19JH0319287	Caulk	Misc	N	White	B	Garage – e04	ND
19JH0319288	Ceiling Plaster	Surf	N	Gray	B	Storage – e03	ND
19JH0319289	Plaster	Misc	N	White	B	Storage – e03	ND
19JH0319290	Felt Paper	Misc	N	Black	B	Storage – e03	ND
19JH0319291	Tar Paper	Misc	N	Black	B	Storage – e03	ND
19JH0319292	Pipe Insulation	Misc	N	Yellow	B	Storage – e03	ND
19JH0319293	Pipe Wrap	Misc	N	White	B	Storage – e03	ND
19JH0319294	Wall Plaster	Surf	N	Gray	B	Water Dept. Restroom – e01B	ND
19JH0319295	Wall Skim Coat	Surf	N	Gray	B	Water Dept. Restroom – e01B	ND
19JH0319296	Door Caulk	Misc	N	Tan	B	Water Dept. Restroom – e01B	ND
19JH0319297	Marble Grout	Misc	N	White	B	Water Dept. Restroom – e01B	ND
19JH0319298	Stair Tread	Misc	N	Black	B	Water Dept. – e01A	ND
19JH0319299	Ceramic Tile Grout	Misc	N	Black	B	Water Dept. – e01A	ND
19JH0319300	Terrazzo Floor	Misc	N	Orange/Gray	B/1 st	Water Dept./Vestibule Stairs – e01	ND
19JH0319301	Ceiling Tile	Misc	N	White	2 nd	Men's Restroom – e204	ND
19JH0319302	Ceramic Wall Tile Adhesive	Misc	N	Gray	2 nd	Men's Restroom – e204	ND
19JH0319303	Grout	Misc	N	Brown	2 nd	Men's Restroom – e204	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319304	Drywall	Misc	N	White	2 nd	Men's Restroom – e204	ND
19JH0319305	12" x 12" Floor Tile	Misc	N	Gray	2 nd	Men's Restroom – e204	ND
19JH0319306	Floor Tile Adhesive	Misc	N	Pink	2 nd	Men's Restroom – e204	ND
19JH0319307	Floor Leveler	Misc	N	Gray	2 nd	Men's Restroom – e204	ND
19JH0319308	Caulk	Misc	N	Tan	1 st	Council Chambers – e111	ND
19JH0319309	Cove Base	Misc	N	Brown	1 st	Council Chambers – e111	ND
19JH0319310	Cove Base Mastic	Misc	N	Yellow	1 st	Council Chambers – e111	ND
19JH0319311	Cove Base Mastic	Misc	N	Clear	1 st	Council Chambers – e111	ND
19JH0319312	Caulk	Misc	N	Tan	1 st	Council Chambers – e111	ND
19JH0319313	Drywall	Misc	N	White	1 st	Council Chambers – AV Room – e11B	ND
19JH0319314	Drywall Joint Compound	Misc	N	White	1 st	Council Chambers – AV Room – e11B	ND
19JH0319315	Drywall Tape	Misc	N	White	1 st	Council Chambers – AV Room – e11B	ND
19JH0319316	Floor Leveler	Misc	N	White	1 st	Council Chambers – AV Room – e11B	ND
19JH0319317	Floor Tile Mastic	Misc	N	Black	1 st	Council Chambers – AV Room – e11B	ND
19JH0319318	Ceiling Tile	Misc	N	Black	2 nd	Conference Room – e206	ND
19JH0319319	Caulk	Misc	N	White	2 nd	Conference Room – e206	ND
19JH0319320	Stair Tread	Misc	N	Black	2 nd	Lobby Stairs – e201B	ND
19JH0319321	Caulk	Misc	N	Brown	2 nd	Lobby Stairs – e201B	ND
19JH0319322	Ceramic Tile Adhesive	Misc	N	Gray	1 st	Men's Restroom – e104	ND
19JH0319323	Grout	Misc	N	Brown	1 st	Men's Restroom – e104	ND
19JH0319324	Wall Panel Adhesive	Misc	N	Tan	1 st	Janitors Closet – e103	ND
19JH0319325	Caulk	Misc	N	Gray	1 st	Janitors Closet – e103	ND
19JH0319326	Caulk	Misc	N	White	1 st	Janitors Closet – e103	ND
19JH0319327	Flooring	Misc	N	Gray	1 st	Janitors Closet – e103	ND
19JH0319328	Flooring Adhesive	Misc	N	Brown	1 st	Janitors Closet – e103	ND
19JH0319329	Duct Caulk	Misc	N	Gray	1 st	Council Chambers Hall – e102	ND
19JH0319330	Duct Insulation	Misc	N	Yellow	1 st	Council Chambers Hall – e102	ND
19JH0319331	Duct Wrap	Misc	N	Silver	1 st	Council Chambers Hall – e102	ND
19JH0319332	Ceiling/Beam Plaster	Surf	N	Gray	1 st	Council Chambers Hall – e102	ND
19JH0319333	Ceiling/Beam Skim Coat	Surf	N	Gray	1 st	Council Chambers Hall – e102	ND

Sample #	Material Substance	Material Type (Surf/TSI/Misc)	Friable (Y or N)	Color	Floor	Location	Asbestos Content
19JH0319334	Grout	Misc	N	Pink	1 st	Council Chambers Stairs – e109	ND
19JH0319335	Caulk	Misc	N	Brown	1 st	Council Chambers Entry/Elevator Lobby – e110	ND
19JH0403336	Drywall	Misc	N	White	2 nd	Engineering/Inspections – e205C	ND
19JH0403338	Drywall Tape	Misc	N	White	2 nd	Engineering/Inspections – e205C	ND
19JH0403339	Drywall	Misc	N	White	2 nd	Engineering/Inspections – e205E	ND
19JH0403341	Drywall Tape	Misc	N	White	2 nd	Engineering/Inspections – e205E	ND
19JH0403345	Drywall	Misc	N	White	2 nd	Human Resources – e203A	ND
19JH0403347	Drywall Tape	Misc	N	White	2 nd	Human Resources – e203A	ND
19JH0403348	Drywall	Misc	N	White	2 nd	Human Resources – e203E	ND
19JH0403350	Drywall Tape	Misc	N	White	2 nd	Human Resources – e203E	ND
19JH0403351	Drywall	Misc	N	White	2 nd	Human Resources – e203B	ND
19JH0403353	Drywall Tape	Misc	N	White	2 nd	Human Resources – e203B	ND

Material Type – Surf=Surfacing, TSI=Thermal System Insulation, Misc=Miscellaneous / **Asbestos Content** – ND=None Detected

5.2 Lead-Based Paint Sampling

Iowa certified lead-based paint inspectors from Impact7G collected one thousand, nine-hundred and twenty-four (1,924) samples (plus forty-four (44) calibration readings) from March 18th-22nd, 2019. The samples were collected from various painted surfaces located throughout the interior of the Property. Complete XRF results are provided in Appendix E.

The summary table identifying LBP components is provided in the Executive Summary.

6.0 OPERATIONS & MAINTENANCE PROGRAM RECOMMENDATIONS

6.1 Asbestos Containing Materials

The Time-Weighted Average (TWA) for airborne concentrations of asbestos is 0.1 fiber/cubic centimeter (f/cc) of air in an eight (8) hour TWA. The excursion limit for airborne concentrations of asbestos is 1 f/cc as averaged over a sampling period of thirty (30) minutes.

In accordance with OSHA 1926.1101, Class I, II, and III asbestos work shall be conducted within regulated areas.

- Class I asbestos work – The removal of TSI and surfacing ACM and Presumed Asbestos Containing Material (PACM).
- Class II asbestos work – Activities involving the removal of ACM which is not TSI or surfacing ACM. This includes, but is not limited to, the removal of asbestos-containing wallboard, floor tile and sheeting, roofing and siding shingles, construction mastics, etc.
- Class III asbestos work – Repair and maintenance operations, where ACM, including TSI and surfacing ACM and PACM, is likely to be disturbed.
- Class IV asbestos work – Maintenance and custodial activities during which employees contact, but do not disturb ACM or PACM and activities to clean up dust, waste and debris resulting from Class I, II, and III activities.

According to OSHA 1926.1101, a “disturbance” is defined as activities that disrupt the matrix of ACM or PACM, crumble or pulverize ACM or PACM, or generate visible debris from ACM or PACM. This includes cutting away small amounts of ACM or PACM, no greater than the amount that can be contained in one standard sized glove bag or waste bag in order to access a building component. In no event shall the amount of ACM or PACM so disturbed exceed that which can be contained in one glove bag or waste bag which shall not exceed 60 inches in length and width.

When completing maintenance activities on ACM or PACM, the following activities or equipment should not be used:

- High-speed abrasive disc saws not equipped with point-of-cut ventilators or enclosures with HEPA filtered exhaust air,
- Compressed air directly on ACM or PACM,
- Dry sweeping, shoveling or other dry clean-up of dust and debris containing ACM or PACM,
- Employee rotation as a means of reducing employee exposure to asbestos,

- Mechanical chipping equipment on ACM or PACM, or
- Dry sanding equipment.

Removal of any ACM or PACM is required to be abated by a State of Iowa Certified Asbestos Abatement Contractor, in accordance with all local, state, and federal guidelines.

6.2 Lead-Based Paint

Annual monitoring will be necessary at the Property since LBP is present. When LBP is present, the potential exists for LBP hazards. Hazards may occur by several causes including, but not limited to the following: the failure of lead hazard control methods; previously intact LBP becoming deteriorated; dangerous levels of lead in dust (dust lead) re-accumulating through friction, impact and deterioration of paint; or, through the introduction of contaminated exterior dust and soil into the interior of the structure. Ongoing monitoring typically includes two different activities: re-evaluation and annual visual assessments. A re-evaluation is a risk assessment that includes limited dust sampling and a visual evaluation of paint films and any existing lead hazard controls. Re-evaluations are supplemented with visual assessments by the Property owner, which should be conducted at least once a year, when the property owner or its management agent (if housing is rented in the future) receives any complaints about deteriorated paint or other potential lead hazards or when significant damage occurs that could affect the integrity of hazard control treatments (e.g. flooding, vandalism, fire). The visual assessment should cover painted surfaces and components. Visual assessments should confirm that all paint known LBP is not deteriorating, that lead hazard control methods have not failed, and that structural problems do not threaten the integrity of any remaining known or suspected LBP.

It should be noted that lead concentrations (in paint) that are less than the levels that identify a surface coating as LBP still have the potential of causing lead poisoning. Should these or any potential LBP painted component and/or surface be disturbed in any manner that generates dust, extreme care must be taken to limit its spread. Any renovation or remodeling work can disturb paint, which may create a hazardous condition. Safe work practices should be implemented during any remodeling project, in addition to using a certified lead abatement contractor or professional certified lead worker. As long as there is lead-based paint present in the structure, there is a potential for a hazardous condition.

Visual Assessments do not replace the need for professional re-evaluation by a certified risk assessor. The professional re-evaluation should include:

1. A review of prior reports to determine where lead-based paint and lead-based paint hazards have been identified, what controls were completed, and when these findings and controls occurred;
2. A visual assessment to identify deteriorated paint, failures of previous hazard controls, visible dust and debris, and bare soil;
3. Environmental testing for lead in dust, newly deteriorated paint, and newly bare soil; and
4. A report describing the findings of the re-evaluation, including the location of any LBP hazards, the location of any failures of previous hazard controls, and as needed, acceptable options for the control of hazards, the repair of previous controls, and modification of monitoring and maintenance practices.

The first re-evaluation should be conducted no later than two years after completion of hazard controls, or, if specific controls or treatment are not conducted, two years from the beginning of ongoing lead-based paint monitoring and maintenance activities. Subsequent re-evaluations should be conducted at two-year intervals, plus or minus 60 days. If two consecutive re-evaluations are conducted two years apart without finding a LBP hazard, re-evaluations may be discontinued.

6.3 General O&M Program Guidance

The O&M program should at a minimum consist of training, cleaning, work practices, monitoring, and recordkeeping to maintain these materials in good condition. A worker should be designated by the employer to manage the O&M program.

Training

OSHA requires employers to provide a training program for employees if there is a potential they might be exposed at or above the applicable TWAs discussed above. The EPA describes three types of training for custodial and maintenance workers:

- Type 1: Awareness Training – Employer provided two-hour training that discusses the background of lead-based paint, its health effects, worker protection, location of hazards in the building, recognition of damage or deterioration, and the O&M program for the building.
- Type 2: Special O&M Training – Employer provided 14-hour training that includes Type 1 topics, lead-based paint regulations, related work practices, handling LBP, respirator use, protective clothing, hands-on training, and decontamination procedures. A suitable alternative for this training is the EPA's Renovate, Repair, and Paint training.
- Type 3: Abatement Training – State certified 40-hour training that includes Type 1 and 2 topics, pre-abatement work activities, work area preparation, decontamination units, safety considerations, additional hands-on exercises, and disposal of ACM.

Cleaning

Similarly, to the above state information, appropriate cleaning methods should also be included in the O&M program. The cleaning methods should then be discussed with custodial and maintenance workers.

Work Practices

The basic procedures outlined below should be used by custodial and maintenance workers to minimize and/or contain hazards when the potential for disturbance exists:

- Wet methods (i.e. low pressure spraying of water)
- Use of mini-enclosures
- Use of portable power tools equipped with special local ventilation attachments (HEPA)
- Area isolation
- Avoidance of certain activities (i.e. sawing, sanding, drilling)

OSHA requires the use of protective clothing by custodial and maintenance workers when dealing with ACM and LBP hazards. The protective clothing should be disposable and consists of full coverage coveralls, head cover, and foot covers. It should also be made of a durable, synthetic fiber that does not allow asbestos fibers or dust to pass through.

The Type 1 and 2 training should discuss proper disrobing and disposal of the protective clothing.

OSHA also requires the use of respirators whenever workers are exposed to, or will likely be exposed to, hazards above the permissible exposure levels discussed above.

Monitoring

The EPA recommends a visual and physical evaluation of hazards during regular monitoring inspections to note the current condition and physical characteristics of the materials. Developing a visual record, with photographs or video, will help determine the degree of damage and when materials need to be repaired or replaced.

Supplemental air monitoring may also be utilized as part of the O&M program. Air monitoring should supplement, not replace, the visual and physical evaluations of hazards. If employees may be exposed to airborne concentrations of hazards above the permissible limits, regulations require both initial and periodic air sampling during the project work.

Recordkeeping

As part of the O&M program, the following documents should be stored in permanent files:

- Inspection and assessment reports,
- O&M program plan,
- Work practices and procedures,
- Respirator use procedures (if applicable),
- Hazard release reports,
- Applications for maintenance work and work approval forms,
- Evaluations of work affecting hazards, and
- Reinspection/surveillance of hazards.

Additional OSHA recordkeeping requirements include:

- Maintaining personal air sampling records from work involving hazard exposure for at least 30 years,
- Data used to qualify for exemptions from OSHA's initial monitoring requirements,
- Maintaining medical records for each employee subject to the medical surveillance for the duration of the worker's employment plus 30 years,
- Maintaining training records for each worker during their employment plus 1 year,
- Hazard communication plan,
- Abatement notification records, and
- Transfers of records.

7.0 CONCLUSIONS / RECOMMENDATIONS

The following conclusions and recommendations are summarized as follows:

- Asbestos was detected in thirty-two (32) of the bulk material samples collected from the building located at 819 First Avenue South, Fort Dodge, Iowa. ACMs include tile cove base, floor tile mastic, wall adhesive/mastic, drywall joint compound, 12" x 12" Floor Tile(s), sink undercoats, ceiling tile(s), floor tile(s), pipe insulation, mudded joints, and pipe wrap. Based on the data collected during the assessment, abatement of the identified ACM is recommended prior to renovation activities.
- Lead was identified in two hundred and sixty-six (266) samples taken from the property. These components include walls, ceilings, window components, ladders, baseboards, shoe molding, door components, stair tread, pipes, jail components, radiators, floors, crown molding, sink tile, wall tile, shelves, shelving components, work bench components, and cabinet components. The complete XRF results are provided in Appendix E. Lead safe work practices should still be used when working in the vicinity of these sample locations to prevent a lead health hazard.

Impact7G recommends the abatement of all ACM located within the inspection area if those building materials are to be disturbed during future renovation or demolition activities. All abatement work shall be completed in accordance with local, state, and federal regulations. A visual inspection is recommended upon completion of abatement work to document that all ACMs within the scope of abatement have been removed. While pre-demolition abatement/removal of LBP components is not required by the Iowa Department Natural Resources (IDNR), Iowa Occupational Safety and Health (IOSH) may require additional personal protective equipment (PPE) be used if these materials are left in the structure during demolition.

Based on the presence of LBP throughout the Property, lead-safe work practices should be utilized during renovation activities. Options for mitigating lead hazards in abatement by removal, enclosure, or encapsulation, or series of interim controls to manage LBP components in place. In general, interim control options will likely be less expensive than abatement control options but will require the development of a management plan. Abatement control options do not require such a plan. Impact7G recommends that the identified LBP components be remediated in accordance with applicable Federal, State and Local Regulations.

If areas of ACM and LBP components will remain, Impact7G recommends establishing an Operations & Maintenance (O&M) program. The O&M program should at a minimum consist of training, cleaning, work practices, monitoring, and recordkeeping to maintain these materials in good condition. Additional details on establishing an O&M program are discussed in Section 6.0 of this report.

This report is designed to aid the building owner, architect, construction manager, general contractor, and/or remediation contractor in locating ACM and/or LBP. This report is not to be used as abatement specifications, as it does not contain needed components to serve as such.

8.0 CONDITIONS & LIMITATIONS

The Iowa Department of Natural Resources' (IDNR) Air Quality Bureau and Occupational Safety and Health Bureau (OSHA) of the Iowa Division of Labor Services require notification of any renovation/demolition activities in non-residential projects if the combined regulated ACM meets or exceeds any of the following thresholds: 160 square feet of surfacing ACM, 260 linear feet of TSI, or 35 cubic feet of ACM debris.

Impact7G has performed the tasks contained within this report in a thorough and professional manner consistent with commonly accepted standard industry practices. The results, findings, conclusions and recommendations expressed in this report are based on conditions observed during our survey of the property. Impact7G cannot guarantee, and does not warrant, that this report has identified all adverse environmental factors and/or conditions affecting the subject property on the date of the inspection. Impact7G cannot and will not warrant that the Inspection that was requested will satisfy the dictates of, or provide, a legal defense in connection with any environmental laws or regulations. It is the responsibility of the client to know and abide by all applicable laws, regulations, and standards, including EPA's Renovation, Repair and Painting regulations. This report is not a bidding document or project specification as it does not contain the necessary components. This report has been prepared on behalf of and exclusively for use by the City of Fort Dodge for specific application to their project as discussed. Contractors, consultants or other third parties reviewing this report must draw their own conclusions regarding data contained within the report, further investigation or required remediation.

It is a violation of law for anyone other than the certified lead professional signing it to alter this report. This report may be supplemented with additional information, so long as any addendum is signed by a lead inspector/risk assessor certified according to Iowa Administrative Code 641 – 70.3(135) and 70.5(135).

APPENDIX A

Qualifications

Certificate of Completion

JACOB HUXFORD

DOB: 09-30-1992

Issued: 02-07-2019



This person is licensed to perform asbestos work in the State of Iowa. ID card is intended for official use only and must be present on jobsite.

Impact7G, Inc.

certifies that

Jacob Huxford

has successfully completed and passed the associated examination for the

Asbestos Inspector Annual Review

course accredited by the State of Missouri and conducted in accordance with the requirements of 40 CFR 763. The person receiving this certificate has completed the required training for asbestos certification under TSCA Title II.

Course Date: February 1, 2019
Examination Date: February 1, 2019
Expiration Date: February 1, 2020
Course Location: 9550 Hickman Road, Suite 105, Clive, IA
Certificate Number: IAVIII7G_20285



Director of Training
9550 Hickman Road, Suite 105
Clive, IA 50325
515-473-6256

License Type	Number	Expires
INSPECTOR	19-1795	02-01-2020



Asbestos

Michael A. Mauro
Labor Commissioner



Iowa Department of Public Health

Protecting and Improving the Health of Iowans

Gerd W. Clabaugh, MPA
Director

Kim Reynolds
Governor

Adam Gregg
Lt. Governor

September 26, 2017

Tyler Silverthorn
700 4th Street SUITE 210
Sioux City, IA 51101

Dear Tyler Silverthorn

The department has reviewed the information you submitted and determined that you have met the requirements for certification in the state of Iowa as a Lead Inspector/Risk Assessor. Your certification number is: LEAD-INSP10031.

Your certification will expire on September 18, 2020. By that date, you must renew your certification in order to perform any lead professional certification activities. To renew your certification, you will need to have completed the appropriate refresher course. Refresher courses are valid if taken within 3-years from the date that you renew.

Please keep a copy of your certification on your person or in an easily retrievable area at the work site. If you submitted your application online or with a valid email address, the certification is being provided to you electronically. You may choose to either print these documents or have them available on your phone or other electronic device for display if requested.

You can find the certification requirements and work practice standards for all lead professionals in Iowa Administrative Code 641 - Chapter 70, which is at: <http://www.idph.iowa.gov/LPP> under "Resources". You **must** be currently certified to perform work that requires certification.

Bureau of Environmental Health Services
Lead Professional Certification
Phone: 800-972-2026
E-mail: Lead.Bureau@idph.iowa.gov



IOWA DEPARTMENT
OF PUBLIC HEALTH

Tyler Silverthorn

Lead Inspector/Risk Assessor

Certification Number: LEAD-INSP10031

Expiration Date: September 18, 2020

JONATHAN REIS

DOB: 02-13-1984

Issued: 08-22-2018



This person is licensed to perform asbestos work in the State of Iowa. ID card is intended for official use only and must be present on jobsite.

License Type	Number	Expires
INSPECTOR	18-0950	08-17-2019
SUPERVISOR	18-0967	05-18-2019



Asbestos

Michael A. Mauro
Labor Commissioner



Iowa Department of Public Health

Protecting and Improving the Health of Iowans

Gerd W. Clabaugh, MPA
Director

Kim Reynolds
Governor

Adam Gregg
Lt. Governor

August 10, 2017

Jon H Reis
2822 SW Village Circle
Ankeny, IA 50023

Dear Jon H Reis

The department has reviewed the information you submitted and determined that you have met the requirements for certification in the state of Iowa as a Lead Inspector/Risk Assessor. Your certification number is: LEAD-INSP10006.

Your certification will expire on July 7, 2020. By that date, you must renew your certification in order to perform any lead professional certification activities. To renew your certification, you will need to have completed the appropriate refresher course. Refresher courses are valid if taken within 3-years from the date that you renew.

Please keep a copy of your certification on your person or in an easily retrievable area at the work site. If you submitted your application online or with a valid email address, the certification is being provided to you electronically. You may choose to either print these documents or have them available on your phone or other electronic device for display if requested.

You can find the certification requirements and work practice standards for all lead professionals in Iowa Administrative Code 641 - Chapter 70, which is at: <http://www.idph.iowa.gov/LPP> under "Resources". You **must** be currently certified to perform work that requires certification.

Bureau of Environmental Health Services
Lead Professional Certification
Phone: 800-972-2026
E-mail: Lead.Bureau@idph.iowa.gov



IOWA DEPARTMENT
OF PUBLIC HEALTH

Jon H Reis

Lead Inspector/Risk Assessor

Certification Number: LEAD-INSP10006

Expiration Date: July 7, 2020

APPENDIX B

Laboratory Reports / Chain of Custody Documentation



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Attention: Jacob Huxford
Impact7G
9550 Hickman Road
Suite 105
Clive, IA 50325

Project: FORT DODGE CITY HALL

Phone: (515) 473-6256

Fax: (515) 528-8005

Received Date: 03/26/2019 8:45 AM

Analysis Date: 03/28/2019 - 04/02/2019

Collected Date:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH031901 <small>161905383-0001</small>	2nd Floor - wall plaster gray	Gray Non-Fibrous Homogeneous		20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031902 <small>161905383-0002</small> <i>Inseparable paint / coating layer included in analysis</i>	2nd Floor - wall skim coat gray	White Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
19JH031903 <small>161905383-0003</small>	2nd Floor - caulk gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031904 <small>161905383-0004</small>	2nd Floor - ceiling plaster gray	Gray Non-Fibrous Homogeneous	<1% Hair	20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031905 <small>161905383-0005</small> <i>Inseparable paint / coating layer included in analysis</i>	2nd Floor - ceiling skim coat gray	White Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
19JH031906 <small>161905383-0006</small>	2nd Floor - ceiling felt paper black	Black Fibrous Homogeneous	70% Cellulose	30% Non-fibrous (Other)	None Detected
19JH031907 <small>161905383-0007</small>	2nd Floor - plaster white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031908 <small>161905383-0008</small>	2nd Floor - felt paper gray	Gray Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031909 <small>161905383-0009</small>	2nd Floor - tar paper black	Black Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected
19JH031910 <small>161905383-0010</small>	2nd Floor - ceiling tile gray	Gray/White Fibrous Homogeneous	70% Cellulose 10% Min. Wool	15% Perlite 5% Non-fibrous (Other)	None Detected
19JH031911 <small>161905383-0011</small>	2nd Floor - wall plaster gray	Gray Non-Fibrous Homogeneous		20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031912 <small>161905383-0012</small> <i>Inseparable paint / coating layer included in analysis</i>	2nd Floor - wall skim coat gray	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031913 <small>161905383-0013</small>	2nd Floor - duct insulation yellow	Yellow Fibrous Homogeneous	98% Glass	2% Non-fibrous (Other)	None Detected
19JH031914 <small>161905383-0014</small>	2nd Floor - dict insulation wrap silver	Brown/Silver Fibrous Homogeneous	60% Cellulose 10% Glass	30% Non-fibrous (Other)	None Detected
19JH031915 <small>161905383-0015</small>	2nd Floor - duct seam tape/caulk silver/gray	Gray/Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH031916 161905383-0016	2nd Floor - cove base gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031917 161905383-0017	2nd Floor - cove base mastic brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031918 161905383-0018	2nd Floor - carpet mastic yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031919 161905383-0019	2nd Floor - drywall white	Brown/White Fibrous Heterogeneous	20% Cellulose	70% Gypsum 10% Non-fibrous (Other)	None Detected
19JH031920 161905383-0020	2nd Floor - drywall joint compound white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031921 161905383-0021	2nd Floor - drywall tape cream	White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031922 161905383-0022	2nd Floor - drywall white	Brown/White Fibrous Heterogeneous	20% Cellulose	70% Gypsum 10% Non-fibrous (Other)	None Detected
19JH031923 161905383-0023	2nd Floor - drywall joint compound white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031924 161905383-0024	2nd Floor - drywall tape cream	White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031925 161905383-0025	2nd Floor - corkboard brown	Brown Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031926 161905383-0026	2nd Floor - corkboard adhesive yellow	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031927 161905383-0027	2nd Floor - floor leveler gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031928 161905383-0028	2nd Floor - carpet adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031929 161905383-0029	2nd Floor - plaster gray	Gray Non-Fibrous Homogeneous		20% Perlite 80% Non-fibrous (Other)	None Detected
19JH031930 161905383-0030	2nd Floor - skim coat gray	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031931 161905383-0031	2nd Floor - countertop cream	Tan/White Non-Fibrous Homogeneous	30% Cellulose	70% Non-fibrous (Other)	None Detected
19JH031932 161905383-0032	2nd Floor - countertop adhesive gold	Gold Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031933 161905383-0033	2nd Floor - sink undercoat gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031934 161905383-0034	2nd Floor - caulk white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH031935 161905383-0035	2nd Floor - caulk white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031936 161905383-0036	2nd Floor - duct/pipe insulation yellow	Yellow Fibrous Homogeneous	98% Glass	2% Non-fibrous (Other)	None Detected
19JH031937 161905383-0037	2nd Floor - duct/pipe insulation wrap silver	Brown/White Fibrous Homogeneous	60% Cellulose 10% Glass	30% Non-fibrous (Other)	None Detected
19JH031938 161905383-0038	1 2nd Floor - cove base (tile) gray	Gray Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH031939 161905383-0039	2nd Floor - cove base mastic gold	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031940 161905383-0040	2 2nd Floor - floor tile mastic black	Black Fibrous Homogeneous	50% Cellulose	40% Non-fibrous (Other)	10% Chrysotile
19JH031941 161905383-0041	2nd Floor - ceiling tile yellow	Gray/White Fibrous Homogeneous	40% Cellulose 40% Min. Wool	15% Perlite 5% Non-fibrous (Other)	None Detected
19JH031942 161905383-0042	2nd Floor - wall insulation brown	Brown/Yellow Fibrous Homogeneous	98% Glass	2% Non-fibrous (Other)	None Detected
19JH031943 161905383-0043	2nd Floor - insulation paper brown	Black Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
19JH031944 161905383-0044	2nd Floor - window caulk brown	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031945 161905383-0045	3 2nd Floor - wall adhesive black	Black Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH031946 161905383-0046	2nd Floor - carpet adhesive dark brown	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031947 161905383-0047	2nd Floor - duct insulation pink	Pink Fibrous Homogeneous	98% Glass	2% Non-fibrous (Other)	None Detected
19JH031948 161905383-0048	2nd Floor - duct insulation wrap silver	White/Silver Fibrous Homogeneous	50% Cellulose 10% Glass	40% Non-fibrous (Other)	None Detected
19JH031949 161905383-0049	2nd Floor - ceiling insulation brown	Gray/White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031950 161905383-0050	2nd Floor - ceiling skim coat gray	Gray Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
19JH031951 161905383-0051	2nd Floor - ceiling plaster gray	Brown Non-Fibrous Homogeneous		20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031952 161905383-0052	2nd Floor - 12x12 floor tile gray	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031953 161905383-0053	2nd Floor - floor tile adhesive	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH031954 <small>161905383-0054</small>	2nd Floor - floor tile adhesive	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031955 <small>161905383-0055</small>	2nd Floor - concrete joint caulk gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031956 <small>161905383-0056</small>	2nd Floor - wall plaster gray	Gray Non-Fibrous Homogeneous		20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031957 <small>161905383-0057</small>	2nd Floor - wall skim coat gray	White Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
<i>Inseparable paint / coating layer included in analysis</i>					
19JH031958 <small>161905383-0058</small>	2nd Floor - gypsum adhesive white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031959 <small>161905383-0059</small>	2nd Floor - marble baseboard adhesive yellow	Gray/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031960 <small>161905383-0060</small>	2nd Floor - cove base brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031961 <small>161905383-0061</small>	2nd Floor - cove base mastic tan	White/Clear Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031962 <small>161905383-0062</small>	2nd Floor - cove base mastic yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031963 <small>161905383-0063</small>	2nd Floor - flooring gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031964 <small>161905383-0064</small>	2nd Floor - flooring adhesive brown	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031965 <small>161905383-0065</small>	2nd Floor - caulk white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031966 <small>161905383-0066</small>	2nd Floor - caulk black	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031967 <small>161905383-0067</small>	2nd Floor - expansion joint foam gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031968 <small>161905383-0068</small>	2nd Floor - cove base black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031969 <small>161905383-0069</small>	2nd Floor - cove base mastic yellow	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031970 <small>161905383-0070</small>	2nd Floor - cove base mastic gold	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031971 <small>161905383-0071</small>	2nd Floor - drywall white	Brown/White Fibrous Heterogeneous	20% Cellulose	70% Gypsum 10% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH031972 <small>161905383-0072</small>	4 2nd Floor - drywall joint compound white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH031973 <small>161905383-0073</small>	2nd Floor - drywall tape cream	White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031974 <small>161905383-0074</small>	2nd Floor - ceiling tile gray	Gray/White Fibrous Homogeneous	5% Cellulose 90% Min. Wool	5% Non-fibrous (Other)	None Detected
19JH031975 <small>161905383-0075</small>	2nd Floor - carpet mastic black/yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031976 <small>161905383-0076</small>	2nd Floor - cove base gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031977 <small>161905383-0077</small>	2nd Floor - cove base mastic brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031978 <small>161905383-0078</small>	2nd Floor - cove base brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031979 <small>161905383-0079</small>	2nd Floor - cove base mastic gold	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031980 <small>161905383-0080</small>	5 2nd Floor - 12x12 floor tile cream w/tan	Tan/White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH031981 <small>161905383-0081</small>	2nd Floor - floor tile mastic black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031982 <small>161905383-0082</small>	2nd Floor - ceiling plaster gray	Gray Non-Fibrous Homogeneous	<1% Hair	20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031983 <small>161905383-0083</small>	2nd Floor - ceiling skim coat gray <i>Inseparable paint / coating layer included in analysis</i>	Tan/White Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
19JH031984 <small>161905383-0084</small>	2nd Floor - wall plaster gray	Gray Non-Fibrous Homogeneous	<1% Hair	20% Quartz 80% Non-fibrous (Other)	None Detected
19JH031985 <small>161905383-0085</small>	2nd Floor - wall skim coat gray <i>Inseparable paint / coating layer included in analysis</i>	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031986 <small>161905383-0086</small>	2nd Floor - countertop black	Black Non-Fibrous Homogeneous	40% Cellulose	60% Non-fibrous (Other)	None Detected
19JH031987 <small>161905383-0087</small>	2nd Floor - countertop adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031988 <small>161905383-0088</small>	2nd Floor - cove base gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031989 <small>161905383-0089</small>	2nd Floor - cove base mastic yellow	Brown/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH031990 <small>161905383-0090</small>	2nd Floor - carpet adhesive yellow	Brown/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031991 6 <small>161905383-0091</small>	2nd Floor - sink undercoat black	Black Non-Fibrous Homogeneous		96% Non-fibrous (Other)	4% Chrysotile
19JH031992 <small>161905383-0092</small>	2nd Floor - drywall white	Brown/White Fibrous Heterogeneous	20% Cellulose	70% Gypsum 10% Non-fibrous (Other)	None Detected
19JH031993 7 <small>161905383-0093</small>	2nd Floor - drywall joint compound white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH031994 <small>161905383-0094</small>	2nd Floor - drywall tape cream	White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH031995 <small>161905383-0095</small>	2nd Floor - cove base black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031996 <small>161905383-0096</small>	2nd Floor - cove base mastic gold	Brown/Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031997 8 <small>161905383-0097</small>	2nd Floor - ceiling tile white	Gray/White Fibrous Homogeneous	90% Min. Wool	10% Non-fibrous (Other)	<1% Amosite
19JH031998 <small>161905383-0098</small>	2nd Floor - carpet adhesive yellow	Brown/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH031999 <small>161905383-0099</small>	2nd Floor - 12x12 floor tile cream	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319100 <small>161905383-0100</small>	2nd Floor - floor tile mastic brown/yellow	Brown/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319101 <small>161905383-0101</small>	2nd Floor - ceiling tile white	Gray Fibrous Homogeneous	40% Cellulose 40% Glass	10% Perlite 10% Non-fibrous (Other)	None Detected
19JH0319102A <small>161905383-0102</small>	1st Floor - ceiling texture white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
<i>Inseparable paint / coating layer included in analysis</i>					
19JH0319102B <small>161905383-0103</small>	1st Floor - ceiling texture white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319102C <small>161905383-0104</small>	1st Floor - ceiling texture white	White Non-Fibrous Homogeneous		5% Mica 95% Non-fibrous (Other)	None Detected
19JH0319103 <small>161905383-0105</small>	1st Floor - fire caulk red	Red Non-Fibrous Homogeneous	5% Glass	95% Non-fibrous (Other)	None Detected
19JH0319104 <small>161905383-0106</small>	1st Floor - drywall white	Brown/White Fibrous Heterogeneous	10% Cellulose	70% Gypsum 20% Non-fibrous (Other)	None Detected
19JH0319105 <small>161905383-0107</small>	1st Floor - drywall joint compound white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319106 <small>161905383-0108</small>	1st Floor - drywall tape white	White Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH0319107 <small>161905383-0109</small>	1st Floor - carpet adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319108 <small>161905383-0110</small>	9 1st Floor - sink undercoat white	White Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH0319109 <small>161905383-0111</small>	1st Floor - countertop brown	Brown Non-Fibrous Homogeneous	70% Cellulose	30% Non-fibrous (Other)	None Detected
19JH0319110 <small>161905383-0112</small>	1st Floor - countertop adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319111 <small>161905383-0113</small>	1st Floor - countertop brown	Brown Non-Fibrous Homogeneous	70% Cellulose	30% Non-fibrous (Other)	None Detected
19JH0319112 <small>161905383-0114</small>	1st Floor - countertop adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319113 <small>161905383-0115</small>	10 1st Floor - 12x12 floor tile brown	Brown Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
19JH0319114 <small>161905383-0116</small>	11 1st Floor - floor tile mastic black	Black Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH0319115 <small>161905383-0117</small>	1st Floor - carpet adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319116 <small>161905383-0118</small>	1st Floor - carpet pad (on wall) black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319117 <small>161905383-0119</small>	12 1st Floor - wall mastic brown	Brown Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH0319118 <small>161905383-0120</small>	13 1st Floor - floor tile maroon	Red Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
19JH0319119 <small>161905383-0121</small>	1st Floor - floor tile mastic black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319120-Floor Tile <small>161905383-0122</small>	14 1st Floor - floor tile green	Green Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
19JH0319120-Mastic <small>161905383-0122A</small>	1st Floor - floor tile green	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319121-Floor Tile <small>161905383-0123</small>	15 1st Floor - floor tile black	Black Non-Fibrous Homogeneous		97% Non-fibrous (Other)	3% Chrysotile
19JH0319121-Mastic <small>161905383-0123A</small>	1st Floor - floor tile black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319122 <small>161905383-0124</small>	1st Floor - flooring gray	Gray Fibrous Heterogeneous	10% Cellulose	90% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319123 <small>161905383-0125</small>	1st Floor - wall plaster gray	Gray Non-Fibrous Homogeneous		30% Quartz 70% Non-fibrous (Other)	None Detected
19JH0319124 <small>161905383-0126</small>	1st Floor - duct insulation yellow	Yellow Fibrous Homogeneous	95% Glass	5% Non-fibrous (Other)	None Detected
19JH0319125 <small>161905383-0127</small>	1st Floor - duct wrap silver	Silver Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
19JH0319126 16 <small>161905383-0128</small>	1st Floor - wall mastic black	Black Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH0319127 <small>161905383-0129</small>	1st Floor - ceiling tile white	Gray/White Fibrous Homogeneous	50% Cellulose 30% Min. Wool	15% Perlite 5% Non-fibrous (Other)	None Detected
19JH0319128 <small>161905383-0130</small>	1st Floor - wall skim coat white	White Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
19JH0319129 <small>161905383-0131</small>	1st Floor - caulk uellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319130 <small>161905383-0132</small>	1st Floor - felt paper black	Black Fibrous Homogeneous	60% Cellulose	40% Non-fibrous (Other)	None Detected
19JH0319131 <small>161905383-0133</small>	1st Floor - plaster white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319132 <small>161905383-0134</small>	1st Floor - felt paper black	Black Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
19JH0319133 <small>161905383-0135</small>	1st Floor - ceiling plaster gray	Gray Non-Fibrous Homogeneous	<1% Hair	20% Quartz 80% Non-fibrous (Other)	None Detected
19JH0319134 <small>161905383-0136</small>	1st Floor - ceiling skim coat gray	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319135A <small>161905383-0137</small>	1st Floor - wall texture white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
<i>Inseparable paint / coating layer included in analysis</i>					
19JH0319135B <small>161905383-0138</small>	1st Floor - wall texture white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
<i>Inseparable paint / coating layer included in analysis</i>					
19JH0319135C <small>161905383-0139</small>	1st Floor - wall texture white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
<i>Inseparable paint / coating layer included in analysis</i>					
19JH0319136 <small>161905383-0140</small>	1st Floor - duct seam tape gray	Gray/Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319137 <small>161905383-0141</small>	1st Floor - ceramic tile mastic yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319138 <small>161905383-0142</small>	1st Floor - wall adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319139 <i>161905383-0143</i>	1st Floor - floor leveler tan	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319140 <i>161905383-0144</i>	1st Floor - carpet adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319141 <i>161905383-0145</i>	1st Floor - 12x12 floor tile tan	Gray/Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319142 <i>161905383-0146</i>	1st Floor - floor tile mastic black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319143 <i>161905383-0147</i> <i>Inseparable paint / coating layer included in analysis</i>	1st Floor - wall skim coat gray	Gray Non-Fibrous Homogeneous		10% Quartz 90% Non-fibrous (Other)	None Detected
19JH0319144 <i>161905383-0148</i>	1st Floor - wall plaster gray	Gray Non-Fibrous Homogeneous		20% Quartz 80% Non-fibrous (Other)	None Detected
19JH0319145 <i>161905383-0149</i>	1st Floor - 1x1 ceiling tile brown	Brown Fibrous Homogeneous	98% Cellulose	2% Non-fibrous (Other)	None Detected
19JH0319146A <i>161905383-0150</i> <i>Inseparable paint / coating layer included in analysis</i>	1st Floor - ceiling texture (on 1x1s) white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319146B <i>161905383-0151</i> <i>Inseparable paint / coating layer included in analysis</i>	1st Floor - ceiling texture (on 1x1s) white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319146C <i>161905383-0152</i> <i>Inseparable paint / coating layer included in analysis</i>	1st Floor - ceiling texture (on 1x1s) white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319147 <i>161905383-0153</i>	1st Floor - 1x1 ceiling tile mastic brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319148 <i>161905383-0154</i>	1st Floor - window glazing black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319149 <i>161905383-0155</i>	1st Floor - window caulk brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319150 <i>161905383-0156</i>	1st Floor - cove base brown	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319151 <i>161905383-0157</i>	1st Floor - cove base mastic yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319152 <i>161905383-0158</i>	1st Floor - caulk white	Brown/Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319153 <i>161905383-0159</i>	1st Floor - ceiling tile white	Gray Fibrous Homogeneous	30% Cellulose 60% Glass	10% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319154 <i>161905383-0160</i>	1st Floor - gypsum block white	White Non-Fibrous Homogeneous	10% Cellulose	75% Gypsum 15% Non-fibrous (Other)	None Detected
19JH0319155 <i>161905383-0161</i>	1st Floor - wall skim coat gray	Gray Non-Fibrous Homogeneous		30% Quartz 70% Non-fibrous (Other)	None Detected
19JH0319156 <i>161905383-0162</i>	1st Floor - wall plaster gray	Gray Non-Fibrous Homogeneous		30% Quartz 70% Non-fibrous (Other)	None Detected
19JH0319157 <i>161905383-0163</i>	1st Floor - caulk white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319158 <i>161905383-0164</i>	1st Floor - marble adhesive white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319159 <i>161905383-0165</i>	1st Floor - cove base gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319160 <i>161905383-0166</i>	1st Floor - cove base mastic yellow	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319161 <i>161905383-0167</i>	1st Floor - linolium flooring brown	Tan/White Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
19JH0319162 <i>161905383-0168</i>	1st Floor - flooring adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319163 <i>161905383-0169</i>	1st Floor - flooring adhesive brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319164 <i>161905383-0170</i>	1st Floor - carpet adhesive yellow	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319165 <i>161905383-0171</i>	1st Floor - drywall white	Brown/White Fibrous Heterogeneous	15% Cellulose	70% Gypsum 15% Non-fibrous (Other)	None Detected
19JH0319166 <i>161905383-0172</i>	1st Floor - drywall joint compound white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319167 <i>161905383-0173</i>	1st Floor - drywall tape cream	White Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
19JH0319168 <i>161905383-0174</i>	1st Floor - ceiling plaster gray	Gray Non-Fibrous Homogeneous	5% Cellulose	20% Quartz 75% Non-fibrous (Other)	None Detected
19JH0319169 <i>161905383-0175</i>	1st Floor - ceiling skim coat gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
<i>Inseparable paint / coating layer included in analysis</i>					
19JH0319170 <i>161905383-0176</i>	1st Floor - ceiling tile gray	Gray Fibrous Homogeneous	30% Cellulose 40% Glass	10% Perlite 20% Non-fibrous (Other)	None Detected
19JH0319171 <i>161905383-0177</i>	1st Floor - gypsum block white	White Non-Fibrous Homogeneous		85% Gypsum 15% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319172 <small>161905383-0178</small>	1st Floor - plaster gray	Gray Non-Fibrous Homogeneous		30% Quartz 70% Non-fibrous (Other)	None Detected
19JH0319173 <small>161905383-0179</small>	1st Floor - gypsum block grout gray	Gray Non-Fibrous Homogeneous	<1% Hair	50% Quartz 50% Non-fibrous (Other)	None Detected
19JH0319174 <small>161905383-0180</small>	1st Floor - wall paper yellow/white	White Fibrous Homogeneous	90% Cellulose	10% Non-fibrous (Other)	None Detected
<small>Inseparable paint / coating layer included in analysis</small>					
19JH0319175 17 <small>161905383-0181</small>	1st Floor - wall panel mastic black	Black Non-Fibrous Homogeneous		98% Non-fibrous (Other)	2% Chrysotile
19JH0319176 <small>161905383-0182</small>	1st Floor - floor leveler white	Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319177 <small>161905383-0183</small>	1st Floor - drywall white	Tan/White Non-Fibrous Homogeneous	8% Cellulose 10% Glass	82% Non-fibrous (Other)	None Detected
19JH0319178 <small>161905383-0184</small>	1st Floor - drywall joint compound white	Tan/White Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
19JH0319179 <small>161905383-0185</small>	1st Floor - drywall tape cream	Tan/White Fibrous Homogeneous	65% Cellulose	35% Non-fibrous (Other)	None Detected
19JH0319180 <small>161905383-0186</small>	1st Floor - caulk tan	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319181 <small>161905383-0187</small>	1st Floor - wall mastic (behind baseboard) black	Brown/Black Fibrous Heterogeneous	70% Cellulose	30% Non-fibrous (Other)	None Detected
19JH0319182 <small>161905383-0188</small>	1st Floor - cove base brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319183 <small>161905383-0189</small>	1st Floor - cove base mastic yellow	Yellow Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319184 <small>161905383-0190</small>	1st Floor - cove base mastic clear	Clear Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319185 <small>161905383-0191</small>	1st Floor - pipe insulation yellow	Yellow Fibrous Heterogeneous	75% Glass	25% Non-fibrous (Other)	None Detected
19JH0319186 <small>161905383-0192</small>	1st Floor - pipe wrap white	White/Silver Fibrous Heterogeneous	25% Cellulose 15% Glass	60% Non-fibrous (Other)	None Detected
19JH0319187 <small>161905383-0193</small>	1st Floor - carpet adhesive gray	Gray Non-Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	None Detected
19JH0319188 <small>161905383-0194</small>	1st Floor - floor leveler gray	Gray Non-Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	None Detected
19JH0319189 <small>161905383-0195</small>	1st Floor - wall insulation yellow	Yellow Fibrous Heterogeneous	60% Min. Wool	40% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319190 <small>161905383-0196</small>	1st Floor - insulation paper brown/black	Brown/Black Non-Fibrous Homogeneous	45% Cellulose	55% Non-fibrous (Other)	None Detected
19JH0319191 <small>161905383-0197</small>	1st Floor - ceiling tile gray	Tan/White Fibrous Heterogeneous	35% Cellulose 15% Glass	50% Non-fibrous (Other)	None Detected
19JH0319192 <small>161905383-0198</small>	1st Floor - duct caulk gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319193 <small>161905383-0199</small>	1st Floor - duct insulation yellow	Yellow/Pink Fibrous Heterogeneous	78% Min. Wool	22% Non-fibrous (Other)	None Detected
19JH0319194 <small>161905383-0200</small>	1st Floor - duct wrap silver	Tan/Silver Fibrous Heterogeneous	25% Cellulose 12% Glass	63% Non-fibrous (Other)	None Detected
19JH0319195 <small>161905383-0201</small>	1st Floor - ceiling tile white	White Fibrous Heterogeneous	25% Min. Wool	75% Non-fibrous (Other)	None Detected
19JH0319196 <small>161905383-0202</small>	1st Floor - wall insulation brown	Brown Fibrous Heterogeneous	35% Cellulose	65% Non-fibrous (Other)	None Detected
19JH0319197 <small>161905383-0203</small>	1st Floor - insulation paper black	Black/Yellow Non-Fibrous Homogeneous	75% Min. Wool	25% Non-fibrous (Other)	None Detected
19JH0319198 <small>161905383-0204</small>	1st Floor - ceiling plaster gray	Gray Fibrous Homogeneous	15% Hair	85% Non-fibrous (Other)	None Detected
19JH0319199 <small>161905383-0205</small>	1st Floor - ceiling skim coat gray	Tan Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319200 <small>161905383-0206</small>	1st Floor - duct tape silver	Silver/Clear Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319201 <small>161905383-0207</small>	1st Floor - window caulk brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319202 <small>161905383-0208</small>	1st Floor - caulk white	White/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319203 <small>161905383-0209</small>	1st Floor - ceiling tile white	Tan/White Fibrous Heterogeneous	40% Cellulose 25% Glass	35% Non-fibrous (Other)	None Detected
19JH0319204 <small>161905383-0210</small>	1st Floor - countertop tan	Tan Non-Fibrous Homogeneous	6% Cellulose	94% Non-fibrous (Other)	None Detected
19JH0319205 <small>161905383-0211</small>	1st Floor - countertop adhesive pink	Red/Pink Non-Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
19JH0319206 <small>161905383-0212</small>	1st Floor - caulk tan	Tan Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
19JH0319207 <small>161905383-0213</small>	1st Floor - backsplash adhesive yellow	Tan/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319208 <small>161905383-0214</small>	1st Floor - floor leveler gray	Gray Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319209 <small>161905383-0215</small>	1st Floor - cove base brown	Brown Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319210 <small>161905383-0216</small>	1st Floor - cove base mastic yellow	Yellow Non-Fibrous Homogeneous	2% Cellulose 3% Synthetic	95% Non-fibrous (Other)	None Detected
19JH0319211 <small>161905383-0217</small>	1st Floor - cove base mastic clear	Clear Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319212 <small>161905383-0218</small>	1st Floor - drywall white	White Fibrous Heterogeneous	4% Cellulose 15% Glass	81% Non-fibrous (Other)	None Detected
19JH0319213 <small>161905383-0219</small>	1st Floor - drywall joint compound white	Tan/White Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
19JH0319214 <small>161905383-0220</small>	1st Floor - drywall tape cream	Tan/White Fibrous Homogeneous	55% Cellulose	45% Non-fibrous (Other)	None Detected
19JH0319215 <small>161905383-0221</small>	1st Floor - ceiling plaster white	White Non-Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	None Detected
19JH0319216 <small>161905383-0222</small>	1st Floor - felt paper black	Gray/Black Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
19JH0319217 <small>161905383-0223</small>	1st Floor - 12x12 floor tile gray	Gray/White Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
19JH0319218 <small>161905383-0224</small>	1st Floor - floor tile adhesive pink	Gray/White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319219 <small>161905383-0225</small>	1st Floor - caulk white	Tan/White/Blue Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319220 <small>161905383-0226</small>	1st Floor - wall plaster gray	Gray/Blue Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319221 <small>161905383-0227</small>	1st Floor - wall skim coat gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319222 <small>161905383-0228</small>	1st Floor - 1x1 ceiling tile brown	Brown/Tan Fibrous Heterogeneous	65% Cellulose	35% Non-fibrous (Other)	None Detected
19JH0319223 <small>161905383-0229</small>	1st Floor - 1x1 ceiling tile mastic brown	Brown Non-Fibrous Homogeneous	12% Cellulose	88% Non-fibrous (Other)	None Detected
19JH0319224 <small>161905383-0230</small>	1st Floor - ceramic tile grout white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319225 <small>161905383-0231</small>	1st Floor - ceramic tile adhesive yellow	Yellow Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319226 <small>161905383-0232</small>	1st Floor - marble grout white	White/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319227 <small>161905383-0233</small>	1st Floor - tar black	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319228A <small>161905383-0234</small>	1st Floor - pipe wrap white	Tan/White Fibrous Homogeneous	55% Cellulose 15% Glass	30% Non-fibrous (Other)	None Detected
19JH0319228B <small>161905383-0235</small>	1st Floor - pipe wrap white	White/Clear Fibrous Homogeneous	65% Cellulose	35% Non-fibrous (Other)	None Detected
19JH0319228C <small>161905383-0236</small>	1st Floor - pipe wrap white	White Fibrous Homogeneous	50% Cellulose	50% Non-fibrous (Other)	None Detected
19JH0319229A 18 <small>161905383-0237</small>	1st Floor - pipe insulation white	White Fibrous Homogeneous		35% Non-fibrous (Other)	65% Chrysotile
19JH0319229B <small>161905383-0238</small>	1st Floor - pipe insulation white				Positive Stop (Not Analyzed)
19JH0319229C <small>161905383-0239</small>	1st Floor - pipe insulation white				Positive Stop (Not Analyzed)
19JH0319230 <small>161905383-0240</small>	1st Floor - pipe wrap white	White/Silver Fibrous Heterogeneous	15% Cellulose 10% Glass	75% Non-fibrous (Other)	None Detected
19JH0319231 <small>161905383-0241</small>	1st Floor - pipe insulation yellow	Yellow Fibrous Homogeneous	70% Glass	30% Non-fibrous (Other)	None Detected
19JH0319232A 19 <small>161905383-0242</small>	1st Floor - mudded joints white	White Fibrous Homogeneous	20% Cellulose	25% Non-fibrous (Other)	55% Chrysotile
19JH0319232B <small>161905383-0243</small>	1st Floor - mudded joints white				Positive Stop (Not Analyzed)
19JH0319232C <small>161905383-0244</small>	1st Floor - mudded joints white				Positive Stop (Not Analyzed)
19JH0319233 <small>161905383-0245</small>	1st Floor - wall plaster gray	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319234 <small>161905383-0246</small>	1st Floor - wall skim coat gray	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319235 <small>161905383-0247</small>	1st Floor - pipe insulation yellow	Yellow Fibrous Homogeneous	72% Glass	28% Non-fibrous (Other)	None Detected
19JH0319236 <small>161905383-0248</small>	1st Floor - pipe wrap white	White/Silver Fibrous Heterogeneous	20% Cellulose 15% Glass	65% Non-fibrous (Other)	None Detected
19JH0319237 <small>161905383-0249</small>	Basement - wall plaster gray	Gray/Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319238 <small>161905383-0250</small>	Basement - wall skim coat gray	Tan/White Fibrous Homogeneous	10% Hair	90% Non-fibrous (Other)	None Detected
19JH0319239 <small>161905383-0251</small>	Basement - ceiling plaster gray	Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319240 <small>161905383-0252</small>	Basement - ceiling skim coat	Tan/White Fibrous Heterogeneous	2% Cellulose 2% Hair	96% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319241 <small>161905383-0253</small>	Basement - pipe insulation yellow	Yellow Fibrous Homogeneous	2% Cellulose 75% Glass	23% Non-fibrous (Other)	None Detected
19JH0319242 <small>161905383-0254</small>	Basement - pipe wrap white	White/Clear Fibrous Heterogeneous	25% Cellulose 15% Glass	60% Non-fibrous (Other)	None Detected
19JH0319243 <small>161905383-0255</small>	Basement - pipe end cap caulk white	White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319244 <small>161905383-0256</small>	Basement - pipe insulation yellow	Yellow Fibrous Homogeneous	2% Cellulose 80% Glass	18% Non-fibrous (Other)	None Detected
19JH0319245 <small>161905383-0257</small>	Basement - pipe wrap white	White/Silver Fibrous Heterogeneous	35% Cellulose 15% Glass	50% Non-fibrous (Other)	None Detected
19JH0319246 <small>161905383-0258</small>	Basement - pipe insulation yellow	Yellow Fibrous Homogeneous	75% Glass	25% Non-fibrous (Other)	None Detected
19JH0319247 <small>161905383-0259</small>	Basement - pipe wrap white	White/Silver Fibrous Heterogeneous	25% Cellulose 12% Glass	63% Non-fibrous (Other)	None Detected
19JH0319248 <small>161905383-0260</small>	Basement - seam caulk white	White Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
19JH0319249 <small>161905383-0261</small>	Basement - pipe insulation yellow	Yellow Fibrous Homogeneous	85% Glass	15% Non-fibrous (Other)	None Detected
19JH0319250 <small>161905383-0262</small>	Basement - pipe wrap white	Silver Fibrous Heterogeneous	33% Cellulose 12% Glass	55% Non-fibrous (Other)	None Detected
19JH0319251 <small>161905383-0263</small>	Basement - cardboard duct brown/black	Brown/Black Fibrous Heterogeneous	45% Cellulose	55% Non-fibrous (Other)	None Detected
19JH0319252 <small>161905383-0264</small>	Basement - ceiling plaster gray	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319253 <small>161905383-0265</small>	Basement - ceiling skim coat gray	Gray/White/Various Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319254 <small>161905383-0266</small>	Basement - plaster white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319255 <small>161905383-0267</small>	Basement - felt paper black	Brown/Black Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (Other)	None Detected
19JH0319256 <small>161905383-0268</small>	Basement - tar paper black	Black Fibrous Heterogeneous	25% Cellulose	75% Non-fibrous (Other)	None Detected
19JH0319257 <small>161905383-0269</small>	Basement - tar soaked plaster gray/black	Brown/Black Fibrous Heterogeneous	15% Cellulose	85% Non-fibrous (Other)	None Detected
19JH0319258 <small>161905383-0270</small>	Basement - duct insulation yellow	Yellow Fibrous Homogeneous	82% Glass	18% Non-fibrous (Other)	None Detected
19JH0319259 <small>161905383-0271</small>	Basement - duct wrap silver	White Fibrous Heterogeneous	10% Cellulose 15% Glass	75% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319260 <small>161905383-0272</small>	Basement - duct tape silver	Silver Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected
19JH0319261 20 <small>161905383-0273</small>	Basement - pipe wrap black	Brown/Black Fibrous Heterogeneous	2% Synthetic 12% Hair	82% Non-fibrous (Other)	4% Chrysotile
19JH0319262 <small>161905383-0274</small>	Basement - tar paper black	Brown/Black Fibrous Heterogeneous	12% Cellulose	88% Non-fibrous (Other)	None Detected
19JH0319263 <small>161905383-0275</small>	Basement - tar black	Gray/Black Non-Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	None Detected
19JH0319264 <small>161905383-0276</small>	Basement - fire caulk red	Gray/Red Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319265 <small>161905383-0277</small>	Basement - caulk silver	Gray/Silver Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319266 <small>161905383-0278</small>	Basement - wall plaster gray	Gray/Various Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319267 <small>161905383-0279</small>	Basement - wall skim coat gray	Tan/White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319268 <small>161905383-0280</small>	Basement - ceiling plaster gray	Gray/White/Black Non-Fibrous Homogeneous	2% Synthetic	98% Non-fibrous (Other)	None Detected
19JH0319269 <small>161905383-0281</small>	Basement - ceiling skim coat gray	Tan/White/Various Fibrous Homogeneous	3% Synthetic	97% Non-fibrous (Other)	None Detected
19JH0319270 <small>161905383-0282</small>	Basement - plaster white	White Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
19JH0319271 <small>161905383-0283</small>	Basement - felt paper black	Gray/Black Non-Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (Other)	None Detected
19JH0319272 <small>161905383-0284</small>	Basement - tar paper black	Brown/Black Fibrous Heterogeneous	45% Cellulose	55% Non-fibrous (Other)	None Detected
19JH0319273 <small>161905383-0285</small>	Basement - pipe insulation yellow	Yellow Fibrous Homogeneous	4% Cellulose 80% Glass	16% Non-fibrous (Other)	None Detected
19JH0319274 <small>161905383-0286</small>	Basement - pipe wrap white	Tan/White Fibrous Heterogeneous	25% Cellulose 17% Glass	58% Non-fibrous (Other)	None Detected
19JH0319275 <small>161905383-0287</small>	Basement - tar black	White/Black Non-Fibrous Homogeneous	3% Cellulose	97% Non-fibrous (Other)	None Detected
19JH0319276 <small>161905383-0288</small>	Basement - grout/concrete gray	Gray/White Fibrous Homogeneous	4% Cellulose	96% Non-fibrous (Other)	None Detected
19JH0319277 <small>161905383-0289</small>	Basement - caulk white	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319278 <small>161905383-0290</small>	Basement - corkboard brown	Brown/White Fibrous Heterogeneous	72% Cellulose	28% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319279 <small>161905383-0291</small>	Basement - marble wall adhesive white	Gray/White/Various Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319280 <small>161905383-0292</small>	Basement - marble wall adhesive white	White Non-Fibrous Homogeneous	2% Fibrous (Other)	98% Non-fibrous (Other)	None Detected
19JH0319281 <small>161905383-0293</small>	Basement - marble sill adhesive white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319282 <small>161905383-0294</small>	Basement - terrazzo floor gray	Gray/White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319283 <small>161905383-0295</small>	Basement - wall plaster gray	Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319284 <small>161905383-0296</small>	Basement - ceiling tile gray	Tan/White Fibrous Heterogeneous	30% Cellulose 35% Glass	35% Non-fibrous (Other)	None Detected
19JH0319285 <small>161905383-0297</small>	Basement - duct insulation yellow	Yellow Fibrous Homogeneous	2% Cellulose 80% Glass	18% Non-fibrous (Other)	None Detected
19JH0319286 <small>161905383-0298</small>	Basement - duct wrap silver	Silver Fibrous Heterogeneous	20% Glass	80% Non-fibrous (Other)	None Detected
19JH0319287 <small>161905383-0299</small>	Basement - caulk white	White Non-Fibrous Homogeneous	2% Cellulose 2% Synthetic	96% Non-fibrous (Other)	None Detected
19JH0319288 <small>161905383-0300</small>	Basement - plaster ceiling gray	Tan Fibrous Heterogeneous	20% Cellulose 2% Synthetic	78% Non-fibrous (Other)	None Detected
19JH0319289 <small>161905383-0301</small>	Basement - plaster white	White Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
19JH0319290 <small>161905383-0302</small>	Basement - felt paper black	Gray/Black Fibrous Homogeneous	25% Cellulose 5% Synthetic	70% Non-fibrous (Other)	None Detected
19JH0319291 <small>161905383-0303</small>	Basement - tar paper black	Black Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (Other)	None Detected
19JH0319292 <small>161905383-0304</small>	Basement - pipe insulation yellow	Yellow Fibrous Homogeneous	80% Glass	20% Non-fibrous (Other)	None Detected
19JH0319293 <small>161905383-0305</small>	Basement - pipe wrap white	White Non-Fibrous Homogeneous	50% Cellulose	50% Non-fibrous (Other)	None Detected
19JH0319294 <small>161905383-0306</small>	Basement - wall plaster gray	Gray/Tan Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319295 <small>161905383-0307</small>	Basement - wall skim coat gray	Gray/White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319296 <small>161905383-0308</small>	Basement - door caulk tan	Tan Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319297 <small>161905383-0309</small>	Basement - marble wall grout white	White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319298 161905383-0310	Basement - stair tread black	Gray/Black Non-Fibrous Homogeneous	2% Cellulose 2% Synthetic	96% Non-fibrous (Other)	None Detected
19JH0319299 161905383-0311	Basement - ceramic tile grout black	White/Black Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319300 161905383-0312	1st Floor - terrazzo floor orange	Gray/White/Orange Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319301 161905383-0313	2nd Floor - ceiling tile white	White Non-Fibrous Heterogeneous	5% Cellulose 75% Min. Wool	20% Non-fibrous (Other)	None Detected
19JH0319302 161905383-0314	2nd Floor - ceramic wall tile adhesive gray	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
19JH0319303 161905383-0315	2nd Floor - ceramic tile grout tan	Tan/White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319304 161905383-0316	2nd Floor - drywall white	White Fibrous Heterogeneous	2% Cellulose 10% Glass	88% Non-fibrous (Other)	None Detected
19JH0319305 161905383-0317	2nd Floor - 12x12 floor tile gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319306 161905383-0318	2nd Floor - floor tile adhesive pink	Pink Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319307 161905383-0319	2nd Floor - floor leveler gray	Gray Non-Fibrous Homogeneous	20% Cellulose	80% Non-fibrous (Other)	None Detected
19JH0319308 161905383-0320	1st Floor - door caulk tan	White Non-Fibrous Homogeneous	2% Synthetic	98% Non-fibrous (Other)	None Detected
19JH0319309 161905383-0321	1st Floor - cove base brown	Brown/Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319310 161905383-0322	1st Floor - cove base mastic yellow	Yellow Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319311 161905383-0323	1st Floor - cove base mastic clear	Clear Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319312 161905383-0324	1st Floor - caulk tan	Tan Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
19JH0319313 161905383-0325	1st Floor - drywall white	White Non-Fibrous Homogeneous	2% Cellulose 2% Glass	96% Non-fibrous (Other)	None Detected
19JH0319314 161905383-0326	1st Floor - drywall joint compound white	White Non-Fibrous Homogeneous	2% Cellulose 2% Synthetic	96% Non-fibrous (Other)	None Detected
19JH0319315 161905383-0327	1st Floor - drywall tape cream	Tan Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319316 161905383-0328	1st Floor - floor leveler white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0319317 161905383-0329	1st Floor - floor tile mastic black	Black Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319318 161905383-0330	2nd Floor - ceiling tile white	White Fibrous Heterogeneous	25% Cellulose 30% Glass	45% Non-fibrous (Other)	None Detected
19JH0319319 161905383-0331	2nd Floor - window caulk white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319320 161905383-0332	2nd Floor - stair tread black	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319321 161905383-0333	2nd Floor - window caulk brown	Brown Non-Fibrous Homogeneous	8% Cellulose	92% Non-fibrous (Other)	None Detected
19JH0319322 161905383-0334	1st Floor - ceramic tile adhesive gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319323 161905383-0335	1st Floor - ceramic tile grout brown	Gray/Yellow/Pink Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319324 161905383-0336	1st Floor - wall panel adhesive tan	Tan/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319325 161905383-0337	1st Floor - caulk gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319326 161905383-0338	1st Floor - caulk white	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319327 161905383-0339	1st Floor - flooring gray	Gray Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319328 161905383-0340	1st Floor - flooring adhesive brown	Brown/Tan Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319329 161905383-0341	1st Floor - duct caulk gray	Gray Fibrous Homogeneous	15% Synthetic	85% Non-fibrous (Other)	None Detected
19JH0319330 161905383-0342	1st Floor - duct insulation yellow	Yellow Fibrous Homogeneous	85% Glass	15% Non-fibrous (Other)	None Detected
19JH0319331 161905383-0343	1st Floor - duct wrap silver	White/Silver Fibrous Heterogeneous	30% Cellulose 15% Synthetic	55% Non-fibrous (Other)	None Detected
19JH0319332 161905383-0344	1st Floor - ceiling/beam plaster gray	Gray/White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
19JH0319333 161905383-0345	1st Floor - ceiling/beam skim coat gray	Tan/White Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319334 161905383-0346	1st Floor - grout pink	Pink Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
19JH0319335 161905383-0347	1st Floor - caulk brown	Black Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161905383

Customer ID: IMPA25

Customer PO:

Project ID:

Analyst(s)

Benjamin Brittain (119)

Heather Graff2 (43)

Jadda Moffett (126)

Trevor Maggart (57)

Richard Harding, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN NVLAP Lab Code 200188-0, AZ0939, CA 2575, CO AL-15132, TX 300262, LA 04135

Initial report from: 04/02/2019 13:14:51



EMSL Analytical, Inc.

6340 CastlePlace Dr. Indianapolis, IN 46250

Tel/Fax: (317) 803-2997 / (317) 803-3047

<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161906093

Customer ID: IMPA25

Customer PO:

Project ID:

Attention: Jacob Huxford
Impact7G
9550 Hickman Road
Suite 105
Clive, IA 50325

Phone: (515) 473-6256

Fax: (515) 528-8005

Received Date: 04/04/2019 8:52 AM

Analysis Date: 04/04/2019

Collected Date: 04/03/2019

Project: Fort Dodge City Hall - Verification Samples

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0403336 <small>161906093-0001</small>	2nd Floor - Drywall, White, e205C	Brown/White Fibrous Heterogeneous	25% Cellulose	70% Gypsum 5% Non-fibrous (Other)	None Detected
19JH0403337 <small>161906093-0002</small> <i>Inseparable paint / coating layer included in analysis</i>	2nd Floor - Drywall, Joint Compound, white, e205C	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH0403338 <small>161906093-0003</small>	2nd Floor - Drywall Tape, Cream, e205C	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH0403339 <small>161906093-0004</small>	2nd Floor - Drywall, White, e205E	Brown/White Fibrous Heterogeneous	35% Cellulose	60% Gypsum 5% Non-fibrous (Other)	None Detected
19JH0403340 <small>161906093-0005</small> <i>Inseparable paint / coating layer included in analysis</i>	2nd Floor - Drywall Joint Compound, White, e205E	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH0403341 <small>161906093-0006</small>	2nd Floor - Drywall Tape, Cream, e205E	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH0403342 <small>161906093-0007</small>	2nd Floor - Ceiling Tile, Gray, e203A	Gray/White/Pink Fibrous Homogeneous	90% Min. Wool	8% Non-fibrous (Other)	<1% Amosite 2% Chrysotile
19JH0403343 <small>161906093-0008</small>	2nd Floor - Ceiling Tile, Gray, e203B	Gray/White/Pink Fibrous Homogeneous	90% Min. Wool	8% Non-fibrous (Other)	<1% Amosite 2% Chrysotile
19JH0403344 <small>161906093-0009</small>	2nd Floor - Ceiling Tile, Gray, e203	Gray/White/Pink Fibrous Homogeneous	90% Min. Wool	8% Non-fibrous (Other)	<1% Amosite 2% Chrysotile
19JH0403345 <small>161906093-0010</small>	2nd Floor - Drywall, White, e203A	Brown/White Fibrous Heterogeneous	25% Cellulose	70% Gypsum 5% Non-fibrous (Other)	None Detected
19JH0403346 <small>161906093-0011</small>	2nd Floor - Drywall Joint Compound, e203A	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH0403347 <small>161906093-0012</small>	2nd Floor - Drywall Tape, Cream, e203A	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
19JH0403348 <small>161906093-0013</small>	2nd Floor - Drywall, White, e203E	Brown/White Fibrous Heterogeneous	35% Cellulose	60% Gypsum 5% Non-fibrous (Other)	None Detected
19JH0403349 <small>161906093-0014</small> <i>Inseparable paint / coating layer included in analysis</i>	2nd Floor - Drywall Joint Compound, White, e203E	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH0403350 <small>161906093-0015</small>	2nd Floor - Drywall Tape, Cream, e203E	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected

Initial report from: 04/04/2019 14:52:54



EMSL Analytical, Inc.


6340 CastlePlace Dr. Indianapolis, IN 46250
Tel/Fax: (317) 803-2997 / (317) 803-3047
<http://www.EMSL.com> / indianapolislab@emsl.com

EMSL Order: 161906093
Customer ID: IMPA25
Customer PO:
Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
19JH0403351 <small>161906093-0016</small>	2nd Floor - Drywall, White, e203B	Brown/White Fibrous Heterogeneous	25% Cellulose	70% Gypsum 5% Non-fibrous (Other)	None Detected
19JH0403352 <small>161906093-0017</small>	2nd Floor - Drywall Joint Compound, White, e203B <i>Inseparable paint / coating layer included in analysis</i>	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	<1% Chrysotile
19JH0403353 <small>161906093-0018</small>	2nd Floor - Drywall Tape, Cream, e203B	Tan Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected

Analyst(s) _____
Ross Matlock (18)


Richard Harding, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Indianapolis, IN NVLAP Lab Code 200188-0, AZ0939, CA 2575, CO AL-15132, TX 300262, LA 04135

Initial report from: 04/04/2019 14:52:54

DATE SENT: 03/25/19



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

161905383

EMSL ANALYTICAL, INC.
6340 Castleplace Drive
Indianapolis, IN 46250
PHONE: (800) 220-3675

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To: Jacob Huxford		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide results: EMAIL	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			
Turnaround Time (TAT) Options			
<input type="checkbox"/> 3-Hour	<input type="checkbox"/> 6-Hour	<input type="checkbox"/> 24-Hour	<input type="checkbox"/> 48-Hour
<input checked="" type="checkbox"/> 72-Hour	<input type="checkbox"/> 96-Hour	<input type="checkbox"/> 1 Week	<input type="checkbox"/> 2 Week
*For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 hr TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytic Price Guide.			
PLM – BULK (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)		TEM – Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763	
<input checked="" type="checkbox"/> Check for Positive Stop – Clearly Identify Homogeneous Group		Filter Pore Size (Air Samples): <input type="checkbox"/> 0.8 µm <input type="checkbox"/> 0.45 µm	
Sampler's Name:		Sampler's Signature:	
Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH031901	Wall Plaster, Gray, 2 nd Floor		3/19/19
02	Wall Skim coat, Gray, 2 nd Floor		3/19/19
03	Caulk, Gray, 2 nd Floor		3/19/19
04	Ceiling Plaster, Gray, 2 nd Floor		3/19/19
05	Ceiling Skim coat, Gray, 2 nd Floor		3/19/19
06	Ceiling felt paper, black, 2 nd Floor		3/19/19
07	Plaster, White, 2 nd Floor		3/19/19
08	Felt paper, Gray, 2 nd Floor		3/19/19
09	Tar Paper, Black, 2 nd Floor		3/19/19
10	Ceiling Tile, Gray, 2 nd Floor		3/19/19
11	Wall Plaster, Gray, 2 nd Floor		3/19/19
12	Wall Skim coat, Gray, 2 nd Floor		3/19/19
13	Duct Insulation, Yellow, 2 nd Floor		3/19/19
Client Sample # (s):	01-13	Total # of Samples:	335 (plus sequences)
Relinquished (Client):	<i>Jacob Huxford</i>	Date:	3/25/19
Received (Lab):	<i>Carolyn M. ...</i>	Date:	3-26-19
Time:		Time:	5:10 pm
Time:		Time:	8:45 PM
Comments/Special Instructions:	Please sample all layers, thank you!		

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To: Jacob Huxford		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH031914	Duct Insulation wrap, silver, 2 nd Floor		3/19/19
15	Duct Seam Tape/Caulk, Silver/Gray, 2 nd Floor		3/19/19
16	Cove Base, Gray, 2 nd Floor		3/19/19
17	Cove base mastic, Brown, 2 nd Floor		3/19/19
18	Carpet mastic, yellow, 2 nd Floor		3/19/19
19	Drywall, White, 2 nd Floor		3/19/19
20	Drywall Joint compound, white, 2 nd Floor		3/19/19
21	Drywall Tape, cream, 2 nd Floor		3/19/19
22	Drywall, White, 2 nd Floor		3/19/19
23	Drywall Joint compound, white, 2 nd Floor		3/19/19
24	Drywall Tape, cream, 2 nd Floor		3/19/19
25	Corkboard, brown, 2 nd Floor		3/19/19
26	Corkboard adhesive, yellow, 2 nd Floor		3/19/19
27	Floor leveler, gray, 2 nd Floor		3/19/19
28	Carpet adhesive, Yellow, 2 nd Floor		3/19/19
29	Plaster, Gray, 2 nd Floor		3/19/19
30	Skim coat, gray, 2 nd Floor		3/19/19
31	Countertop, Cream, 2 nd Floor		3/19/19
32	Countertop adhesive, gold, 2 nd Floor		3/19/19

Client Sample # (s):	14-32	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			
Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH031933	Sink undercoat, gray, 2 nd Floor		3/19/19
34	Caulk, White, 2 nd Floor		3/19/19
35	Caulk, White, 2 nd Floor		3/19/19
36	Duct/Pipe Insulation, Yellow, 2 nd Floor		3/19/19
37	Duct/Pipe Insulation Wrap, Silver, 2 nd Floor		3/19/19
38	Cove base (tile), Gray, 2 nd Floor		3/19/19
39	Cove base mastic, Gold, 2 nd Floor		3/19/19
40	Floor Tile Mastic, Black, 2 nd Floor		3/19/19
41	Ceiling Tile, Yellow, 2 nd Floor		3/19/19
42	Wall Insulation, Brown, 2 nd Floor		3/19/19
43	Insulation paper, brown, 2 nd Floor		3/19/19
44	Window Caulk, Brown, 2 nd Floor		3/19/19
45	Wall Adhesive, Black, 2 nd Floor		3/19/19
46	Carpet adhesive, Dark brown, 2 nd Floor		3/19/19
47	Duct insulation, Pink, 2 nd Floor		3/19/19
48	Duct insulation wrap, silver, 2 nd Floor		3/19/19
49	Ceiling insulation, brown, 2 nd Floor		3/19/19
Client Sample # (s):	33-49	Total # of Samples:	335
Relinquished (Client):		Date:	Time:
Received (Lab):		Date:	Time:
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

EMSL Analytical, Inc.
2001 East 52nd Street



Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH031950	Ceiling skim coat, Gray, 2 nd Floor		3/19/19
51	Ceiling Plaster, Gray, 2 nd Floor		3/19/19
52	12x12 Floor Tile, Gray, 2 nd Floor		3/19/19
53	Floor Tile Adhesive, 2 nd Floor		3/19/19
54	Floor Tile Adhesive, 2 nd Floor		3/19/19
55	Concrete joint caulk, gray, 2 nd Floor		3/19/19
56	Wall plaster, gray, 2 nd Floor		3/19/19
57	Wall Skim coat, gray, 2 nd Floor		3/19/19
58	Gypsum adhesive, White, 2 nd Floor		3/19/19
59	Marble Baseboard adhesive, yellow, 2 nd Floor		3/19/19
60	Cove base, brown, 2 nd Floor		3/19/19
61	Cove base mastic, tan, 2 nd Floor		3/19/19
62	Cove base mastic, yellow, 2 nd Floor		3/19/19
63	Flooring, Gray, 2 nd Floor		3/19/19
64	Flooring adhesive, Brown, 2 nd Floor		3/19/19
65	Caulk, White, 2 nd Floor		3/19/19
66	Caulk, Black, 2 nd Floor		3/19/19

Client Sample # (s):	50-66	Total # of Samples:	335
Relinquished (Client):		Date:	
Received (Lab):		Date:	
		Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! 😊

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH031967	Expansion Joint Foam, Gray, 2 nd Floor		3/19/19
68	Cove base, black, 2 nd Floor		3/19/19
69	Cove base mastic, yellow, 2 nd Floor		3/19/19
70	Cove base mastic, gold, 2 nd Floor		3/19/19
71	Drywall, White, 2 nd Floor		3/19/19
72	Drywall Joint compound, white, 2 nd Floor		3/19/19
73	Drywall Tape, cream, 2 nd Floor		3/19/19
74	Ceiling tile, Gray, 2 nd Floor		3/19/19
75	Carpet mastic, black/yellow, 2 nd Floor		3/19/19
76	Cove base, gray, 2 nd Floor		3/19/19
77	Cove base mastic, brown, 2 nd Floor		3/19/19
78	Cove base, Brown, 2 nd Floor		3/19/19
79	Cove base mastic, Gold, 2 nd Floor		3/19/19
80	12x12 Floor Tile, Cream w/ tan, 2 nd Floor		3/19/19
81	Floor Tile mastic, black, 2 nd Floor		3/19/19
82	Ceiling Plaster, gray, 2 nd Floor		3/19/19
83	Ceiling Skim Coat, Gray, 2 nd Floor		3/19/19

Client Sample # (s):	67-83	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd Street



Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH031984	Wall Plaster, gray, 2 nd Floor		3/19/19
85	Wall skim coat, gray, 2 nd Floor		3/19/19
86	Countertop, Black, 2 nd Floor		3/19/19
87	Countertop adhesive, yellow, 2 nd Floor		3/19/19
88	Cove base, gray, 2 nd Floor		3/19/19
89	Cove base mastic, yellow, 2 nd Floor		3/19/19
90	Carpet adhesive, yellow, 2 nd Floor		3/19/19
91	Sink undercoat, black, 2 nd Floor		3/19/19
92	Drywall, White, 2 nd Floor		3/19/19
93	Drywall Joint compound, white, 2 nd Floor		3/19/19
94	Drywall Tape, cream, 2 nd Floor		3/19/19
95	Cove base, black, 2 nd Floor		3/19/19
96	Cove base mastic, gold, 2 nd Floor		3/19/19
97	Ceiling Tile, white, 2 nd Floor		3/19/19
98	Carpet adhesive, yellow, 2 nd Floor		3/19/19
99	12x12 Floor Tile, Cream, 2 nd Floor		3/19/19
100	Floor tile mastic, Brown/Yellow, 2 nd Floor		3/19/19

Client Sample # (s):	84-100	Total # of Samples:	335
Relinquished (Client):		Date:	
Received (Lab):		Date:	
Time:		Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS DIVISION

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: <u>jhuxford@impact7g.com</u>		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319101	Ceiling tile, white, 2 nd Floor		3/19/19
102 ABC	Ceiling Texture, White, 1 st Floor		3/19/19
103	Fire Caulk, Red, 1 st Floor		3/19/19
104	Drywall, white, 1 st Floor		3/19/19
105	Drywall Joint compound, white, 1 st Floor		3/19/19
106	Drywall Tape, white, 1 st Floor		3/19/19
107	Carpet adhesive, yellow, 1 st Floor		3/19/19
108	Sink undercoat, white, 1 st Floor		3/19/19
109	Countertop, Brown, 1 st Floor		3/19/19
110	Countertop adhesive, yellow, 1 st Floor		3/19/19
111	Countertop, Brown, 1 st Floor		3/19/19
112	Countertop adhesive, yellow, 1 st Floor		3/19/19
113	12x12 Floor tile, Brown, 1 st Floor		3/19/19
114	Floor tile mastic, black, 1 st Floor		3/19/19
115	Carpet adhesive, yellow, 1 st Floor		3/19/19
116	Carpet pad (on wall), black, 1 st Floor		3/19/19
117	Wall Mastic, Brown, 1 st Floor		3/19/19

Client Sample # (s):	101-117	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRADING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319118	Floor Tile, Maroon, 1 st Floor		3/19/19
119	Floor Tile Mastic, Black, 1 st Floor		3/19/19
120	Floor Tile, Green, 1 st Floor		3/19/19
121	Floor Tile, Black, 1 st Floor		3/19/19
122	Flooring, gray, 1 st Floor		3/19/19
123	Wall Plaster, Gray, 1 st Floor		3/19/19
124	Duct Insulation, yellow, 1 st Floor		3/19/19
125	Duct wrap, Silver, 1 st Floor		3/19/19
126	Wall mastic, Black, 1 st Floor		3/19/19
127	Ceiling tile, white, 1 st Floor		3/19/19
128	Wall Skim coat, white, 1 st Floor		3/19/19
129	Caulk, yellow, 1 st Floor		3/19/19
130	Felt paper, Black, 1 st Floor		3/19/19
131	Plaster, white, 1 st Floor		3/19/19
132	Felt paper, Black, 1 st Floor		3/19/19
133	Ceiling Plaster, Gray, 1 st Floor		3/19/19
134	Ceiling Skim Coat, gray, 1 st Floor		3/19/19
Client Sample # (s):	118-134	Total # of Samples:	335
Relinquished (Client):		Date:	
Received (Lab):		Date:	
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: <u>jhuxford@impact7g.com</u>		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319135 ABC	Wall Texture, White, 1 st Floor		3/19/19
136	Duct seam tape, gray, 1 st Floor		3/19/19
137	Ceramic tile mastic, yellow, 1 st Floor		3/19/19
138	Wall adhesive, yellow, 1 st Floor		3/19/19
139	Floor leveler, Tan, 1 st Floor		3/19/19
140	Carpet adhesive, Yellow, 1 st Floor		3/19/19
141	12x12 Floor Tile, tan, 1 st Floor		3/19/19
142	Floor tile mastic, black, 1 st Floor		3/19/19
143	Wall Skim coat, gray, 1 st Floor		3/19/19
144	Wall plaster, gray, 1 st Floor		3/19/19
145	1x1 ceiling tile, brown, 1 st Floor		3/19/19
146 ABC	Ceiling texture (on 1x1s), White, 1 st Floor		3/19/19
147	1x1 ceiling tile mastic, brown, 1 st Floor		3/19/19
148	Window glazing, black, 1 st Floor		3/19/19
149	Window caulk, brown, 1 st Floor		3/19/19
150	Cove base, Brown, 1 st Floor		3/19/19
151	Cove base mastic, yellow, 1 st Floor		3/19/19

Client Sample # (s):	135-151	Total # of Samples:	335
Relinquished (Client):		Date:	
Received (Lab):		Date:	
Time:		Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! 😊

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRADING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: <u>jhuxford@impact7g.com</u>		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319152	Caulk, white, 1 st Floor		3/19/19
153	Ceiling Tile, White, 1 st Floor		3/19/19
154	Gypsum block, white, 1 st Floor		3/19/19
155	Wall Skim coat, gray, 1 st Floor		3/19/19
156	Wall Plaster, gray, 1 st Floor		3/19/19
157	Caulk, White, 1 st Floor		3/19/19
158	Marble adhesive, white, 1 st Floor		3/19/19
159	Cove base, gray, 1 st Floor		3/19/19
160	Cove base mastic, yellow, 1 st Floor		3/19/19
161	Linoleum Flooring, Brown, 1 st Floor		3/19/19
162	Flooring adhesive, yellow, 1 st Floor		3/19/19
163	Flooring adhesive, brown, 1 st Floor		3/19/19
164	Carpet adhesive, yellow, 1 st Floor		3/19/19
165	Drywall, white, 1 st Floor		3/19/19
166	Drywall joint compound, white, 1 st Floor		3/19/19
167	Drywall tape, cream, 1 st Floor		3/19/19
168	Ceiling plaster, gray, 1 st Floor		3/20/19
Client Sample # (s):	125-168	Total # of Samples:	335
Relinquished (Client):		Date:	Time:
Received (Lab):		Date:	Time:

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! 😊

EMSL Analytical, Inc.
2001 East 52nd Street



EMBL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319169	Ceiling skim coat, gray, 1 st Floor		3/20/19
170	Ceiling tile, gray, 1 st Floor		3/20/19
171	Gypsum block, white, 1 st Floor		3/20/19
172	Plaster, gray, 1 st Floor		3/20/19
173	Gypsum block grout, gray, 1 st Floor		3/20/19
174	Wall paper, yellow/white, 1 st Floor		3/20/19
175	Wall panel mastic, black, 1 st Floor		3/20/19
176	Floor leveler, white, 1 st Floor		3/20/19
177	Drywall, white, 1 st Floor		3/20/19
178	Drywall joint compound, white, 1 st Floor		3/20/19
179	Drywall tape, cream, 1 st Floor		3/20/19
180	Caulk, tan, 1 st Floor		3/20/19
181	Wall Mastic (behind baseboard), black, 1 st Floor		3/20/19
182	Cove base, brown, 1 st Floor		3/20/19
183	Cove base mastic, yellow, 1 st Floor		3/20/19
184	Cove base mastic, clear, 1 st Floor		3/20/19
185	Pipe insulation, yellow, 1 st Floor		3/20/19

Client Sample # (s):	169-185	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			
Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319186	Pipe wrap, white, 1 st Floor		3/20/19
187	Carpet adhesive, gray, 1 st Floor		3/20/19
188	Floor leveler, gray, 1 st Floor		3/20/19
189	Wall insulation, Yellow, 1 st Floor		3/20/19
190	Insulation paper, brown/black, 1 st Floor		3/20/19
191	Ceiling tile, gray, 1 st Floor		3/20/19
192	Duct caulk, gray, 1 st Floor		3/20/19
193	Duct insulation, yellow, 1 st Floor		3/20/19
194	Duct wrap, silver, 1 st Floor		3/20/19
195	Ceiling tile, white, 1 st Floor		3/20/19
196	Wall insulation, brown, 1 st Floor		3/20/19
197	Insulation paper, black, 1 st Floor		3/20/19
198	Ceiling plaster, gray, 1 st Floor		3/20/19
199	Ceiling skim coat, gray, 1 st Floor		3/20/19
200	Duct tape, silver, 1 st Floor		3/20/19
201	Window caulk, brown, 1 st Floor		3/20/19
202	Caulk, White, 1 st Floor		3/20/19
Client Sample # (s):	186-202	Total # of Samples:	335
Relinquished (Client):		Date:	Time:
Received (Lab):		Date:	Time:
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: <u>jhuxford@impact7g.com</u>		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319203	Ceiling tile, white, 1 st Floor		3/20/19
204	Countertop, tan, 1 st Floor		3/20/19
205	Countertop adhesive, pink, 1 st Floor		3/20/19
206	Caulk, tan, 1 st Floor		3/20/19
207	Backsplash adhesive, yellow, 1 st Floor		3/20/19
208	Floor leveler, gray, 1 st Floor		3/20/19
209	Cove base, brown, 1 st Floor		3/20/19
210	Cove base mastic, yellow, 1 st Floor		3/20/19
211	Cove base mastic, clear, 1 st Floor		3/20/19
212	Drywall, white, 1 st Floor		3/20/19
213	Drywall joint compound, white, 1 st Floor		3/20/19
214	Drywall tape, cream, 1 st Floor		3/20/19
215	Ceiling plaster, white, 1 st Floor		3/20/19
216	Felt paper, black, 1 st Floor		3/20/19
217	12x12 Floor tile, gray, 1 st Floor		3/20/19
218	Floor tile adhesive, pink, 1 st Floor		3/20/19
219	Caulk, white, 1 st Floor		3/20/19

Client Sample # (s):	203-219	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! 😊

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRADING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: <u>jhuxford@impact7g.com</u>		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319220	Wall plaster, gray, 1 st Floor		3/20/19
221	Wall skim coat, gray, 1 st Floor		3/20/19
222	1x1 Ceiling Tile, Brown, 1 st Floor		3/20/19
223	1x1 ceiling tile mastic, Brown, 1 st Floor		3/20/19
224	Ceramic tile grout, white, 1 st Floor		3/20/19
225	Ceramic tile adhesive, yellow, 1 st Floor		3/20/19
226	Marble grout, white, 1 st Floor		3/20/19
227	Tar, black, 1 st Floor		3/20/19
228 ABC	Pipe Wrap, white, 1 st Floor		3/20/19
229 ABC	Pipe Insulation, white, 1 st Floor		3/20/19
230	Pipe wrap, white, 1 st Floor		3/20/19
231	Pipe insulation, yellow, 1 st Floor		3/20/19
232 ABC	Mudded Joints, White, 1 st Floor		3/20/19
233	Wall Plaster, Gray, 1 st Floor		3/20/19
234	Wall Skim coat, gray, 1 st Floor		3/20/19
235	Pipe insulation, yellow, 1 st Floor		3/20/19
236	Pipe wrap, white, 1 st Floor		3/20/19

Client Sample # (s):	220-236	Total # of Samples:	335
Relinquished (Client):		Date:	
Received (Lab):		Date:	
		Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! 😊

EMSL Analytical, Inc.
2001 East 52nd Street



Asbestos Chain of Custody
EMSL Order Number *(Lab Use Only)*:

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: <u>jhuxford@impact7g.com</u>		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319237	Wall plaster, gray, basement		3/20/19
238	Wall skim coat, gray, basement		3/20/19
239	Ceiling plaster, gray, basement		3/20/19
240	Ceiling skim coat, basement		3/20/19
241	Pipe insulation, yellow, basement		3/20/19
242	Pipe wrap, white, basement		3/20/19
243	Pipe end cap caulk, white, basement		3/20/19
244	Pipe insulation, yellow, basement		3/20/19
245	Pipe wrap, white, basement		3/20/19
246	Pipe insulation, yellow, basement		3/20/19
247	Pipe wrap, white, basement		3/20/19
248	Seam caulk, white, basement		3/20/19
249	Pipe insulation, yellow, basement		3/20/19
250	Pipe wrap, white, basement		3/20/19
251	Cardboard duct, brown/black, basement		3/20/19
252	Ceiling plaster, gray, basement		3/20/19
253	Ceiling skim coat, gray, basement		3/20/19

Client Sample # (s):	237-253	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319254	Plaster, white, basement		3/20/19
255	Felt paper, black, basement		3/20/19
256	Tar paper, black, basement		3/20/19
257	Tar soaked plaster, gray/black, basement		3/20/19
258	Duct Insulation, yellow, basement		3/20/19
259	Duct wrap, silver, basement		3/20/19
260	Duct tape, silver, basement		3/20/19
261	Pipe wrap, black, basement		3/20/19
262	Tar paper, black, basement		3/20/19
263	Tar, black, basement		3/20/19
264	Fire caulk, red, basement		3/20/19
265	Caulk, silver, basement		3/20/19
266	Wall Plaster, Gray, basement		3/20/19
267	Wall Skim coat, gray, basement		3/20/19
268	Ceiling plaster, gray, basement		3/20/19
269	Ceiling skim coat, gray, basement		3/20/19
270	Plaster, white,		3/20/19

Client Sample # (s):	254-270	Total # of Samples:	335
Relinquished (Client):		Date:	
Received (Lab):		Date:	
		Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd StreetEMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING
Asbestos Chain of Custody
 EMSL Order Number (Lab Use Only):

5383

 Indianapolis, IN 46205
 PHONE: (317) 803-2997
 FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			
Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319271	Felt paper, black, basement		3/20/19
272	Tar paper, black, basement		3/20/19
273	Pipe Insulation, yellow, basement		3/20/19
274	Pipe Wrap, White, basement		3/20/19
275	Tar, black, basement		3/20/19
276	Grout/concrete, gray, basement		3/20/19
277	Caulk, white, basement		3/20/19
278	Corkboard, brown, basement		3/20/19
279	Marble wall adhesive, white, basement		3/20/19
280	Marble wall adhesive, white, basement		3/20/19
281	Marble sill adhesive, white, basement		3/20/19
282	Terrazzo floor, gray, basement		3/20/19
283	Wall Plaster, gray, basement		3/20/19
284	Ceiling tile, gray, basement		3/20/19
285	Duct Insulation, Yellow, basement		3/20/19
286	Duct wrap, silver, basement		3/20/19
287	Caulk, white, basement		3/20/19
Client Sample # (s):	217-287	Total # of Samples:	335
Relinquished (Client):		Date:	Time:
Received (Lab):		Date:	Time:
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319288	Plaster ceiling, gray, basement		3/20/19
289	Plaster, white, basement		3/20/19
290	Felt paper, black, basement		3/20/19
291	Tar paper, black, basement		3/20/19
292	Pipe Insulation, yellow, basement		3/20/19
293	Pipe wrap, white, basement		3/20/19
294	Wall plaster, gray, basement		3/20/19
295	Wall skim coat, gray, basement		3/20/19
296	Door caulk, tan, basement		3/20/19
297	Marble wall grout, white, basement		3/20/19
298	Stair tread, black, basement		3/20/19
299	Ceramic tile grout, black, basement		3/20/19
300	Terrazzo Floor, orange, 1 st floor		3/20/19
301	Ceiling tile, white, 2 nd Floor		3/20/19
302	Ceramic wall tile adhesive, gray, 2 nd floor		3/20/19
303	Ceramic tile grout, tan, 2 nd floor		3/20/19
304	Drywall, white, 2 nd Floor		3/20/19
Client Sample # (s):	288-304	Total # of Samples:	335
Relinquished (Client):		Date:	Time:
Received (Lab):		Date:	Time:

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! 😊

EMSL Analytical, Inc.
2001 East 52nd Street



EMBL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319305	12x12 Floor Tile, gray, 2 nd floor		3/20/19
306	Floor tile adhesive, pink, 2 nd floor		3/20/19
307	Floor leveler, gray, 2 nd floor		3/20/19
308	Door caulk, tan, 1 st floor		3/20/19
309	Cove base, brown, 1 st floor		3/20/19
310	Cove base mastic, yellow, 1 st floor		3/20/19
311	Cove base mastic, clear, 1 st floor		3/20/19
312	Caulk, tan, 1 st floor		3/20/19
313	Drywall, white, 1 st Floor		3/20/19
314	Drywall joint compound, white, 1 st Floor		3/20/19
315	Drywall tape, cream, 1 st Floor		3/20/19
316	Floor leveler, white, 1 st Floor		3/20/19
317	Floor Tile mastic, black, 1 st Floor		3/20/19
318	Ceiling tile, white, 2 nd floor		3/21/19
319	Window caulk, white, 2 nd Floor		3/21/19
320	Stair treat, black, 2 nd Floor		3/21/19
321	Window caulk, brown, 2 nd floor		3/21/19

Client Sample # (s):	305-321	Total # of Samples:	335
Relinquished (Client):	Date:	Time:	
Received (Lab):	Date:	Time:	

Comments/Special Instructions: PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRADING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

5383

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<i>Third Party Billing requires written authorization from third party.</i>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To:		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall			
US State Samples Taken: IA			

Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0319322	Ceramic tile adhesive, gray, 1 st floor		3/21/19
323	Ceramic tile grout, brown, 1 st floor		3/21/19
324	Wall panel adhesive, tan, 1 st floor		3/21/19
325	Caulk, gray, 1 st floor		3/21/19
326	Caulk, white, 1 st floor		3/21/19
327	Flooring, gray, 1 st floor		3/21/19
328	Flooring adhesive, brown, 1 st floor		3/21/19
329	Duct caulk, gray, 1 st floor		3/21/19
330	Duct insulation, yellow, 1 st floor		3/21/19
331	Duct wrap, silver, 1 st floor		3/21/19
332	Ceiling/beam plaster, gray, 1 st floor		3/21/19
333	Ceiling/beam skim coat, gray, 1 st floor		3/21/19
334	Grout, pink, 1 st floor		3/21/19
335	Caulk, brown, 1 st floor		3/21/19

Client Sample # (s):	322-335	Total # of Samples:	335
Relinquished (Client):	<i>Carolyn Med</i>	Date:	3-25-19
Received (Lab):	<i>Carolyn Med</i>	Date:	3-26-19
Time:		Time:	5:10pm
Time:		Time:	8:45PM
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

DATE SENT: 04/03/19



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS • TRAINING

Asbestos Chain of Custody

EMSL Order Number (Lab Use Only):

161906093

EMSL ANALYTICAL, INC.
6340 Castleplace Drive
Indianapolis, IN 46250
PHONE: (800) 220-3675

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		Third Party Billing requires written authorization from third party.	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To: Jacob Huxford		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide results:EMAIL	
Project Name: Fort Dodge City Hall – Verification Samples			
US State Samples Taken: IA			
Turnaround Time (TAT) Options			
<input type="checkbox"/> 3-Hour	<input type="checkbox"/> 6-Hour	<input checked="" type="checkbox"/> 24-Hour	<input type="checkbox"/> 48-Hour
<input type="checkbox"/> 72-Hour	<input type="checkbox"/> 96-Hour	<input type="checkbox"/> 1 Week	<input type="checkbox"/> 2 Week
*For TEM Air 3 hr through 6 hr, please call ahead to schedule. *There is a premium charge for 3 hr TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytic Price Guide.			
PLM – BULK (reporting limit) <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)		TEM – Air <input type="checkbox"/> 4-4.5hr TAT (AHERA only) <input type="checkbox"/> AHERA 40 CFR, Part 763	
<input checked="" type="checkbox"/> Check for Positive Stop – Clearly Identify Homogeneous Group		Filter Pore Size (Air Samples): <input type="checkbox"/> 0.8 µm <input type="checkbox"/> 0.45 µm	
Sampler's Name: <i>Jacob Huxford</i>		Sampler's Signature: <i>Jacob Huxford</i>	
Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0403336	Drywall, White, 2 nd Floor, e205C		04/03/19
337	Drywall Joint compound, white, 2 nd Floor, e205C		04/03/19
338	Drywall Tape, cream, 2 nd Floor, e205C		04/03/19
339	Drywall, White, 2 nd Floor, e205E		04/03/19
340	Drywall Joint compound, white, 2 nd Floor, e205E		04/03/19
341	Drywall Tape, cream, 2 nd Floor, e205E		04/03/19
342	Ceiling Tile, Gray, 2 nd Floor, e203A		04/03/19
343	Ceiling Tile, Gray, 2 nd Floor, e203B		04/03/19
344	Ceiling Tile, Gray, 2 nd Floor, e203E		04/03/19
345	Drywall, White, 2 nd Floor, e203A		04/03/19
346	Drywall Joint compound, white, 2 nd Floor, e203A		04/03/19
347	Drywall Tape, cream, 2 nd Floor, e203A		04/03/19
348	Drywall, White, 2 nd Floor, e203E		04/03/19
Client Sample # (s):	19JH0403336-19JH0403348	Total # of Samples:	18
Relinquished (Client):	<i>Jacob Huxford</i>	Date:	3/25/19 4-3-19
Received (Lab):	<i>[Signature]</i>	Date:	4/4/19
Comments/Special Instructions:	Please sample all layers, thank you!		

EMSL Analytical, Inc.
2001 East 52nd Street



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody
EMSL Order Number (Lab Use Only):

Indianapolis, IN 46205
PHONE: (317) 803-2997
FAX: (317) 803-3047

Company: IMPACT7G		EMSL – Bill to: Same	
Street: 9550 Hickman Road Suit 105		<small>Third Party Billing requires written authorization from third party.</small>	
City: Clive	State: IA	Zip Code: 50325	Country: USA
Report To: Jacob Huxford		Phone: 515-473-6256	Fax: 515-685-2236
Email Address: jhuxford@impact7g.com		Please Provide Results: E-mail	
Project Name: Fort Dodge City Hall – Verification samples			
US State Samples Taken: IA			
Sample #	Sample Description	Volume/Area (Air)	Date/Time Sampled
19JH0403349	Drywall Joint compound, white, 2 nd Floor, <i>ed03E</i>		04/03/19
350	Drywall Tape, cream, 2 nd Floor, <i>ed03E</i>		04/03/19
351	Drywall, white, 2 nd Floor, <i>ed03B</i>		04/03/19
352	Drywall Joint compound, white, 2 nd Floor, <i>ed03B</i>		04/03/19
353	Drywall Tape, cream, 2 nd Floor, <i>ed03B</i>		04/03/19
Client Sample # (s):	19JH0403349-19JH0403353	Total # of Samples:	18
Relinquished (Client):	<i>Jacob Huxford</i>	Date:	<i>4-3-19</i>
Received (Lab):		Time:	<i>4:16pm</i>
Comments/Special Instructions:	PLEASE SAMPLE ALL LAYERS, ADHESIVES, TEXTURES, ETC. Thanks! ☺		

APPENDIX C

Photographs

Photograph table includes photos of asbestos containing materials (ACM).

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Tile Cove Base – Gray</p> <p><u>Location:</u> Economic Development – Kitchen – e211J</p> <p><u>Sample:</u> 19JH031938</p> <p>Photo #1</p>	
<p><u>Description:</u> Floor Tile Mastic - Black</p> <p><u>Location:</u> Economic Development – Kitchen – e211J</p> <p><u>Sample:</u> 19JH031940</p> <p>Photo #2</p>	
<p><u>Description:</u> Wall Adhesive – Black</p> <p><u>Location:</u> Economic Development – Waiting Room – e211A</p> <p><u>Sample:</u> 19JH031945</p> <p>Photo #3</p>	


Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Inspections/Engineering – Lobby – e205A</p> <p><u>Sample:</u> 19JH031972</p> <p>Photo #4</p>	
<p><u>Description:</u> 12" x 12" Floor Tile – Cream w/ Tan Streaks</p> <p><u>Location:</u> Inspections/Engineering – e205B</p> <p><u>Sample:</u> 19JH031980</p> <p>Photo #5</p>	
<p><u>Description:</u> Sink Undercoat – White</p> <p><u>Location:</u> Human Resources – Storage – e203F</p> <p><u>Sample:</u> 19JH031991</p> <p>Photo #6</p>	

Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Human Resources – Storage – e203F</p> <p><u>Sample:</u> 19JH031992</p> <p>Photo #7</p>	
<p><u>Description:</u> Ceiling Tile - White</p> <p><u>Location:</u> Human Resources – Storage – e203F</p> <p><u>Sample:</u> 19JH031997</p> <p>Photo #8</p>	
<p><u>Description:</u> Sink Undercoat - White</p> <p><u>Location:</u> Storage – e147</p> <p><u>Sample:</u> 19JH0319108</p> <p>Photo #9</p>	

Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> 12" x 12" Floor Tile – Brown and Floor Tile Mastic – Black</p> <p><u>Location:</u> Breakroom – e143A and Conference Room (David) – e143B</p> <p><u>Sample:</u> 19JH0319113 and 19JH0319114</p> <p>Photo #10</p>	 <p>A photograph showing a section of a floor tile with a yellowish-brown fibrous texture. A small, irregular piece of black mastic is attached to the tile. Next to the tile is a clear plastic bag containing a sample, with a white label that has the numbers 112, 113, and 115 written on it.</p>
<p><u>Description:</u> Wall Mastic – Brown</p> <p><u>Location:</u> Breakroom – e143A</p> <p><u>Sample:</u> 19JH0319117</p> <p>Photo #11</p>	 <p>A photograph showing a person's hand holding a clear plastic bag with a white label that has the number 117 written on it. The bag is positioned next to a wall where brown mastic has been applied, showing some texture and color variations.</p>
<p><u>Description:</u> Floor Tile – Maroon, Green, and Black</p> <p><u>Location:</u> Breakroom – e143A</p> <p><u>Sample:</u> 19JH0319118, 19JH0319120, and 19JH0319121</p> <p>Photo #12</p>	 <p>A photograph showing three clear plastic bags containing floor tile samples. The bags are labeled with numbers 118, 119, 120, and 121. The samples inside the bags are maroon, green, and black in color. The bags are placed on a dark, textured surface.</p>

Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p style="text-align: center;">ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Wall Mastic – Black</p> <p><u>Location:</u> Breakroom – e143A</p> <p><u>Sample:</u> 19JH0319126</p> <p>Photo #13</p>	
<p><u>Description:</u> Wall Panel Mastic – Black</p> <p><u>Location:</u> City Administrator – Storage/Attorney (Ryan) – e135</p> <p><u>Sample:</u> 19JH0319175</p> <p>Photo #14</p>	
<p><u>Description:</u> Pipe Insulation – White</p> <p><u>Location:</u> Electrical Room – e158</p> <p><u>Sample:</u> 19JH0319229 ABC</p> <p>Photo #15</p>	


Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Pipe Insulation – White</p> <p><u>Location:</u> Electrical Room – e158</p> <p><u>Sample:</u> 19JH0319229 ABC</p> <p>Photo #16</p>	 A photograph showing a large pipe wrapped in white insulation, situated in a dark, confined space. A white metal tray is visible in the foreground, and a red string is hanging from the ceiling.
<p><u>Description:</u> Mudded Joint – White</p> <p><u>Location:</u> Electrical Room – e158</p> <p><u>Sample:</u> 19JH0319232 ABC</p> <p>Photo #17</p>	 A close-up photograph of a mudded joint on a pipe. A person's hand is holding a clear plastic bag with a white label that has 'J32' written on it, positioned to collect a sample from the joint.
<p><u>Description:</u> Pipe Wrap - Black</p> <p><u>Location:</u> Storage e13A</p> <p><u>Sample:</u> 19JH0319261</p> <p>Photo #18</p>	 A photograph of a pipe wrapped in black material. The pipe is connected to a metal valve or fitting, and the surrounding area appears to be a storage room with a concrete floor.

Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Engineering/Inspections – e205C</p> <p><u>Sample:</u> 19JH0403337</p> <p>Photo #19</p>	
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Engineering/Inspections – e205E</p> <p><u>Sample:</u> 19JH0403340</p> <p>Photo #20</p>	
<p><u>Description:</u> Ceiling Tile - White</p> <p><u>Location:</u> Human Resources – Storage – e203E</p> <p><u>Sample:</u> 19JH0403342</p> <p>Photo #21</p>	

Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Ceiling Tile - White</p> <p><u>Location:</u> Human Resources – Storage – e203A</p> <p><u>Sample:</u> 19JH0403343</p> <p>Photo #22</p>	
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Human Resources – Storage – e203A</p> <p><u>Sample:</u> 19JH0403346</p> <p>Photo #23</p>	
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Human Resources – Storage – e203E</p> <p><u>Sample:</u> 19JH0403349</p> <p>Photo #24</p>	

Photograph table includes photos of ACMs.

<p>3/19/19 – 4/3/2019 Photographer: Jacob Huxford</p>	<p>ACM Inspection Fort Dodge City Hall</p>
<p><u>Description:</u> Drywall Joint Compound – White</p> <p><u>Location:</u> Human Resources – Storage – e203B</p> <p><u>Sample:</u> 19JH0403352</p> <p>Photo #25</p>	

Photograph table includes general photos of lead-based paint (LBP).

<p>3/18/19 – 3/22/19 Photographer: Tyler Silverthorn</p>	<p>LBP Inspection Fort Dodge City Hall</p>
<p><u>Component:</u> Plaster Walls and Ceiling</p> <p><u>Location:</u> Inspections Large Office</p> <p>Photo #1</p>	
<p><u>Components:</u> Spiral Stair Components</p> <p><u>Location:</u> Spiral Staircase</p> <p>Photo #2</p>	
<p><u>Component:</u> Walls and Ceiling above Drop Ceiling</p> <p><u>Location:</u> Throughout</p> <p>Photo #3</p>	

Photograph table includes general photos of LBP.

<p>3/18/19 – 3/22/19 Photographer: Tyler Silverthorn</p>	<p>LBP Inspection Fort Dodge City Hall</p>
<p><u>Component:</u> Interior Window Components</p> <p><u>Location:</u> Inspections Office 2</p> <p>Photo #4</p>	 A photograph showing a close-up of a window frame and a blue door or panel. The window is partially open, showing a view of the outdoors. The wall is a light-colored, textured surface.
<p><u>Component:</u> Walls, Ceiling, and Pipe</p> <p><u>Location:</u> Econ. Devel. Storage</p> <p>Photo #5</p>	 A photograph of a storage area. The ceiling is dark with exposed pipes and a bright light fixture. The floor is cluttered with various items, including a blue bin, boxes, and other materials.
<p><u>Component:</u> Jail Cell Components</p> <p><u>Location:</u> Econ. Devel. Jail</p> <p>Photo #6</p>	 A photograph showing a jail cell. The cell is made of metal bars and has a door. The floor is dark, and there are some items on the floor. The walls are also made of metal.

Photograph table includes general photos of LBP.

<p>3/18/19 – 3/22/19 Photographer: Tyler Silverthorn</p>	<p>LBP Inspection Fort Dodge City Hall</p>
<p><u>Component:</u> Safe Components</p> <p><u>Location:</u> Econ. Devel. N Hall</p> <p>Photo #7</p>	
<p><u>Component:</u> Radiator and Walls</p> <p><u>Location:</u> 2nd Floor W Hall</p> <p>Photo #8</p>	
<p><u>Component:</u> Vault Door Components</p> <p><u>Location:</u> Throughout</p> <p>Photo #9</p>	

Photograph table includes general photos of LBP.

<p>3/18/19 – 3/22/19 Photographer: Tyler Silverthorn</p>	<p>LBP Inspection Fort Dodge City Hall</p>
<p><u>Component:</u> Door Stop</p> <p><u>Location:</u> SW Entry</p> <p>Photo #10</p>	
<p><u>Component:</u> Pipe</p> <p><u>Location:</u> Basement-E13B</p> <p>Photo #11</p>	
<p><u>Component:</u> Pipe</p> <p><u>Location:</u> Basement-E13A</p> <p>Photo #12</p>	

Photograph table includes general photos of LBP.

<p>3/18/19 – 3/22/19 Photographer: Tyler Silverthorn</p>	<p>LBP Inspection Fort Dodge City Hall</p>
<p><u>Component:</u> Drive In Wall Stripe</p> <p><u>Location:</u> Basement-E04</p> <p>Photo #13</p>	
<p><u>Component:</u> Stud Cross Member</p> <p><u>Location:</u> Basement-E11</p> <p>Photo #14</p>	
<p><u>Component:</u> Steps</p> <p><u>Location:</u> Basement-E02</p> <p>Photo #15</p>	

Photograph table includes general photos of LBP.

<p>3/18/19 – 3/22/19 Photographer: Tyler Silverthorn</p>	<p style="text-align: center;">LBP Inspection Fort Dodge City Hall</p>
<p><u>Component:</u> Radiator</p> <p><u>Location:</u> Basement-Throughout</p> <p>Photo #19</p>	 <p>A photograph showing a radiator mounted on a wall in a basement. The radiator is a long, horizontal unit with a metal frame. Above it, there are several pipes and a light fixture. To the right, a large white pipe runs vertically. In the background, there are several cardboard boxes and other items on the floor.</p>
<p><u>Component:</u> Walls</p> <p><u>Location:</u> E Stairway to Front Entry</p> <p>Photo #20</p>	 <p>A photograph of a staircase. The walls are painted a light blue color. The stairs have a blue handrail on the right side. The floor is a light-colored material, possibly concrete or tile. The staircase leads up to a dark doorway at the top.</p>
<p><u>Component:</u> Floor Stripe and Drain</p> <p><u>Location:</u> Basement-E01A</p> <p>Photo #21</p>	 <p>A photograph of a floor drain. The drain is a square metal grate set into a concrete floor. A yellow stripe is painted on the floor, extending from the drain towards the bottom left. There is some water or liquid on the floor around the drain.</p>

APPENDIX D


Sample Location Map(s)



DATE:	04/08/19
DRAWN BY:	TS
CHECKED BY:	JR
SCALE:	N/A
PROJECT NO.:	N/A
PROJECT NAME:	FORT DODGE CITY HALL
REVISED BY:	N/A
REVISED DATE:	1 OF 1

Asbestos Legend	
Label	Material Substance
CT	Ceiling Tile
DJC	Drywall Joint Compound
FT	Floor Tile
FTM	Floor Tile Mastic
MF	Mudded Fitting
PI	Pipe Insulation
PW	Pipe Wrap
SU	Sink Undercoating
TCB	Tile Cove Base
WA	Wall Adhesive
WM	Wall Mastic
WPM	Wall Panel Mastic

Legend
■ Positive ACM
 1 OF 1






DATE:	06/28/19
DRAWN BY:	TS
DESIGNED BY:	JR
SCALE:	N/A
STATUS:	N/A
PROJECT NO.:	N/A
HEET NO.:	1 OF 1

Asbestos Legend	
Label	Material Substance
CT	Ceiling Tile
DJC	Drywall Joint Compound
FT	Floor Tile
FTM	Floor Tile Mastic
MF	Mudded Fitting
PI	Pipe Insulation
PW	Pipe Wrap
SU	Sink Undercoating
TCB	Tile Cove Base
WA	Wall Adhesive
WM	Wall Mastic
WPM	Wall Panel Mastic

Legend

■ Positive ACM



A

B

C

D




DATE:	04/08/19
DRAWN BY:	TS
CHECKED BY:	JR
SCALE:	N/A
PROJECT NO.:	N/A
PROJECT NAME:	FORT DODGE CITY HALL
REVISED:	N/A
1 OF 1	

Asbestos Legend	
Label	Material Substance
CT	Ceiling Tile
DJC	Drywall Joint Compound
FT	Floor Tile
FTM	Floor Tile Mastic
MF	Mudded Fitting
PI	Pipe Insulation
PW	Pipe Wrap
SU	Sink Undercoating
TCB	Tile Cove Base
WA	Wall Adhesive
WM	Wall Mastic
WPM	Wall Panel Mastic

Legend

■ Positive ACM






DATE:	04/08/19
DRAWN BY:	TS
CHECKED BY:	JR
SCALE:	N/A
PROJECT NO.:	N/A
PROJECT NAME:	FORT DODGE CITY HALL
REVISION:	N/A
1 OF 1	

Legend

Positive LBP





DATE	06/28/19
DRAWN BY	TS
CHECKED BY	JR
SCALE	N/A
STATUS	N/A
PROJECT	FORT DODGE CITY HALL
PROJECT NO.	N/A
REVISION	N/A
SHEET NO.	1 OF 1

Legend

Positive LBP



APPENDIX E

LBP Results

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
CAL	3/18/2019 11:02	cps												0	0
CAL	3/18/2019 11:18	cps											6.1	0	6.1
CAL	3/18/2019 11:20	mg/cm ²										1.21	1.1	0.1	1.2
CAL	3/18/2019 11:20	mg/cm ²										1.27	3.2	1.9	5.1
1	3/18/2019 11:27	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	9.16	12.5	10.1	22.6
2	3/18/2019 11:27	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	9.21	16.4	11.5	27.9
3	3/18/2019 11:28	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	10	19	12.3	31.3
4	3/18/2019 11:28	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	10	6.1	4.7	10.8
5	3/18/2019 11:28	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Inspections Large Office	Positive	10	18.1	11.9	30
6	3/18/2019 11:29	mg/cm ²	Floor	Vinyl	All	Intact	Beige		2	Inspections Large Office	Negative	1.08	0	0.02	0.02
7	3/18/2019 11:29	mg/cm ²	Baseboard	Wood	All	Deteriorated	Beige	Impact	2	Inspections Large Office	Negative	5.12	0.4	0.5	0.9
8	3/18/2019 11:29	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Beige	Impact	2	Inspections Large Office	Negative	1.94	0.16	0.17	0.33
9	3/18/2019 11:29	mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	Beige	Cracking	2	Inspections Large Office	Negative	3.51	0.3	0.35	0.65
10	3/18/2019 11:29	mg/cm ²	Window Inside Stop	Wood	A	Deteriorated	Beige	Cracking	2	Inspections Large Office	Negative	3.23	0.27	0.3	0.57
11	3/18/2019 11:30	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey	Chewable	2	Inspections Large Office	Negative	1	0	0.02	0.02
12	3/18/2019 11:30	mg/cm ²	Window Casing/Header	Wood	B	Deteriorated	Beige	Cracking	2	Inspections Large Office	Negative	2.6	0.26	0.26	0.52
13	3/18/2019 11:30	mg/cm ²	Window Inside Stop	Wood	B	Deteriorated	Beige	Cracking	2	Inspections Large Office	Negative	2.56	0.26	0.26	0.52
14	3/18/2019 11:30	mg/cm ²	Window Sill	Ceramic	B	Intact	Grey	Chewable	2	Inspections Large Office	Negative	1	0	0.02	0.02
15	3/18/2019 11:31	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Beige	Cracking	2	Inspections Large Office	Negative	4.08	0.29	0.36	0.65
16	3/18/2019 11:31	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Beige	Cracking	2	Inspections Large Office	Negative	3.91	0.4	0.4	0.8
17	3/18/2019 11:31	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey	Chewable	2	Inspections Large Office	Negative	1.55	0.01	0.02	0.03
18	3/18/2019 11:31	mg/cm ²	Outer Door Casing/Header	Wood	D	Deteriorated	Beige	Impact	2	Inspections Large Office	Negative	4.49	0.4	0.4	0.8
19	3/18/2019 11:31	mg/cm ²	Inner Door Casing/Header	Wood	D	Deteriorated	Stain	Impact	2	Inspections Large Office	Negative	1.29	0.03	0.06	0.09
20	3/18/2019 11:31	mg/cm ²	Door Jamb	Wood	D	Deteriorated	Stain	Friction	2	Inspections Large Office	Negative	2.17	0.04	0.1	0.14
21	3/18/2019 11:31	mg/cm ²	Door Stop	Wood	D	Deteriorated	Stain	Impact	2	Inspections Large Office	Negative	1	0.01	0.03	0.04
22	3/18/2019 11:32	mg/cm ²	Radiator	Metal	All	Deteriorated	Beige	Chipping	2	Inspections Large Office	Negative	3.17	0.18	0.24	0.42
23	3/18/2019 11:33	mg/cm ²	Bulletin Wall Casing	Wood	D	Intact	Beige		2	Inspections Large Office	Negative	1.82	0.05	0.1	0.15
24	3/18/2019 11:33	mg/cm ²	Window Casing Molding	Wood	All	Intact	Beige		2	Inspections Large Office	Negative	2.38	0.12	0.07	0.19
25	3/18/2019 11:34	mg/cm ²	Window Frame	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Large Office	Positive	9.97	15	11	26
26	3/18/2019 11:40	mg/cm ²	Wall	Wood	A	Intact	Grey		2	Inspections Lobby	Negative	2.68	0.15	0.21	0.36
27	3/18/2019 11:40	mg/cm ²	Wall	Wood	B	Intact	Grey		2	Inspections Lobby	Negative	3.76	0.4	0.4	0.8
28	3/18/2019 11:40	mg/cm ²	Wall	Drywall	C	Intact	Blue		2	Inspections Lobby	Negative	1	0	0.02	0.02
29	3/18/2019 11:40	mg/cm ²	Wall	Drywall	D	Intact	Grey		2	Inspections Lobby	Negative	1	0	0.02	0.02
30	3/18/2019 11:44	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Lobby	Positive	10	12.4	10.2	22.6
31	3/18/2019 11:45	mg/cm ²	Roof Access Ladder	Metal	D	Deteriorated	Black	Friction	2	Inspections Lobby	Positive	1.3	2	0.9	2.9
32	3/18/2019 11:45	mg/cm ²	Wall Behind Ladder	Plaster	D	Deteriorated	Black	Cracking	2	Inspections Lobby	Positive	2.12	12.3	10.4	22.7
33	3/18/2019 11:45	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Lobby	Positive	8.86	12.4	9.8	22.2
34	3/18/2019 11:53	mg/cm ²	Floor	Carpet	All	Intact	Grey		2	Inspections Lobby	Negative	1.02	0	0.02	0.02
35	3/18/2019 11:53	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		2	Inspections Lobby	Negative	1	0	0.02	0.02
36	3/18/2019 11:53	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		2	Inspections Lobby	Negative	1	0	0.02	0.02
37	3/18/2019 11:53	mg/cm ²	Door Stop	Wood	D	Intact	Stain		2	Inspections Lobby	Negative	1	0	0.02	0.02
38	3/18/2019 11:53	mg/cm ²	Door	Wood	D	Intact	Stain		2	Inspections Lobby	Negative	1	0	0.02	0.02
39	3/18/2019 11:53	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		2	Inspections Lobby	Negative	4.05	0.04	0.13	0.17
40	3/18/2019 11:54	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Stain	Impact	2	Inspections Lobby	Negative	1	0.02	0.05	0.07
41	3/18/2019 11:54	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Stain	Friction	2	Inspections Lobby	Negative	1	0.01	0.03	0.04
42	3/18/2019 11:54	mg/cm ²	Door Stop	Wood	C	Deteriorated	Stain	Impact	2	Inspections Lobby	Negative	1	0.01	0.03	0.04
43	3/18/2019 11:54	mg/cm ²	Door	Wood	C	Deteriorated	Stain	Friction/Impact	2	Inspections Lobby	Negative	1.71	0.01	0.05	0.06
44	3/18/2019 11:57	mg/cm ²	Wall	Drywall	A	Intact	Blue		2	Inspections Office 2	Negative	1.64	0.12	0.13	0.25
45	3/18/2019 11:58	mg/cm ²	Wall	Wood	B	Intact	Grey		2	Inspections Office 2	Negative	7.57	0.24	0.34	0.58
46	3/18/2019 11:58	mg/cm ²	Wall	Wood	C	Intact	Blue		2	Inspections Office 2	Negative	1.46	0.04	0.08	0.12
47	3/18/2019 11:58	mg/cm ²	Wall	Drywall	D	Intact	Grey		2	Inspections Office 2	Negative	1.99	0.19	0.14	0.33
48	3/18/2019 11:58	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Inspections Office 2	Negative	1	0	0.02	0.02
49	3/18/2019 11:58	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Brown	Cracking	2	Inspections Office 2	Positive	3.11	1.4	0.3	1.7
50	3/18/2019 11:59	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Brown	Cracking	2	Inspections Office 2	Positive	2.69	0.8	0.2	1
51	3/18/2019 11:59	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey	Chewable	2	Inspections Office 2	Negative	1.13	0	0.02	0.02
52	3/18/2019 12:05	mg/cm ²	Wall	Drywall	A	Intact	Beige		2	Inspections Office 1 Hall	Negative	6.27	0.25	0.32	0.57
53	3/18/2019 12:05	mg/cm ²	Wall	Wood	B	Intact	Beige		2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
54	3/18/2019 12:05	mg/cm ²	Wall	Wood	C	Intact	Beige		2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
55	3/18/2019 12:05	mg/cm ²	Wall	Wood	D	Intact	Beige		2	Inspections Office 1 Hall	Negative	4.1	0.05	0.17	0.22

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
56	3/18/2019 12:05	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Stain	Impact	2	Inspections Office 1 Hall	Negative	1.01	0.02	0.05	0.07
57	3/18/2019 12:05	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Stain	Friction	2	Inspections Office 1 Hall	Negative	1.46	0.02	0.06	0.08
58	3/18/2019 12:06	mg/cm ²	Door Stop	Wood	C	Deteriorated	Stain	Impact	2	Inspections Office 1 Hall	Negative	1.62	0.03	0.08	0.11
59	3/18/2019 12:06	mg/cm ²	Door	Wood	C	Deteriorated	Stain	Friction/Impact	2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
60	3/18/2019 12:06	mg/cm ²	Door Frame	Wood	D	Intact	White		2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
61	3/18/2019 12:06	mg/cm ²	Door Casing/Header	Metal	D	Intact	Grey		2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
62	3/18/2019 12:06	mg/cm ²	Door Jamb	Metal	D	Intact	Grey	Friction	2	Inspections Office 1 Hall	Negative	5.49	0.02	0.1	0.12
63	3/18/2019 12:06	mg/cm ²	Door Stop	Metal	D	Intact	Grey	Impact	2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
64	3/18/2019 12:06	mg/cm ²	Door	Metal	D	Intact	Grey	Friction/Impact	2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
65	3/18/2019 12:08	mg/cm ²	Wall	Wood	A	Intact	Yellow		2	Inspections Office 1 Hall	Negative	1	0	0.02	0.02
66	3/18/2019 12:08	mg/cm ²	Wall	Drywall	A	Intact	Yellow		2	Inspections Office 1	Negative	4.34	0.23	0.28	0.51
67	3/18/2019 12:11	mg/cm ²	Wall	Drywall	B	Intact	Beige		2	Inspections Office 1	Negative	2.24	0.15	0.18	0.33
68	3/18/2019 12:12	mg/cm ²	Wall	Wood	C	Intact	Yellow		2	Inspections Office 1	Negative	3.55	0.18	0.27	0.45
69	3/18/2019 12:12	mg/cm ²	Wall	Wood	D	Intact	Beige		2	Inspections Office 1	Negative	2.3	0.05	0.11	0.16
70	3/18/2019 12:12	mg/cm ²	Floor	Carpet	All	Intact	Grey		2	Inspections Office 1	Negative	1	0	0.02	0.02
71	3/18/2019 12:12	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Yellow	Cracking	2	Inspections Office 1	Negative	3.82	0.7	0.2	0.9
72	3/18/2019 12:12	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Yellow	Cracking	2	Inspections Office 1	Positive	5.26	1.8	0.8	2.6
73	3/18/2019 12:13	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey	Chewable	2	Inspections Office 1	Negative	1	0	0.02	0.02
74	3/18/2019 12:14	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Inspections Office 1	Positive	7.81	12.1	15.8	27.9
75	3/18/2019 12:19	mg/cm ²	Wall	Brick	A	Intact	Red		2	Elevator Room	Negative	1	0	0.02	0.02
76	3/18/2019 12:19	mg/cm ²	Wall	Concrete	B	Intact	Beige		2	Elevator Room	Negative	1	0	0.02	0.02
77	3/18/2019 12:19	mg/cm ²	Wall	Concrete	C	Intact	Beige		2	Elevator Room	Negative	1	0	0.02	0.02
78	3/18/2019 12:20	mg/cm ²	Wall	Concrete	D	Intact	Beige		2	Elevator Room	Negative	1	0	0.02	0.02
79	3/18/2019 12:20	mg/cm ²	Floor	Vinyl	All	Intact	Grey		2	Elevator Room	Negative	1	0	0.02	0.02
80	3/18/2019 12:20	mg/cm ²	Window Sash	Metal	C	Intact	Black		2	Elevator Room	Negative	1	0	0.02	0.02
81	3/18/2019 12:21	mg/cm ²	Elevator Door Casing	Wood	B	Intact	Stain		2	Elevator Room	Negative	1.15	0.01	0.03	0.04
82	3/18/2019 12:21	mg/cm ²	Elevator Door Frame	Metal	B	Deteriorated	Brown	Friction	2	Elevator Room	Negative	1	0	0.02	0.02
83	3/18/2019 12:21	mg/cm ²	Elevator Door	Metal	A	Deteriorated	Brown	Friction/Impact	2	Elevator Room	Negative	1	0	0.02	0.02
84	3/18/2019 12:23	mg/cm ²	Doorway Upper Jamb	Metal	B	Deteriorated	Beige	Friction	2	Elevator Room	Negative	1	0	0.02	0.02
85	3/18/2019 12:27	mg/cm ²	Wall	Drywall	A	Intact	Brown		2	Elevator Lobby	Negative	1	0	0.02	0.02
86	3/18/2019 12:28	mg/cm ²	Wall	Drywall	B	Intact	Brown		2	Elevator Lobby	Negative	4.18	0.07	0.07	0.14
87	3/18/2019 12:28	mg/cm ²	Wall	Drywall	C	Intact	Brown		2	Elevator Lobby	Negative	1	0	0.02	0.02
88	3/18/2019 12:28	mg/cm ²	Wall	Drywall	D	Intact	Brown		2	Elevator Lobby	Negative	1	0	0.02	0.02
89	3/18/2019 12:28	mg/cm ²	Floor	Vinyl	All	Intact	Grey		2	Elevator Lobby	Negative	1	0	0.02	0.02
90	3/18/2019 12:29	mg/cm ²	Window Casing/Header	Wood	D	Intact	Black		2	Elevator Lobby	Positive	4.99	0.9	0.1	1
91	3/18/2019 12:29	mg/cm ²	Window Inside Stop	Wood	D	Intact	Black		2	Elevator Lobby	Negative	1	0	0.02	0.02
92	3/18/2019 12:29	mg/cm ²	Window Sash	Metal	D	Intact	Brown		2	Elevator Lobby	Negative	1	0	0.02	0.02
93	3/18/2019 12:29	mg/cm ²	Window Sill	Ceramic	D	Intact	Grey	Chewable	2	Elevator Lobby	Negative	1	0	0.02	0.02
94	3/18/2019 12:35	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		2	Elevator Lobby	Negative	1	0	0.02	0.02
95	3/18/2019 12:35	mg/cm ²	Door Jamb	Wood	A	Intact	Stain	Friction	2	Elevator Lobby	Negative	1	0	0.02	0.02
96	3/18/2019 12:35	mg/cm ²	Door Stop	Wood	A	Intact	Stain	Impact	2	Elevator Lobby	Negative	1	0	0.02	0.02
97	3/18/2019 12:35	mg/cm ²	Door	Wood	A	Intact	Stain	Friction/Impact	2	Elevator Lobby	Negative	1	0	0.02	0.02
98	3/18/2019 12:37	mg/cm ²	Door Casing/Header	Metal	C	Intact	Grey		2	Elevator Lobby	Negative	1	0	0.02	0.02
99	3/18/2019 12:37	mg/cm ²	Door Jamb	Metal	C	Intact	Grey		2	Elevator Lobby	Negative	1	0	0.02	0.02
100	3/18/2019 12:37	mg/cm ²	Door Stop	Metal	C	Intact	Grey		2	Elevator Lobby	Negative	1	0	0.02	0.02
101	3/18/2019 12:37	mg/cm ²	Door	Metal	C	Intact	Grey		2	Elevator Lobby	Negative	1	0	0.02	0.02
102	3/18/2019 12:38	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Elevator Lobby	Positive	10	11.1	9.1	20.2
103	3/18/2019 12:39	mg/cm ²	Wall Above Drop Ceiling	Plaster	B/C/D	Deteriorated	Green	Cracking	2	Elevator Lobby	Positive	10	14.2	10	24.2
104	3/18/2019 12:39	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	B/C/D	Deteriorated	Green	Cracking	2	Elevator Lobby	Negative	1.73	0.13	0.14	0.27
105	3/18/2019 12:45	mg/cm ²	Wall	Drywall	A	Intact	Beige		2	Spiral Staircase	Negative	1	0	0.02	0.02
106	3/18/2019 12:45	mg/cm ²	Wall	Drywall	B	Intact	Beige		2	Spiral Staircase	Negative	1	0	0.02	0.02
107	3/18/2019 12:45	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Spiral Staircase	Positive	5.69	15.2	11.2	26.4
108	3/18/2019 12:45	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	2	Spiral Staircase	Positive	5.75	15.2	11.3	26.5
109	3/18/2019 12:46	mg/cm ²	Baseboard	Wood	C/D	Deteriorated	Beige	Impact	2	Spiral Staircase	Positive	7.02	3.8	2.3	6.1
110	3/18/2019 12:46	mg/cm ²	Shoe Molding	Wood	C/D	Deteriorated	Beige	Impact	2	Spiral Staircase	Positive	5.24	5.7	3.4	9.1
111	3/18/2019 12:47	mg/cm ²	Door Threshold	Concrete	A	Deteriorated	White	Friction	2	Spiral Staircase	Positive	1.97	1.8	0.7	2.5
112	3/18/2019 12:47	mg/cm ²	Stair Landing	Metal	All	Intact	Red	Friction	2	Spiral Staircase	Negative	1.37	0.15	0.14	0.29
113	3/18/2019 12:47	mg/cm ²	Stair Railing	Metal	All	Intact	Red	Friction	2	Spiral Staircase	Negative	1.17	0.28	0.17	0.45
114	3/18/2019 12:48	mg/cm ²	Stair Tread	Metal	All	Intact	Red	Friction	2	Spiral Staircase	Positive	1.72	2.3	1.2	3.5

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
115	3/18/2019 12:49	mg/cm ²	Stair Railing	Metal	All	Intact	Red	Friction	2	Spiral Staircase	Negative	1	0.01	0.04	0.05
116	3/18/2019 12:49	mg/cm ²	Pipe	Metal	C	Intact	Beige		2	Spiral Staircase	Negative	1.97	0.16	0.25	0.41
117	3/18/2019 12:51	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Spiral Staircase	Positive	7.32	14.4	10.4	24.8
118	3/18/2019 12:53	mg/cm ²	Wall	Brick	C/D	Intact	Beige		2	Spiral Staircase	Negative	1.87	0.15	0.14	0.29
119	3/18/2019 12:53	mg/cm ²	Wall	Concrete	A	Intact	Beige		2	Spiral Staircase	Positive	6.97	19	12.4	31.4
120	3/18/2019 12:54	mg/cm ²	Stair Railing Wall Mount	Metal	D	Intact	Red		2	Spiral Staircase	Negative	4.4	0.03	0.15	0.18
121	3/18/2019 12:54	mg/cm ²	Stair Center Post	Metal	-	Intact	Red		2	Spiral Staircase	Negative	1	0	0.02	0.02
122	3/18/2019 12:57	mg/cm ²	Wall	Drywall	A	Intact	Grey		2	Vending Area	Negative	1.11	0	0.02	0.02
123	3/18/2019 12:57	mg/cm ²	Wall	Drywall	B	Intact	Grey		2	Vending Area	Negative	4.96	0.11	0.1	0.21
124	3/18/2019 12:57	mg/cm ²	Wall	Drywall	C	Intact	Grey		2	Vending Area	Negative	1	0	0.02	0.02
125	3/18/2019 12:57	mg/cm ²	Wall	Drywall	D	Intact	Grey		2	Vending Area	Negative	6.78	0.15	0.22	0.37
126	3/18/2019 12:57	mg/cm ²	Floor	Vinyl	All	Intact	Grey		2	Vending Area	Negative	1	0	0.02	0.02
127	3/18/2019 13:01	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Green		2	Vending Area	Positive	10	11.5	9.6	21.1
128	3/18/2019 13:01	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Green		2	Vending Area	Negative	3.31	0.3	0.12	0.42
129	3/18/2019 13:01	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	Beige		2	Vending Area	Positive	10	20.6	12.6	33.2
130	3/18/2019 13:01	mg/cm ²	Ceiling Frame Above Drop Ceiling	Wood	All	Intact	Brown		2	Vending Area	Positive	4.23	0.6	0.4	1
131	3/18/2019 13:07	mg/cm ²	Wall	Plaster	A	Intact	Brown		2	Conference Room	Positive	5.42	0.5	0.5	1
132	3/18/2019 13:08	mg/cm ²	Wall	Plaster	B	Intact	Brown		2	Conference Room	Negative	9.26	0.14	0.77	0.91
133	3/18/2019 13:09	mg/cm ²	Wall	Plaster	C	Intact	Brown		2	Conference Room	Positive	6.92	0.4	0.6	1
134	3/18/2019 13:10	mg/cm ²	Wall	Wood	D	Intact	Brown		2	Conference Room	Negative	1	0	0.02	0.02
135	3/18/2019 13:10	mg/cm ²	Floor	Carpet	All	Intact	Blue		2	Conference Room	Negative	1	0	0.02	0.02
136	3/18/2019 13:11	mg/cm ²	Window Casing/Header	Wood	C	Intact	Brown		2	Conference Room	Negative	4.25	0.23	0.34	0.57
137	3/18/2019 13:11	mg/cm ²	Window Inside Stop	Wood	C	Intact	Black		2	Conference Room	Negative	1	0	0.02	0.02
138	3/18/2019 13:12	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey	Chewable	2	Conference Room	Negative	5.41	0.13	0.86	0.99
139	3/18/2019 13:12	mg/cm ²	Window Frame	Wood	C	Intact	White		2	Conference Room	Negative	6.11	0.07	0.87	0.94
140	3/18/2019 13:12	mg/cm ²	Door Casing/Header	Wood	C	Intact	White		2	Conference Room	Negative	3.24	0.3	0.67	0.97
141	3/18/2019 13:13	mg/cm ²	Chair Rail	Wood	All	Intact	White		2	Conference Room	Negative	3.17	0.26	0.3	0.56
142	3/18/2019 13:13	mg/cm ²	Chair Rail	Wood	All	Intact	Brown		2	Conference Room	Negative	4.4	0.5	0.4	0.9
143	3/18/2019 13:13	mg/cm ²	Wainscoting Frame	Wood	All	Intact	White		2	Conference Room	Negative	2.35	0.3	0.29	0.59
144	3/18/2019 13:14	mg/cm ²	Wainscoting Panel	Wood	All	Intact	Brown		2	Conference Room	Negative	2.66	0.18	0.22	0.4
145	3/18/2019 13:14	mg/cm ²	Baseboard	Wood	All	Intact	White		2	Conference Room	Negative	1.66	0.16	0.16	0.32
146	3/18/2019 13:15	mg/cm ²	Radiator Cover Top	Wood	C	Intact	Brown		2	Conference Room	Negative	2.08	0.05	0.1	0.15
147	3/18/2019 13:15	mg/cm ²	Radiator Cover Frame	Wood	C	Intact	White		2	Conference Room	Negative	1.19	0.05	0.07	0.12
148	3/18/2019 13:15	mg/cm ²	Radiator Cover Panel	Wood	C	Intact	Brown		2	Conference Room	Negative	7.55	0	0	0
149	3/18/2019 13:16	mg/cm ²	Door Casing/Header	Wood	A	Intact	White		2	Conference Room	Negative	1.91	0.2	0.19	0.39
150	3/18/2019 13:16	mg/cm ²	Door Casing/Header	Wood	A	Intact	Brown		2	Conference Room	Negative	2.18	0.16	0.19	0.35
151	3/18/2019 13:16	mg/cm ²	Door Casing/Header	Wood	A	Intact	Brown		2	Conference Room	Negative	1.92	0.17	0.18	0.35
152	3/18/2019 13:16	mg/cm ²	Door Lamb	Wood	A	Intact	Brown		2	Conference Room	Negative	1	0	0.02	0.02
153	3/18/2019 13:17	mg/cm ²	Door Stop	Wood	A	Intact	Stain		2	Conference Room	Negative	1.91	0.06	0.11	0.17
154	3/18/2019 13:17	mg/cm ²	Door	Wood	A	Intact	Stain		2	Conference Room	Negative	1	0	0.02	0.02
155	3/18/2019 13:24	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	White	Cracking	2	Conference Room	Negative	1.48	0.23	0.17	0.4
156	3/18/2019 13:25	mg/cm ²	Crown Molding Above Drop Ceiling	Plaster	All	Deteriorated	White	Cracking	2	Conference Room	Negative	2.18	0.24	0.21	0.45
157	3/18/2019 13:25	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	White	Cracking	2	Conference Room	Negative	1.55	0.18	0.05	0.23
158	3/18/2019 13:25	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Brown	Cracking	2	Conference Room	Negative	1.58	0.17	0.15	0.32
159	3/18/2019 13:25	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	White	Cracking	2	Conference Room	Negative	1.87	0.21	0.18	0.39
160	3/18/2019 13:25	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Brown	Cracking	2	Conference Room	Negative	2.02	0.5	0.3	0.8
161	3/18/2019 13:26	mg/cm ²	Wall Archway Above Drop Ceiling	Wood	All	Deteriorated	Brown	Cracking	2	Conference Room	Negative	1.46	0.11	0.12	0.23
162	3/18/2019 13:32	mg/cm ²	Door Casing/Header	Wood	D	Intact	Beige		2	Conference Room	Negative	1	0	0.02	0.02
163	3/18/2019 13:32	mg/cm ²	Door Lamb	Wood	D	Intact	Beige	Friction	2	Conference Room	Negative	1	0	0.02	0.02
164	3/18/2019 13:32	mg/cm ²	Door Stop	Wood	D	Intact	Beige		2	Conference Room	Negative	1	0	0.02	0.02
165	3/18/2019 13:33	mg/cm ²	Door	Wood	D	Intact	Beige		2	Conference Room	Negative	1	0	0.02	0.02
166	3/18/2019 13:36	mg/cm ²	Wall	Drywall	A	Intact	Grey		2	E/W Hallway	Negative	1	0	0.02	0.02
167	3/18/2019 13:36	mg/cm ²	Wall	Drywall	B	Intact	Grey		2	E/W Hallway	Negative	1	0	0.02	0.02
168	3/18/2019 13:37	mg/cm ²	Wall	Plaster	C	Intact	Grey		2	E/W Hallway	Negative	6.63	0.3	0.67	0.97
169	3/18/2019 13:37	mg/cm ²	Wall	Drywall	D	Intact	Grey		2	E/W Hallway	Negative	4.92	0.02	0.07	0.09
170	3/18/2019 13:38	mg/cm ²	Columns	Wood	All	Intact	Beige		2	E/W Hallway	Negative	2.75	0.4	0.1	0.5
171	3/18/2019 13:39	mg/cm ²	Column Panels	Wood	All	Intact	Brown		2	E/W Hallway	Negative	10	0.7	0.2	0.9
172	3/18/2019 13:39	mg/cm ²	Column Base Trim	Plaster	All	Intact	Beige		2	E/W Hallway	Positive	10	23.2	21.1	44.3
173	3/18/2019 13:40	mg/cm ²	Floor	Concrete	All	Intact	Grey		2	E/W Hallway	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
174	3/18/2019 13:40	mg/cm ²	Floor	Concrete	All	Intact	Brown		2	E/W Hallway	Negative	4.61	0	0	0
175	3/18/2019 13:41	mg/cm ²	Floor	Concrete	All	Intact	Grey		2	E/W Hallway	Negative	1	0	0.02	0.02
176	3/18/2019 13:41	mg/cm ²	Baseboard	Concrete	All	Intact	Grey		2	E/W Hallway	Negative	1	0	0.02	0.02
177	3/18/2019 13:42	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	E/W Hallway	Negative	6.52	0	0	0
178	3/18/2019 13:42	mg/cm ²	Crown Molding	Wood	All	Intact	White		2	E/W Hallway	Negative	3.82	0.05	0.77	0.82
179	3/18/2019 13:43	mg/cm ²	Crown Molding	Wood	All	Intact	Brown		2	E/W Hallway	Negative	2.28	0	0	0
180	3/18/2019 13:43	mg/cm ²	Crown Molding	Wood	All	Intact	Beige		2	E/W Hallway	Negative	3.55	0.28	0.68	0.96
181	3/18/2019 13:43	mg/cm ²	Wainscoting	Wood	A	Intact	Stain		2	E/W Hallway	Negative	1	0.01	0.03	0.04
182	3/18/2019 13:46	mg/cm ²	Wall	Ceramic	A	Intact	Grey		2	Mens Restroom	Negative	1	0.01	0.04	0.05
183	3/18/2019 13:46	mg/cm ²	Wall	Ceramic	B	Intact	Grey		2	Mens Restroom	Negative	2.58	0.02	0.12	0.14
184	3/18/2019 13:47	mg/cm ²	Wall	Ceramic	C	Intact	Grey		2	Mens Restroom	Negative	1	0.01	0.04	0.05
185	3/18/2019 13:47	mg/cm ²	Wall	Ceramic	D	Intact	Grey		2	Mens Restroom	Negative	2.41	0.02	0.12	0.14
186	3/18/2019 13:47	mg/cm ²	Floor	Vinyl	All	Intact	Grey		2	Mens Restroom	Negative	1	0	0.02	0.02
187	3/18/2019 13:48	mg/cm ²	Radiator	Metal	C	Intact	Grey		2	Mens Restroom	Negative	2.48	0.3	0.28	0.58
188	3/18/2019 13:48	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		2	Mens Restroom	Negative	1	0	0.02	0.02
189	3/18/2019 13:48	mg/cm ²	Door Lamb	Wood	D	Intact	Stain	Friction	2	Mens Restroom	Negative	1	0	0.02	0.02
190	3/18/2019 13:48	mg/cm ²	Door Stop	Wood	D	Intact	Stain	Impact	2	Mens Restroom	Negative	1	0	0.02	0.02
191	3/18/2019 13:48	mg/cm ²	Door	Wood	D	Intact	Stain	Friction/Impact	2	Mens Restroom	Negative	1	0	0.02	0.02
192	3/18/2019 13:49	mg/cm ²	Stall Door Frame	Metal	All	Intact	Grey		2	Mens Restroom	Negative	1	0	0.03	0.03
193	3/18/2019 13:49	mg/cm ²	Stall Door	Metal	All	Intact	Grey	Friction/Impact	2	Mens Restroom	Negative	1	0	0.03	0.03
194	3/18/2019 13:51	mg/cm ²	Wall Above Drop Ceiling	Plaster	C	Deteriorated	Beige		2	Mens Restroom	Negative	1.79	0.08	0.11	0.19
195	3/18/2019 13:52	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	Beige		2	Mens Restroom	Negative	2.76	0.14	0.19	0.33
196	3/18/2019 13:52	mg/cm ²	Ceiling Trim Above Drop Ceiling	Wood	All	Deteriorated	White	Cracking	2	Mens Restroom	Negative	1.94	0.08	0.13	0.21
197	3/18/2019 13:59	mg/cm ²	Wall	Plaster	A	Intact	White		2	Human Rights Lobby	Negative	1	0	0.02	0.02
198	3/18/2019 13:59	mg/cm ²	Wall	Wood	B	Intact	Stain		2	Human Rights Lobby	Negative	1.22	0.3	0.19	0.49
199	3/18/2019 14:02	mg/cm ²	Wall	Plaster	C	Intact	White		2	Human Rights Lobby	Negative	10	0.28	0.68	0.96
200	3/18/2019 14:02	mg/cm ²	Wall	Plaster	D	Intact	White		2	Human Rights Lobby	Negative	3.95	0.02	0.04	0.06
201	3/18/2019 14:02	mg/cm ²	Floor	Carpet	All	Intact	Grey		2	Human Rights Lobby	Negative	1	0	0.02	0.02
202	3/18/2019 14:03	mg/cm ²	Window Casing/Header	Wood	B	Deteriorated	Brown	Cracking	2	Human Rights Lobby	Negative	1	0.07	0.08	0.15
203	3/18/2019 14:04	mg/cm ²	Window Inside Stop	Wood	B	Deteriorated	Brown	Cracking	2	Human Rights Lobby	Negative	1.23	0.15	0.13	0.28
204	3/18/2019 14:04	mg/cm ²	Window Sill	Ceramic	B	Intact	Grey	Chewable	2	Human Rights Lobby	Negative	1	0	0.02	0.02
205	3/18/2019 14:05	mg/cm ²	Radiator Cover Top	Wood	B	Deteriorated	Stain	Friction	2	Human Rights Lobby	Negative	1.66	0.04	0.08	0.12
206	3/18/2019 14:05	mg/cm ²	Radiator Frame	Wood	B	Deteriorated	Stain	Impact	2	Human Rights Lobby	Negative	1.04	0.03	0.05	0.08
207	3/18/2019 14:05	mg/cm ²	Radiator	Metal	B	Intact	Brown		2	Human Rights Lobby	Negative	1.55	0.21	0.17	0.38
208	3/18/2019 14:06	mg/cm ²	Cabinet Face	Wood	C	Intact	Stain		2	Human Rights Lobby	Negative	1.5	0.03	0.07	0.1
209	3/18/2019 14:06	mg/cm ²	Cabinet Door	Wood	C	Intact	Stain		2	Human Rights Lobby	Negative	1.07	0.1	0.1	0.2
210	3/18/2019 14:06	mg/cm ²	Cabinet Interior	Wood	C	Intact	Stain		2	Human Rights Lobby	Negative	1.42	0.05	0.08	0.13
211	3/18/2019 14:06	mg/cm ²	Cabinet Shelf	Wood	C	Intact	Stain		2	Human Rights Lobby	Negative	1.75	0.05	0.1	0.15
212	3/18/2019 14:07	mg/cm ²	Countertop	Wood	C	Intact	Black		2	Human Rights Lobby	Negative	1	0	0.02	0.02
213	3/18/2019 14:07	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Stain	Impact	2	Human Rights Lobby	Negative	1	0.05	0.07	0.12
214	3/18/2019 14:07	mg/cm ²	Door Lamb	Wood	A	Deteriorated	Stain	Friction	2	Human Rights Lobby	Negative	1.66	0.04	0.08	0.12
215	3/18/2019 14:07	mg/cm ²	Door Stop	Wood	A	Deteriorated	Stain	Impact	2	Human Rights Lobby	Negative	1.15	0.06	0.08	0.14
216	3/18/2019 14:08	mg/cm ²	Door	Wood	A	Deteriorated	Stain	Friction/Impact	2	Human Rights Lobby	Negative	1	0	0.02	0.02
217	3/18/2019 14:08	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		2	Human Rights Lobby	Negative	1.51	0.01	0.05	0.06
218	3/18/2019 14:08	mg/cm ²	Door Lamb	Wood	D	Intact	Stain		2	Human Rights Lobby	Negative	1.24	0.01	0.03	0.04
219	3/18/2019 14:08	mg/cm ²	Door Stop	Wood	D	Intact	Stain		2	Human Rights Lobby	Negative	2.13	0.04	0.1	0.14
220	3/18/2019 14:09	mg/cm ²	Door	Wood	D	Intact	Stain		2	Human Rights Lobby	Negative	1	0	0.02	0.02
221	3/18/2019 14:10	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Human Rights Lobby	Negative	3.2	0.19	0.76	0.95
222	3/18/2019 14:12	mg/cm ²	Wall	Wood	A	Intact	Stain		2	Human Rights Office 1	Negative	1.11	0.27	0.17	0.44
223	3/18/2019 14:12	mg/cm ²	Wall	Plaster	B	Intact	White		2	Human Rights Office 1	Negative	1	0	0.02	0.02
224	3/18/2019 14:12	mg/cm ²	Wall	Plaster	C	Intact	White		2	Human Rights Office 1	Negative	1	0	0.02	0.02
225	3/18/2019 14:13	mg/cm ²	Wall	Plaster	D	Intact	White		2	Human Rights Office 1	Negative	10	0.27	0.66	0.93
226	3/18/2019 14:13	mg/cm ²	Floor	Carpet	All	Intact	Grey		2	Human Rights Office 1	Negative	1	0	0.02	0.02
227	3/18/2019 14:13	mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	Brown	Chipping	2	Human Rights Office 1	Negative	1.42	0.17	0.26	0.43
228	3/18/2019 14:14	mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	Brown	Cracking	2	Human Rights Office 1	Negative	1.39	0.11	0.12	0.23
229	3/18/2019 14:15	mg/cm ²	Window Inside Stop	Wood	A	Deteriorated	Brown	Cracking	2	Human Rights Office 1	Negative	1.04	0.11	0.1	0.21
230	3/18/2019 14:16	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige		2	Human Rights Office 1	Negative	1.72	0.07	0.04	0.11
231	3/18/2019 14:27	mg/cm ²	Wall	Wood	A	Intact	Stain		2	Human Rights Office 2	Negative	1.08	0.25	0.16	0.41
232	3/18/2019 14:28	mg/cm ²	Wall	Plaster	B	Intact	White		2	Human Rights Office 2	Negative	5.1	0.3	0.59	0.89

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
233	3/18/2019 14:28	mg/cm ²	Wall	Plaster	C	Intact	White		2	Human Rights Office 2	Negative	1	0	0.02	0.02
234	3/18/2019 14:28	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	2	Human Rights Office 2	Negative	10	0.12	0.87	0.99
235	3/18/2019 14:29	mg/cm ²	Floor	Carpet	All	Intact	Grey		2	Human Rights Office 2	Negative	5.42	0.04	0.07	0.11
236	3/18/2019 14:29	mg/cm ²	Radiator	Metal	A	Deteriorated	Grey	Chipping	2	Human Rights Office 2	Negative	2.02	0.13	0.15	0.28
237	3/18/2019 14:29	mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	Grey	Chipping	2	Human Rights Office 2	Negative	1.43	0.12	0.12	0.24
238	3/18/2019 14:29	mg/cm ²	Bookshelf Supports	Wood	C	Intact	Stain		2	Human Rights Office 2	Negative	1	0.03	0.05	0.08
239	3/18/2019 14:30	mg/cm ²	Bookshelf	Wood	C	Intact	Stain		2	Human Rights Office 2	Negative	1	0.03	0.05	0.08
240	3/18/2019 14:31	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Human Rights Office 2	Negative	1.78	0.11	0.04	0.15
241	3/18/2019 14:34	mg/cm ²	Wall Above Drop Ceiling	Plaster	A	Deteriorated	Green	Cracking	2	Human Rights Office 2	Positive	1.69	0.5	0.5	1
242	3/18/2019 14:34	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	A	Deteriorated	Brown	Cracking	2	Human Rights Office 2	Negative	1	0.02	0.05	0.07
243	3/18/2019 14:38	mg/cm ²	Wall	Wood	A	Intact	Stain		2	Human Rights Storage	Negative	1	0.21	0.14	0.35
244	3/18/2019 14:38	mg/cm ²	Wall	Wood	B	Intact	Stain		2	Human Rights Storage	Negative	1.36	0.4	0.2	0.6
245	3/18/2019 14:38	mg/cm ²	Wall	Plaster	C	Intact	White		2	Human Rights Storage	Negative	1	0	0.02	0.02
246	3/18/2019 14:39	mg/cm ²	Wall	Plaster	D	Intact	White		2	Human Rights Storage	Negative	1	0	0.02	0.02
247	3/18/2019 14:40	mg/cm ²	Window Casing/Header	Wood	A/B	Deteriorated	Brown	Cracking	2	Human Rights Storage	Negative	1	0.08	0.09	0.17
248	3/18/2019 14:40	mg/cm ²	Window Inside Stop	Wood	A/B	Deteriorated	Brown	Cracking	2	Human Rights Storage	Negative	1.01	0.11	0.1	0.21
249	3/18/2019 14:40	mg/cm ²	Window Sill	Ceramic	A/B	Intact	Grey		2	Human Rights Storage	Negative	1	0	0.02	0.02
250	3/18/2019 14:40	mg/cm ²	Floor	Carpet	All	Intact	Red		2	Human Rights Storage	Negative	1	0	0.02	0.02
251	3/18/2019 14:44	mg/cm ²	Wall	Plaster	A	Intact	Beige		2	Purchasing Hall	Negative	4.16	0	0	0
252	3/18/2019 14:45	mg/cm ²	Wall	Plaster	B	Intact	Beige		2	Purchasing Hall	Negative	4.62	0.26	0.68	0.94
253	3/18/2019 14:45	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Purchasing Hall	Negative	6.69	0.3	0.67	0.97
254	3/18/2019 14:45	mg/cm ²	Wall	Plaster	D	Intact	Beige		2	Purchasing Hall	Negative	6.87	0	0	0
255	3/18/2019 14:46	mg/cm ²	Floor	Carpet	All	Intact	Red		2	Purchasing Hall	Negative	2.71	0.02	0.07	0.09
256	3/18/2019 14:46	mg/cm ²	Baseboard	Wood	All	Deteriorated	White	Impact	2	Purchasing Hall	Negative	1.24	0.06	0.09	0.15
257	3/18/2019 14:46	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	White	Impact	2	Purchasing Hall	Negative	1.46	0.08	0.11	0.19
258	3/18/2019 14:47	mg/cm ²	Door Casing/Header	Wood	A/B	Deteriorated	White	Impact	2	Purchasing Hall	Negative	2.14	0.17	0.19	0.36
259	3/18/2019 14:47	mg/cm ²	Door Jamb	Wood	A/B	Deteriorated	White	Friction	2	Purchasing Hall	Negative	1.69	0.11	0.13	0.24
260	3/18/2019 14:47	mg/cm ²	Door Stop	Wood	A/B	Deteriorated	White	Impact	2	Purchasing Hall	Negative	3.23	0.24	0.3	0.54
261	3/18/2019 14:48	mg/cm ²	Door	Wood	A/B	Deteriorated	White	Friction/Impact	2	Purchasing Hall	Negative	1.79	0.11	0.14	0.25
262	3/18/2019 14:48	mg/cm ²	Door Transom Sash	Wood	A/B	Deteriorated	White	Friction/Impact	2	Purchasing Hall	Negative	1.19	0.06	0.08	0.14
263	3/18/2019 14:48	mg/cm ²	Vault Casing/Header	Metal	D	Intact	White		2	Purchasing Hall	Positive	3.48	14.8	11.2	26
264	3/18/2019 14:48	mg/cm ²	Vault Door	Metal	D	Intact	White	Friction/Impact	2	Purchasing Hall	Positive	3.39	18.4	12.6	31
265	3/18/2019 14:50	mg/cm ²	Vault Door Jamb	Metal	D	Deteriorated	Grey	Friction	2	Purchasing Hall	Positive	1.29	1.6	0.5	2.1
266	3/18/2019 14:50	mg/cm ²	Vault Door Threshold	Metal	D	Deteriorated	Green	Friction	2	Purchasing Hall	Negative	1.17	0.4	0.2	0.6
267	3/18/2019 14:52	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Purchasing Hall	Negative	1.41	0.02	0.06	0.08
268	3/18/2019 14:54	mg/cm ²	Pipe	Metal	A	Intact	White		2	Purchasing Hall	Negative	7.61	0.13	0.14	0.27
269	3/18/2019 14:55	mg/cm ²	Wall	Concrete	A	Intact	Yellow		2	Purchasing Vault	Negative	2.44	0.18	0.77	0.95
270	3/18/2019 14:56	mg/cm ²	Wall	Concrete	B	Intact	Yellow		2	Purchasing Vault	Negative	6.12	0.13	0.27	0.4
271	3/18/2019 14:56	mg/cm ²	Wall	Concrete	C	Intact	Yellow		2	Purchasing Vault	Negative	1.61	0.03	0.02	0.05
272	3/18/2019 14:56	mg/cm ²	Wall	Concrete	D	Intact	Yellow		2	Purchasing Vault	Negative	2.14	0.04	0.04	0.08
273	3/18/2019 14:56	mg/cm ²	Floor	Concrete	All	Intact	Grey		2	Purchasing Vault	Negative	1	0	0.02	0.02
274	3/18/2019 14:57	mg/cm ²	Ceiling	Concrete	All	Intact	Yellow		2	Purchasing Vault	Negative	2.35	0.05	0.03	0.08
275	3/18/2019 14:57	mg/cm ²	Door Casing/Header	Metal	B	Deteriorated	Red	Impact	2	Purchasing Vault	Negative	1	0.04	0.08	0.12
276	3/18/2019 15:01	mg/cm ²	Wall	Plaster	A	Intact	White		2	Purchasing Office	Negative	2.99	0.11	0.86	0.97
277	3/18/2019 15:01	mg/cm ²	Wall	Plaster	B	Intact	White		2	Purchasing Office	Negative	4.02	0.22	0.77	0.99
278	3/18/2019 15:02	mg/cm ²	Wall	Plaster	C	Intact	White		2	Purchasing Office	Negative	4.34	0.4	0.5	0.9
279	3/18/2019 15:03	mg/cm ²	Wall	Plaster	D	Intact	Blue		2	Purchasing Office	Positive	4.07	0.4	0.6	1
280	3/18/2019 15:03	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Purchasing Office	Negative	4.03	0.13	0.08	0.21
281	3/18/2019 15:04	mg/cm ²	Crown Molding	Wood	All	Intact	Beige		2	Purchasing Office	Negative	3.42	0.13	0.32	0.45
282	3/18/2019 15:04	mg/cm ²	Floor	Carpet	All	Intact	Red		2	Purchasing Office	Negative	1.95	0.01	0.03	0.04
283	3/18/2019 15:04	mg/cm ²	Baseboard	Wood	All	Deteriorated	Beige	Impact	2	Purchasing Office	Negative	2.17	0.27	0.34	0.61
284	3/18/2019 15:04	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Beige	Impact	2	Purchasing Office	Negative	1.41	0.24	0.25	0.49
285	3/18/2019 15:05	mg/cm ²	Window Casing/Header	Wood	A	Intact	Grey		2	Purchasing Office	Negative	4.04	0.3	0.39	0.69
286	3/18/2019 15:05	mg/cm ²	Window Inside Stop	Wood	A	Intact	Grey		2	Purchasing Office	Negative	1.99	0.08	0.13	0.21
287	3/18/2019 15:05	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		2	Purchasing Office	Negative	1	0	0.02	0.02
288	3/18/2019 15:05	mg/cm ²	Radiator	Metal	A	Deteriorated	Beige	Chipping	2	Purchasing Office	Negative	3.12	0.06	0.14	0.2
289	3/18/2019 15:06	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Beige	Impact	2	Purchasing Office	Negative	2.34	0.17	0.21	0.38
290	3/18/2019 15:08	mg/cm ²	Door Casing/Header	Wood	C	Intact	Stain		2	Purchasing Hall	Negative	1	0.01	0.05	0.06
291	3/18/2019 15:08	mg/cm ²	Door Jamb	Wood	C	Intact	Stain		2	Purchasing Hall	Negative	3.36	0.06	0.23	0.29

Fort Dodge City Hall - Total XRF Results

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
292	3/18/2019 15:08	mg/cm ²	Door Stop	Wood	C	Intact	Stain		2	Purchasing Hall	Negative	3.16	0.06	0.22	0.28
293	3/18/2019 15:08	mg/cm ²	Door	Wood	C	Intact	Stain		2	Purchasing Hall	Negative	1	0	0.02	0.02
294	3/18/2019 15:33	mg/cm ²	Wall	Concrete	A	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	6.03	2.3	1.3	3.6
295	3/18/2019 15:33	mg/cm ²	Wall	Concrete	B	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	4.92	1.5	0.4	1.9
296	3/18/2019 15:35	mg/cm ²	Wall	Concrete	C	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	4.51	2.8	1.4	4.2
297	3/18/2019 15:35	mg/cm ²	Wall	Concrete	D	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	5.03	1.9	0.9	2.8
298	3/18/2019 15:35	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Negative	2.15	0.12	0.06	0.18
CAL	3/18/2019 15:36	mg/cm ²										1.06	0.8	0.2	1
CAL	3/18/2019 15:36	mg/cm ²										1.59	3.8	2.6	6.4
CAL	3/18/2019 16:28	cps										14.3		0	14.3
CAL	3/18/2019 16:29	mg/cm ²										1.18	0.9	0.1	1
CAL	3/18/2019 16:29	mg/cm ²										1.33	2.9	1.4	4.3
CAL	3/18/2019 16:29	mg/cm ²										1.69	4.3	3	7.3
299	3/18/2019 16:32	mg/cm ²	Window Casing/Header	Wood	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Negative	1.16	0.06	0.12	0.18
300	3/18/2019 16:32	mg/cm ²	Window Jamb	Wood	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Negative	1.44	0.06	0.16	0.22
301	3/18/2019 16:33	mg/cm ²	Window Jamb	Wood	All	Deteriorated	White	Chipping	2	Econ. Devel. SW Storage	Positive	2.06	24.4	21.8	46.2
302	3/18/2019 16:33	mg/cm ²	Window Exterior Stop	Wood	All	Deteriorated	White	Chipping	2	Econ. Devel. SW Storage	Positive	2.2	29.2	24.9	54.1
303	3/18/2019 16:33	mg/cm ²	Window Sill	Wood	All	Deteriorated	Grey	Chewable	2	Econ. Devel. SW Storage	Negative	1.2	0.12	0.12	0.24
304	3/18/2019 16:33	mg/cm ²	Window Apron	Wood	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Negative	1	0.04	0.08	0.12
305	3/18/2019 16:33	mg/cm ²	Radiator	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Negative	1	0.03	0.05	0.08
306	3/18/2019 16:34	mg/cm ²	Pipe	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	4.71	1.4	0.4	1.8
307	3/18/2019 16:34	mg/cm ²	Window Sill	Concrete	All	Deteriorated	Grey	Chewable	2	Econ. Devel. SW Storage	Negative	1.53	0.09	0.07	0.16
308	3/18/2019 16:34	mg/cm ²	Window Trough	Wood	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Negative	1.25	0.4	0.2	0.6
309	3/18/2019 16:35	mg/cm ²	Door Casing/Header	Metal	A	Deteriorated	Grey	Impact	2	Econ. Devel. SW Storage	Positive	2.35	2.2	1.2	3.4
310	3/18/2019 16:35	mg/cm ²	Door Jamb	Metal	A	Deteriorated	Grey	Friction	2	Econ. Devel. SW Storage	Positive	2.13	2.3	1.1	3.4
311	3/18/2019 16:36	mg/cm ²	Door	Metal	A	Deteriorated	Grey	Friction/Impact	2	Econ. Devel. SW Storage	Positive	2.62	3.4	2.1	5.5
312	3/18/2019 16:36	mg/cm ²	Vent Frame	Metal	A	Intact	Grey		2	Econ. Devel. SW Storage	Positive	3.98	2.7	1.3	4
313	3/18/2019 16:38	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Chipping	2	Econ. Devel. SW Storage	Positive	5.21	3.8	2.7	6.5
314	3/18/2019 16:46	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	2	Econ. Devel. Office 10	Negative	8.06	0	0	0
315	3/18/2019 16:46	mg/cm ²	Wall	Drywall	B	Intact	White		2	Econ. Devel. Office 10	Negative	1	0	0.02	0.02
316	3/18/2019 16:46	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	2	Econ. Devel. Office 10	Negative	10	0	0	0
317	3/18/2019 16:46	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	2	Econ. Devel. Office 10	Negative	7.39	0.12	0.22	0.34
318	3/18/2019 16:47	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 10	Negative	1	0	0.02	0.02
319	3/18/2019 16:47	mg/cm ²	Baseboard	Plaster	All	Intact	White		2	Econ. Devel. Office 10	Negative	6.52	0.11	0.2	0.31
320	3/18/2019 16:47	mg/cm ²	Window Casing/Header	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Office 10	Negative	1.75	0.06	0.1	0.16
321	3/18/2019 16:47	mg/cm ²	Window Inside Stop	Wood	D	Intact	White		2	Econ. Devel. Office 10	Negative	1.03	0.02	0.03	0.05
322	3/18/2019 16:47	mg/cm ²	Window Sill	Ceramic	D	Intact	Brown	Chewable	2	Econ. Devel. Office 10	Negative	5.07	2.2	1.1	3.3
323	3/18/2019 16:49	mg/cm ²	Door Casing/Header	Metal	C	Deteriorated	White	Impact	2	Econ. Devel. Office 10	Positive	1.76	0.07	0.11	0.18
324	3/18/2019 16:49	mg/cm ²	Door Threshold	Metal	C	Deteriorated	Grey	Friction	2	Econ. Devel. Office 10	Negative	1	0.02	0.04	0.06
325	3/18/2019 16:51	mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Stain	Impact	2	Econ. Devel. Office 10	Negative	1	0	0.02	0.02
326	3/18/2019 16:51	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Stain	Friction	2	Econ. Devel. Office 10	Negative	1	0	0.02	0.02
327	3/18/2019 16:51	mg/cm ²	Door Stop	Wood	B	Deteriorated	Stain	Impact	2	Econ. Devel. Office 10	Negative	1	0.02	0.04	0.07
328	3/18/2019 16:51	mg/cm ²	Door	Wood	B	Deteriorated	Stain	Friction/Impact	2	Econ. Devel. Office 10	Negative	1	0.02	0.04	0.06
329	3/18/2019 16:53	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Black		2	Econ. Devel. Office 10	Negative	2.26	0.13	0.86	0.99
330	3/18/2019 16:53	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Black	Cracking	2	Econ. Devel. Office 10	Negative	1.73	0.08	0.05	0.13
331	3/18/2019 16:56	mg/cm ²	Wall	Plaster	A	Intact	White		2	Econ. Devel. S Hall	Negative	5.15	0	0	0
332	3/18/2019 16:56	mg/cm ²	Wall	Plaster	B	Intact	White		2	Econ. Devel. S Hall	Negative	1.64	0.03	0.05	0.08
333	3/18/2019 16:56	mg/cm ²	Wall	Plaster	C	Intact	White		2	Econ. Devel. S Hall	Negative	5.74	0.27	0.72	0.99
334	3/18/2019 16:56	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. S Hall	Negative	1	0	0.02	0.02
335	3/18/2019 16:57	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. S Hall	Negative	1.28	0.01	0.04	0.05
336	3/18/2019 16:58	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		2	Econ. Devel. S Hall	Negative	1	0	0.02	0.02
337	3/18/2019 16:58	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		2	Econ. Devel. S Hall	Negative	1	0	0.02	0.02
338	3/18/2019 16:58	mg/cm ²	Door Stop	Wood	A	Intact	Stain		2	Econ. Devel. S Hall	Negative	1	0	0.02	0.02
339	3/18/2019 16:58	mg/cm ²	Door	Wood	A	Intact	Stain		2	Econ. Devel. S Hall	Negative	1	0	0.02	0.02
340	3/18/2019 16:59	mg/cm ²	Door Frame	Metal	A	Intact	White		2	Econ. Devel. S Hall	Positive	7.9	3.6	1.9	5.5
341	3/18/2019 16:59	mg/cm ²	Door Threshold	Metal	A	Deteriorated	Grey	Friction	2	Econ. Devel. S Hall	Negative	1.96	0.5	0.3	0.8
342	3/18/2019 17:00	mg/cm ²	Door Casing/Header	Metal	C	Intact	White		2	Econ. Devel. S Hall	Positive	7.84	8.1	5.3	13.4
343	3/18/2019 17:00	mg/cm ²	Door Jamb	Metal	C	Deteriorated	Grey	Friction	2	Econ. Devel. S Hall	Positive	1.92	4.2	3	7.2
344	3/18/2019 17:00	mg/cm ²	Door	Metal	C	Deteriorated	White	Friction/Impact	2	Econ. Devel. S Hall	Positive	7.96	4.5	2.9	7.4

Fort Dodge City Hall - Total XRF Results

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
345	3/18/2019 17:00	mg/cm ²	Door Threshold	Metal	C	Deteriorated	Grey	Friction	2	Econ. Devel. S Hall	Positive	2.66	0.7	0.3	1
346	3/18/2019 17:02	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Black	Cracking	2	Econ. Devel. S Hall	Negative	3.11	0.18	0.21	0.39
347	3/18/2019 17:05	mg/cm ²	Wall	Plaster	A	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Positive	5.22	7	5.8	12.8
348	3/18/2019 17:05	mg/cm ²	Wall	Plaster	D	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Positive	4.31	8.4	6.4	14.8
349	3/18/2019 17:06	mg/cm ²	Cell Door	Metal	All	Deteriorated	Grey	Friction/Impact	2	Econ. Devel. Jail	Positive	2.78	4.9	3	7.9
350	3/18/2019 17:06	mg/cm ²	Cell Door Frame	Metal	All	Deteriorated	Grey	Friction	2	Econ. Devel. Jail	Positive	2.43	4.6	2.6	7.2
351	3/18/2019 17:07	mg/cm ²	Locking Cabinet	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.15	4.5	3.4	7.9
352	3/18/2019 17:07	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	2	Econ. Devel. Jail	Negative	1.34	0.06	0.06	0.12
353	3/18/2019 17:08	mg/cm ²	Cell Walls	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.72	4.5	2.7	7.2
354	3/18/2019 17:09	mg/cm ²	Bed Frame	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.26	5.6	4.3	9.9
355	3/18/2019 17:10	mg/cm ²	Radiator	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Negative	2.28	0.09	0.14	0.23
356	3/18/2019 17:14	mg/cm ²	Wall	Plaster	B	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Positive	4.52	10.8	5.5	16.3
357	3/18/2019 17:14	mg/cm ²	Radiator	Metal	B	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	3.35	4.5	3	7.5
358	3/18/2019 17:15	mg/cm ²	Window Casing/Header	Wood	All	Deteriorated	Grey	Cracking	2	Econ. Devel. Jail	Negative	1.34	0.09	0.15	0.24
359	3/18/2019 17:15	mg/cm ²	Window Jamb	Wood	All	Deteriorated	White	Chipping	2	Econ. Devel. Jail	Positive	2.28	36	30.1	66.1
360	3/18/2019 17:16	mg/cm ²	Window Sill	Concrete	All	Deteriorated	Grey	Chewable	2	Econ. Devel. Jail	Negative	1.12	0.05	0.04	0.09
361	3/18/2019 17:16	mg/cm ²	Outer Cell Wall	Metal	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Positive	2.69	7.8	6.7	14.5
362	3/18/2019 17:16	mg/cm ²	Pipe	Metal	B	Deteriorated	Grey	Chipping	2	Econ. Devel. Jail	Negative	1.99	0.25	0.43	0.68
363	3/18/2019 17:19	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Chipping	2	Econ. Devel. Office 9	Positive	4.84	12.2	10.5	22.7
364	3/18/2019 17:26	mg/cm ²	Wall	Drywall	A	Intact	White		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
365	3/18/2019 17:27	mg/cm ²	Wall	Plaster	B	Intact	White		2	Econ. Devel. Office 9	Negative	6.47	0.01	0.02	0.03
366	3/18/2019 17:27	mg/cm ²	Wall	Plaster	C	Intact	White		2	Econ. Devel. Office 9	Negative	8.8	0.7	0.2	0.9
367	3/18/2019 17:27	mg/cm ²	Wall	Drywall	D	Intact	Brown		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
368	3/18/2019 17:28	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
369	3/18/2019 17:29	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
370	3/18/2019 17:30	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
371	3/18/2019 17:30	mg/cm ²	Door Stop	Wood	A	Intact	Stain		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
372	3/18/2019 17:30	mg/cm ²	Door	Wood	A	Intact	Stain		2	Econ. Devel. Office 9	Negative	1	0	0.02	0.02
373	3/18/2019 17:39	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 9	Negative	4.18	0.4	0.4	0.8
374	3/18/2019 17:46	mg/cm ²	Wall	Drywall	B	Intact	White		2	Econ. Devel. W Hall	Negative	1	0	0.02	0.02
375	3/18/2019 17:46	mg/cm ²	Wall	Drywall	C	Intact	White		2	Econ. Devel. W Hall	Negative	1	0	0.02	0.02
376	3/18/2019 17:46	mg/cm ²	Wall	Drywall	D	Intact	White		2	Econ. Devel. W Hall	Negative	1	0	0.02	0.02
377	3/18/2019 17:47	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. W Hall	Negative	1	0	0.02	0.02
378	3/18/2019 17:47	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. W Hall	Negative	1	0	0.02	0.02
379	3/18/2019 17:53	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. W Hall	Positive	5.14	1.3	0.3	1.6
CAL	3/18/2019 18:00	mg/cm ²										1.16	0.9	0.1	1
CAL	3/18/2019 18:01	mg/cm ²										1.22	2.5	1.2	3.7
CAL	3/18/2019 18:02	cps										14.55	0	14.55	0
CAL	3/19/2019 10:07	cps										13.57	0	13.57	0
CAL	3/19/2019 10:20	mg/cm ²										1.31	1.1	0.1	1.2
CAL	3/19/2019 10:20	mg/cm ²										1.36	3.2	1.5	4.7
380	3/19/2019 10:31	mg/cm ²	Wall	Drywall	A	Intact	White		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
381	3/19/2019 10:32	mg/cm ²	Wall	Drywall	B	Intact	White		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
382	3/19/2019 10:32	mg/cm ²	Wall	Drywall	C	Intact	White		2	Econ. Devel. Office 7	Negative	1	0	0.03	0.03
383	3/19/2019 10:32	mg/cm ²	Wall	Drywall	D	Intact	White		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
384	3/19/2019 10:32	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
385	3/19/2019 10:32	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
386	3/19/2019 10:32	mg/cm ²	Radiator Cover Top	Wood	D	Intact	Stain		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
387	3/19/2019 10:33	mg/cm ²	Window Casing/Header	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Office 7	Negative	7.51	0.29	0.56	0.85
388	3/19/2019 10:33	mg/cm ²	Window Inside Stop	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
389	3/19/2019 10:33	mg/cm ²	Window Sill	Wood	D	Intact	Stain		2	Econ. Devel. Office 7	Negative	1	0	0.02	0.02
390	3/19/2019 10:33	mg/cm ²	Window Molding on Casing	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Office 7	Negative	1.47	0.01	0.04	0.05
391	3/19/2019 10:35	mg/cm ²	Wall Above Drop Ceiling	Plaster	D	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Negative	3.36	0.4	0.4	0.8
392	3/19/2019 10:36	mg/cm ²	Wall Above Drop Ceiling	Plaster	A	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Positive	4.72	0.6	0.4	1
393	3/19/2019 10:42	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Positive	3.57	0.5	0.5	1
394	3/19/2019 10:42	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	2	Econ. Devel. Office 7	Positive	5.57	0.9	1.3	2.2
395	3/19/2019 10:49	mg/cm ²	Wall	Drywall	A	Intact	Beige		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
396	3/19/2019 10:49	mg/cm ²	Wall	Drywall	B	Intact	Beige		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
397	3/19/2019 10:49	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Econ. Devel. Office 6	Positive	10	5	3.6	8.6

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
398	3/19/2019 10:49	mg/cm ²	Wall	Plaster	D	Intact	Beige		2	Econ. Devel. Office 6	Positive	10	3.7	2.7	6.4
399	3/19/2019 10:49	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
400	3/19/2019 10:49	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
401	3/19/2019 10:49	mg/cm ²	Window Casing/Header	Wood	D	Intact	Beige		2	Econ. Devel. Office 6	Negative	7.76	0.28	0.49	0.77
402	3/19/2019 10:50	mg/cm ²	Window Molding on Casing	Wood	D	Intact	Beige		2	Econ. Devel. Office 6	Negative	2.78	0.03	0.1	0.13
403	3/19/2019 10:50	mg/cm ²	Window Inside Stop	Wood	D	Intact	Beige		2	Econ. Devel. Office 6	Negative	3.76	0.11	0.22	0.33
404	3/19/2019 10:50	mg/cm ²	Window Sill	Ceramic	D	Intact	Grey		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
405	3/19/2019 10:50	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
406	3/19/2019 10:50	mg/cm ²	Door Jamb	Wood	B	Intact	Stain		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
407	3/19/2019 10:50	mg/cm ²	Door Stop	Wood	B	Intact	Stain		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
408	3/19/2019 10:50	mg/cm ²	Door	Wood	B	Intact	Stain		2	Econ. Devel. Office 6	Negative	1	0	0.02	0.02
409	3/19/2019 10:53	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 6	Positive	4.54	3.3	1.4	4.7
410	3/19/2019 10:55	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	C	Intact	Beige		2	Econ. Devel. Office 6	Negative	2.7	0.11	0.18	0.29
411	3/19/2019 11:07	mg/cm ²	Wall	Drywall	A	Intact	Beige		2	Econ. Devel. Office 8	Negative	1	0	0.02	0.02
412	3/19/2019 11:07	mg/cm ²	Wall	Plaster	B	Intact	Beige		2	Econ. Devel. Office 8	Positive	10	4.2	2.7	6.9
413	3/19/2019 11:07	mg/cm ²	Wall	Plaster	C	Intact	Beige		2	Econ. Devel. Office 8	Positive	10	2.4	1.2	3.6
414	3/19/2019 11:07	mg/cm ²	Wall	Drywall	D	Intact	Beige		2	Econ. Devel. Office 8	Negative	1	0	0.02	0.02
415	3/19/2019 11:07	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 8	Negative	1.4	0	0.02	0.02
416	3/19/2019 11:07	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Office 8	Negative	1	0	0.02	0.02
417	3/19/2019 11:07	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		2	Econ. Devel. Office 8	Negative	1	0	0.02	0.02
418	3/19/2019 11:08	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		2	Econ. Devel. Office 8	Negative	1	0	0.03	0.03
419	3/19/2019 11:08	mg/cm ²	Door Stop	Wood	D	Intact	Stain		2	Econ. Devel. Office 8	Negative	1	0	0.02	0.02
420	3/19/2019 11:08	mg/cm ²	Door	Wood	D	Intact	Stain		2	Econ. Devel. Office 8	Negative	1	0	0.02	0.02
421	3/19/2019 11:13	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 8	Positive	2.98	3.6	2.4	6
422	3/19/2019 11:20	mg/cm ²	Wall	Drywall	A	Intact	White		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
423	3/19/2019 11:20	mg/cm ²	Wall	Drywall	B	Intact	White		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
424	3/19/2019 11:20	mg/cm ²	Wall	Drywall	C	Intact	White		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
425	3/19/2019 11:20	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. Office 5	Positive	10	4	2.7	6.7
426	3/19/2019 11:20	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 5	Negative	5.09	0.02	0.09	0.11
427	3/19/2019 11:20	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
428	3/19/2019 11:20	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
429	3/19/2019 11:21	mg/cm ²	Door Jamb	Wood	B	Intact	Stain		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
430	3/19/2019 11:21	mg/cm ²	Door Stop	Wood	B	Intact	Stain		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
431	3/19/2019 11:21	mg/cm ²	Door	Wood	B	Intact	Stain		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
432	3/19/2019 11:21	mg/cm ²	Window Casing/Header	Wood	D	Intact	White		2	Econ. Devel. Office 5	Negative	4.75	0.14	0.29	0.43
433	3/19/2019 11:21	mg/cm ²	Window Inside Stop	Wood	D	Intact	White		2	Econ. Devel. Office 5	Negative	4.13	0.21	0.33	0.54
CAL	3/19/2019 11:38	cps											14.39	0	14.39
CAL	3/19/2019 11:39	mg/cm ²										1.29	1.1	0.1	1.2
CAL	3/19/2019 11:39	mg/cm ²										1.64	4.4	3	7.4
434	3/19/2019 11:40	mg/cm ²	Window Inside Stop	Wood	D	Intact	White		2	Econ. Devel. Office 5	Negative	4.91	0.18	0.33	0.51
435	3/19/2019 11:41	mg/cm ²	Window Sill	Ceramic	D	Intact	Grey		2	Econ. Devel. Office 5	Negative	1	0	0.02	0.02
436	3/19/2019 11:41	mg/cm ²	Window Molding On Casing	Wood	D	Intact	White		2	Econ. Devel. Office 5	Negative	3.68	0.04	0.14	0.18
437	3/19/2019 11:43	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 5	Positive	6.07	2.9	1.3	4.2
438	3/19/2019 11:43	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 5	Negative	1.62	0.07	0.11	0.18
439	3/19/2019 11:45	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Blue		2	Econ. Devel. Office 5	Positive	6.99	3	1.4	4.4
440	3/19/2019 11:46	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	White		2	Econ. Devel. Office 5	Positive	10	3.3	2.3	5.6
441	3/19/2019 11:54	mg/cm ²	Wall	Drywall	A	Intact	White		2	Econ. Devel. Lobby	Negative	1	0	0.02	0.02
442	3/19/2019 11:54	mg/cm ²	Wall	Plaster	B	Intact	White		2	Econ. Devel. Lobby	Negative	1	0	0.02	0.02
443	3/19/2019 11:54	mg/cm ²	Wall	Drywall	C	Intact	White		2	Econ. Devel. Lobby	Negative	1	0	0.02	0.02
444	3/19/2019 11:55	mg/cm ²	Wall	Drywall	D	Intact	White		2	Econ. Devel. Lobby	Negative	1	0	0.02	0.02
445	3/19/2019 11:55	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Lobby	Negative	1	0	0.02	0.02
446	3/19/2019 11:55	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Lobby	Negative	1	0	0.02	0.02
447	3/19/2019 11:58	mg/cm ²	Wall Above Drop Ceiling	Plaster	B	Deteriorated	Beige	Cracking	2	Econ. Devel. Lobby	Negative	2.29	0.12	0.87	0.99
448	3/19/2019 11:58	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Lobby	Negative	1.13	0.05	0.08	0.13
449	3/19/2019 11:58	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Lobby	Negative	2.23	0.16	0.07	0.23
450	3/19/2019 11:58	mg/cm ²	Wall Above Drop Ceiling	Plaster	C	Deteriorated	Beige	Cracking	2	Econ. Devel. Lobby	Negative	1.56	0.06	0.09	0.15
451	3/19/2019 12:02	mg/cm ²	Door Casing/Header	Wood	B	Intact	Brown		2	Econ. Devel. Lobby	Negative	1.11	0.03	0.05	0.18
452	3/19/2019 12:03	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Brown	Friction	2	Econ. Devel. Lobby	Negative	1.18	0.03	0.08	0.11
453	3/19/2019 12:03	mg/cm ²	Door Stop	Wood	B	Intact	Stain		2	Econ. Devel. Lobby	Negative	1	0	0.04	0.04

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
454	3/19/2019 12:03	mg/cm ²	Door	Wood	B	Intact	Stain		2	Econ. Devel. Lobby	Negative	1	0	0.03	0.03
455	3/19/2019 12:05	mg/cm ²	Wall	Plaster	A	Intact	White		2	Econ. Devel. Kitchen	Negative	4.94	0.02	0.05	0.07
456	3/19/2019 12:06	mg/cm ²	Wall	Drywall	B	Intact	White		2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
457	3/19/2019 12:06	mg/cm ²	Wall	Plaster	C	Intact	White		2	Econ. Devel. Kitchen	Negative	4.18	0	0	0
458	3/19/2019 12:06	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. Kitchen	Negative	10	0	0	0
459	3/19/2019 12:07	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Econ. Devel. Kitchen	Negative	8.6	0	0	0
460	3/19/2019 12:09	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Kitchen	Negative	1.27	0.01	0.03	0.04
461	3/19/2019 12:09	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
462	3/19/2019 12:09	mg/cm ²	Radiator	Metal	C	Deteriorated	White	Chipping	2	Econ. Devel. Kitchen	Negative	1.37	0.01	0.04	0.05
463	3/19/2019 12:10	mg/cm ²	Door Casing/Header	Wood	A	Intact	White		2	Econ. Devel. Kitchen	Negative	4.79	0.24	0.39	0.63
464	3/19/2019 12:11	mg/cm ²	Door Jamb	Wood	A	Intact	White		2	Econ. Devel. Kitchen	Negative	3.29	0.16	0.26	0.42
465	3/19/2019 12:11	mg/cm ²	Door Stop	Wood	A	Intact	White		2	Econ. Devel. Kitchen	Negative	1.39	0.07	0.1	0.17
466	3/19/2019 12:11	mg/cm ²	Door	Wood	A	Intact	White		2	Econ. Devel. Kitchen	Negative	1.17	0.06	0.09	0.15
467	3/19/2019 12:11	mg/cm ²	Door Transom Sash	Wood	A	Intact	White		2	Econ. Devel. Kitchen	Negative	1.22	0.04	0.08	0.12
468	3/19/2019 12:12	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
469	3/19/2019 12:12	mg/cm ²	Door Jamb	Wood	B	Intact	Stain		2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
470	3/19/2019 12:12	mg/cm ²	Door Stop	Wood	B	Intact	Stain		2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
471	3/19/2019 12:13	mg/cm ²	Door	Wood	B	Intact	Stain		2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
472	3/19/2019 12:15	mg/cm ²	Window Casing/Header	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Kitchen	Negative	6.45	0.13	0.29	0.42
473	3/19/2019 12:15	mg/cm ²	Window Inside Stop	Wood	D	Deteriorated	White	Cracking	2	Econ. Devel. Kitchen	Positive	8.41	0.4	0.6	1
474	3/19/2019 12:15	mg/cm ²	Window Sill	Plaster	D	Deteriorated	White	Chewable	2	Econ. Devel. Kitchen	Negative	1	0	0.02	0.02
475	3/19/2019 12:18	mg/cm ²	Wall	Wood	A	Intact	Yellow		2	Econ. Devel. Office 4	Negative	1	0	0.02	0.02
476	3/19/2019 12:18	mg/cm ²	Wall	Wood	B	Intact	Yellow		2	Econ. Devel. Office 4	Negative	1	0	0.02	0.02
477	3/19/2019 12:19	mg/cm ²	Wall	Drywall	C	Intact	Yellow		2	Econ. Devel. Office 4	Negative	5.75	0.06	0.14	0.2
478	3/19/2019 12:21	mg/cm ²	Wall	Plaster	D	Intact	Yellow		2	Econ. Devel. Office 4	Negative	10	0	0	0
479	3/19/2019 12:21	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 4	Negative	3.76	0.01	0.06	0.07
480	3/19/2019 12:21	mg/cm ²	Baseboard	Wood	All	Intact	Brown		2	Econ. Devel. Office 4	Negative	1.4	0.06	0.09	0.15
481	3/19/2019 12:23	mg/cm ²	Window Casing/Header	Wood	D	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 4	Negative	2.27	0.14	0.19	0.33
482	3/19/2019 12:23	mg/cm ²	Window Inside Stop	Wood	D	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 4	Negative	3.93	0.3	0.39	0.69
483	3/19/2019 12:23	mg/cm ²	Window Sill	Ceramic	D	Intact	Grey		2	Econ. Devel. Office 4	Negative	1.75	0.01	0.02	0.03
484	3/19/2019 12:24	mg/cm ²	Door Casing/Header	Wood	C	Intact	Brown		2	Econ. Devel. Office 4	Negative	1.37	0.11	0.17	0.28
485	3/19/2019 12:24	mg/cm ²	Door Jamb	Wood	C	Intact	Brown		2	Econ. Devel. Office 4	Negative	2.08	0.19	0.28	0.47
486	3/19/2019 12:24	mg/cm ²	Door Stop	Wood	C	Intact	Brown		2	Econ. Devel. Office 4	Negative	1.51	0.11	0.18	0.29
487	3/19/2019 12:24	mg/cm ²	Door	Wood	C	Intact	Brown		2	Econ. Devel. Office 4	Negative	1.23	0.09	0.1	0.19
488	3/19/2019 12:24	mg/cm ²	Door Transom Sash	Wood	C	Intact	Brown		2	Econ. Devel. Office 4	Negative	1.27	0.07	0.1	0.17
489	3/19/2019 12:25	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Stain	Impact	2	Econ. Devel. Office 4	Negative	1	0.01	0.03	0.04
490	3/19/2019 12:25	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Stain	Friction	2	Econ. Devel. Office 4	Negative	2.31	0.02	0.08	0.1
491	3/19/2019 12:25	mg/cm ²	Door Stop	Wood	A	Deteriorated	Stain	Impact	2	Econ. Devel. Office 4	Negative	1.22	0.01	0.05	0.06
492	3/19/2019 12:25	mg/cm ²	Door	Wood	A	Deteriorated	Stain	Friction/Impact	2	Econ. Devel. Office 4	Negative	1	0	0.03	0.03
493	3/19/2019 12:27	mg/cm ²	Wall	Wood	A	Deteriorated	White		2	Econ. Devel. Office 3/4 Hall	Negative	1	0	0.03	0.03
494	3/19/2019 12:27	mg/cm ²	Wall	Wood	B	Intact	White		2	Econ. Devel. Office 3/4 Hall	Negative	1	0	0.02	0.02
495	3/19/2019 12:27	mg/cm ²	Wall	Wood	C	Intact	White		2	Econ. Devel. Office 3/4 Hall	Negative	1	0	0.02	0.02
496	3/19/2019 12:27	mg/cm ²	Wall	Wood	D	Intact	White		2	Econ. Devel. Office 3/4 Hall	Negative	1.22	0.01	0.03	0.04
497	3/19/2019 12:27	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 3/4 Hall	Negative	6.05	0.09	0.27	0.36
498	3/19/2019 12:28	mg/cm ²	Baseboard	Wood	D	Intact	Brown		2	Econ. Devel. Office 3/4 Hall	Negative	1	0.05	0.07	0.12
499	3/19/2019 12:29	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Green		2	Econ. Devel. Office 3/4 Hall	Negative	2.11	0.05	0.09	0.14
500	3/19/2019 12:29	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	Beige		2	Econ. Devel. Office 3/4 Hall	Negative	2.88	0.17	0.15	0.32
501	3/19/2019 12:29	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	B	Intact	Stain		2	Econ. Devel. Office 3/4 Hall	Negative	1	0.05	0.16	0.21
502	3/19/2019 12:33	mg/cm ²	Wall	Plaster	A	Intact	Yellow		2	Econ. Devel. Office 3	Negative	9.66	0	0	0
503	3/19/2019 12:33	mg/cm ²	Wall	Wood	B	Intact	Yellow		2	Econ. Devel. Office 3	Negative	1	0	0.02	0.02
504	3/19/2019 12:33	mg/cm ²	Wall	Wood	C	Intact	Yellow		2	Econ. Devel. Office 3	Negative	1	0	0.02	0.02
505	3/19/2019 12:34	mg/cm ²	Wall	Plaster	D	Intact	Yellow		2	Econ. Devel. Office 3	Negative	8.5	0.15	0.83	0.98
506	3/19/2019 12:34	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 3	Negative	1.04	0	0.02	0.02
507	3/19/2019 12:34	mg/cm ²	Baseboard	Wood	All	Intact	White		2	Econ. Devel. Office 3	Negative	1.48	0.1	0.12	0.22
508	3/19/2019 12:34	mg/cm ²	Radiator	Metal	A	Intact	White		2	Econ. Devel. Office 3	Negative	4.79	0.06	0.2	0.26
509	3/19/2019 12:34	mg/cm ²	Window Casing/Header	Wood	A/D	Intact	White		2	Econ. Devel. Office 3	Negative	2.38	0.13	0.26	0.39
510	3/19/2019 12:35	mg/cm ²	Window Molding On Casing	Wood	A/D	Intact	White		2	Econ. Devel. Office 3	Negative	1.46	0.06	0.09	0.15
511	3/19/2019 12:35	mg/cm ²	Window Inside Stop	Wood	A/D	Intact	White		2	Econ. Devel. Office 3	Negative	1.23	0.06	0.08	0.14
512	3/19/2019 12:35	mg/cm ²	Window Sill	Ceramic	A/D	Intact	Grey		2	Econ. Devel. Office 3	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
513	3/19/2019 12:36 mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Stain	Cracking	2	Econ. Devel. Office 3	Negative	1.95	0.02	0.07	0.09	
514	3/19/2019 12:37 mg/cm ²	Door Lamb	Wood	C	Deteriorated	Stain	Friction	2	Econ. Devel. Office 3	Negative	1	0.01	0.03	0.04	
515	3/19/2019 12:37 mg/cm ²	Door Stop	Wood	C	Deteriorated	Stain	Impact	2	Econ. Devel. Office 3	Negative	1.56	0.04	0.08	0.12	
516	3/19/2019 12:37 mg/cm ²	Door	Wood	C	Deteriorated	Stain	Friction/Impact	2	Econ. Devel. Office 3	Negative	1.08	0.01	0.03	0.04	
517	3/19/2019 12:38 mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Green	Cracking	2	Econ. Devel. Office 3	Positive	1.82	0.23	0.77	1	
518	3/19/2019 12:39 mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 3	Negative	2.13	0.12	0.05	0.17	
519	3/19/2019 12:39 mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Stain	Cracking	2	Econ. Devel. Office 3	Negative	1	0.02	0.05	0.07	
520	3/19/2019 12:39 mg/cm ²	Window Casing/Header	Wood	A/D	Deteriorated	Black	Cracking	2	Econ. Devel. Office 3	Negative	1.17	0.07	0.12	0.19	
521	3/19/2019 12:43 mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	2	Econ. Devel. Office 3a	Positive	6.97	0.4	0.6	1	
522	3/19/2019 12:43 mg/cm ²	Wall	Wood	B	Intact	White	Cracking	2	Econ. Devel. Office 3a	Negative	1.62	0.01	0.05	0.06	
523	3/19/2019 12:44 mg/cm ²	Wall	Drywall	C	Intact	White	Cracking	2	Econ. Devel. Office 3a	Negative	1	0	0.02	0.02	
524	3/19/2019 12:44 mg/cm ²	Wall	Plaster	D	Intact	White	Cracking	2	Econ. Devel. Office 3a	Negative	10	0.26	0.69	0.95	
525	3/19/2019 12:44 mg/cm ²	Floor	Carpet	All	Intact	Brown	Cracking	2	Econ. Devel. Office 3a	Negative	2.24	0.01	0.05	0.06	
526	3/19/2019 12:44 mg/cm ²	Baseboard	Wood	All	Intact	Brown	Cracking	2	Econ. Devel. Office 3a	Negative	1.89	0.08	0.12	0.2	
527	3/19/2019 12:45 mg/cm ²	Radiator	Metal	A	Intact	White	Cracking	2	Econ. Devel. Office 3a	Negative	6.88	0.11	0.25	0.36	
528	3/19/2019 12:45 mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	Brown	Chipping	2	Econ. Devel. Office 3a	Negative	2.86	0.22	0.26	0.48	
529	3/19/2019 12:45 mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 3a	Negative	1.36	0.11	0.17	0.28	
530	3/19/2019 12:45 mg/cm ²	Window Inside Stop	Wood	A	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 3a	Negative	2.51	0.17	0.22	0.39	
531	3/19/2019 12:45 mg/cm ²	Window Molding On Casing	Wood	A	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 3a	Negative	2.09	0.08	0.13	0.21	
532	3/19/2019 12:45 mg/cm ²	Window Sill	Wood	A	Intact	Grey	Cracking	2	Econ. Devel. Office 3a	Negative	1	0	0.02	0.02	
533	3/19/2019 12:47 mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 3a	Negative	3.57	0.19	0.27	0.46	
534	3/19/2019 12:47 mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Green	Cracking	2	Econ. Devel. Office 3a	Negative	3.49	0	0	0	
535	3/19/2019 12:47 mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 3a	Negative	1.59	0.08	0.15	0.23	
536	3/19/2019 12:47 mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	Black	Cracking	2	Econ. Devel. Office 3a	Negative	1.45	0.14	0.19	0.33	
537	3/19/2019 12:52 mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	2	Econ. Devel. Office 2	Negative	4.61	0.5	0.1	0.6	
538	3/19/2019 12:52 mg/cm ²	Wall	Wood	B	Intact	White	Cracking	2	Econ. Devel. Office 2	Negative	2.47	0.02	0.08	0.1	
539	3/19/2019 12:52 mg/cm ²	Wall	Wood	C	Intact	Brown	Cracking	2	Econ. Devel. Office 2	Negative	1.89	0.03	0.08	0.11	
540	3/19/2019 12:52 mg/cm ²	Wall	Wood	D	Intact	White	Cracking	2	Econ. Devel. Office 2	Negative	1	0	0.02	0.02	
541	3/19/2019 12:53 mg/cm ²	Floor	Carpet	All	Intact	Brown	Cracking	2	Econ. Devel. Office 2	Negative	3.42	0.03	0.11	0.14	
542	3/19/2019 12:53 mg/cm ²	Baseboard	Wood	All	Intact	Brown	Cracking	2	Econ. Devel. Office 2	Negative	2.65	0.4	0.3	0.7	
543	3/19/2019 12:54 mg/cm ²	Radiator	Metal	A	Deteriorated	White	Chipping	2	Econ. Devel. Office 2	Negative	2.33	0.21	0.22	0.43	
544	3/19/2019 12:56 mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	White	Chipping	2	Econ. Devel. Office 2	Negative	2.22	0.08	0.13	0.21	
545	3/19/2019 12:56 mg/cm ²	Window Casing/Header	Wood	A	Intact	Brown	Cracking	2	Econ. Devel. Office 2	Negative	1.52	0.23	0.25	0.48	
546	3/19/2019 12:56 mg/cm ²	Window Molding On Casing	Wood	A	Intact	Brown	Cracking	2	Econ. Devel. Office 2	Negative	1.96	0.26	0.22	0.48	
547	3/19/2019 12:56 mg/cm ²	Window Inside Stop	Wood	A	Intact	Brown	Cracking	2	Econ. Devel. Office 2	Negative	1.83	0.23	0.21	0.44	
548	3/19/2019 12:56 mg/cm ²	Window Sill	Ceramic	A	Intact	Grey	Cracking	2	Econ. Devel. Office 2	Negative	1	0	0.02	0.02	
549	3/19/2019 12:58 mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Brown	Cracking	2	Econ. Devel. Office 2	Negative	2.84	0.5	0.1	0.6	
550	3/19/2019 12:59 mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 2	Negative	4.04	0.27	0.68	0.95	
551	3/19/2019 12:59 mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Beige	Cracking	2	Econ. Devel. Office 2	Negative	1.99	0.13	0.16	0.29	
552	3/19/2019 13:04 mg/cm ²	Wall	Drywall	A	Intact	White	Cracking	2	Econ. Devel. N Hall	Negative	1	0	0.02	0.02	
553	3/19/2019 13:04 mg/cm ²	Wall	Plaster	B	Intact	White	Cracking	2	Econ. Devel. N Hall	Negative	10	0.25	0.71	0.96	
554	3/19/2019 13:04 mg/cm ²	Wall	Drywall	C	Intact	White	Cracking	2	Econ. Devel. N Hall	Negative	1	0	0.02	0.02	
555	3/19/2019 13:04 mg/cm ²	Wall	Drywall	D	Intact	White	Cracking	2	Econ. Devel. N Hall	Negative	4.35	0.02	0.04	0.06	
556	3/19/2019 13:05 mg/cm ²	Floor	Carpet	All	Intact	Brown	Cracking	2	Econ. Devel. N Hall	Negative	3.08	0.01	0.03	0.04	
557	3/19/2019 13:05 mg/cm ²	Baseboard	Wood	All	Intact	Stain	Cracking	2	Econ. Devel. N Hall	Negative	1	0	0.02	0.02	
558	3/19/2019 13:05 mg/cm ²	Lower Cabinet Face	Wood	C	Deteriorated	Stain	Impact	2	Econ. Devel. N Hall	Negative	1.4	0.03	0.07	0.1	
559	3/19/2019 13:05 mg/cm ²	Lower Cabinet Door	Wood	C	Deteriorated	Stain	Friction/Impact	2	Econ. Devel. N Hall	Negative	1.64	0.07	0.11	0.18	
560	3/19/2019 13:05 mg/cm ²	Lower Cabinet Shelf	Wood	C	Deteriorated	Stain	Friction	2	Econ. Devel. N Hall	Negative	1	0	0.03	0.03	
561	3/19/2019 13:05 mg/cm ²	Upper Cabinet Face	Wood	C	Deteriorated	Stain	Impact	2	Econ. Devel. N Hall	Negative	1	0	0.02	0.02	
562	3/19/2019 13:06 mg/cm ²	Upper Cabinet Door	Wood	C	Deteriorated	Stain	Friction/Impact	2	Econ. Devel. N Hall	Negative	1	0	0.02	0.02	
563	3/19/2019 13:06 mg/cm ²	Upper Cabinet Shelf	Wood	C	Deteriorated	Stain	Friction	2	Econ. Devel. N Hall	Negative	1	0	0.02	0.02	
564	3/19/2019 13:06 mg/cm ²	Safe Frame	Metal	C	Deteriorated	Brown	Friction	2	Econ. Devel. N Hall	Positive	1.43	2.3	1.1	3.4	
565	3/19/2019 13:06 mg/cm ²	Safe Door	Metal	C	Deteriorated	Brown	Friction/Impact	2	Econ. Devel. N Hall	Positive	1.35	1.2	0.2	1.4	
566	3/19/2019 13:08 mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Stain	Cracking	2	Econ. Devel. N Hall	Negative	1	0.08	0.12	0.2	
567	3/19/2019 13:08 mg/cm ²	Door Lamb	Wood	B	Deteriorated	Stain	Friction	2	Econ. Devel. N Hall	Negative	1.2	0.12	0.12	0.24	
568	3/19/2019 13:08 mg/cm ²	Door Stop	Wood	B	Deteriorated	Stain	Impact	2	Econ. Devel. N Hall	Negative	1	0.01	0.04	0.05	
569	3/19/2019 13:09 mg/cm ²	Door Transom Sash	Wood	B	Deteriorated	Stain	Cracking	2	Econ. Devel. N Hall	Negative	1	0.05	0.07	0.12	
570	3/19/2019 13:09 mg/cm ²	Countertop	Wood	C	Deteriorated	Stain	Friction	2	Econ. Devel. N Hall	Negative	1.28	0.04	0.1	0.14	
571	3/19/2019 13:11 mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	White	Cracking	2	Econ. Devel. N Hall	Negative	5.24	0.5	0.4	0.9	

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
572	3/19/2019 13:11	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		2	Econ. Devel. N Hall	Negative	4.67	0.27	0.71	0.98
573	3/19/2019 13:11	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	White		2	Econ. Devel. N Hall	Negative	1.69	0.07	0.11	0.18
574	3/19/2019 13:11	mg/cm ²	Column Trim	Wood	C	Intact	White		2	Econ. Devel. N Hall	Negative	3.09	0.18	0.24	0.42
575	3/19/2019 13:12	mg/cm ²	Column	Plaster	C	Intact	White		2	Econ. Devel. N Hall	Positive	4.46	0.4	0.6	1
576	3/19/2019 13:20	mg/cm ²	Wall	Plaster	A	Intact	White		2	Econ. Devel. Vault Hall	Negative	2.65	0.3	0.61	0.91
577	3/19/2019 13:20	mg/cm ²	Wall	Plaster	B	Intact	White		2	Econ. Devel. Vault Hall	Negative	5.09	0.14	0.82	0.96
578	3/19/2019 13:20	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	2	Econ. Devel. Vault Hall	Negative	3.85	0	0	0
579	3/19/2019 13:24	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. Vault Hall	Negative	3.63	0.05	0.9	0.95
580	3/19/2019 13:24	mg/cm ²	Floor	Carpet	All	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	7.78	0.13	0.11	0.24
581	3/19/2019 13:24	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	1.18	0.01	0.05	0.06
582	3/19/2019 13:24	mg/cm ²	Shoe Molding	Wood	All	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	1.18	0.02	0.08	0.1
583	3/19/2019 13:24	mg/cm ²	Door Casing/Header	Wood	C	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	1	0	0.03	0.03
584	3/19/2019 13:24	mg/cm ²	Door Jamb	Wood	C	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	1	0	0.03	0.03
585	3/19/2019 13:24	mg/cm ²	Door Stop	Wood	C	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	1	0.01	0.04	0.05
586	3/19/2019 13:25	mg/cm ²	Door	Wood	C	Intact	Stain		2	Econ. Devel. Vault Hall	Negative	1	0	0.02	0.02
587	3/19/2019 13:25	mg/cm ²	Vault Door Casing/Header	Metal	B	Deteriorated	Grey	Cracking	2	Econ. Devel. Vault Hall	Positive	2.07	12.8	11.2	24
588	3/19/2019 13:25	mg/cm ²	Vault Door Jamb	Metal	B	Deteriorated	Green	Friction	2	Econ. Devel. Vault Hall	Positive	1.31	1.4	0.3	1.7
589	3/19/2019 13:25	mg/cm ²	Vault Door	Metal	B	Deteriorated	Grey	Friction/Impact	2	Econ. Devel. Vault Hall	Positive	1.83	22.1	14.2	36.3
590	3/19/2019 13:25	mg/cm ²	Vault Door Threshold	Metal	B	Deteriorated	Grey	Friction	2	Econ. Devel. Vault Hall	Negative	1.34	0.5	0.3	0.8
591	3/19/2019 13:26	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Econ. Devel. Vault Hall	Negative	3.94	0.12	0.23	0.35
592	3/19/2019 13:28	mg/cm ²	Wall	Concrete	A	Intact	Beige		2	Econ. Devel. Vault	Negative	1.78	0.05	0.02	0.07
593	3/19/2019 13:28	mg/cm ²	Wall	Concrete	B	Intact	Beige		2	Econ. Devel. Vault	Negative	1.93	0.05	0.06	0.11
594	3/19/2019 13:28	mg/cm ²	Wall	Concrete	C	Intact	Beige		2	Econ. Devel. Vault	Negative	3.19	0	0	0
595	3/19/2019 13:29	mg/cm ²	Wall	Concrete	D	Intact	Beige		2	Econ. Devel. Vault	Negative	1.23	0.02	0.02	0.04
596	3/19/2019 13:29	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	2	Econ. Devel. Vault	Negative	1.12	0.05	0.05	0.1
597	3/19/2019 13:29	mg/cm ²	Door Casing/Header	Metal	D	Deteriorated	Red	Cracking	2	Econ. Devel. Vault	Negative	1	0.01	0.04	0.05
598	3/19/2019 13:30	mg/cm ²	Ceiling	Concrete	All	Intact	Beige		2	Econ. Devel. Vault	Negative	2.05	0.05	0.04	0.09
599	3/19/2019 13:33	mg/cm ²	Wall	Plaster	A	Intact	White		2	Econ. Devel. Office 1	Negative	4.33	0.2	0.77	0.97
600	3/19/2019 13:33	mg/cm ²	Wall	Plaster	B	Intact	White		2	Econ. Devel. Office 1	Negative	3.31	0.16	0.76	0.92
601	3/19/2019 13:33	mg/cm ²	Wall	Plaster	C	Intact	White		2	Econ. Devel. Office 1	Negative	3.28	0.3	0.69	0.99
602	3/19/2019 13:33	mg/cm ²	Wall	Plaster	D	Intact	White		2	Econ. Devel. Office 1	Positive	2.91	0.3	0.7	1
603	3/19/2019 13:34	mg/cm ²	Ceiling	Plaster	All	Intact	White		2	Econ. Devel. Office 1	Negative	2.61	0	0	0
604	3/19/2019 13:34	mg/cm ²	Crown Molding	Wood	All	Intact	Stain		2	Econ. Devel. Office 1	Negative	1.37	0.03	0.15	0.18
605	3/19/2019 13:34	mg/cm ²	Floor	Carpet	All	Intact	Brown		2	Econ. Devel. Office 1	Positive	10	2.8	1.1	3.9
606	3/19/2019 13:35	mg/cm ²	Baseboard	Wood	All	Intact	Stain		2	Econ. Devel. Office 1	Negative	1.8	0.02	0.1	0.12
607	3/19/2019 13:35	mg/cm ²	Shoe Molding	Wood	All	Intact	Stain		2	Econ. Devel. Office 1	Negative	2.96	0.1	0.19	0.29
608	3/19/2019 13:35	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		2	Econ. Devel. Office 1	Negative	1	0.01	0.05	0.06
609	3/19/2019 13:35	mg/cm ²	Window Inside Stop	Wood	A	Intact	Stain		2	Econ. Devel. Office 1	Negative	1.15	0.04	0.07	0.11
610	3/19/2019 13:36	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		2	Econ. Devel. Office 1	Negative	1	0	0.02	0.02
611	3/19/2019 13:36	mg/cm ²	Radiator	Metal	A	Intact	White		2	Econ. Devel. Office 1	Negative	1.72	0.06	0.1	0.16
612	3/19/2019 13:41	mg/cm ²	Wall	Drywall	A	Intact	Grey		2	Lobby W Hall	Negative	1	0	0.02	0.02
613	3/19/2019 13:41	mg/cm ²	Wall	Drywall	B	Intact	Grey		2	Lobby W Hall	Negative	1	0	0.02	0.02
614	3/19/2019 13:42	mg/cm ²	Wall	Plaster	C	Intact	White		2	Lobby W Hall	Positive	5.9	2.1	0.9	3
615	3/19/2019 13:42	mg/cm ²	Wall	Plaster	D	Intact	Grey		2	Lobby W Hall	Positive	6.46	2.2	1.1	3.3
616	3/19/2019 13:43	mg/cm ²	Wall Near Stairway	Plaster	A	Intact	White		2	Lobby W Hall	Positive	5.25	2.7	1.5	4.2
617	3/19/2019 13:43	mg/cm ²	Wall Near Stairway	Plaster	B	Deteriorated	White	Cracking	2	Lobby W Hall	Positive	6.36	2	0.9	2.9
618	3/19/2019 13:44	mg/cm ²	Radiator	Metal	A	Deteriorated	White	Chipping	2	Lobby W Hall	Positive	7.09	2	1	3
619	3/19/2019 13:44	mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	Dark Brown	Chipping	2	Lobby W Hall	Positive	5.11	1.5	0.4	1.9
620	3/19/2019 13:44	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	2	Lobby W Hall	Negative	1	0	0.02	0.02
621	3/19/2019 13:45	mg/cm ²	Baseboard	Wood	B/D	Intact	Brown		2	Lobby W Hall	Negative	1	0	0.03	0.03
622	3/19/2019 13:45	mg/cm ²	Shoe Molding	Wood	B/D	Intact	Brown		2	Lobby W Hall	Negative	1.95	0.06	0.11	0.17
623	3/19/2019 13:46	mg/cm ²	Baseboard	Wood	All	Intact	Dark Brown		2	Lobby W Hall	Negative	3.44	0.03	0.12	0.15
624	3/19/2019 13:46	mg/cm ²	Shoe Molding	Wood	All	Intact	Dark Brown		2	Lobby W Hall	Negative	1.96	0.02	0.07	0.09
625	3/19/2019 13:46	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	2	Lobby W Hall	Negative	2.06	0.02	0.12	0.14
626	3/19/2019 13:47	mg/cm ²	Outer Door Casing/Header	Metal	C	Intact	White		2	Lobby W Hall	Positive	4.08	3.7	1.7	5.4
627	3/19/2019 13:48	mg/cm ²	Window Casing/Header	Wood	B	Deteriorated	Black	Cracking	2	Lobby W Hall SW Stairway	Negative	2.06	0.12	0.16	0.28
628	3/19/2019 13:48	mg/cm ²	Window Molding On Casing	Wood	B	Deteriorated	Black	Cracking	2	Lobby W Hall SW Stairway	Negative	1.44	0.05	0.12	0.17
629	3/19/2019 13:48	mg/cm ²	Window Inside Stop	Wood	B	Deteriorated	Black	Cracking	2	Lobby W Hall SW Stairway	Negative	1.04	0.02	0.05	0.07
630	3/19/2019 13:48	mg/cm ²	Window Sill	Concrete	B	Intact	Grey		2	Lobby W Hall SW Stairway	Negative	1	0.01	0.02	0.03

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
631	3/19/2019 13:50	mg/cm ²	Stair Newell Post	Wood	All	Deteriorated	Brown	Impact	2	Lobby W Hall SW Stairway	Negative	2.61	0.13	0.18	0.31
632	3/19/2019 13:50	mg/cm ²	Stair Newell Post	Wood	All	Deteriorated	White	Impact	2	Lobby W Hall SW Stairway	Negative	2.91	0.12	0.19	0.31
633	3/19/2019 13:51	mg/cm ²	Stair Railing	Wood	All	Deteriorated	White	Friction	2	Lobby W Hall SW Stairway	Negative	1.17	0.02	0.07	0.09
634	3/19/2019 13:51	mg/cm ²	Stair Spindles	Metal	All	Deteriorated	Brown	Chipping	2	Lobby W Hall SW Stairway	Negative	1.61	0.09	0.12	0.21
635	3/19/2019 13:51	mg/cm ²	Stair Tread	Concrete	All	Deteriorated	Grey	Friction	2	Lobby W Hall SW Stairway	Negative	1	0	0.02	0.02
636	3/19/2019 13:51	mg/cm ²	Stair Riser	Concrete	All	Deteriorated	Grey	Impact	2	Lobby W Hall SW Stairway	Negative	1.27	0.04	0.07	0.11
637	3/19/2019 13:51	mg/cm ²	Stair Stringer	Metal	All	Deteriorated	Brown	Cracking	2	Lobby W Hall SW Stairway	Negative	1.87	0.15	0.14	0.29
638	3/19/2019 13:52	mg/cm ²	Lower Wall	Plaster	B	Deteriorated	White	Cracking	2	Lobby W Hall SW Stairway	Negative	3.94	0.13	0.8	0.93
639	3/19/2019 13:52	mg/cm ²	Lower Wall	Plaster	D	Intact	White		2	Lobby W Hall SW Stairway	Negative	1	0	0.02	0.02
640	3/19/2019 13:52	mg/cm ²	Lower Wall	Concrete	D	Intact	White		2	Lobby W Hall SW Stairway	Negative	1	0	0.02	0.02
641	3/19/2019 13:53	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	2	Lobby W Hall Closet	Negative	1.18	0.4	0.2	0.6
642	3/19/2019 13:53	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	2	Lobby W Hall Closet	Negative	1.38	0.4	0.2	0.6
643	3/19/2019 13:53	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	2	Lobby W Hall Closet	Negative	1	0.3	0.17	0.47
644	3/19/2019 13:53	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	2	Lobby W Hall Closet	Negative	1.34	0.6	0.3	0.9
645	3/19/2019 13:56	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	2	Lobby W Hall Closet	Negative	1	0	0.02	0.02
646	3/19/2019 13:56	mg/cm ²	Baseboard	Wood	All	Deteriorated	Beige	Chipping	2	Lobby W Hall Closet	Positive	2.19	0.8	1.1	1.9
647	3/19/2019 13:56	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Beige	Impact	2	Lobby W Hall Closet	Negative	1.77	0.28	0.23	0.51
648	3/19/2019 13:57	mg/cm ²	Shelf Support	Wood	All	Deteriorated	Beige	Chipping	2	Lobby W Hall Closet	Negative	1.56	0.6	0.1	0.7
649	3/19/2019 13:57	mg/cm ²	Shelf	Wood	All	Deteriorated	Beige	Friction	2	Lobby W Hall Closet	Negative	1.26	0.4	0.1	0.5
650	3/19/2019 13:57	mg/cm ²	Door Casing/Header	Wood	D	Deteriorated	Stain	Impact	2	Lobby W Hall Closet	Negative	2.02	0.16	0.18	0.34
651	3/19/2019 13:57	mg/cm ²	Door Jamb	Wood	D	Deteriorated	Stain	Friction	2	Lobby W Hall Closet	Negative	1	0.05	0.07	0.12
652	3/19/2019 13:57	mg/cm ²	Door Stop	Wood	D	Deteriorated	Stain	Impact	2	Lobby W Hall Closet	Negative	1.67	0.08	0.12	0.2
653	3/19/2019 13:57	mg/cm ²	Door	Wood	D	Deteriorated	Stain	Friction/Impact	2	Lobby W Hall Closet	Negative	1.04	0.04	0.07	0.11
654	3/19/2019 13:59	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	2	Lobby W Hall Closet	Negative	3.25	0.09	0.13	0.22
655	3/19/2019 14:08	mg/cm ²	Wall	Ceramic	A	Intact	Grey		2	Womens Restroom	Negative	1	0.01	0.04	0.05
656	3/19/2019 14:08	mg/cm ²	Wall	Ceramic	B	Intact	Grey		2	Womens Restroom	Negative	1	0.01	0.04	0.05
657	3/19/2019 14:09	mg/cm ²	Wall	Ceramic	C	Intact	Grey		2	Womens Restroom	Negative	1	0	0.04	0.04
658	3/19/2019 14:09	mg/cm ²	Wall	Ceramic	D	Intact	Grey		2	Womens Restroom	Negative	1	0.01	0.04	0.05
659	3/19/2019 14:09	mg/cm ²	Floor	Vinyl	All	Intact	Grey		2	Womens Restroom	Negative	1	0	0.02	0.02
660	3/19/2019 14:09	mg/cm ²	Radiator	Metal	C	Intact	Grey		2	Womens Restroom	Positive	2.42	1.5	0.6	2.1
661	3/19/2019 14:09	mg/cm ²	Stall Frame	Metal	D	Intact	Grey		2	Womens Restroom	Negative	1	0	0.04	0.04
662	3/19/2019 14:09	mg/cm ²	Stall Door	Metal	D	Intact	Grey		2	Womens Restroom	Negative	1	0	0.03	0.03
663	3/19/2019 14:10	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		2	Womens Restroom	Negative	1	0	0.02	0.02
664	3/19/2019 14:10	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		2	Womens Restroom	Negative	1	0	0.02	0.02
665	3/19/2019 14:10	mg/cm ²	Door Stop	Wood	A	Intact	Stain		2	Womens Restroom	Negative	1	0	0.02	0.02
666	3/19/2019 14:10	mg/cm ²	Door	Wood	A	Intact	Stain		2	Womens Restroom	Negative	1	0	0.02	0.02
667	3/19/2019 14:10	mg/cm ²	Window Casing/Header	Wood	C	Intact	Stain		2	Womens Restroom	Negative	1	0	0.02	0.02
668	3/19/2019 14:10	mg/cm ²	Window Molding On Casing	Wood	C	Deteriorated	Brown	Cracking	2	Womens Restroom	Negative	1.67	0.04	0.08	0.12
669	3/19/2019 14:10	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Brown	Cracking	2	Womens Restroom	Negative	1.95	0.1	0.14	0.24
670	3/19/2019 14:10	mg/cm ²	Window Sill	Ceramic	C	Intact	Brown		2	Womens Restroom	Negative	1	0	0.02	0.02
671	3/19/2019 14:12	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	2	Womens Restroom	Positive	2.81	0.08	0.92	1
672	3/19/2019 14:12	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	White	Cracking	2	Womens Restroom	Negative	3.48	0.27	0.31	0.58
673	3/19/2019 14:15	mg/cm ²	Wall	Plaster	A	Intact	Grey		2	Central Staircase	Positive	5.79	0.3	0.7	1
674	3/19/2019 14:15	mg/cm ²	Wall	Plaster	B	Intact	Grey		2	Central Staircase	Negative	7.1	0.09	0.88	0.97
675	3/19/2019 14:15	mg/cm ²	Wall	Plaster	D	Intact	Grey		2	Central Staircase	Negative	6.95	0	0	0
676	3/19/2019 14:18	mg/cm ²	Floor	Ceramic	All	Intact	Grey		2	Central Staircase	Negative	1	0	0.02	0.02
677	3/19/2019 14:18	mg/cm ²	Stair Tread	Ceramic	All	Intact	Grey		2	Central Staircase	Negative	1	0	0.02	0.02
678	3/19/2019 14:18	mg/cm ²	Stair Riser	Metal	All	Intact	Brown		2	Central Staircase	Negative	1.43	0.15	0.14	0.29
679	3/19/2019 14:19	mg/cm ²	Stair Stringer	Metal	All	Intact	Brown		2	Central Staircase	Negative	1.79	0.16	0.16	0.32
680	3/19/2019 14:19	mg/cm ²	Railing	Wood	All	Intact	Stain		2	Central Staircase	Negative	1.78	0.02	0.1	0.12
681	3/19/2019 14:19	mg/cm ²	Stair Newell Post	Metal	All	Intact	Brown		2	Central Staircase	Negative	1.38	0.09	0.11	0.2
682	3/19/2019 14:19	mg/cm ²	Stair Spindles	Metal	All	Intact	Brown		2	Central Staircase	Negative	1	0.05	0.07	0.12
683	3/19/2019 14:19	mg/cm ²	Stair Railing	Wood	All	Intact	Brown		2	Central Staircase	Negative	1	0.01	0.03	0.04
684	3/19/2019 14:19	mg/cm ²	Stair Stringer	Metal	All	Intact	Brown		2	Central Staircase	Negative	1.29	0.12	0.12	0.24
685	3/19/2019 14:22	mg/cm ²	Arched Ceiling	Plaster	All	Intact	White		2	Central Staircase	Positive	10	2.3	1	3.3
686	3/19/2019 14:23	mg/cm ²	Ceiling Molding	Plaster	All	Intact	White		2	Central Staircase	Positive	10	1.2	0.4	1.6
687	3/19/2019 14:26	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		2	Central Staircase	Negative	1.48	0.17	0.21	0.38
688	3/19/2019 14:26	mg/cm ²	Window Sash	Wood	A	Intact	Stain		2	Central Staircase	Negative	1	0	0.02	0.02
689	3/19/2019 14:27	mg/cm ²	Window Inside Stop	Wood	A	Intact	Stain		2	Central Staircase	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
690	3/19/2019 14:27	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		2	Central Staircase	Negative	1.95	0	0.02	0.02
691	3/19/2019 14:27	mg/cm ²	Window Jamb	Vinyl	A	Intact	Brown		2	Central Staircase	Negative		1	0	0.02
692	3/19/2019 14:32	mg/cm ²	Wall	Plaster	A	Intact	White		2	Server Room	Negative	4.43	0.2	0.79	0.99
693	3/19/2019 14:32	mg/cm ²	Wall	Wood	B	Intact	Stain		2	Server Room	Negative	2.31	0.02	0.08	0.1
694	3/19/2019 14:32	mg/cm ²	Wall	Plaster	C	Intact	White		2	Server Room	Positive	5.94	0.28	0.72	1
695	3/19/2019 14:33	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	2	Server Room	Negative	3.11	0.24	0.75	0.99
696	3/19/2019 14:33	mg/cm ²	Chair Rail	Wood	All	Deteriorated	White	Cracking	2	Server Room	Negative	1.88	0.2	0.28	0.48
697	3/19/2019 14:34	mg/cm ²	Wainscoting Panel	Wood	All	Deteriorated	White	Cracking	2	Server Room	Negative	2.28	0.4	0.3	0.7
698	3/19/2019 14:34	mg/cm ²	Wainscoting Frame	Wood	All	Deteriorated	White	Cracking	2	Server Room	Negative	1.53	0.14	0.2	0.34
699	3/19/2019 14:34	mg/cm ²	Floor	Vinyl	All	Intact	Beige		2	Server Room	Negative	1	0	0.02	0.02
700	3/19/2019 14:34	mg/cm ²	Floor	Carpet	All	Intact	Green		2	Server Room	Negative	1	0	0.02	0.02
701	3/19/2019 14:36	mg/cm ²	Window Outer Casing/Header	Wood	C	Intact	White		2	Server Room	Negative	2.85	0	0	0
702	3/19/2019 14:36	mg/cm ²	Window Inner Casing/Header	Wood	C	Intact	White		2	Server Room	Negative	3.29	0.12	0.22	0.34
703	3/19/2019 14:36	mg/cm ²	Window Inside Stop	Wood	C	Intact	Black		2	Server Room	Negative	1	0	0.02	0.02
704	3/19/2019 14:36	mg/cm ²	Window Sill	Wood	C	Intact	White		2	Server Room	Negative	1.49	0.15	0.15	0.3
705	3/19/2019 14:37	mg/cm ²	Radiator Cover Frame	Wood	C	Deteriorated	White	Cracking	2	Server Room	Negative	2.15	0.09	0.14	0.23
706	3/19/2019 14:37	mg/cm ²	Radiator Cover Top	Wood	C	Deteriorated	White	Friction	2	Server Room	Negative	3.61	0.16	0.26	0.42
707	3/19/2019 14:37	mg/cm ²	Door Casing/Header	Wood	A	Intact	White		2	Server Room	Negative	1.35	0.15	0.2	0.35
708	3/19/2019 14:38	mg/cm ²	Door Casing/Header	Wood	A	Intact	White		2	Server Room	Negative	2.4	0.25	0.35	0.6
709	3/19/2019 14:38	mg/cm ²	Door Jamb	Wood	A	Intact	White		2	Server Room	Negative	2.33	0.24	0.34	0.58
710	3/19/2019 14:38	mg/cm ²	Door Stop	Wood	A	Intact	Stain		2	Server Room	Negative	6.06	0.11	0.45	0.56
711	3/19/2019 14:39	mg/cm ²	Door	Wood	A	Intact	Stain		2	Server Room	Negative	1	0	0.02	0.02
712	3/19/2019 14:40	mg/cm ²	Door Header	Wood	A	Intact	White		2	Server Room	Negative	2.09	0.24	0.32	0.56
CAL	3/19/2019 15:06	mg/cm ²		Wood	A	Intact	White				Negative	1.09	0.8	0.2	1
CAL	3/19/2019 15:07	mg/cm ²		Wood	A	Intact	White				Negative	1.21	0.9	0.1	1
CAL	3/19/2019 15:07	mg/cm ²		Drywall	A	Intact	White		1/2	Storage 1	Negative	1.34	1.1	0.1	1.2
713	3/19/2019 15:10	mg/cm ²	Wall	Drywall	B	Intact	White		1/2	Storage 1	Negative	1	0	0.02	0.02
714	3/19/2019 15:10	mg/cm ²	Wall	Drywall	C	Intact	Brown		1/2	Storage 1	Negative	1	0	0.02	0.02
715	3/19/2019 15:10	mg/cm ²	Wall	Drywall	C	Intact	Brown		1/2	Storage 1	Negative	1	0	0.02	0.02
716	3/19/2019 15:10	mg/cm ²	Wall	Drywall	D	Intact	Brown		1/2	Storage 1	Negative	1	0	0.02	0.02
717	3/19/2019 15:10	mg/cm ²	Ceiling	Drywall	All	Intact	White		1/2	Storage 1	Negative	1	0	0.02	0.02
718	3/19/2019 15:10	mg/cm ²	Floor	Carpet	All	Intact	Brown		1/2	Storage 1	Negative	1	0	0.02	0.02
719	3/19/2019 15:10	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1/2	Storage 1	Negative	1	0	0.02	0.02
720	3/19/2019 15:10	mg/cm ²	Window Casing/Header	Wood	B	Intact	Stain		1/2	Storage 1	Negative	1	0	0.02	0.02
721	3/19/2019 15:11	mg/cm ²	Window Sash	Wood	B	Intact	Stain		1/2	Storage 1	Negative	1	0	0.02	0.02
722	3/19/2019 15:11	mg/cm ²	Window Sill	Wood	B	Intact	Stain		1/2	Storage 1	Negative	1	0	0.02	0.02
723	3/19/2019 15:11	mg/cm ²	Window Jamb	Vinyl	B	Intact	White		1/2	Storage 1	Negative	1	0	0.02	0.02
724	3/19/2019 15:11	mg/cm ²	Window Trough	Metal	B	Intact	Brown		1/2	Storage 1	Positive	4.76	0.3	0.7	1
725	3/19/2019 15:12	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		1/2	Storage 1	Negative	1	0	0.02	0.02
726	3/19/2019 15:12	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Stain	Friction	1/2	Storage 1	Negative	1.12	0.09	0.14	0.23
727	3/19/2019 15:12	mg/cm ²	Door Stop	Wood	A	Deteriorated	Stain	Impact	1/2	Storage 1	Negative	1.83	0.07	0.16	0.23
728	3/19/2019 15:12	mg/cm ²	Door	Wood	A	Deteriorated	Stain	Friction/Impact	1/2	Storage 1	Negative	1	0.12	0.14	0.26
729	3/19/2019 15:14	mg/cm ²	Wall	Wood	A	Intact	White		1/2	SW Stair Outside Storage 1	Negative	1	0	0.02	0.02
730	3/19/2019 15:14	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	1/2	SW Stair Outside Storage 1	Negative	8.7	0.15	0.8	0.95
731	3/19/2019 15:15	mg/cm ²	Wall	Plaster	C	Intact	White		1/2	SW Stair Outside Storage 1	Negative	3.44	0	0	0
732	3/19/2019 15:15	mg/cm ²	Wall	Plaster	D	Intact	White		1/2	SW Stair Outside Storage 1	Positive	5.82	2.7	1.6	4.3
733	3/19/2019 15:15	mg/cm ²	Ceiling	Plaster	All	Intact	White		1/2	SW Stair Outside Storage 1	Negative	5.34	0.09	0.84	0.93
734	3/19/2019 15:15	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	1/2	SW Stair Outside Storage 1	Negative	1	0	0.02	0.02
735	3/19/2019 15:15	mg/cm ²	Baseboard	Wood	All	Intact	Dark Brown		1/2	SW Stair Outside Storage 1	Negative	2.48	0.06	0.18	0.24
736	3/19/2019 15:15	mg/cm ²	Shoe Molding	Wood	All	Intact	Dark Brown		1/2	SW Stair Outside Storage 1	Negative	1.51	0.01	0.07	0.08
737	3/19/2019 15:16	mg/cm ²	Door Casing/Header	Wood	C	Intact	Dark Brown		1/2	SW Stair Outside Storage 1	Negative	1.65	0.14	0.15	0.29
738	3/19/2019 15:16	mg/cm ²	Door	Wood	C	Intact	Dark Brown		1/2	SW Stair Outside Storage 1	Negative	2.52	0.19	0.31	0.5
739	3/19/2019 15:17	mg/cm ²	Door Casing/Header	Wood	A	Intact	White		1/2	SW Stair Outside Storage 1	Negative	1	0	0.02	0.02
740	3/19/2019 15:17	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		1/2	SW Stair Outside Storage 1	Negative	1	0	0.02	0.02
741	3/19/2019 15:18	mg/cm ²	Door Stop	Wood	A	Intact	Stain		1/2	SW Stair Outside Storage 1	Negative	1	0	0.02	0.02
742	3/19/2019 15:18	mg/cm ²	Door	Wood	A	Intact	White		1/2	SW Stair Outside Storage 1	Negative	1	0	0.02	0.02
743	3/19/2019 15:18	mg/cm ²	Closet Ceiling	Plaster	All	Intact	Grey		1/2	SW Stair Outside Storage 1	Negative	2.46	0.18	0.16	0.34
744	3/19/2019 15:19	mg/cm ²	Closet Door Threshold	Wood	A	Intact	Grey		1/2	SW Stair Outside Storage 1	Negative	1.26	0.03	0.06	0.09
745	3/19/2019 15:19	mg/cm ²	Wall	Wood	B	Intact	White		1/2	SW Stairway to Main Floor	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
746	3/19/2019 15:20	mg/cm ²	Wall	Plaster	D	Intact	White		1/2	SW Stairway to Main Floor	Positive	3.47	0.5	0.5	1
747	3/19/2019 15:21	mg/cm ²	Stair Tread	Concrete	All	Deteriorated	Grey	Friction	1/2	SW Stairway to Main Floor	Negative		1	0	0.02
748	3/19/2019 15:21	mg/cm ²	Stair Riser	Concrete	All	Deteriorated	Grey	Impact	1/2	SW Stairway to Main Floor	Negative	1.34	0.05	0.08	0.13
749	3/19/2019 15:21	mg/cm ²	Stair Stringer	Metal	All	Intact	Brown		1/2	SW Stairway to Main Floor	Negative	1.43	0.13	0.13	0.26
750	3/19/2019 15:21	mg/cm ²	Stair Railing	Wood	All	Deteriorated	Brown	Friction	1/2	SW Stairway to Main Floor	Negative	1.82	0.01	0.06	0.07
751	3/19/2019 15:21	mg/cm ²	Stair Newell Post	Metal	All	Deteriorated	Brown	Impact	1/2	SW Stairway to Main Floor	Negative	2.33	0.11	0.15	0.26
752	3/19/2019 15:30	mg/cm ²	Wall	Drywall	A	Intact	Brown		1/2	Storage 2	Negative	1	0	0.02	0.02
753	3/19/2019 15:30	mg/cm ²	Wall	Drywall	B	Intact	White		1/2	Storage 2	Negative	1.28	0	0.02	0.02
754	3/19/2019 15:30	mg/cm ²	Wall	Drywall	C	Intact	White		1/2	Storage 2	Negative	1	0	0.02	0.02
755	3/19/2019 15:30	mg/cm ²	Wall	Drywall	D	Intact	Brown		1/2	Storage 2	Negative	1	0	0.02	0.02
756	3/19/2019 15:31	mg/cm ²	Ceiling	Drywall	All	Intact	White		1/2	Storage 2	Negative	1	0	0.02	0.02
757	3/19/2019 15:31	mg/cm ²	Floor	Carpet	All	Intact	Brown		1/2	Storage 2	Negative	1	0	0.02	0.02
758	3/19/2019 15:31	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1/2	Storage 2	Negative	1	0	0.02	0.02
759	3/19/2019 15:31	mg/cm ²	Radiator	Metal	C	Deteriorated	Beige	Chipping	1/2	Storage 2	Negative	6.49	0.16	0.12	0.28
760	3/19/2019 15:32	mg/cm ²	Window Casing/Header	Wood	All	Intact	Stain		1/2	Storage 2	Negative	1	0	0.02	0.02
761	3/19/2019 15:32	mg/cm ²	Window Sash	Wood	All	Intact	Stain		1/2	Storage 2	Negative	1	0	0.02	0.02
762	3/19/2019 15:32	mg/cm ²	Window Sill	Wood	All	Intact	Stain		1/2	Storage 2	Negative	1	0	0.02	0.02
763	3/19/2019 15:32	mg/cm ²	Window Jamb	Vinyl	All	Intact	White		1/2	Storage 2	Negative	1	0	0.02	0.02
764	3/19/2019 15:33	mg/cm ²	Window Trough	Metal	All	Intact	Brown		1/2	Storage 2	Negative	1	0	0.02	0.02
765	3/19/2019 15:35	mg/cm ²	Wall	Drywall	A	Intact	White		1/2	Storage 3	Negative	1	0	0.02	0.02
766	3/19/2019 15:35	mg/cm ²	Wall	Drywall	B	Intact	White		1/2	Storage 3	Negative	1	0	0.02	0.02
767	3/19/2019 15:35	mg/cm ²	Wall	Drywall	C	Intact	White		1/2	Storage 3	Negative	1	0	0.02	0.02
768	3/19/2019 15:35	mg/cm ²	Wall	Drywall	D	Intact	White		1/2	Storage 3	Negative	1	0	0.02	0.02
769	3/19/2019 15:35	mg/cm ²	Ceiling	Drywall	All	Deteriorated	White	Cracking	1/2	Storage 3	Negative	1	0	0.02	0.02
770	3/19/2019 15:35	mg/cm ²	Floor	Carpet	All	Intact	Brown		1/2	Storage 3	Negative	1	0	0.02	0.02
771	3/19/2019 15:36	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1/2	Storage 3	Negative	1	0	0.02	0.02
772	3/19/2019 15:36	mg/cm ²	Window Casing/Header	Wood	C	Intact	Stain		1/2	Storage 3	Negative	1	0	0.02	0.02
773	3/19/2019 15:36	mg/cm ²	Window Sash	Wood	C	Intact	Stain		1/2	Storage 3	Negative	1	0	0.02	0.02
774	3/19/2019 15:38	mg/cm ²	Window Sill	Wood	C	Intact	Stain		1/2	Storage 3	Negative	1	0	0.02	0.02
775	3/19/2019 15:39	mg/cm ²	Window Jamb	Vinyl	C	Intact	White		1/2	Storage 3	Negative	1	0	0.02	0.02
776	3/19/2019 15:39	mg/cm ²	Window Trough	Metal	C	Intact	Brown		1/2	Storage 3	Negative	1	0	0.02	0.02
777	3/19/2019 15:39	mg/cm ²	Cabinet Face	Wood	D	Intact	Stain		1/2	Storage 3	Negative	1	0	0.02	0.02
778	3/19/2019 15:39	mg/cm ²	Cabinet Door	Wood	D	Intact	Stain		1/2	Storage 3	Negative	1	0	0.02	0.02
779	3/19/2019 15:39	mg/cm ²	Wall Behind Cabinet	Plaster	D	Deteriorated	Beige	Chipping	1/2	Storage 3	Negative	3.52	0	0	0
780	3/19/2019 15:40	mg/cm ²	Baseboard Behind Cabinet	Wood	D	Deteriorated	Black	Chipping	1/2	Storage 3	Negative	1.21	0.08	0.14	0.22
781	3/19/2019 15:42	mg/cm ²	Wall	Drywall	B	Intact	Beige		1/2	Stairway to Conference 1	Negative	1	0	0.02	0.02
782	3/19/2019 15:42	mg/cm ²	Wall	Drywall	D	Intact	Beige		1/2	Stairway to Conference 1	Negative	1	0	0.02	0.02
783	3/19/2019 15:42	mg/cm ²	Stair Tread	Carpet	All	Intact	Blue		1/2	Stairway to Conference 1	Negative	1	0	0.02	0.02
784	3/19/2019 15:42	mg/cm ²	Stair Riser	Carpet	All	Intact	Blue		1/2	Stairway to Conference 1	Negative	1	0	0.02	0.02
785	3/19/2019 15:47	mg/cm ²	Wall	Drywall	A	Intact	Beige		1	Conference 1	Negative	1	0	0.02	0.02
786	3/19/2019 15:47	mg/cm ²	Wall	Drywall	B	Intact	Beige		1	Conference 1	Negative	1	0	0.02	0.02
787	3/19/2019 15:47	mg/cm ²	Wall	Drywall	C	Intact	Beige		1	Conference 1	Negative	1	0	0.02	0.02
788	3/19/2019 15:48	mg/cm ²	Wall	Drywall	D	Intact	Beige		1	Conference 1	Negative	1	0	0.02	0.02
789	3/19/2019 15:48	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Conference 1	Negative	1	0	0.02	0.02
790	3/19/2019 15:48	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Conference 1	Negative	1	0	0.03	0.03
791	3/19/2019 15:49	mg/cm ²	Window Casing/Header	Wood	D	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
792	3/19/2019 15:49	mg/cm ²	Window Sash	Wood	D	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
793	3/19/2019 15:49	mg/cm ²	Window Sill	Wood	D	Intact	Stain		1	Conference 1	Negative	1.24	0	0.03	0.03
794	3/19/2019 15:49	mg/cm ²	Window Jamb	Vinyl	D	Intact	White		1	Conference 1	Negative	1	0	0.02	0.02
795	3/19/2019 15:50	mg/cm ²	Window Trough	Metal	D	Intact	Brown		1	Conference 1	Negative	1	0	0.02	0.02
796	3/19/2019 15:50	mg/cm ²	Exterior Door Casing/Header	Wood	D	Deteriorated	Beige	Impact	1	Conference 1	Negative	1	0	0.02	0.02
797	3/19/2019 15:50	mg/cm ²	Exterior Door Sidelight Sill	Wood	D	Intact	Beige		1	Conference 1	Negative	1	0.02	0.06	0.08
798	3/19/2019 15:50	mg/cm ²	Exterior Door Jamb	Wood	D	Deteriorated	Beige	Friction	1	Conference 1	Negative	1	0	0.02	0.02
799	3/19/2019 15:50	mg/cm ²	Exterior Door Stop	Wood	D	Deteriorated	Beige	Impact	1	Conference 1	Negative	1	0	0.02	0.02
800	3/19/2019 15:51	mg/cm ²	Exterior Door	Metal	D	Deteriorated	White	Friction/Impact	1	Conference 1	Negative	1	0	0.02	0.02
801	3/19/2019 15:51	mg/cm ²	Exterior Door Sidelight Jamb	Wood	D	Intact	Beige		1	Conference 1	Negative	2.44	0.09	0.16	0.25
802	3/19/2019 15:54	mg/cm ²	Wall Above Drop Ceiling	Plaster	D	Deteriorated	Beige	Cracking	1	Conference 1	Negative	2.92	0.29	0.1	0.39
803	3/19/2019 15:56	mg/cm ²	Wall Above Drop Ceiling	Plaster	B	Deteriorated	Beige	Cracking	1	Conference 1	Positive	9.64	3.9	2.6	6.5
804	3/19/2019 15:56	mg/cm ²	Wall Above Drop Ceiling	Plaster	B	Deteriorated	Yellow	Cracking	1	Conference 1	Negative	2.5	0.23	0.07	0.3

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
805	3/19/2019 15:57	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Yellow	Cracking	1	Conference 1	Positive	7.77	4.2	3.1	7.3
806	3/19/2019 16:01	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
807	3/19/2019 16:02	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
808	3/19/2019 16:02	mg/cm ²	Door Stop	Wood	A	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
809	3/19/2019 16:02	mg/cm ²	Door	Wood	A	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
810	3/19/2019 16:02	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
811	3/19/2019 16:02	mg/cm ²	Door Jamb	Wood	B	Intact	Stain		1	Conference 1	Negative	1	0	0.02	0.02
812	3/19/2019 16:02	mg/cm ²	Door Stop	Wood	B	Intact	Stain		1	Conference 1	Negative	1	0	0.04	0.04
813	3/19/2019 16:02	mg/cm ²	Door	Metal	B	Intact	Grey		1	Conference 1	Negative	1	0	0.02	0.02
814	3/19/2019 16:03	mg/cm ²	Vault Door Casing/Header	Metal	B	Intact	Beige		1	Conference 1	Positive	5.2	12.1	10.8	22.9
815	3/19/2019 16:03	mg/cm ²	Vault Door Jamb	Metal	B	Deteriorated	Green	Friction	1	Conference 1	Positive	1.25	1.4	0.3	1.7
816	3/19/2019 16:03	mg/cm ²	Vault Door	Metal	B	Deteriorated	Beige	Friction/Impact	1	Conference 1	Positive	3.54	14.8	11.7	26.5
817	3/19/2019 16:03	mg/cm ²	Vault Door Threshold	Metal	B	Deteriorated	Green	Friction	1	Conference 1	Negative	2.86	0.02	0.06	0.08
818	3/19/2019 16:07	mg/cm ²	Wall	Concrete	A	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	2.09	0.15	0.83	0.98
819	3/19/2019 16:07	mg/cm ²	Wall	Concrete	B	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1.17	0.02	0.02	0.04
820	3/19/2019 16:07	mg/cm ²	Wall	Concrete	C	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1	0.02	0.07	0.09
821	3/19/2019 16:07	mg/cm ²	Wall	Concrete	D	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1.38	0.03	0.04	0.07
822	3/19/2019 16:08	mg/cm ²	Floor	Concrete	All	Deteriorated	Beige	Friction	1	Conference 1 Vault	Negative	1	0	0.02	0.02
823	3/19/2019 16:08	mg/cm ²	Door Casing/Header	Metal	D	Deteriorated	White	Impact	1	Conference 1 Vault	Negative	5.1	0.13	0.3	0.43
824	3/19/2019 16:08	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1	0	0.02	0.02
825	3/19/2019 16:08	mg/cm ²	Shelf	Wood	A	Deteriorated	Beige	Friction	1	Conference 1 Vault	Negative	1	0	0.02	0.02
826	3/19/2019 16:08	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1	0	0.02	0.02
827	3/19/2019 16:08	mg/cm ²	Shelf Support	Wood	B	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1	0	0.02	0.02
828	3/19/2019 16:08	mg/cm ²	Shelf	Wood	D	Deteriorated	Beige	Friction	1	Conference 1 Vault	Negative	1	0	0.02	0.02
829	3/19/2019 16:09	mg/cm ²	Cabinet Frame	Wood	D	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1	0.01	0.05	0.06
830	3/19/2019 16:09	mg/cm ²	Cabinet Base	Wood	D	Deteriorated	Beige	Impact	1	Conference 1 Vault	Negative	1.28	0.03	0.08	0.11
831	3/19/2019 16:09	mg/cm ²	Cabinet Face	Wood	D	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1.21	0.01	0.06	0.07
832	3/19/2019 16:10	mg/cm ²	Cabinet Crown Molding	Wood	D	Deteriorated	Beige	Cracking	1	Conference 1 Vault	Negative	1.67	0.01	0.06	0.07
833	3/19/2019 16:12	mg/cm ²	Wall Above Drop Ceiling	Concrete	All	Deteriorated	Brown	Cracking	1	Conference 1 Vault	Negative	2.03	0.3	0.69	0.99
834	3/19/2019 16:12	mg/cm ²	Ceiling Above Drop Ceiling	Concrete	All	Deteriorated	Brown	Cracking	1	Conference 1 Vault	Negative	1.59	0.03	0.02	0.05
835	3/19/2019 16:15	mg/cm ²	Radiator	Metal	A	Deteriorated	Grey	Chipping	1	Conference 1	Negative	2.5	0.4	0.3	0.7
836	3/19/2019 16:17	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	1	Conference 1 Hallway	Negative	6.84	0.2	0.26	0.46
837	3/19/2019 16:17	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	1	Conference 1 Hallway	Negative	3.84	0.03	0.96	0.99
838	3/19/2019 16:18	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	1	Conference 1 Hallway	Negative	10	0.3	0.69	0.99
839	3/19/2019 16:18	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	1	Conference 1 Hallway	Negative	1.94	0	0.03	0.03
840	3/19/2019 16:20	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Conference 1 Hallway	Negative	5.32	0.16	0.82	0.98
841	3/19/2019 16:21	mg/cm ²	Door Casing/Header	Wood	A	Intact	Dark Brown		1	Conference 1 Hallway	Negative	1	0.03	0.09	0.12
842	3/19/2019 16:21	mg/cm ²	Door Jamb	Wood	A	Intact	Dark Brown		1	Conference 1 Hallway	Negative	1.83	0.12	0.21	0.33
843	3/19/2019 16:21	mg/cm ²	Door Stop	Wood	A	Intact	Dark Brown		1	Conference 1 Hallway	Negative	3.5	0.08	0.27	0.35
844	3/19/2019 16:21	mg/cm ²	Door Jamb	Wood	A	Intact	Brown		1	Conference 1 Hallway	Negative	3.02	0.29	0.32	0.61
845	3/19/2019 16:21	mg/cm ²	Door	Wood	A	Intact	Dark Brown		1	Conference 1 Hallway	Negative	1	0.04	0.09	0.13
846	3/19/2019 16:23	mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Dark Brown	Impact	1	Conference 1 Hallway	Negative	1	0.02	0.05	0.07
847	3/19/2019 16:23	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Dark Brown	Friction	1	Conference 1 Hallway	Negative	1	0.01	0.03	0.04
848	3/19/2019 16:23	mg/cm ²	Door Stop	Wood	B	Deteriorated	Dark Brown	Impact	1	Conference 1 Hallway	Negative	1.35	0.02	0.08	0.1
849	3/19/2019 16:28	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Conference 2	Negative	1	0	0.02	0.02
850	3/19/2019 16:28	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Conference 2	Negative	1	0	0.02	0.02
851	3/19/2019 16:28	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Conference 2	Negative	1.46	0	0.02	0.02
852	3/19/2019 16:29	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Conference 2	Negative	1	0	0.02	0.02
853	3/19/2019 16:29	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Conference 2	Negative	1	0	0.02	0.02
854	3/19/2019 16:29	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Conference 2	Negative	1	0	0.02	0.02
855	3/19/2019 16:29	mg/cm ²	Window Casing/Header	Wood	D	Intact	Stain		1	Conference 2	Negative	1	0	0.02	0.02
856	3/19/2019 16:29	mg/cm ²	Window Sash	Wood	D	Intact	Stain		1	Conference 2	Negative	1	0	0.02	0.02
857	3/19/2019 16:29	mg/cm ²	Window Sill	Wood	D	Intact	Stain		1	Conference 2	Negative	1	0	0.02	0.02
858	3/19/2019 16:29	mg/cm ²	Window Jamb	Vinyl	D	Intact	White		1	Conference 2	Negative	1	0	0.02	0.02
859	3/19/2019 16:30	mg/cm ²	Window Trough	Metal	D	Intact	Brown		1	Conference 2	Negative	1	0	0.02	0.02
860	3/19/2019 16:35	mg/cm ²	Radiator Cover Frame	Metal	D	Intact	Brown		1	Conference 2	Negative	1.6	0.08	0.12	0.2
861	3/19/2019 16:35	mg/cm ²	Radiator	Metal	D	Deteriorated	Grey	Chipping	1	Conference 2	Negative	2.65	0.4	0.3	0.7
862	3/19/2019 16:37	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Green	Cracking	1	Conference 2	Negative	2.31	0.11	0.1	0.21
863	3/19/2019 16:43	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	1	Storage 4	Negative	10	0	0	0

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
864	3/19/2019 16:43	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	1	Storage 4	Negative	2.92	0.08	0.11	0.19
865	3/19/2019 16:43	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	1	Storage 4	Negative	4.26	0	0	0
866	3/19/2019 16:43	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	1	Storage 4	Negative	10	0	0	0
867	3/19/2019 16:44	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Brown	Impact	1	Storage 4	Negative	3.6	0.26	0.33	0.59
868	3/19/2019 16:44	mg/cm ²	Door	Wood	C	Deteriorated	Black	Friction/Impact	1	Storage 4	Negative	1.47	0.07	0.1	0.17
869	3/19/2019 16:44	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	Storage 4	Negative	7.29	0.14	0.84	0.98
870	3/19/2019 16:45	mg/cm ²	Wall	Plaster	A	Intact	Green		1	Storage 4 Restroom	Negative	6.11	0.24	0.72	0.96
871	3/19/2019 16:49	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	1	Storage 4 Restroom	Negative	8.43	0	0	0
872	3/19/2019 16:49	mg/cm ²	Wall	Plaster	B	Intact	Green		1	Storage 4 Restroom	Positive	4.78	0.4	0.6	1
873	3/19/2019 16:49	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	1	Storage 4 Restroom	Negative	2.73	0	0	0
874	3/19/2019 16:50	mg/cm ²	Wall	Plaster	C	Intact	Green		1	Storage 4 Restroom	Negative	3.26	0.08	0.07	0.15
875	3/19/2019 16:50	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	1	Storage 4 Restroom	Negative	3.53	0.12	0.13	0.25
876	3/19/2019 16:50	mg/cm ²	Wall	Drywall	D	Intact	Green		1	Storage 4 Restroom	Negative	1	0	0.02	0.02
877	3/19/2019 16:50	mg/cm ²	Wall	Drywall	D	Deteriorated	White	Cracking	1	Storage 4 Restroom	Negative	1	0	0.02	0.02
878	3/19/2019 16:50	mg/cm ²	Sink Tile	Ceramic	B	Deteriorated	White	Cracking	1	Storage 4 Restroom	Positive	2.68	5.2	3.3	8.5
879	3/19/2019 16:50	mg/cm ²	Pillar	Wood	B	Deteriorated	White	Cracking	1	Storage 4 Restroom	Negative	1	0	0.02	0.02
880	3/19/2019 16:50	mg/cm ²	Cabinet Face	Wood	B	Deteriorated	White	Impact	1	Storage 4 Restroom	Negative	1.79	0.04	0.09	0.13
881	3/19/2019 16:51	mg/cm ²	Cabinet Door	Wood	B	Deteriorated	White	Friction/Impact	1	Storage 4 Restroom	Negative	3.86	0.13	0.25	0.38
882	3/19/2019 16:51	mg/cm ²	Cabinet Interior	Wood	B	Deteriorated	Beige	Cracking	1	Storage 4 Restroom	Negative	1.25	0.06	0.09	0.15
883	3/19/2019 16:51	mg/cm ²	Cabinet Shelf	Wood	B	Deteriorated	Beige	Friction	1	Storage 4 Restroom	Negative	1.81	0.06	0.1	0.16
884	3/19/2019 16:51	mg/cm ²	Door Casing/Header	Wood	D	Deteriorated	Green	Impact	1	Storage 4 Restroom	Negative	2.02	0.08	0.13	0.21
885	3/19/2019 16:51	mg/cm ²	Door Lamb	Wood	D	Deteriorated	Green	Friction	1	Storage 4 Restroom	Negative	1.76	0.1	0.13	0.23
886	3/19/2019 16:51	mg/cm ²	Door Stop	Wood	D	Deteriorated	Brown	Impact	1	Storage 4 Restroom	Negative	2.82	0.14	0.21	0.35
887	3/19/2019 16:51	mg/cm ²	Door Lamb	Wood	D	Deteriorated	Brown	Friction	1	Storage 4 Restroom	Negative	3.31	0.11	0.21	0.32
888	3/19/2019 16:51	mg/cm ²	Door	Wood	D	Deteriorated	Green	Friction	1	Storage 4 Restroom	Negative	1.78	0.03	0.08	0.11
889	3/19/2019 16:52	mg/cm ²	Ceiling	Plaster	All	Intact	Green		1	Storage 4 Restroom	Negative	3.37	0.05	0.88	0.93
890	3/19/2019 16:52	mg/cm ²	Vent	Metal	All	Intact	Green		1	Storage 4 Restroom	Negative	1	0	0.02	0.02
891	3/19/2019 16:53	mg/cm ²	Pillar	Wood	B	Intact	Green		1	Storage 4 Restroom	Negative	1	0	0.02	0.02
892	3/19/2019 16:53	mg/cm ²	Pipe	Metal	All	Intact	Green		1	Storage 4 Restroom	Negative	5.07	0.07	0.22	0.29
893	3/19/2019 16:53	mg/cm ²	Pipe	Metal	All	Intact	White		1	Storage 4 Restroom	Negative	7	0.1	0.32	0.42
894	3/19/2019 16:58	mg/cm ²	Wall	Drywall	A	Deteriorated	Yellow	Cracking	1	Conference 3	Negative	1	0	0.02	0.02
895	3/19/2019 16:58	mg/cm ²	Wall	Drywall	B	Intact	Yellow		1	Conference 3	Negative	1	0	0.02	0.02
896	3/19/2019 16:58	mg/cm ²	Wall	Plaster	C	Deteriorated	Orange	Cracking	1	Conference 3	Positive	6.14	0.2	0.8	1
897	3/19/2019 16:58	mg/cm ²	Wall	Drywall	D	Intact	Yellow		1	Conference 3	Negative	1	0	0.02	0.02
898	3/19/2019 16:59	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Conference 3	Positive	10	1	0.2	1.2
899	3/19/2019 17:00	mg/cm ²	Window Casing/Header	Wood	D	Intact	Black		1	Conference 3	Negative	1.22	0.14	0.17	0.31
900	3/19/2019 17:00	mg/cm ²	Window Inside Stop	Wood	D	Intact	Black		1	Conference 3	Negative	1.79	0.2	0.19	0.39
901	3/19/2019 17:00	mg/cm ²	Window Sill	Ceramic	D	Intact	Black		1	Conference 3	Negative	1.3	0.02	0.02	0.04
902	3/19/2019 17:00	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		1	Conference 3	Negative	1	0.01	0.04	0.05
903	3/19/2019 17:01	mg/cm ²	Door Lamb	Wood	B	Intact	Stain		1	Conference 3	Negative	1	0.01	0.04	0.05
904	3/19/2019 17:01	mg/cm ²	Door Stop	Wood	B	Intact	Stain		1	Conference 3	Negative	2.16	0.09	0.21	0.3
905	3/19/2019 17:01	mg/cm ²	Door	Wood	B	Intact	Stain		1	Conference 3	Negative	1	0.01	0.03	0.04
906	3/19/2019 17:03	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Conference 3	Negative	3.4	0	0	0
907	3/19/2019 17:03	mg/cm ²	Ceiling Tile Above Drop Ceiling	Wood	All	Intact	White		1	Conference 3	Negative	1	0	0.02	0.02
908	3/19/2019 17:04	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	White		1	Conference 3	Negative	1	0	0.02	0.02
909	3/19/2019 17:04	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	White		1	Conference 3	Negative	6.58	0.08	0.28	0.36
910	3/19/2019 17:06	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Conference 3	Negative	5.43	0	0	0
911	3/19/2019 17:07	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Conference 3	Negative	3.42	0.09	0.03	0.12
912	3/19/2019 17:12	mg/cm ²	Wall	Plaster	A	Intact	Beige		1	Admin Waiting	Negative	1.18	0.03	0.06	0.09
913	3/19/2019 17:12	mg/cm ²	Wall	Drywall	B	Intact	Beige		1	Admin Waiting	Negative	1	0	0.02	0.02
914	3/19/2019 17:13	mg/cm ²	Wall	Drywall	C	Intact	Beige		1	Admin Waiting	Negative	1.42	0	0.02	0.02
915	3/19/2019 17:13	mg/cm ²	Wall	Wood	D	Intact	Beige		1	Admin Waiting	Negative	2.36	0.07	0.14	0.21
916	3/19/2019 17:13	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Admin Waiting	Negative	4.09	0.04	0.14	0.18
917	3/19/2019 17:13	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin Waiting	Negative	1	0	0.02	0.02
918	3/19/2019 17:13	mg/cm ²	Door Casing/Header	Wood	All	Intact	Stain		1	Admin Waiting	Negative	1	0	0.02	0.02
919	3/19/2019 17:13	mg/cm ²	Door Lamb	Wood	All	Intact	Stain		1	Admin Waiting	Negative	1	0	0.02	0.02
920	3/19/2019 17:13	mg/cm ²	Door Stop	Wood	All	Intact	Stain		1	Admin Waiting	Negative	1	0	0.02	0.02
921	3/19/2019 17:13	mg/cm ²	Door	Wood	All	Intact	Stain		1	Admin Waiting	Negative	1	0	0.02	0.02
922	3/19/2019 17:15	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Admin Waiting	Negative	1.43	0.06	0.09	0.15

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
923	3/19/2019 17:17	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Waiting	Negative	1.57	0.05	0.09	0.14
924	3/19/2019 17:19	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Admin Waiting	Negative	2.97	0.18	0.24	0.42
925	3/19/2019 17:19	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Stain		1	Admin Waiting	Negative	1.37	0.11	0.12	0.23
926	3/19/2019 17:19	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Waiting	Negative	3.79	0.15	0.09	0.24
927	3/19/2019 17:23	mg/cm ²	Wall	Drywall	A	Intact	Yellow		1	Admin Office 1	Negative	1	0.05	0.07	0.12
928	3/19/2019 17:23	mg/cm ²	Wall	Drywall	A	Intact	Blue		1	Admin Office 1	Negative	6.02	0.27	0.47	0.74
929	3/19/2019 17:24	mg/cm ²	Wall	Drywall	B	Intact	Yellow		1	Admin Office 1	Negative	1	0	0.02	0.02
930	3/19/2019 17:24	mg/cm ²	Wall	Drywall	B	Intact	Blue		1	Admin Office 1	Negative	1	0	0.02	0.02
931	3/19/2019 17:24	mg/cm ²	Wall	Drywall	C	Intact	Yellow		1	Admin Office 1	Negative	1	0	0.02	0.02
932	3/19/2019 17:24	mg/cm ²	Wall	Drywall	C	Intact	Blue		1	Admin Office 1	Negative	1	0	0.02	0.02
933	3/19/2019 17:24	mg/cm ²	Wall	Drywall	D	Intact	Yellow		1	Admin Office 1	Negative	2.84	0.09	0.18	0.27
934	3/19/2019 17:24	mg/cm ²	Wall	Drywall	D	Intact	Blue		1	Admin Office 1	Negative	5.5	0.21	0.39	0.6
935	3/19/2019 17:25	mg/cm ²	Chair Rail	Wood	All	Intact	Stain		1	Admin Office 1	Negative	1	0	0.02	0.02
936	3/19/2019 17:25	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Admin Office 1	Negative	3.26	0.03	0.1	0.13
937	3/19/2019 17:26	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin Office 1	Negative	1	0	0.02	0.02
938	3/19/2019 17:27	mg/cm ²	Baseboard Heater	Metal	All	Intact	Blue		1	Admin Office 1	Negative	1.75	0.02	0.05	0.07
939	3/19/2019 17:27	mg/cm ²	Window Casing/Header	Wood	All	Intact	Stain		1	Admin Office 1	Negative	1.22	0.08	0.1	0.18
940	3/19/2019 17:27	mg/cm ²	Window Inside Stop	Wood	All	Intact	Stain		1	Admin Office 1	Negative	1	0.08	0.09	0.17
941	3/19/2019 17:27	mg/cm ²	Window Sill	Ceramic	All	Intact	Grey		1	Admin Office 1	Negative	1.56	0	0.02	0.02
942	3/19/2019 17:28	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	1	Admin Office 1	Negative	3.2	0.25	0.22	0.47
943	3/19/2019 17:28	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	1	Admin Office 1	Negative	3.34	0.15	0.23	0.38
944	3/19/2019 17:28	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	White	Cracking	1	Admin Office 1	Negative	1.25	0.05	0.07	0.12
945	3/19/2019 17:28	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Stain		1	Admin Office 1	Negative	1.29	0.1	0.11	0.21
946	3/19/2019 17:32	mg/cm ²	Wall	Drywall	A	Intact	Yellow		1	Admin Restroom Hall	Negative	3.25	0.05	0.1	0.15
947	3/19/2019 17:32	mg/cm ²	Wall	Drywall	B	Intact	Yellow		1	Admin Restroom Hall	Negative	2.21	0.03	0.07	0.1
948	3/19/2019 17:32	mg/cm ²	Wall	Drywall	C	Intact	Yellow		1	Admin Restroom Hall	Negative	7.86	0.13	0.23	0.36
949	3/19/2019 17:33	mg/cm ²	Wall	Drywall	D	Intact	Yellow		1	Admin Restroom Hall	Negative	2.13	0.04	0.06	0.1
950	3/19/2019 17:33	mg/cm ²	Floor	Ceramic	All	Intact	Blue		1	Admin Restroom Hall	Negative	1	0	0.02	0.02
951	3/19/2019 17:33	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin Restroom Hall	Negative	1	0	0.02	0.02
952	3/19/2019 17:36	mg/cm ²	Wall	Plaster	A	Intact	Yellow		1	Admin Restroom	Positive	10	3.3	1.4	4.7
953	3/19/2019 17:36	mg/cm ²	Wall	Plaster	B	Intact	Yellow		1	Admin Restroom	Positive	10	2.9	1.4	4.3
954	3/19/2019 17:36	mg/cm ²	Wall	Plaster	C	Intact	Yellow		1	Admin Restroom	Positive	6.14	0.5	0.5	1
955	3/19/2019 17:37	mg/cm ²	Wall	Plaster	D	Intact	Yellow		1	Admin Restroom	Positive	8.87	2.2	1.1	3.3
956	3/19/2019 17:37	mg/cm ²	Wainscoting	Ceramic	All	Intact	Grey		1	Admin Restroom	Negative	1	0	0.02	0.02
957	3/19/2019 17:37	mg/cm ²	Floor	Vinyl	All	Intact	Grey		1	Admin Restroom	Negative	1	0	0.02	0.02
958	3/19/2019 17:37	mg/cm ²	Radiator	Metal	D	Intact	Brown		1	Admin Restroom	Positive	2.55	1.1	0.2	1.3
959	3/19/2019 17:37	mg/cm ²	Window Casing/Header	Wood	D	Intact	Stain		1	Admin Restroom	Negative	1.39	0.06	0.09	0.15
960	3/19/2019 17:38	mg/cm ²	Window Inside Stop	Wood	D	Intact	Stain		1	Admin Restroom	Negative	1	0.02	0.05	0.07
961	3/19/2019 17:38	mg/cm ²	Window Sill	Wood	D	Intact	Grey		1	Admin Restroom	Negative	2.79	0	0	0
962	3/19/2019 17:38	mg/cm ²	Door Jamb	Ceramic	B	Intact	Stain		1	Admin Restroom	Negative	1.52	0.06	0.14	0.2
963	3/19/2019 17:38	mg/cm ²	Door Stop	Wood	B	Intact	Stain		1	Admin Restroom	Negative	1	0.04	0.07	0.11
964	3/19/2019 17:38	mg/cm ²	Door	Wood	B	Intact	Stain		1	Admin Restroom	Negative	3.14	0.4	0.3	0.7
965	3/19/2019 17:39	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Admin Restroom	Positive	6.7	4.4	2.9	7.3
966	3/19/2019 17:42	mg/cm ²	Wall	Wood	A	Intact	Yellow		1	Admin N Hall	Negative	1	0.02	0.04	0.06
967	3/19/2019 17:42	mg/cm ²	Wall	Wood	B	Intact	Yellow		1	Admin N Hall	Negative	2.42	0.07	0.14	0.21
968	3/19/2019 17:42	mg/cm ²	Wall	Wood	C	Intact	Yellow		1	Admin N Hall	Negative	1.07	0.02	0.04	0.06
969	3/19/2019 17:42	mg/cm ²	Wall	Wood	D	Intact	Yellow		1	Admin N Hall	Negative	5.55	0.27	0.46	0.73
970	3/19/2019 17:43	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Admin N Hall	Negative	1	0	0.02	0.02
971	3/19/2019 17:43	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin N Hall	Negative	1	0	0.03	0.03
972	3/19/2019 17:45	mg/cm ²	Closet Wall	Drywall	All	Intact	White		1	Admin N Hall	Negative	1	0	0.02	0.02
973	3/19/2019 17:45	mg/cm ²	Closet Wall	Drywall	All	Intact	Beige		1	Admin N Hall	Negative	1	0	0.02	0.02
974	3/19/2019 17:45	mg/cm ²	Closet Shelf Support	Wood	All	Intact	Beige		1	Admin N Hall	Negative	1	0	0.02	0.02
975	3/19/2019 17:46	mg/cm ²	Closet Shelf	Wood	All	Intact	Beige		1	Admin N Hall	Negative	1	0	0.02	0.02
976	3/19/2019 17:51	mg/cm ²	Wall	Drywall	A	Intact	Yellow		1	Admin Vault Hall	Negative	1	0	0.02	0.02
977	3/19/2019 17:51	mg/cm ²	Wall	Drywall	B	Intact	Yellow		1	Admin Vault Hall	Negative	1	0	0.02	0.02
978	3/19/2019 17:51	mg/cm ²	Wall	Drywall	C	Intact	Yellow		1	Admin Vault Hall	Negative	1	0	0.02	0.02
979	3/19/2019 17:51	mg/cm ²	Wall	Drywall	D	Intact	Yellow		1	Admin Vault Hall	Negative	1	0	0.02	0.02
980	3/19/2019 17:52	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Admin Vault Hall	Negative	6.06	0.05	0.2	0.25
981	3/19/2019 17:52	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin Vault Hall	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
982	3/19/2019 17:52	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		1	Admin Vault Hall	Negative	1	0	0.02	0.02
983	3/19/2019 17:52	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		1	Admin Vault Hall	Negative	1	0	0.02	0.02
984	3/19/2019 17:52	mg/cm ²	Door Stop	Wood	D	Intact	Stain		1	Admin Vault Hall	Negative	1	0	0.02	0.02
985	3/19/2019 17:52	mg/cm ²	Door	Wood	D	Intact	Stain		1	Admin Vault Hall	Negative	1	0	0.02	0.02
986	3/19/2019 17:53	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Yellow		1	Admin Vault Hall	Negative	2.55	0.16	0.16	0.32
987	3/19/2019 17:53	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Vault Hall	Negative	2.68	0.16	0.21	0.37
988	3/19/2019 17:56	mg/cm ²	Vault Door Casing/Header	Metal	B	Intact	Beige		1	Admin Vault Hall	Positive	6.03	14.6	11.7	26.3
989	3/19/2019 17:56	mg/cm ²	Vault Door Jamb	Metal	B	Deteriorated	Green	Friction	1	Admin Vault Hall	Positive	1.39	1.9	0.8	2.7
990	3/19/2019 17:56	mg/cm ²	Vault Door	Metal	B	Deteriorated	Beige	Friction/Impact	1	Admin Vault Hall	Positive	5.99	17.4	12.1	29.5
991	3/19/2019 17:56	mg/cm ²	Vault Door Threshold	Metal	B	Deteriorated	Green	Friction	1	Admin Vault Hall	Negative	1.32	0.8	0.1	0.9
992	3/19/2019 17:58	mg/cm ²	Wall	Concrete	A	Intact	White		1	Admin Vault	Negative	1.76	0.04	0.02	0.06
993	3/19/2019 17:58	mg/cm ²	Wall	Concrete	B	Intact	White		1	Admin Vault	Negative	2.19	0.26	0.73	0.99
994	3/19/2019 17:58	mg/cm ²	Wall	Concrete	C	Intact	White		1	Admin Vault	Negative	2.09	0	0	0
995	3/19/2019 17:58	mg/cm ²	Wall	Concrete	C	Intact	White		1	Admin Vault	Positive	2.07	0.4	0.6	1
996	3/19/2019 17:59	mg/cm ²	Ceiling	Concrete	All	Intact	White		1	Admin Vault	Negative	3.3	0.3	0.64	0.94
997	3/19/2019 17:59	mg/cm ²	Door Casing/Header	Metal	D	Intact	White		1	Admin Vault	Negative	1.89	0.01	0.05	0.06
998	3/19/2019 17:59	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	White		1	Admin Vault	Negative	1	0.02	0.04	0.06
999	3/19/2019 17:59	mg/cm ²	Shelf Support	Wood	A	Deteriorated	White		1	Admin Vault	Negative	5.08	0.15	0.32	0.47
1000	3/19/2019 17:59	mg/cm ²	Shelf	Wood	A	Deteriorated	White		1	Admin Vault	Negative	2.02	0.08	0.13	0.21
1001	3/19/2019 18:04	mg/cm ²	Wall	Wood	A	Intact	Yellow		1	Admin Office 3	Negative	4.63	0.26	0.34	0.6
1002	3/19/2019 18:04	mg/cm ²	Wall	Wood	B	Intact	Yellow		1	Admin Office 3	Negative	2.91	0.17	0.24	0.41
1003	3/19/2019 18:05	mg/cm ²	Wall	Drywall	C	Intact	Yellow		1	Admin Office 3	Negative	1	0	0.02	0.02
1004	3/19/2019 18:05	mg/cm ²	Wall	Drywall	D	Intact	Yellow		1	Admin Office 3	Negative	1	0	0.02	0.02
1005	3/19/2019 18:05	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Admin Office 3	Negative	4.11	0.05	0.05	0.1
1006	3/19/2019 18:05	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin Office 3	Negative	1	0	0.02	0.02
1007	3/19/2019 18:05	mg/cm ²	Door Casing/Header	Wood	C	Intact	Stain		1	Admin Office 3	Negative	1	0	0.02	0.02
1008	3/19/2019 18:05	mg/cm ²	Door Jamb	Wood	C	Intact	Stain		1	Admin Office 3	Negative	1	0	0.02	0.02
1009	3/19/2019 18:05	mg/cm ²	Door Stop	Wood	C	Intact	Stain		1	Admin Office 3	Negative	1	0	0.02	0.02
1010	3/19/2019 18:06	mg/cm ²	Door	Wood	C	Intact	Stain		1	Admin Office 3	Negative	1	0	0.02	0.02
1011	3/19/2019 18:06	mg/cm ²	Baseboard Heater	Metal	All	Intact	Yellow		1	Admin Office 3	Negative	1.12	0.01	0.04	0.05
1012	3/19/2019 18:06	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		1	Admin Office 3	Negative	1	0.07	0.11	0.18
1013	3/19/2019 18:06	mg/cm ²	Window Inside Stop	Wood	A	Intact	Stain		1	Admin Office 3	Negative	1	0.1	0.1	0.2
1014	3/19/2019 18:06	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		1	Admin Office 3	Negative	1	0	0.02	0.02
1015	3/19/2019 18:07	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Admin Office 3	Negative	1.7	0.11	0.1	0.21
1016	3/19/2019 18:07	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Office 3	Negative	3.55	0.2	0.73	0.93
1017	3/19/2019 18:07	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Office 3	Negative	2.68	0	0	0
1018	3/19/2019 18:07	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Stain		1	Admin Office 3	Negative	1	0.05	0.07	0.12
1019	3/19/2019 18:11	mg/cm ²	Wall	Drywall	A	Intact	Yellow		1	Admin Office 2	Negative	3.23	0.03	0.12	0.15
1020	3/19/2019 18:12	mg/cm ²	Wall	Drywall	B	Intact	Yellow		1	Admin Office 2	Negative	1	0	0.02	0.02
1021	3/19/2019 18:12	mg/cm ²	Wall	Drywall	C	Intact	Yellow		1	Admin Office 2	Negative	1	0	0.02	0.02
1022	3/19/2019 18:12	mg/cm ²	Wall	Drywall	D	Intact	Yellow		1	Admin Office 2	Negative	1.52	0.01	0.04	0.05
1023	3/19/2019 18:12	mg/cm ²	Floor	Carpet	All	Intact	Blue		1	Admin Office 2	Negative	1	0	0.02	0.02
1024	3/19/2019 18:12	mg/cm ²	Baseboard	Wood	All	Intact	Stain		1	Admin Office 2	Negative	1	0	0.02	0.02
1025	3/19/2019 18:12	mg/cm ²	Baseboard Heater	Metal	All	Intact	Yellow		1	Admin Office 2	Negative	1.28	0.01	0.04	0.05
1026	3/19/2019 18:12	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		1	Admin Office 2	Negative	1.27	0.11	0.16	0.27
1027	3/19/2019 18:12	mg/cm ²	Window Inside Stop	Wood	A	Intact	Stain		1	Admin Office 2	Negative	1.17	0.13	0.12	0.25
1028	3/19/2019 18:13	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		1	Admin Office 2	Negative	1	0	0.02	0.02
1029	3/19/2019 18:13	mg/cm ²	Door Casing/Header	Wood	C	Intact	Stain		1	Admin Office 2	Negative	1	0	0.02	0.02
1030	3/19/2019 18:13	mg/cm ²	Door Jamb	Wood	C	Intact	Stain		1	Admin Office 2	Negative	1	0	0.02	0.02
1031	3/19/2019 18:13	mg/cm ²	Door Stop	Wood	C	Intact	Stain		1	Admin Office 2	Negative	1	0	0.02	0.02
1032	3/19/2019 18:13	mg/cm ²	Door	Wood	C	Intact	Stain		1	Admin Office 2	Negative	1	0	0.02	0.02
1033	3/19/2019 18:15	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Admin Office 2	Negative	2.69	0.22	0.25	0.47
1034	3/19/2019 18:16	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Office 2	Negative	2.75	0.16	0.16	0.32
1035	3/19/2019 18:16	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Admin Office 2	Negative	3.12	0.1	0.16	0.26
1036	3/19/2019 18:16	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Brown		1	Admin Office 2	Negative	1.47	0.5	0.4	0.9
1037	3/19/2019 18:29	mg/cm ²	Wall	Plaster	B	Intact	Grey		1	Lobby W Hall	Positive	7.88	1.7	0.6	2.3
1038	3/19/2019 18:30	mg/cm ²	Wall	Plaster	D	Intact	Grey		1	Lobby W Hall	Positive	10	1.2	0.2	1.4
1039	3/19/2019 18:32	mg/cm ²	Column Frame	Plaster	All	Intact	White		1	Lobby W Hall	Positive	10	1.2	0.3	1.5
1040	3/19/2019 18:33	mg/cm ²	Column Panel	Plaster	All	Intact	Beige		1	Lobby W Hall	Negative	4.54	0.02	0.03	0.05

Fort Dodge City Hall - Total XRF Results

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1041	3/19/2019 18:33	mg/cm ²	Column Baseboard	Ceramic	All	Intact	Black		1	Lobby W Hall	Negative	1	0	0.02	0.02
1042	3/19/2019 18:33	mg/cm ²	Baseboard	Wood	C/D	Deteriorated	Black	Impact	1	Lobby W Hall	Negative	1.21	0.01	0.04	0.05
1043	3/19/2019 18:34	mg/cm ²	Floor	Concrete	All	Intact	Grey		1	Lobby W Hall	Negative	1	0	0.02	0.02
1044	3/19/2019 18:34	mg/cm ²	Floor	Concrete	All	Intact	Brown		1	Lobby W Hall	Negative	1	0	0.02	0.02
1045	3/19/2019 18:34	mg/cm ²	Floor	Ceramic	All	Intact	Grey		1	Lobby W Hall	Negative	1	0	0.02	0.02
1046	3/19/2019 18:35	mg/cm ²	Hose Case Casing	Wood	B	Intact	Stain		1	Lobby W Hall	Positive	1.19	0.7	0.3	1
1047	3/19/2019 18:35	mg/cm ²	Hose Case Frame	Metal	B	Intact	Brown		1	Lobby W Hall	Negative	1.27	0.17	0.22	0.39
1048	3/19/2019 18:35	mg/cm ²	Hose Case Door	Metal	B	Intact	Brown		1	Lobby W Hall	Negative	1.22	0.16	0.2	0.36
1049	3/19/2019 18:35	mg/cm ²	Wall	Plaster	C	Intact	Grey		1	Lobby W Hall	Positive	10	7.4	4.6	12
1050	3/19/2019 18:36	mg/cm ²	Door Casing/Header	Wood	D	Deteriorated	Black	Impact	1	Lobby W Hall	Negative	1	0	0.02	0.02
1051	3/19/2019 18:36	mg/cm ²	Door	Wood	D	Intact	Stain		1	Lobby W Hall	Negative	1	0	0.02	0.02
1052	3/19/2019 18:37	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Lobby W Hall	Positive	10	0.4	0.6	1
1053	3/19/2019 18:38	mg/cm ²	Crown Molding	Plaster	All	Intact	White		1	Lobby W Hall	Positive	10	1.2	0.5	1.7
1054	3/19/2019 18:40	mg/cm ²	Wall	Plaster	A	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	2.17	0.08	0.1	0.18
1055	3/19/2019 18:40	mg/cm ²	Wall	Plaster	B	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	2.04	0.11	0.15	0.26
1056	3/19/2019 18:40	mg/cm ²	Wall	Plaster	C	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	2.27	0.1	0.15	0.25
1057	3/19/2019 18:40	mg/cm ²	Wall	Plaster	D	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	2.43	0.11	0.17	0.28
1058	3/19/2019 18:40	mg/cm ²	Baseboard	Wood	All	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	1.15	0.03	0.06	0.09
1059	3/19/2019 18:40	mg/cm ²	Shelf Support	Wood	C	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	2.19	0.11	0.14	0.25
1060	3/19/2019 18:40	mg/cm ²	Shelf	Wood	C	Deteriorated	Yellow	Chipping	1	Lobby W Hall Closet	Negative	1.66	0.05	0.1	0.15
1061	3/19/2019 18:41	mg/cm ²	Panel Frame	Metal	A	Deteriorated	Grey	Friction	1	Lobby W Hall Closet	Negative	1	0.2	0.19	0.39
1062	3/19/2019 18:41	mg/cm ²	Panel Door	Metal	A	Deteriorated	Grey	Friction/Impact	1	Lobby W Hall Closet	Negative	1	0.11	0.14	0.25
1063	3/19/2019 18:41	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Yellow	Impact	1	Lobby W Hall Closet	Negative	1.21	0.03	0.06	0.09
1064	3/19/2019 18:42	mg/cm ²	Door Casing/Header	Wood	D	Deteriorated	Stain		1	Lobby W Hall Closet	Negative	1.11	0.1	0.07	0.13
1065	3/19/2019 18:42	mg/cm ²	Door Jamb	Wood	D	Deteriorated	Stain	Friction	1	Lobby W Hall Closet	Negative	1.11	0.1	0.11	0.21
1066	3/19/2019 18:42	mg/cm ²	Door Stop	Wood	D	Deteriorated	Stain	Impact	1	Lobby W Hall Closet	Negative	1	0.02	0.04	0.06
1067	3/19/2019 18:42	mg/cm ²	Door	Wood	D	Deteriorated	Stain	Friction/Impact	1	Lobby W Hall Closet	Negative	1	0	0.02	0.02
1068	3/19/2019 18:43	mg/cm ²	Wall	Plaster	A	Intact	White		1	SW Stairway Hall	Negative	4.07	0.3	0.07	0.37
1069	3/19/2019 18:47	mg/cm ²	Wall	Plaster	B	Intact	White		1	SW Stairway Hall	Positive	5.72	2.6	1.4	4
1070	3/19/2019 18:47	mg/cm ²	Wall	Wood	C	Intact	White		1	SW Stairway Hall	Negative	1	0	0.02	0.02
1071	3/19/2019 18:47	mg/cm ²	Wall	Plaster	D	Intact	White		1	SW Stairway Hall	Negative	2.08	0.22	0.13	0.35
1072	3/19/2019 18:47	mg/cm ²	Radiator	Metal	A	Deteriorated	White	Chipping	1	SW Stairway Hall	Positive	5.15	1	0.2	1.2
1073	3/19/2019 18:47	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	1	SW Stairway Hall	Negative	1	0	0.02	0.02
1074	3/19/2019 18:48	mg/cm ²	Baseboard	Wood	All	Deteriorated	Brown	Impact	1	SW Stairway Hall	Negative	1	0.01	0.05	0.06
1075	3/19/2019 18:48	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Brown	Impact	1	SW Stairway Hall	Negative	2.98	0.03	0.11	0.14
1076	3/19/2019 18:48	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Brown	Impact	1	SW Stairway Hall	Negative	1.93	0.22	0.21	0.43
1077	3/19/2019 18:48	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Brown	Friction	1	SW Stairway Hall	Negative	2.69	0.3	0.44	0.74
1078	3/19/2019 18:48	mg/cm ²	Door Stop	Wood	B	Deteriorated	Brown	Impact	1	SW Stairway Hall	Negative	2.66	0.29	0.41	0.7
1079	3/19/2019 18:48	mg/cm ²	Closet Door	Wood	A	Deteriorated	White	Friction/Impact	1	SW Stairway Hall	Negative	1	0	0.02	0.02
1080	3/19/2019 18:48	mg/cm ²	Stair Tread	Concrete	All	Deteriorated	Grey	Friction	1	SW Stairway	Negative	1	0	0.02	0.02
1081	3/19/2019 18:48	mg/cm ²	Stair Riser	Metal	All	Deteriorated	Grey	Impact	1	SW Stairway	Negative	2.84	0.05	0.12	0.17
1082	3/19/2019 18:49	mg/cm ²	Stair Stringer	Metal	All	Intact	Brown		1	SW Stairway	Negative	1.21	0.04	0.07	0.11
1083	3/19/2019 18:49	mg/cm ²	Stair Railing	Wood	All	Deteriorated	Brown	Friction	1	SW Stairway	Negative	1	0.01	0.04	0.05
1084	3/19/2019 18:49	mg/cm ²	Stair Spindles	Metal	All	Intact	White		1	SW Stairway	Negative	1.38	0.02	0.05	0.07
1085	3/19/2019 18:49	mg/cm ²	Stair Newell Post	Metal	All	Deteriorated	Brown	Impact	1	SW Stairway	Negative	1.54	0.05	0.08	0.13
1086	3/19/2019 18:50	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	SW Stairway	Negative	8.75	0	0	0
1087	3/19/2019 18:51	mg/cm ²	Window Casing/Header	Wood	B	Intact	Black		1	SW Stairway	Negative	1.58	0.05	0.12	0.17
1088	3/19/2019 18:51	mg/cm ²	Window Inside Stop	Wood	B	Intact	Black		1	SW Stairway	Negative	1.43	0.07	0.1	0.17
1089	3/19/2019 18:51	mg/cm ²	Window Sill	Ceramic	B	Intact	Brown		1	SW Stairway	Negative	1	0.01	0.02	0.03
1090	3/19/2019 18:51	mg/cm ²	Stair Lower Wall	Wood	D	Intact	White		1	SW Stairway	Positive	4.04	2.5	1.3	3.8
CAL	3/19/2019 18:52	mg/cm ²										1.2	0.9	0.1	1
CAL	3/19/2019 18:53	mg/cm ²										1.1	0.8	0.2	1
CAL	3/19/2019 18:53	mg/cm ²										1.16	0.9	0.1	1
CAL	3/19/2019 18:55	cps										13.12	0	13.12	0
CAL	3/20/2019 7:32	cps										12.98	0	12.98	0
CAL	3/20/2019 7:32	mg/cm ²										1.09	0.8	0.2	1
CAL	3/20/2019 7:32	mg/cm ²										1.96	5.7	4.1	9.8
CAL	3/20/2019 7:33	mg/cm ²										1.63	4.1	2.8	6.9
1091	3/20/2019 7:37	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Billing Storage	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1092	3/20/2019 7:37	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Billing Storage	Negative	1	0	0.02	0.02
1093	3/20/2019 7:37	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Billing Storage	Negative	9.36	0	0	0
1094	3/20/2019 7:37	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Billing Storage	Negative	1	0	0.02	0.02
1095	3/20/2019 7:38	mg/cm ²	Door Casing/Header	Wood	B	Intact	Stain		1	Billing Storage	Negative	1	0	0.02	0.02
1096	3/20/2019 7:38	mg/cm ²	Door Jamb	Wood	B	Intact	Stain		1	Billing Storage	Negative	1	0	0.02	0.02
1097	3/20/2019 7:38	mg/cm ²	Door Stop	Wood	B	Intact	Stain		1	Billing Storage	Negative	1	0	0.02	0.02
1098	3/20/2019 7:38	mg/cm ²	Door	Wood	B	Intact	Stain		1	Billing Storage	Negative	1	0	0.02	0.02
1099	3/20/2019 7:38	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Billing Storage	Negative	1	0	0.02	0.02
1100	3/20/2019 7:39	mg/cm ²	Electrical Panel Backer	Wood	D	Intact	Black		1	Billing Storage	Negative	1	0	0.02	0.02
1101	3/20/2019 7:39	mg/cm ²	Baseboard	Wood	D	Intact	Beige		1	Billing Storage	Negative	1	0	0.02	0.02
1102	3/20/2019 7:40	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	1	Billing Storage	Negative	3.37	0.07	0.07	0.14
1103	3/20/2019 7:41	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Green		1	Billing Storage	Negative	3.12	0.16	0.23	0.39
1104	3/20/2019 7:41	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Green		1	Billing Storage	Negative	1.68	0.08	0.12	0.2
1105	3/20/2019 7:45	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Billing Workroom	Negative	1	0	0.02	0.02
1106	3/20/2019 7:45	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Billing Workroom	Negative	1	0	0.02	0.02
1107	3/20/2019 7:46	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Billing Workroom	Negative	1	0	0.02	0.02
1108	3/20/2019 7:46	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Billing Workroom	Negative	1	0	0.02	0.02
1109	3/20/2019 7:46	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Billing Workroom	Negative	1	0	0.02	0.02
1110	3/20/2019 7:46	mg/cm ²	Radiator	Metal	C	Intact	Brown		1	Billing Workroom	Negative	7.3	0.18	0.35	0.53
1111	3/20/2019 7:46	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Stain	Cracking	1	Billing Workroom	Negative	1	0.07	0.11	0.18
1112	3/20/2019 7:47	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Stain	Cracking	1	Billing Workroom	Negative	1.34	0.11	0.12	0.23
1113	3/20/2019 7:47	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey		1	Billing Workroom	Negative	1	0	0.02	0.02
1114	3/20/2019 7:47	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		1	Billing Workroom	Negative	1	0	0.02	0.02
1115	3/20/2019 7:47	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		1	Billing Workroom	Negative	1	0	0.03	0.03
1116	3/20/2019 7:47	mg/cm ²	Door Stop	Wood	A	Intact	Stain		1	Billing Workroom	Negative	1	0	0.02	0.02
1117	3/20/2019 7:47	mg/cm ²	Door	Wood	A	Intact	Stain		1	Billing Workroom	Negative	1	0	0.02	0.02
1118	3/20/2019 7:48	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	1	Billing Workroom	Negative	2.56	0.05	0.09	0.14
1119	3/20/2019 7:50	mg/cm ²	Wall Above Drop Ceiling	Plaster	C	Deteriorated	Green	Cracking	1	Billing Workroom	Negative	3.25	0	0	0
1120	3/20/2019 7:51	mg/cm ²	Wall	Drywall	A	Intact	Beige		1	Billing Main Office	Negative	1	0	0.02	0.02
1121	3/20/2019 7:51	mg/cm ²	Wall	Drywall	B	Intact	Beige		1	Billing Main Office	Negative	1	0	0.02	0.02
1122	3/20/2019 7:55	mg/cm ²	Wall	Drywall	C	Intact	Beige		1	Billing Main Office	Negative	1	0	0.02	0.02
1123	3/20/2019 7:55	mg/cm ²	Wall	Drywall	D	Intact	Beige		1	Billing Main Office	Negative	1	0	0.02	0.02
1124	3/20/2019 7:56	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Billing Main Office	Negative	1	0	0.02	0.02
1125	3/20/2019 7:56	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Stain	Cracking	1	Billing Main Office	Negative	1	0.06	0.11	0.17
1126	3/20/2019 7:56	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Stain	Cracking	1	Billing Main Office	Negative	1.51	0.27	0.27	0.54
1127	3/20/2019 7:56	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey		1	Billing Main Office	Negative	1	0	0.02	0.02
1128	3/20/2019 7:56	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		1	Billing Main Office	Negative	1	0	0.02	0.02
1129	3/20/2019 7:57	mg/cm ²	Window Jamb	Wood	A	Intact	Stain		1	Billing Main Office	Negative	1	0	0.03	0.03
1130	3/20/2019 7:57	mg/cm ²	Window Sill	Wood	A	Intact	Stain		1	Billing Main Office	Negative	1	0	0.03	0.03
1131	3/20/2019 7:57	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		1	Billing Main Office	Negative	1	0	0.02	0.02
1132	3/20/2019 7:57	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		1	Billing Main Office	Negative	1	0	0.02	0.02
1133	3/20/2019 7:57	mg/cm ²	Door Stop	Wood	D	Intact	Stain		1	Billing Main Office	Negative	1	0	0.02	0.02
1134	3/20/2019 7:57	mg/cm ²	Door	Wood	D	Intact	Stain		1	Billing Main Office	Negative	1	0	0.03	0.03
1135	3/20/2019 7:59	mg/cm ²	Wall Above Drop Ceiling	Plaster	C	Intact	Green		1	Billing Main Office	Negative	3.49	0.27	0.32	0.59
1136	3/20/2019 7:59	mg/cm ²	Wall Above Drop Ceiling	Plaster	C	Intact	Beige		1	Billing Main Office	Negative	2.39	0	0	0
1137	3/20/2019 7:59	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Billing Main Office	Negative	2.16	0	0	0
1138	3/20/2019 8:00	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Green		1	Billing Main Office	Negative	3.46	0.27	0.34	0.61
1139	3/20/2019 8:04	mg/cm ²	Wall	Plaster	A	Intact	Beige		1	Billing Office	Negative	10	0.27	0.72	0.99
1140	3/20/2019 8:05	mg/cm ²	Wall	Plaster	B	Intact	Beige		1	Billing Office	Negative	10	0	0	0
1141	3/20/2019 8:05	mg/cm ²	Wall	Plaster	C	Intact	Beige		1	Billing Office	Negative	4.93	0	0	0
1142	3/20/2019 8:05	mg/cm ²	Wall	Plaster	D	Intact	Beige		1	Billing Office	Negative	8.36	0.05	0.94	0.99
1143	3/20/2019 8:05	mg/cm ²	Floor	Carpet	All	Intact	Beige		1	Billing Office	Negative	1	0	0.02	0.02
1144	3/20/2019 8:05	mg/cm ²	Window Casing/Header	Wood	C	Deteriorated	Stain	Cracking	1	Billing Office	Negative	1.19	0.1	0.15	0.25
1145	3/20/2019 8:06	mg/cm ²	Window Inside Stop	Wood	C	Deteriorated	Stain	Cracking	1	Billing Office	Negative	1	0.09	0.13	0.22
1146	3/20/2019 8:06	mg/cm ²	Window Sill	Ceramic	C	Intact	Grey		1	Billing Office	Negative	1	0	0.02	0.02
1147	3/20/2019 8:06	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		1	Billing Office	Negative	1.24	0.01	0.06	0.07
1148	3/20/2019 8:06	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		1	Billing Office	Negative	1.61	0.02	0.08	0.1
1149	3/20/2019 8:06	mg/cm ²	Door Stop	Wood	D	Intact	Stain		1	Billing Office	Negative	4.37	0.06	0.19	0.25
1150	3/20/2019 8:06	mg/cm ²	Door	Wood	D	Intact	Stain		1	Billing Office	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1151	3/20/2019 8:07	mg/cm ²	Radiator	Metal	C	Intact	White		1	Billing Office	Negative	1.59	0.12	0.13	0.25
1152	3/20/2019 8:08	mg/cm ²	Wall Above Drop Ceiling	Plaster	D	Deteriorated	Green	Cracking	1	Billing Office	Negative	3.24	0.27	0.3	0.57
1153	3/20/2019 8:08	mg/cm ²	Wall Above Drop Ceiling	Plaster	D	Deteriorated	Brown	Cracking	1	Billing Office	Negative	3.76	0.3	0.24	0.54
1154	3/20/2019 8:08	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	White	Cracking	1	Billing Office	Negative	2.05	0	0	0
1155	3/20/2019 8:09	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	Stain	Cracking	1	Billing Office	Negative	1	0.06	0.07	0.13
1156	3/20/2019 8:13	mg/cm ²	Wall	Plaster	A	Intact	Grey		1	Lobby Hall	Negative	10	0	0	0
1157	3/20/2019 8:14	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Lobby Hall	Negative	10	0.6	0.2	0.8
1158	3/20/2019 8:14	mg/cm ²	Crown Molding	Plaster	All	Intact	White		1	Lobby Hall	Negative	5.37	0.4	0.4	0.8
1159	3/20/2019 8:17	mg/cm ²	Wall	Drywall	B	Intact	Grey		1	Lobby Hall	Negative	1	0	0.02	0.02
1160	3/20/2019 8:17	mg/cm ²	Wall	Drywall	C	Intact	Grey		1	Lobby Hall	Negative	1	0	0.02	0.02
1161	3/20/2019 8:18	mg/cm ²	Wall	Plaster	D	Intact	Grey		1	Lobby Hall	Negative	5.28	0.18	0.81	0.99
1162	3/20/2019 8:18	mg/cm ²	Wall Tile	Ceramic	D	Intact	Grey		1	Lobby Hall	Positive	3.17	4.7	3.2	7.9
1163	3/20/2019 8:22	mg/cm ²	Wall	Wood	A	Intact	Stain		1	Foyer	Negative	1	0.01	0.04	0.05
1164	3/20/2019 8:22	mg/cm ²	Wall	Plaster	B	Intact	Grey		1	Foyer	Positive	10	3.4	2.3	5.7
1165	3/20/2019 8:22	mg/cm ²	Wall	Plaster	D	Intact	Grey		1	Foyer	Positive	6.21	2.6	1.5	4.1
1166	3/20/2019 8:23	mg/cm ²	Ceiling	Drywall	All	Intact	White		1	Foyer	Negative	1	0	0.02	0.02
1167	3/20/2019 8:26	mg/cm ²	Wall	Ceramic	A	Intact	Brown		1	Front Entry	Negative	1	0	0.02	0.02
1168	3/20/2019 8:26	mg/cm ²	Wall	Ceramic	B	Intact	Brown		1	Front Entry	Negative	1	0	0.02	0.02
1169	3/20/2019 8:26	mg/cm ²	Wall	Ceramic	C	Intact	Brown		1	Front Entry	Negative	1	0	0.02	0.02
1170	3/20/2019 8:26	mg/cm ²	Wall	Ceramic	D	Intact	Brown		1	Front Entry	Negative	3.61	0	0	0
1171	3/20/2019 8:26	mg/cm ²	Vent Frame	Metal	A	Intact	Black		1	Front Entry	Negative	1.51	0.26	0.27	0.53
1172	3/20/2019 8:27	mg/cm ²	Ceiling	Plaster	All	Intact	White		1	Front Entry	Positive	10	7.9	4.6	12.5
1173	3/20/2019 8:27	mg/cm ²	Crown Molding	Plaster	All	Intact	White		1	Front Entry	Positive	10	5.3	3.7	9
1174	3/20/2019 8:33	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1175	3/20/2019 8:33	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1176	3/20/2019 8:33	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1177	3/20/2019 8:33	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1178	3/20/2019 8:34	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1179	3/20/2019 8:34	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1180	3/20/2019 8:34	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1181	3/20/2019 8:34	mg/cm ²	Door Stop	Wood	D	Intact	Stain		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1182	3/20/2019 8:34	mg/cm ²	Door	Wood	D	Intact	Stain		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1183	3/20/2019 8:35	mg/cm ²	Ceiling Lower Crown Molding	Plaster	All	Deteriorated	Beige	Cracking	1	Park and Rec Main Office	Negative	2.37	0.11	0.11	0.22
1184	3/20/2019 8:37	mg/cm ²	Radiator	Metal	A	Intact	Beige		1	Park and Rec Main Office	Negative	1	0.01	0.03	0.04
1185	3/20/2019 8:37	mg/cm ²	Wall	Plaster	A	Intact	Beige		1	Park and Rec Main Office	Negative	1.4	0.07	0.09	0.16
1186	3/20/2019 8:38	mg/cm ²	Ceiling	Plaster	All	Intact	Beige		1	Park and Rec Main Office	Negative	1.1	0.05	0.06	0.11
1187	3/20/2019 8:38	mg/cm ²	Crown Molding	Wood	All	Intact	Stain		1	Park and Rec Main Office	Negative	1.41	0.13	0.13	0.26
1188	3/20/2019 8:40	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		1	Park and Rec Main Office	Negative	1.26	0.1	0.11	0.21
1189	3/20/2019 8:40	mg/cm ²	Window Inside Stop	Wood	A	Intact	Stain		1	Park and Rec Main Office	Negative	1.18	0.09	0.1	0.19
1190	3/20/2019 8:41	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		1	Park and Rec Main Office	Negative	1	0	0.02	0.02
1191	3/20/2019 8:44	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1192	3/20/2019 8:44	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1193	3/20/2019 8:44	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1194	3/20/2019 8:44	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1195	3/20/2019 8:44	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1196	3/20/2019 8:45	mg/cm ²	Radiator	Metal	A/B	Intact	Brown		1	Park and Rec Office 2	Positive	6.59	2.8	1.4	4.2
1197	3/20/2019 8:45	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1198	3/20/2019 8:45	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1199	3/20/2019 8:45	mg/cm ²	Door Stop	Wood	D	Intact	Stain		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1200	3/20/2019 8:45	mg/cm ²	Door	Wood	D	Intact	Stain		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1201	3/20/2019 8:45	mg/cm ²	Window Casing/Header	Wood	A	Intact	Stain		1	Park and Rec Office 2	Negative	1.26	0.03	0.09	0.12
1202	3/20/2019 8:46	mg/cm ²	Window Inside Stop	Wood	A	Intact	Stain		1	Park and Rec Office 2	Negative	1.44	0.05	0.09	0.14
1203	3/20/2019 8:46	mg/cm ²	Window Sill	Ceramic	A	Intact	Grey		1	Park and Rec Office 2	Negative	1	0	0.02	0.02
1204	3/20/2019 8:46	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Park and Rec Office 2	Negative	3.49	0.28	0.7	0.98
1205	3/20/2019 8:47	mg/cm ²	Wall Above Drop Ceiling	Plaster	All	Intact	Beige		1	Park and Rec Office 2	Negative	4.44	0.4	0.5	0.9
1206	3/20/2019 8:47	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Park and Rec Office 2	Negative	2.89	0.18	0.81	0.99
1207	3/20/2019 8:47	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Intact	Beige		1	Park and Rec Office 2	Negative	2.37	0.3	0.28	0.58
1208	3/20/2019 8:47	mg/cm ²	Pipe	Metal	B	Deteriorated	Beige	Chipping	1	Park and Rec Office 2	Negative	1.7	0.3	0.22	0.52
1209	3/20/2019 8:53	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Park and Rec Office 1	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1210	3/20/2019 8:53	mg/cm^2	Wall	Drywall	B	Intact	Brown		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1211	3/20/2019 8:53	mg/cm^2	Wall	Drywall	C	Intact	Brown		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1212	3/20/2019 8:53	mg/cm^2	Wall	Drywall	D	Intact	Brown		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1213	3/20/2019 8:54	mg/cm^2	Floor	Carpet	All	Intact	Brown		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1214	3/20/2019 8:54	mg/cm^2	Radiator	Metal	A	Intact	Brown		1	Park and Rec Office 1	Positive	10	7.1	4.8	11.9
1215	3/20/2019 8:54	mg/cm^2	Window Casing/Header	Wood	A	Intact	Stain		1	Park and Rec Office 1	Negative	1.02	0.09	0.1	0.19
1216	3/20/2019 8:54	mg/cm^2	Window Inside Stop	Wood	A	Intact	Stain		1	Park and Rec Office 1	Negative	1.95	0.5	0.3	0.8
1217	3/20/2019 8:54	mg/cm^2	Window Sill	Ceramic	A	Intact	Grey		1	Park and Rec Office 1	Negative	1.85	0	0.02	0.02
1218	3/20/2019 8:54	mg/cm^2	Door Casing/Header	Wood	C	Intact	Stain		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1219	3/20/2019 8:54	mg/cm^2	Door Jamb	Wood	C	Intact	Stain		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1220	3/20/2019 8:54	mg/cm^2	Door Stop	Wood	C	Intact	Stain		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1221	3/20/2019 8:55	mg/cm^2	Door	Wood	C	Intact	Stain		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1222	3/20/2019 8:55	mg/cm^2	Ceiling	Wood	All	Intact	White		1	Park and Rec Office 1	Negative	1	0	0.02	0.02
1223	3/20/2019 9:00	mg/cm^2	Wall	Drywall	A	Intact	Brown		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1224	3/20/2019 9:00	mg/cm^2	Wall	Drywall	B	Intact	Brown		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1225	3/20/2019 9:01	mg/cm^2	Wall	Drywall	C	Intact	Brown		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1226	3/20/2019 9:01	mg/cm^2	Wall	Drywall	D	Intact	Brown		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1227	3/20/2019 9:01	mg/cm^2	Floor	Carpet	All	Intact	Brown		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1228	3/20/2019 9:01	mg/cm^2	Radiator	Metal	A	Intact	Brown		1	Park and Rec Workroom	Negative	3.52	0.23	0.29	0.52
1229	3/20/2019 9:01	mg/cm^2	Window Casing/Header	Wood	A	Intact	Stain		1	Park and Rec Workroom	Negative	1.45	0.14	0.15	0.29
1230	3/20/2019 9:01	mg/cm^2	Window Inside Stop	Wood	A	Intact	Stain		1	Park and Rec Workroom	Negative	1.13	0.11	0.11	0.22
1231	3/20/2019 9:01	mg/cm^2	Window Sill	Ceramic	A	Intact	Grey		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1232	3/20/2019 9:02	mg/cm^2	Door Casing/Header	Wood	C	Intact	Stain		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1233	3/20/2019 9:02	mg/cm^2	Door Jamb	Wood	C	Intact	Stain		1	Park and Rec Workroom	Negative	1	0	0.03	0.03
1234	3/20/2019 9:02	mg/cm^2	Door Stop	Wood	C	Intact	Stain		1	Park and Rec Workroom	Negative	1	0	0.02	0.02
1235	3/20/2019 9:02	mg/cm^2	Door	Wood	C	Intact	Stain		1	Park and Rec Workroom	Negative	1.48	0.01	0.06	0.07
1236	3/20/2019 9:03	mg/cm^2	Wall Above Drop Ceiling	Plaster	All	Intact	Brown		1	Park and Rec Workroom	Negative	2.35	0.3	0.24	0.54
1237	3/20/2019 9:03	mg/cm^2	Wall Above Drop Ceiling	Plaster	All	Intact	Brown		1	Park and Rec Workroom	Negative	1.51	0.06	0.1	0.16
1238	3/20/2019 9:03	mg/cm^2	Ceiling Above Drop Ceiling	Plaster	All	Intact	White		1	Park and Rec Workroom	Negative	2.24	0.12	0.16	0.28
1239	3/20/2019 9:04	mg/cm^2	Crown Molding Above Drop Ceiling	Wood	All	Intact	Brown		1	Park and Rec Workroom	Negative	1	0.08	0.09	0.17
1240	3/20/2019 9:07	mg/cm^2	Door Casing/Header	Metal	B	Intact	Beige		1	Park and Rec Vault	Negative	1	0	0.02	0.02
1241	3/20/2019 9:08	mg/cm^2	Door Jamb	Metal	B	Intact	Beige	Friction	1	Park and Rec Vault	Positive	2.4	1.5	0.5	2
1242	3/20/2019 9:08	mg/cm^2	Door	Metal	B	Intact	Black	Friction/Impact	1	Park and Rec Vault	Positive	2.23	17.7	12.8	30.5
1243	3/20/2019 9:08	mg/cm^2	Door Threshold	Metal	B	Deteriorated	Green	Friction	1	Park and Rec Vault	Negative	1.32	0.7	0.2	0.9
1244	3/20/2019 9:08	mg/cm^2	Wall	Concrete	A	Intact	Beige		1	Park and Rec Vault	Negative	3.17	0.09	0.86	0.95
1245	3/20/2019 9:08	mg/cm^2	Wall	Concrete	B	Intact	Beige		1	Park and Rec Vault	Negative	8.96	0.26	0.73	0.99
1246	3/20/2019 9:09	mg/cm^2	Wall	Concrete	C	Intact	Beige		1	Park and Rec Vault	Negative	2.6	0.03	0.02	0.05
1247	3/20/2019 9:09	mg/cm^2	Wall	Concrete	D	Intact	Beige		1	Park and Rec Vault	Negative	4.04	0.3	0.68	0.98
1248	3/20/2019 9:10	mg/cm^2	Ceiling	Concrete	All	Intact	Beige		1	Park and Rec Vault	Negative	3.03	0.04	0.03	0.07
1249	3/20/2019 9:10	mg/cm^2	Shelf	Wood	All	Intact	Beige		1	Park and Rec Vault	Negative	1	0	0.02	0.02
1250	3/20/2019 9:10	mg/cm^2	Vault Door Casing/Header	Metal	D	Intact	Black		1	Park and Rec W Hall	Positive	2.11	16.7	12.4	29.1
1251	3/20/2019 9:13	mg/cm^2	Wall	Plaster	A	Intact	Brown		1	Park and Rec Restroom	Negative	10	0.11	0.87	0.98
1252	3/20/2019 9:13	mg/cm^2	Wall	Plaster	B	Intact	Brown		1	Park and Rec Restroom	Negative	3.28	0.18	0.41	0.59
1253	3/20/2019 9:13	mg/cm^2	Wall	Plaster	C	Intact	Brown		1	Park and Rec Restroom	Negative	6.1	0.24	0.71	0.95
1254	3/20/2019 9:15	mg/cm^2	Wall	Plaster	D	Intact	Brown		1	Park and Rec Restroom	Negative	8.29	0	0.88	0.88
1255	3/20/2019 9:15	mg/cm^2	Wainscoting	Ceramic	All	Intact	Grey		1	Park and Rec Restroom	Negative	1	0	0.02	0.02
1256	3/20/2019 9:16	mg/cm^2	Floor	Vinyl	All	Intact	Grey		1	Park and Rec Restroom	Negative	1	0	0.02	0.02
1257	3/20/2019 9:16	mg/cm^2	Door Casing/Header	Wood	D	Intact	Stain		1	Park and Rec Restroom	Negative	1	0	0.02	0.02
1258	3/20/2019 9:16	mg/cm^2	Door Jamb	Wood	D	Intact	Stain		1	Park and Rec Restroom	Negative	1	0.01	0.03	0.04
1259	3/20/2019 9:16	mg/cm^2	Door Stop	Wood	D	Intact	Stain		1	Park and Rec Restroom	Negative	1	0	0.02	0.02
1260	3/20/2019 9:16	mg/cm^2	Door	Wood	D	Intact	Stain		1	Park and Rec Restroom	Negative	1	0	0.03	0.03
1261	3/20/2019 9:16	mg/cm^2	Window Casing/Header	Wood	B	Intact	Stain		1	Park and Rec Restroom	Negative	1	0.02	0.05	0.07
1262	3/20/2019 9:16	mg/cm^2	Window Inside Stop	Wood	B	Intact	Stain		1	Park and Rec Restroom	Negative	1.28	0.06	0.09	0.15
1263	3/20/2019 9:17	mg/cm^2	Window Sill	Ceramic	B	Intact	Grey		1	Park and Rec Restroom	Negative	1	0	0.02	0.02
1264	3/20/2019 9:17	mg/cm^2	Radiator	Metal	A	Intact	Grey		1	Park and Rec Restroom	Negative	2.01	0.23	0.3	0.53
1265	3/20/2019 9:19	mg/cm^2	Wall Above Drop Ceiling	Plaster	D	Intact	Green		1	Park and Rec Restroom	Negative	3.3	0.2	0.08	0.28
1266	3/20/2019 9:20	mg/cm^2	Wall Above Drop Ceiling	Plaster	D	Intact	Green		1	Park and Rec Restroom	Negative	1.28	0.06	0.13	0.19
1267	3/20/2019 9:22	mg/cm^2	Wall	Drywall	A	Intact	Brown		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1268	3/20/2019 9:22	mg/cm^2	Wall	Drywall	B	Intact	Brown		1	Park and Rec Storage	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1269	3/20/2019 9:23	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1270	3/20/2019 9:23	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1271	3/20/2019 9:23	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1272	3/20/2019 9:23	mg/cm ²	Door Casing/Header	Wood	D	Intact	Stain		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1273	3/20/2019 9:23	mg/cm ²	Door Jamb	Wood	D	Intact	Stain		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1274	3/20/2019 9:23	mg/cm ²	Door Stop	Wood	D	Intact	Stain		1	Park and Rec Storage	Negative	1	0	0.02	0.02
1275	3/20/2019 9:23	mg/cm ²	Door	Wood	D	Intact	Stain		1	Park and Rec Storage	Negative	1	0	0.03	0.03
1276	3/20/2019 9:24	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Beige	Cracking	1	Park and Rec Storage	Positive	1.7	4.8	3.7	8.5
1277	3/20/2019 9:28	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Council Chambers	Negative	1	0	0.02	0.02
1278	3/20/2019 9:28	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Council Chambers	Negative	1	0	0.03	0.03
1279	3/20/2019 9:29	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Council Chambers	Negative	1	0	0.02	0.02
1280	3/20/2019 9:29	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Council Chambers	Negative	1	0	0.02	0.02
1281	3/20/2019 9:32	mg/cm ²	Spiral Stair Railing	Metal	D	Intact	Brown		1	Council Chambers	Negative	1	0	0.02	0.02
1282	3/20/2019 9:32	mg/cm ²	Spiral Stair Wall	Brick	C	Intact	Brown		1	Council Chambers	Negative	2.43	0.2	0.22	0.42
1283	3/20/2019 9:34	mg/cm ²	Wall	Vinyl	A	Intact	White		1	Council Chambers Custodian	Negative	10	0	0	0
1284	3/20/2019 9:34	mg/cm ²	Wall	Vinyl	B	Intact	White		1	Council Chambers Custodian	Negative	1	0	0.03	0.03
1285	3/20/2019 9:34	mg/cm ²	Wall	Vinyl	C	Intact	White		1	Council Chambers Custodian	Negative	1	0	0.02	0.02
1286	3/20/2019 9:34	mg/cm ²	Wall	Brick	D	Intact	White		1	Council Chambers Custodian	Negative	1.81	0.18	0.12	0.3
1287	3/20/2019 9:34	mg/cm ²	Floor	Vinyl	All	Intact	Grey		1	Council Chambers Custodian	Negative	1	0	0.02	0.02
1288	3/20/2019 9:37	mg/cm ²	Wall	Ceramic	A	Intact	Brown		1	Council Chambers Restroom	Negative	4.85	0.13	0.44	0.57
1289	3/20/2019 9:37	mg/cm ²	Wall	Ceramic	B	Intact	Brown		1	Council Chambers Restroom	Negative	3.88	0.13	0.38	0.51
1290	3/20/2019 9:37	mg/cm ²	Wall	Ceramic	C	Intact	Brown		1	Council Chambers Restroom	Negative	3.34	0.08	0.29	0.37
1291	3/20/2019 9:38	mg/cm ²	Wall	Ceramic	D	Intact	Brown		1	Council Chambers Restroom	Negative	3.35	0.08	0.29	0.37
1292	3/20/2019 9:38	mg/cm ²	Floor	Ceramic	All	Intact	Brown		1	Council Chambers Restroom	Negative	4.21	0.11	0.25	0.36
1293	3/20/2019 9:41	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Chipping	1	Council Chambers Restroom	Positive	1.27	0.19	0.81	1
1294	3/20/2019 9:41	mg/cm ²	Wall Above Drop Ceiling	Brick	D	Deteriorated	Grey	Chipping	1	Council Chambers Restroom	Negative	1.53	0.2	0.14	0.34
1295	3/20/2019 9:45	mg/cm ²	Wall	Brick	A	Deteriorated	Grey	Chipping	1	SE Elevator Room	Negative	1.83	0.27	0.07	0.34
1296	3/20/2019 9:45	mg/cm ²	Wall	Concrete	B	Intact	Brown		1	SE Elevator Room	Negative	1	0	0.02	0.02
1297	3/20/2019 9:45	mg/cm ²	Wall	Concrete	C	Intact	Brown		1	SE Elevator Room	Negative	2.46	0.01	0.03	0.04
1298	3/20/2019 9:46	mg/cm ²	Wall	Concrete	D	Intact	Brown		1	SE Elevator Room	Negative	1	0	0.02	0.02
1299	3/20/2019 9:46	mg/cm ²	Floor	Ceramic	All	Intact	Brown		1	SE Elevator Room	Negative	6.89	0.21	0.42	0.63
1300	3/20/2019 9:46	mg/cm ²	Elevator Door Casing/Header	Wood	B	Intact	Stain		1	SE Elevator Room	Negative	1	0	0.02	0.02
1301	3/20/2019 9:46	mg/cm ²	Elevator Door Frame	Metal	B	Deteriorated	Brown	Friction	1	SE Elevator Room	Negative	1	0	0.02	0.02
1302	3/20/2019 9:46	mg/cm ²	Elevator Door	Metal	B	Deteriorated	Brown	Friction/Impact	1	SE Elevator Room	Negative	1	0	0.02	0.02
1303	3/20/2019 9:46	mg/cm ²	Doorway Upper Jamb	Metal	A	Intact	Brown		1	SE Elevator Room	Negative	5.28	0.02	0.13	0.15
1304	3/20/2019 9:48	mg/cm ²	Wall	Brick	A	Deteriorated	Grey	Cracking	1	SE Entry	Negative	1.69	0.08	0.05	0.13
1305	3/20/2019 9:52	mg/cm ²	Wall	Drywall	A	Intact	Brown		1	Council Chambers A/V Room	Negative	1	0	0.02	0.02
1306	3/20/2019 9:52	mg/cm ²	Wall	Drywall	B	Intact	Brown		1	Council Chambers A/V Room	Negative	1	0	0.02	0.02
1307	3/20/2019 9:52	mg/cm ²	Wall	Drywall	C	Intact	Brown		1	Council Chambers A/V Room	Negative	1	0	0.02	0.02
1308	3/20/2019 9:52	mg/cm ²	Wall	Drywall	D	Intact	Brown		1	Council Chambers A/V Room	Negative	1	0	0.02	0.02
1309	3/20/2019 9:53	mg/cm ²	Floor	Carpet	All	Intact	Brown		1	Council Chambers A/V Room	Negative	1	0	0.02	0.02
1310	3/20/2019 9:58	mg/cm ²	Door Casing/Header	Metal	C	Intact	Stain		1	Council Chambers A/V Room	Negative	2.02	0.01	0.03	0.04
1311	3/20/2019 9:58	mg/cm ²	Door	Wood	C	Intact	Stain		1	Council Chambers A/V Room	Negative	1	0	0.03	0.03
1312	3/20/2019 10:00	mg/cm ²	Stair Stringer	Metal	All	Intact	Beige		1	SE Stairway	Negative	4.42	0.02	0.13	0.15
1313	3/20/2019 10:00	mg/cm ²	Stair Railing	Metal	All	Intact	Brown		1	SE Stairway	Negative	1	0	0.02	0.02
1314	3/20/2019 10:03	mg/cm ²	Vault Door Casing/Header	Metal	B	Intact	Brown		1	Billing Main Office	Positive	5.98	14.4	11.7	26.1
1315	3/20/2019 10:03	mg/cm ²	Vault Door	Metal	B	Intact	Brown	Friction/Impact	1	Billing Main Office	Positive	4.9	17.3	12.9	30.2
1316	3/20/2019 10:03	mg/cm ²	Vault Door Jamb	Metal	B	Intact	Green	Friction	1	Billing Main Office	Positive	1.32	1.5	0.4	1.9
1317	3/20/2019 10:04	mg/cm ²	Vault Door Threshold	Metal	B	Deteriorated	Green	Friction	1	Billing Main Office	Positive	1.55	0.7	0.3	1
1318	3/20/2019 10:04	mg/cm ²	Wall	Concrete	A	Intact	White		1	Billing Vault	Positive	5.46	0.16	0.84	1
1319	3/20/2019 10:05	mg/cm ²	Wall	Concrete	B	Intact	White		1	Billing Vault	Negative	2.69	0.04	0.04	0.08
1320	3/20/2019 10:05	mg/cm ²	Wall	Concrete	C	Intact	White		1	Billing Vault	Negative	2.64	0.3	0.68	0.98
1321	3/20/2019 10:05	mg/cm ²	Wall	Concrete	D	Intact	White		1	Billing Vault	Negative	4.52	0.09	0.89	0.98
1322	3/20/2019 10:08	mg/cm ²	Door Casing/Header	Metal	D	Intact	Black		1	Billing Vault	Negative	1.75	0.06	0.14	0.2
1323	3/20/2019 10:10	mg/cm ²	Ceiling	Concrete	All	Intact	White		1	Billing Vault	Negative	2.65	0.04	0.07	0.11
1324	3/20/2019 10:23	mg/cm ²	Wall	Plaster	A	Intact	White		1	SW Entry Hall	Positive	4.56	3.9	1.9	5.8
1325	3/20/2019 10:23	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	1	SW Entry Hall	Positive	3.59	4.5	3.1	7.6
1326	3/20/2019 10:23	mg/cm ²	Wall	Plaster	C	Intact	White		1	SW Entry Hall	Positive	3.91	4.9	3.5	8.4
1327	3/20/2019 10:23	mg/cm ²	Wall	Drywall	D	Intact	White		1	SW Entry Hall	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1328	3/20/2019 10:24	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	SW Entry Hall	Positive	8.95	13.9	10.8	24.7
1329	3/20/2019 10:24	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	1	SW Entry Hall	Negative	1.54	0.01	0.03	0.04
1330	3/20/2019 10:24	mg/cm ²	Baseboard	Wood	All	Intact	Brown		1	SW Entry Hall	Negative	2.73	0.09	0.23	0.32
1331	3/20/2019 10:24	mg/cm ²	Shoe Molding	Wood	All	Intact	Brown		1	SW Entry Hall	Negative	2.18	0.09	0.2	0.29
1332	3/20/2019 10:24	mg/cm ²	Window Casing/Header	Wood	B	Intact	Black		1	SW Entry Hall	Negative	1.14	0.07	0.12	0.19
1333	3/20/2019 10:24	mg/cm ²	Window Inside Stop	Wood	B	Intact	Black		1	SW Entry Hall	Negative	1	0.02	0.05	0.07
1334	3/20/2019 10:25	mg/cm ²	Window Sill	Ceramic	B	Intact	Grey		1	SW Entry Hall	Negative	3.08	0	0	0
1335	3/20/2019 10:26	mg/cm ²	Crown Molding	Wood	All	Intact	White		1	SW Entry Hall	Negative	1	0	0.02	0.02
1336	3/20/2019 10:27	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Brown	Impact	1	SW Entry Hall	Negative	1	0.03	0.08	0.11
1337	3/20/2019 10:27	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Brown	Friction	1	SW Entry Hall	Negative	1.28	0.06	0.09	0.15
1338	3/20/2019 10:27	mg/cm ²	Door Stop	Wood	A	Deteriorated	Brown	Impact	1	SW Entry Hall	Negative	1	0.05	0.07	0.12
1339	3/20/2019 10:27	mg/cm ²	Door Casing/Header	Wood	D	Intact	Brown		1	SW Entry Hall	Negative	1	0	0.02	0.02
1340	3/20/2019 10:27	mg/cm ²	Door Jamb	Wood	D	Intact	Brown		1	SW Entry Hall	Negative	1	0	0.02	0.02
1341	3/20/2019 10:27	mg/cm ²	Door Stop	Wood	D	Intact	Brown		1	SW Entry Hall	Negative	1	0	0.02	0.02
1342	3/20/2019 10:27	mg/cm ²	Door	Wood	D	Intact	Stain		1	SW Entry Hall	Negative	1	0	0.02	0.02
1343	3/20/2019 10:28	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Brown	Impact	1	SW Entry Hall	Negative	1	0.03	0.08	0.11
1344	3/20/2019 10:28	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Brown	Friction	1	SW Entry Hall	Negative	4.25	0.05	0.17	0.22
1345	3/20/2019 10:28	mg/cm ²	Door Stop	Wood	C	Deteriorated	Brown	Impact	1	SW Entry Hall	Positive	2.97	26	23.8	49.8
1346	3/20/2019 10:32	mg/cm ²	Wall	Brick	A	Intact	White		1	SW Entry	Negative	2.22	0.01	0.02	0.03
1347	3/20/2019 10:32	mg/cm ²	Wall	Brick	B	Intact	White		1	SW Entry	Negative	1	0	0.02	0.02
1348	3/20/2019 10:32	mg/cm ²	Wall	Wood	C	Intact	Stain		1	SW Entry	Negative	1	0	0.02	0.02
1349	3/20/2019 10:32	mg/cm ²	Wall	Brick	D	Intact	White		1	SW Entry	Negative	1.07	0	0.02	0.02
1350	3/20/2019 10:32	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	SW Entry	Negative	2.17	0.02	0.05	0.07
1351	3/20/2019 10:33	mg/cm ²	Crown Molding	Wood	All	Intact	White		1	SW Entry	Negative	2.77	0.08	0.16	0.24
1352	3/20/2019 10:33	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	1	SW Entry	Negative	1	0.01	0.02	0.03
1353	3/20/2019 10:33	mg/cm ²	Wood Beam	Wood	B	Intact	White		1	SW Entry	Positive	4.75	14.1	10.1	24.2
1354	3/20/2019 10:33	mg/cm ²	Baseboard	Wood	C	Deteriorated	Brown	Impact	1	SW Entry	Negative	1	0	0.02	0.02
1355	3/20/2019 10:35	mg/cm ²	Door Casing/Header	Wood	A	Intact	Brown		1	SW Entry	Positive	2.27	32.7	28.3	61
1356	3/20/2019 10:36	mg/cm ²	Door Transom Sash	Wood	A	Intact	White		1	SW Entry	Positive	2.36	39.3	31.8	71.1
1357	3/20/2019 10:36	mg/cm ²	Door Transom Jamb	Wood	A	Deteriorated	Brown	Cracking	1	SW Entry	Positive	2.62	30.1	26.1	56.2
1358	3/20/2019 10:37	mg/cm ²	Door Casing/Header	Metal	B	Intact	Blue		1	SW Entry	Negative	1	0	0.02	0.02
1359	3/20/2019 10:37	mg/cm ²	Door Jamb	Metal	B	Intact	Black		1	SW Entry	Negative	1	0	0.02	0.02
1360	3/20/2019 10:37	mg/cm ²	Door Stop	Metal	B	Intact	Blue		1	SW Entry	Negative	1	0	0.02	0.02
1361	3/20/2019 10:37	mg/cm ²	Door	Metal	B	Deteriorated	Black	Friction/Impact	1	SW Entry	Negative	1	0	0.02	0.02
1362	3/20/2019 10:39	mg/cm ²	Door Casing/Header	Wood	D	Intact	Blue		1	SW Entry	Negative	1	0	0.02	0.02
1363	3/20/2019 10:39	mg/cm ²	Door Jamb	Metal	D	Intact	Blue		1	SW Entry	Negative	1	0	0.02	0.02
1364	3/20/2019 10:39	mg/cm ²	Door Stop	Metal	D	Intact	Blue		1	SW Entry	Negative	1	0	0.02	0.02
1365	3/20/2019 10:40	mg/cm ²	Door	Metal	D	Intact	Blue		1	SW Entry	Negative	1	0	0.02	0.02
1366	3/20/2019 10:53	mg/cm ²	Wall	Wood	A	Intact	Stain		1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1367	3/20/2019 10:53	mg/cm ²	Wall	Brick	A	Intact	Beige		1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1368	3/20/2019 10:53	mg/cm ²	Wall	Wood	B	Intact	Stain		1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1369	3/20/2019 10:54	mg/cm ²	Wall	Drywall	C	Deteriorated	Beige	Cracking	1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1370	3/20/2019 10:54	mg/cm ²	Wall	Concrete	D	Intact	Beige		1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1371	3/20/2019 10:54	mg/cm ²	Floor	Carpet	All	Intact	Red		1	SW Entry Storage 2	Negative	2.46	0.03	0.09	0.12
1372	3/20/2019 10:54	mg/cm ²	Radiator	Metal	A	Intact	Grey		1	SW Entry Storage 2	Negative	2.02	0.04	0.13	0.17
1373	3/20/2019 10:54	mg/cm ²	Door Jamb	Metal	D	Intact	White		1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1374	3/20/2019 10:54	mg/cm ²	Door Casing/Header	Wood	B	Intact	Blue		1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1375	3/20/2019 10:55	mg/cm ²	Door Threshold	Wood	B	Deteriorated	Blue	Friction	1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1376	3/20/2019 10:55	mg/cm ²	Closet Wall	Drywall	All	Deteriorated	Green	Cracking	1	SW Entry Storage 2	Negative	1	0	0.02	0.02
1377	3/20/2019 10:55	mg/cm ²	Shelf Support	Wood	All	Deteriorated	Beige	Cracking	1	SW Entry Storage 2	Negative	1.58	0.01	0.04	0.05
1378	3/20/2019 10:55	mg/cm ²	Shelf	Wood	All	Deteriorated	Beige	Friction	1	SW Entry Storage 2	Negative	1	0	0.03	0.03
1379	3/20/2019 10:57	mg/cm ²	Window Sash	Wood	C	Deteriorated	White	Cracking	1	SW Entry Storage 2	Positive	2.11	2.8	1.6	4.4
1380	3/20/2019 10:58	mg/cm ²	Vent	Metal	C	Deteriorated	Beige	Cracking	1	SW Entry Storage 2	Negative	3.19	0.04	0.19	0.23
1381	3/20/2019 10:59	mg/cm ²	Ceiling Above Drop Ceiling	Plaster	All	Deteriorated	Grey	Cracking	1	SW Entry Storage 2	Negative	3.02	0.16	0.8	0.96
1382	3/20/2019 10:59	mg/cm ²	Crown Molding Above Drop Ceiling	Wood	All	Deteriorated	White	Cracking	1	SW Entry Storage 2	Negative	5.66	0.24	0.59	0.83
1383	3/20/2019 11:01	mg/cm ²	Wall	Drywall	A	Intact	White		1	SW Entry Storage 3	Negative	1	0	0.02	0.02
1384	3/20/2019 11:01	mg/cm ²	Wall	Drywall	B	Intact	White		1	SW Entry Storage 3	Negative	1	0	0.02	0.02
1385	3/20/2019 11:01	mg/cm ²	Wall	Drywall	C	Intact	White		1	SW Entry Storage 3	Negative	1	0	0.02	0.02
1386	3/20/2019 11:02	mg/cm ²	Wall	Drywall	D	Intact	White		1	SW Entry Storage 3	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1387	3/20/2019 11:02	mg/cm ²	Floor	Wood	All	Deteriorated	Grey	Friction	1	SW Entry Storage 3	Negative	1	0	0.02	0.02
1388	3/20/2019 11:03	mg/cm ²	Mail Drop	Metal	C	Intact	Grey		1	SW Entry Storage 3	Negative	1	0	0.02	0.02
1389	3/20/2019 11:12	mg/cm ²	Wall	Drywall	A	Intact	White		1	SW Electrical Room	Negative	1	0	0.02	0.02
1390	3/20/2019 11:12	mg/cm ²	Wall	Drywall	B	Intact	White		1	SW Electrical Room	Negative	1	0	0.02	0.02
1391	3/20/2019 11:12	mg/cm ²	Wall	Drywall	D	Intact	White		1	SW Electrical Room	Negative	1	0	0.02	0.02
1392	3/20/2019 11:13	mg/cm ²	Wall	Brick	A	Intact	Red		1	SW Electrical Room	Negative	1.73	0.01	0.03	0.04
1393	3/20/2019 11:13	mg/cm ²	Radiator	Metal	A	Intact	Brown		1	SW Electrical Room	Negative	2.14	0.03	0.11	0.14
1394	3/20/2019 11:14	mg/cm ²	Door Casing/Header	Metal	B	Intact	Blue		1	SW Electrical Room	Negative	1	0	0.02	0.02
1395	3/20/2019 11:14	mg/cm ²	Door Jamb	Metal	B	Intact	Blue		1	SW Electrical Room	Negative	1	0	0.02	0.02
1396	3/20/2019 11:14	mg/cm ²	Door Stop	Metal	B	Intact	Blue		1	SW Electrical Room	Negative	1	0	0.02	0.02
1397	3/20/2019 11:14	mg/cm ²	Door	Metal	B	Intact	Blue		1	SW Electrical Room	Negative	1	0	0.02	0.02
1398	3/20/2019 11:16	mg/cm ²	Wall	Brick	A	Intact	Brown		1	SW Electrical Room	Negative	1	0	0.02	0.02
1399	3/20/2019 11:16	mg/cm ²	Crown Molding	Wood	A	Deteriorated	White	Chipping	1	SW Electrical Room	Negative	1	0.01	0.03	0.04
1400	3/20/2019 11:16	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Chipping	1	SW Electrical Room	Negative	3.07	0.06	0.09	0.15
1401	3/20/2019 11:16	mg/cm ²	Wall	Brick	D	Deteriorated	Black	Chipping	1	SW Electrical Room	Negative	5.11	0.04	0.12	0.16
1402	3/20/2019 11:20	mg/cm ²	Wall	Wood	A	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1403	3/20/2019 11:20	mg/cm ²	Wall	Wood	B	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1404	3/20/2019 11:20	mg/cm ²	Wall	Wood	C	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1405	3/20/2019 11:20	mg/cm ²	Wall	Wood	D	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1406	3/20/2019 11:21	mg/cm ²	Floor	Carpet	All	Intact	Red		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1407	3/20/2019 11:21	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1408	3/20/2019 11:21	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1409	3/20/2019 11:21	mg/cm ²	Door Stop	Wood	A	Intact	Stain		1	SW Entry Storage 1	Negative	1	0	0.02	0.02
1410	3/20/2019 11:21	mg/cm ²	Door	Wood	A	Intact	Stain		1	SW Entry Storage 1	Negative	1	0.01	0.04	0.05
1411	3/20/2019 11:27	mg/cm ²	Wall	Wood	A	Intact	White		1	SW Basement Entry Hall	Negative	1	0	0.02	0.02
1412	3/20/2019 11:27	mg/cm ²	Wall	Wood	A	Deteriorated	White	Cracking	1	SW Basement Entry Hall	Positive	3.22	2	0.8	2.8
1413	3/20/2019 11:27	mg/cm ²	Wall	Plaster	B	Intact	White		1	SW Basement Entry Hall	Positive	5.71	2.4	1.2	3.6
1414	3/20/2019 11:27	mg/cm ²	Wall	Plaster	C	Intact	White		1	SW Basement Entry Hall	Positive	4.69	1.2	0.2	1.4
1415	3/20/2019 11:27	mg/cm ²	Wall	Plaster	D	Intact	White		1	SW Basement Entry Hall	Positive	4.72	1.7	0.6	2.3
1416	3/20/2019 11:29	mg/cm ²	Ceiling	Wood	All	Intact	White		1	SW Basement Entry Hall	Negative	1	0	0.02	0.02
1417	3/20/2019 11:29	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	1	SW Basement Entry Hall	Negative	1	0	0.02	0.02
1418	3/20/2019 11:29	mg/cm ²	Baseboard	Wood	All	Intact	Brown		1	SW Basement Entry Hall	Negative	1.39	0.03	0.07	0.1
1419	3/20/2019 11:29	mg/cm ²	Shoe Molding	Wood	All	Intact	Brown		1	SW Basement Entry Hall	Negative	2.07	0.02	0.07	0.09
1420	3/20/2019 11:30	mg/cm ²	Closet Door	Wood	A	Deteriorated	White	Friction/Impact	1	SW Basement Entry Hall	Positive	3.64	3	1.9	4.9
1421	3/20/2019 11:32	mg/cm ²	Door Casing/Header	Wood	C	Intact	Brown		1	SW Basement Entry Hall	Negative	1.36	0.09	0.15	0.24
1422	3/20/2019 11:32	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Brown	Friction	1	SW Basement Entry Hall	Negative	2.22	0.11	0.22	0.33
1423	3/20/2019 11:32	mg/cm ²	Door Stop	Wood	C	Deteriorated	Brown	Impact	1	SW Basement Entry Hall	Negative	1.64	0.06	0.14	0.2
1424	3/20/2019 11:32	mg/cm ²	Pipe	Metal	B	Deteriorated	White	Chipping	1	SW Basement Entry Hall	Negative	2.16	0.03	0.08	0.11
1425	3/20/2019 11:36	mg/cm ²	Under Stair Tread	Metal	All	Intact	White		1	SW Basement Entry Hall	Negative	2.32	0.04	0.1	0.14
1426	3/20/2019 11:36	mg/cm ²	Under Stair Riser	Metal	All	Intact	White		1	SW Basement Entry Hall	Negative	4.07	0.14	0.24	0.38
1427	3/20/2019 11:36	mg/cm ²	Under Stair Stringer	Metal	All	Intact	White		1	SW Basement Entry Hall	Negative	2.57	0.09	0.15	0.24
1428	3/20/2019 11:37	mg/cm ²	Under Stair Fram	Metal	All	Intact	White		1	SW Basement Entry Hall	Negative	3.45	0.16	0.24	0.4
1429	3/20/2019 11:40	mg/cm ²	Door Casing/Header	Wood	D	Intact	Brown		1	SW Basement Entry Hall	Negative	1	0.03	0.07	0.1
1430	3/20/2019 11:40	mg/cm ²	Door Jamb	Wood	D	Deteriorated	Brown	Friction	1	SW Basement Entry Hall	Negative	1	0.03	0.06	0.09
1431	3/20/2019 11:40	mg/cm ²	Door Stop	Wood	D	Deteriorated	Black	Impact	1	SW Basement Entry Hall	Negative	1.6	0.06	0.14	0.2
1432	3/20/2019 11:40	mg/cm ²	Door Jamb	Wood	D	Deteriorated	Black	Friction	1	SW Basement Entry Hall	Negative	3.3	0.1	0.21	0.31
1433	3/20/2019 11:41	mg/cm ²	Door	Wood	D	Deteriorated	Brown	Friction/Impact	1	SW Basement Entry Hall	Negative	1.6	0.07	0.15	0.22
1434	3/20/2019 11:44	mg/cm ²	Wall	Plaster	A	Intact	Grey		1	SW Basement Stair	Negative	1.78	0.03	0.03	0.06
1435	3/20/2019 11:44	mg/cm ²	Wall	Plaster	A	Intact	Dark Grey		1	SW Basement Stair	Negative	1.6	0.1	0.04	0.14
1436	3/20/2019 11:44	mg/cm ²	Wall	Plaster	B	Intact	Grey		1	SW Basement Stair	Negative	2.93	0.1	0.15	0.25
1437	3/20/2019 11:44	mg/cm ²	Wall	Plaster	B	Intact	Dark Grey		1	SW Basement Stair	Negative	1.65	0.09	0.13	0.22
1438	3/20/2019 11:45	mg/cm ²	Wall	Plaster	C	Deteriorated	Grey	Cracking	1	SW Basement Stair	Negative	2.07	0.24	0.75	0.99
1439	3/20/2019 11:45	mg/cm ²	Wall	Plaster	C	Deteriorated	Dark Grey	Cracking	1	SW Basement Stair	Negative	1.77	0.11	0.03	0.14
1440	3/20/2019 11:45	mg/cm ²	Wall	Plaster	D	Deteriorated	Grey	Cracking	1	SW Basement Stair	Negative	1.56	0.04	0.03	0.07
1441	3/20/2019 11:46	mg/cm ²	Wall	Plaster	D	Deteriorated	Dark Grey	Cracking	1	SW Basement Stair	Negative	2.16	0	0	0
1442	3/20/2019 11:46	mg/cm ²	Under Stair Tread	Metal	A	Intact	Grey		1	SW Basement Stair	Negative	1.93	0.03	0.09	0.12
1443	3/20/2019 11:46	mg/cm ²	Under Stair Riser	Metal	A	Intact	Grey		1	SW Basement Stair	Negative	1	0.01	0.04	0.05
1444	3/20/2019 11:46	mg/cm ²	Under Stair Stringer	Metal	A	Intact	Grey		1	SW Basement Stair	Negative	2.38	0.06	0.12	0.18
1445	3/20/2019 11:47	mg/cm ²	Wall Wood	Wood	C	Deteriorated	Grey	Chipping	1	SW Basement Stair	Negative	3.85	0.05	0.23	0.28

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1446	3/20/2019 11:47	mg/cm ²	Baseboard	Wood	All	Deteriorated	Grey	Impact	1	SW Basement Stair	Negative	2.04	0.14	0.17	0.31
1447	3/20/2019 11:48	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Grey	Impact	1	SW Basement Stair	Negative	1.62	0.11	0.14	0.25
1448	3/20/2019 11:48	mg/cm ²	Landing Floor	Concrete	All	Deteriorated	Brown	Friction	1	SW Basement Stair	Negative	1	0.01	0.02	0.03
1449	3/20/2019 11:48	mg/cm ²	Stair Tread	Concrete	All	Deteriorated	Brown	Friction	1	SW Basement Stair	Negative	1.78	0.01	0.03	0.04
1450	3/20/2019 11:49	mg/cm ²	Stair Riser	Concrete	All	Deteriorated	Brown	Impact	1	SW Basement Stair	Negative	1	0	0.02	0.02
1451	3/20/2019 11:49	mg/cm ²	Stair Stringer	Wood	All	Deteriorated	Grey	Chipping	1	SW Basement Stair	Negative	1	0.05	0.1	0.15
1452	3/20/2019 11:54	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	1	SW Map Room	Positive	3.15	5.1	3.3	8.4
1453	3/20/2019 11:54	mg/cm ²	Wall	Wood	A	Deteriorated	Brown	Cracking	1	SW Map Room	Positive	3.05	3.9	2.6	6.5
1454	3/20/2019 11:54	mg/cm ²	Wall	Wood	B	Deteriorated	Beige	Cracking	1	SW Map Room	Negative	1	0	0.02	0.02
1455	3/20/2019 11:55	mg/cm ²	Wall	Plaster	B	Deteriorated	Brown	Cracking	1	SW Map Room	Negative	1.41	0.01	0.05	0.06
1456	3/20/2019 11:55	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	1	SW Map Room	Positive	3.42	5.7	3.9	9.6
1457	3/20/2019 11:55	mg/cm ²	Wall	Plaster	C	Deteriorated	Brown	Cracking	1	SW Map Room	Positive	3.09	12	10.1	22.1
1458	3/20/2019 11:55	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	1	SW Map Room	Positive	3.56	6.4	4.3	10.7
1459	3/20/2019 11:55	mg/cm ²	Wall	Plaster	D	Deteriorated	Brown	Cracking	1	SW Map Room	Positive	3.58	4.8	3.3	8.1
1460	3/20/2019 11:56	mg/cm ²	Floor	Concrete	All	Deteriorated	Red	Friction	1	SW Map Room	Negative	1	0	0.02	0.02
1461	3/20/2019 11:56	mg/cm ²	Radiator	Metal	A	Deteriorated	Grey	Chipping	1	SW Map Room	Positive	4.84	4.5	3	7.5
1462	3/20/2019 11:56	mg/cm ²	Radiator Pipe	Metal	A	Deteriorated	Grey	Chipping	1	SW Map Room	Negative	1.54	0.05	0.12	0.17
1463	3/20/2019 11:57	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	1	SW Map Room	Positive	4.59	0.9	1.2	2.1
1464	3/20/2019 11:58	mg/cm ²	Door Jamb	Wood	B	Intact	Beige		1	SW Map Room	Negative	1	0	0.02	0.02
1465	3/20/2019 11:58	mg/cm ²	Door Stop	Wood	B	Intact	Brown		1	SW Map Room	Negative	1	0	0.02	0.02
1466	3/20/2019 11:58	mg/cm ²	Door	Wood	B	Intact	Stain		1	SW Map Room	Negative	1	0	0.02	0.02
1467	3/20/2019 12:02	mg/cm ²	Ceiling	Plaster	All	Intact	Beige		1	SW Map Room	Negative	3.44	0.1	0.08	0.18
CAL	3/20/2019 12:16	mg/cm ²										1.22	0.9	0.1	1
CAL	3/20/2019 12:17	mg/cm ²										1.23	1	0.1	1.1
CAL	3/20/2019 12:17	mg/cm ²										1.2	0.9	0.1	1
1468	3/20/2019 12:21	mg/cm ²	Baseboard	Wood	All	Deteriorated	Brown	Impact	1	SW Map Room	Negative	1.4	0.04	0.07	0.11
1469	3/20/2019 12:21	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Brown	Impact	1	SW Map Room	Negative	2.38	0.11	0.24	0.35
1470	3/20/2019 12:43	mg/cm ²	Wall	Plaster	A	Deteriorated	Grey	Cracking	Basement	E14	Negative	1.51	0.09	0.03	0.12
1471	3/20/2019 12:43	mg/cm ²	Wall	Plaster	B	Deteriorated	Grey	Cracking	Basement	E14	Positive	1.99	0.5	0.5	1
1472	3/20/2019 12:44	mg/cm ²	Wall	Plaster	C	Deteriorated	Grey	Cracking	Basement	E14	Positive	1.89	0.5	0.5	1
1473	3/20/2019 12:44	mg/cm ²	Wall	Plaster	D	Deteriorated	Grey	Cracking	Basement	E14	Negative	1.29	0.08	0.04	0.12
1474	3/20/2019 12:44	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement	E14	Negative	1.52	0.05	0.03	0.08
1475	3/20/2019 12:45	mg/cm ²	Baseboard	Wood	All	Deteriorated	Grey	Chipping	Basement	E14	Negative	1.76	0.12	0.15	0.27
1476	3/20/2019 12:45	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement	E14	Negative	1.33	0.03	0.05	0.08
1477	3/20/2019 12:45	mg/cm ²	Pipe	Metal	C	Deteriorated	Grey	Chipping	Basement	E14	Negative	1	0.02	0.04	0.06
1478	3/20/2019 12:47	mg/cm ²	Wall	Brick	A	Deteriorated	White	Cracking	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1479	3/20/2019 12:47	mg/cm ²	Wall	Brick	B	Deteriorated	White	Cracking	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1480	3/20/2019 12:47	mg/cm ²	Wall	Brick	C	Deteriorated	White	Cracking	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1481	3/20/2019 12:48	mg/cm ²	Wall	Brick	D	Deteriorated	White	Cracking	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1482	3/20/2019 12:48	mg/cm ²	Ceiling	Concrete	All	Deteriorated	Grey	Cracking	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1483	3/20/2019 12:48	mg/cm ²	Door Frame	Metal	B	Deteriorated	Grey	Cracking	Basement	E14 Closet Entry	Negative	1	0.04	0.06	0.1
1484	3/20/2019 12:50	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Stain	Cracking	Basement	E14 Closet Entry	Negative	1.14	0.05	0.07	0.12
1485	3/20/2019 12:50	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Stain	Friction	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1486	3/20/2019 12:50	mg/cm ²	Door Stop	Wood	A	Deteriorated	Stain	Impact	Basement	E14 Closet Entry	Negative	1	0	0.02	0.02
1487	3/20/2019 12:50	mg/cm ²	Door	Wood	A	Deteriorated	Stain	Friction/Impact	Basement	E14 Closet Entry	Negative	1.14	0.05	0.08	0.13
1488	3/20/2019 12:50	mg/cm ²	Closet Shelf	Wood	All	Deteriorated	Stain	Friction	Basement	E14 Closet Entry	Negative	1.93	0.02	0.06	0.08
1489	3/20/2019 12:51	mg/cm ²	Shoe Molding	Wood	C	Deteriorated	Grey	Impact	Basement	E14 Closet Entry	Negative	2	0.05	0.11	0.16
1490	3/20/2019 12:53	mg/cm ²	Wall	Plaster	A	Deteriorated	Grey	Cracking	Basement	E14 Hall	Negative	1.2	0.04	0.05	0.09
1491	3/20/2019 12:53	mg/cm ²	Wall	Plaster	B	Deteriorated	Grey	Cracking	Basement	E14 Hall	Negative	1	0.04	0.04	0.08
1492	3/20/2019 12:53	mg/cm ²	Wall	Drywall	C	Intact	White		Basement	E14 Hall	Negative	1	0	0.02	0.02
1493	3/20/2019 12:53	mg/cm ²	Wall	Plaster	D	Deteriorated	Grey	Cracking	Basement	E14 Hall	Negative	1.1	0.04	0.04	0.08
1494	3/20/2019 12:54	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement	E14 Hall	Negative	1	0.01	0.02	0.03
1495	3/20/2019 12:54	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement	E14 Hall	Negative	1	0.01	0.05	0.06
1496	3/20/2019 12:54	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement	E14 Hall	Negative	1.52	0.02	0.02	0.04
1497	3/20/2019 12:59	mg/cm ²	Wall	Drywall	A	Intact	White		Basement	E15	Negative	1	0	0.02	0.02
1498	3/20/2019 12:59	mg/cm ²	Wall	Plaster	B	Deteriorated	Grey	Cracking	Basement	E15	Negative	1.58	0.07	0.06	0.13
1499	3/20/2019 12:59	mg/cm ²	Wall	Plaster	C	Deteriorated	Grey	Cracking	Basement	E15	Negative	1.6	0.06	0.06	0.12
1500	3/20/2019 13:00	mg/cm ²	Wall	Plaster	D	Deteriorated	Grey	Cracking	Basement	E15	Negative	1.39	0.04	0.05	0.09
1501	3/20/2019 13:00	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement	E15	Negative	1.29	0.02	0.03	0.05

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1502	3/20/2019 13:00	mg / cm ^2	Door Casing/Header	Metal	A	Intact	Blue		Basement E15		Negative	1	0	0.02	0.02
1503	3/20/2019 13:00	mg / cm ^2	Door Jamb	Metal	A	Intact	Blue		Basement E15		Negative	4.34	0.01	0.07	0.08
1504	3/20/2019 13:01	mg / cm ^2	Door Stop	Metal	A	Intact	Blue		Basement E15		Negative	10	0.3	0.64	0.94
1505	3/20/2019 13:01	mg / cm ^2	Door	Metal	A	Intact	Blue		Basement E15		Negative	1	0	0.02	0.02
1506	3/20/2019 13:04	mg / cm ^2	Wall	Brick	A	Deteriorated	Red	Cracking	Basement E13B		Negative	1.27	0	0.02	0.02
1507	3/20/2019 13:04	mg / cm ^2	Wall	Brick	B	Deteriorated	Red	Cracking	Basement E13B		Negative	1	0	0.02	0.02
1508	3/20/2019 13:04	mg / cm ^2	Wall	Brick	C	Deteriorated	Red	Cracking	Basement E13B		Negative	2.55	0.03	0.06	0.09
1509	3/20/2019 13:04	mg / cm ^2	Pipe	Metal	-	Intact	Yellow		Basement E13B		Positive	1.93	2	0.7	2.7
1510	3/20/2019 13:04	mg / cm ^2	Ceiling	Plaster	All	Deteriorated	Black	Cracking	Basement E13B		Negative	2.18	0.01	0.05	0.06
1511	3/20/2019 13:05	mg / cm ^2	Doorway	Brick	A	Deteriorated	White	Chipping	Basement E13B		Negative	1	0	0.02	0.02
1512	3/20/2019 13:07	mg / cm ^2	Wall	Brick	A	Deteriorated	White	Cracking	Basement E13C		Negative	1	0	0.02	0.02
1513	3/20/2019 13:07	mg / cm ^2	Wall	Brick	B	Deteriorated	White	Cracking	Basement E13C		Negative	2.03	0.01	0.04	0.05
1514	3/20/2019 13:07	mg / cm ^2	Wall	Brick	C	Deteriorated	White	Cracking	Basement E13C		Negative	1	0	0.02	0.02
1515	3/20/2019 13:09	mg / cm ^2	Wall	Brick	D	Deteriorated	White	Cracking	Basement E13C		Negative	1	0	0.02	0.02
1516	3/20/2019 13:09	mg / cm ^2	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement E13C		Negative	1	0.01	0.02	0.03
1517	3/20/2019 13:11	mg / cm ^2	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement E13C		Negative	1	0	0.02	0.02
1518	3/20/2019 13:11	mg / cm ^2	Wall	Brick	A	Deteriorated	White	Cracking	Basement E13C Entry		Negative	1	0	0.02	0.02
1519	3/20/2019 13:11	mg / cm ^2	Wall	Brick	B	Deteriorated	White	Cracking	Basement E13C Entry		Negative	1	0	0.02	0.02
1520	3/20/2019 13:11	mg / cm ^2	Wall	Brick	C	Deteriorated	White	Cracking	Basement E13C Entry		Negative	1	0	0.02	0.02
1521	3/20/2019 13:12	mg / cm ^2	Wall	Brick	D	Deteriorated	White	Cracking	Basement E13C Entry		Negative	1	0	0.02	0.02
1522	3/20/2019 13:12	mg / cm ^2	Ceiling	Concrete	All	Deteriorated	White	Cracking	Basement E13C Entry		Negative	1	0.01	0.02	0.03
1523	3/20/2019 13:12	mg / cm ^2	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement E13C Entry		Negative	5.73	0.07	0.23	0.3
1524	3/20/2019 13:12	mg / cm ^2	Pipe	Metal	C	Deteriorated	White	Chipping	Basement E13C Entry		Negative	2.22	0.02	0.1	0.12
1525	3/20/2019 13:12	mg / cm ^2	Door Casing/Header	Metal	B	Deteriorated	Grey	Impact	Basement E13C Entry		Negative	2.47	0.02	0.1	0.12
1526	3/20/2019 13:12	mg / cm ^2	Door Jamb	Metal	B	Deteriorated	Grey	Friction	Basement E13C Entry		Negative	1	0.01	0.04	0.05
1527	3/20/2019 13:12	mg / cm ^2	Door Stop	Metal	B	Deteriorated	Grey	Impact	Basement E13C Entry		Negative	1.06	0.06	0.1	0.16
1528	3/20/2019 13:14	mg / cm ^2	Door	Metal	B	Deteriorated	Grey	Friction/Impact	Basement E13C Entry		Negative	1	0	0.02	0.02
1529	3/20/2019 13:15	mg / cm ^2	Wall	Drywall	A	Intact	White		Basement E13A		Negative	3.38	0.01	0.05	0.06
1530	3/20/2019 13:15	mg / cm ^2	Wall	Brick	B	Deteriorated	White	Cracking	Basement E13A		Negative	1	0	0.02	0.02
1531	3/20/2019 13:15	mg / cm ^2	Wall	Brick	C	Deteriorated	White	Cracking	Basement E13A		Negative	1	0	0.02	0.02
1532	3/20/2019 13:15	mg / cm ^2	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement E13A		Negative	1	0	0.02	0.02
1533	3/20/2019 13:15	mg / cm ^2	Pipe	Metal	C	Deteriorated	White	Chipping	Basement E13A		Positive	1.24	1.3	0.3	1.6
1534	3/20/2019 13:16	mg / cm ^2	Door Casing/Header	Metal	A	Deteriorated	Blue	Impact	Basement E13A		Negative	1	0	0.02	0.02
1535	3/20/2019 13:16	mg / cm ^2	Door Jamb	Metal	A	Deteriorated	Blue	Friction	Basement E13A		Negative	1	0	0.02	0.02
1536	3/20/2019 13:16	mg / cm ^2	Door Stop	Metal	A	Deteriorated	Blue	Impact	Basement E13A		Negative	1	0	0.02	0.02
1537	3/20/2019 13:16	mg / cm ^2	Door	Metal	A	Deteriorated	Blue	Friction/Impact	Basement E13A		Negative	1	0	0.02	0.02
1538	3/20/2019 13:17	mg / cm ^2	Wall	Brick	D	Intact	Red		Basement E13A		Negative	1	0	0.02	0.02
1539	3/20/2019 13:18	mg / cm ^2	Ceiling	Concrete	All	Deteriorated	Black	Cracking	Basement E13A		Negative	1	0	0.02	0.18
1540	3/20/2019 13:22	mg / cm ^2	Wall	Brick	A	Deteriorated	White	Cracking	Basement E13		Negative	1.21	0.11	0.07	0.18
1541	3/20/2019 13:23	mg / cm ^2	Wall	Brick	B	Deteriorated	White	Cracking	Basement E13		Negative	1	0	0.02	0.02
1542	3/20/2019 13:23	mg / cm ^2	Wall	Drywall	C	Deteriorated	White	Cracking	Basement E13		Negative	1	0	0.02	0.02
1543	3/20/2019 13:23	mg / cm ^2	Wall	Brick	D	Deteriorated	White	Cracking	Basement E13		Negative	1	0	0.02	0.02
1544	3/20/2019 13:24	mg / cm ^2	Outer Door Frame	Metal	A	Intact	Blue		Basement E13		Negative	2.79	0	0.03	0.03
1545	3/20/2019 13:24	mg / cm ^2	Door Jamb	Metal	A	Deteriorated	Blue	Friction	Basement E13		Negative	1	0	0.03	0.03
1546	3/20/2019 13:24	mg / cm ^2	Door Stop	Metal	A	Deteriorated	Blue	Impact	Basement E13		Negative	1	0	0.02	0.02
1547	3/20/2019 13:24	mg / cm ^2	Door	Metal	A	Deteriorated	Blue	Friction/Impact	Basement E13		Negative	1	0	0.02	0.02
1548	3/20/2019 13:24	mg / cm ^2	Door Frame	Metal	A	Deteriorated	White	Chipping	Basement E13		Negative	4.36	0.04	0.13	0.17
1549	3/20/2019 13:24	mg / cm ^2	Coal Door	Metal	B	Deteriorated	Grey	Chipping	Basement E13		Negative	3.54	0.03	0.1	0.13
1550	3/20/2019 13:26	mg / cm ^2	Ceiling	Plaster	All	Deteriorated	Black	Cracking	Basement E13		Negative	1	0	0.02	0.02
1551	3/20/2019 13:29	mg / cm ^2	Window Casing/Header	Wood	D	Deteriorated	Brown	Cracking	Basement E13		Negative	1	0.02	0.05	0.07
1552	3/20/2019 13:30	mg / cm ^2	Window Sash	Wood	D	Deteriorated	Brown	Friction/Impact	Basement E13		Positive	1.47	2	0.9	2.9
1553	3/20/2019 13:30	mg / cm ^2	Window Inside Stop	Wood	D	Deteriorated	Brown	Cracking	Basement E13		Negative	1	0	0.02	0.02
1554	3/20/2019 13:30	mg / cm ^2	Window Jamb	Wood	D	Deteriorated	Brown	Friction	Basement E13		Negative	2.13	0.02	0.06	0.08
1555	3/20/2019 13:38	mg / cm ^2	Wall	Concrete	A	Deteriorated	White	Cracking	Basement E04 Stair		Negative	3.53	0	0	0
1556	3/20/2019 13:38	mg / cm ^2	Wall	Plaster	C	Deteriorated	White	Cracking	Basement E04 Stair		Negative	2.64	0	0	0
1557	3/20/2019 13:39	mg / cm ^2	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E04 Stair		Negative	2.96	0.19	0.78	0.97
1558	3/20/2019 13:39	mg / cm ^2	Ceiling	Wood	All	Deteriorated	White	Cracking	Basement E04 Stair		Negative	1	0	0.02	0.02
1559	3/20/2019 13:39	mg / cm ^2	Wood Framing	Wood	C	Deteriorated	White	Cracking	Basement E04 Stair		Negative	1	0	0.03	0.03
1560	3/20/2019 13:39	mg / cm ^2	Upper Wall	Wood	A/D	Deteriorated	White	Cracking	Basement E04 Stair		Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1561	3/20/2019 13:39	mg/cm ²	Upper Wall Framing	Wood	A/D	Deteriorated	White	Cracking	Basement	E04 Stair	Negative	1	0	0.02	0.02
1562	3/20/2019 13:39	mg/cm ²	Railing	Metal	A/D	Deteriorated	White	Friction	Basement	E04 Stair	Negative	3.41	0.02	0.09	0.11
1563	3/20/2019 13:40	mg/cm ²	Stair Wall	Wood	D	Deteriorated	White	Cracking	Basement	E04 Stair	Negative	1.25	0.01	0.06	0.07
1564	3/20/2019 13:42	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement	E04	Negative	1.97	0.05	0.03	0.08
1565	3/20/2019 13:42	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	E04	Negative	1.92	0.05	0.06	0.11
1566	3/20/2019 13:42	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement	E04	Positive	10	10.4	5.6	16
1567	3/20/2019 13:43	mg/cm ²	Wall	Wood	D	Deteriorated	White	Cracking	Basement	E04	Negative	1	0	0.02	0.02
1568	3/20/2019 13:43	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement	E04	Negative	2.66	0.14	0.81	0.95
1569	3/20/2019 13:43	mg/cm ²	Ceiling	Drywall	All	Deteriorated	White	Cracking	Basement	E04	Negative	1.38	0.03	0.04	0.07
1570	3/20/2019 13:44	mg/cm ²	Floor	Concrete	All	Deteriorated	Brown	Friction	Basement	E04	Negative	1	0	0.02	0.02
1571	3/20/2019 13:44	mg/cm ²	Floor Stripe	Concrete	-	Deteriorated	Yellow	Friction	Basement	E04	Negative	1.44	0.01	0.02	0.03
1572	3/20/2019 13:45	mg/cm ²	Baseboard	Wood	All	Intact	Blue	Impact	Basement	E04	Negative	1	0.02	0.04	0.06
1573	3/20/2019 13:45	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Blue	Impact	Basement	E04	Negative	1.19	0.02	0.06	0.08
1574	3/20/2019 13:46	mg/cm ²	Door Casing/Header	Wood	D	Deteriorated	Blue	Impact	Basement	E04	Negative	1	0	0.02	0.02
1575	3/20/2019 13:47	mg/cm ²	Door	Wood	D	Deteriorated	Blue	Friction/Impact	Basement	E04	Negative	1	0	0.02	0.02
1576	3/20/2019 13:47	mg/cm ²	Door Casing/Header	Wood	D	Deteriorated	Blue	Impact	Basement	E04	Negative	1.93	0.05	0.11	0.16
1577	3/20/2019 13:47	mg/cm ²	Door	Wood	D	Deteriorated	Blue	Friction/Impact	Basement	E04	Negative	1.74	0.09	0.17	0.26
1578	3/20/2019 13:48	mg/cm ²	Cornet Guard	Wood	D	Deteriorated	White	Cracking	Basement	E04	Negative	2.42	0.05	0.17	0.22
1579	3/20/2019 13:48	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Blue	Impact	Basement	E04	Negative	1.64	0.08	0.12	0.2
1580	3/20/2019 13:48	mg/cm ²	Door	Wood	A	Deteriorated	Blue	Friction/Impact	Basement	E04	Negative	2.57	0.16	0.3	0.46
1581	3/20/2019 13:50	mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Blue	Impact	Basement	E04	Negative	2.71	0.11	0.19	0.3
1582	3/20/2019 13:50	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Blue	Friction	Basement	E04	Negative	3	0.15	0.24	0.39
1583	3/20/2019 13:50	mg/cm ²	Door Stop	Wood	B	Deteriorated	Blue	Impact	Basement	E04	Negative	1.38	0.08	0.15	0.23
1584	3/20/2019 13:50	mg/cm ²	Door Threshold	Concrete	B	Deteriorated	Yellow	Friction	Basement	E04	Negative	6.11	0.03	0.07	0.1
1585	3/20/2019 13:50	mg/cm ²	Door Step	Concrete	B	Deteriorated	Yellow	Friction	Basement	E04	Negative	1	0	0.02	0.02
1586	3/20/2019 13:51	mg/cm ²	Drive in Wall Stripe	Concrete	-	Deteriorated	Yellow	Impact	Basement	E04	Positive	3.24	3.4	2.3	5.7
1587	3/20/2019 13:55	mg/cm ²	Wall	Concrete	A	Deteriorated	White	Cracking	Basement	E12	Negative	2.97	0	0	0
1588	3/20/2019 13:56	mg/cm ²	Wall	Drywall	B	Deteriorated	White	Cracking	Basement	E12	Negative	1	0	0.02	0.02
1589	3/20/2019 13:56	mg/cm ²	Wall	Concrete	C	Deteriorated	White	Cracking	Basement	E12	Negative	2.93	0.15	0.84	0.99
1590	3/20/2019 13:56	mg/cm ²	Wall	Concrete	D	Deteriorated	White	Cracking	Basement	E12	Negative	2.96	0.27	0.67	0.94
1591	3/20/2019 13:56	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement	E12	Negative	1.2	0.03	0.02	0.05
1592	3/20/2019 13:57	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement	E12	Negative	1	0.02	0.04	0.06
1593	3/20/2019 13:57	mg/cm ²	Floor	Concrete	All	Deteriorated	Beige	Friction	Basement	E12	Negative	1	0.01	0.02	0.03
1594	3/20/2019 13:57	mg/cm ²	Window Sill	Concrete	D	Deteriorated	Blue	Chewable	Basement	E12	Negative	2.33	0	0	0
1595	3/20/2019 13:58	mg/cm ²	Window Sill	Concrete	D	Deteriorated	White	Chewable	Basement	E12	Positive	1.34	1.1	0.1	1.2
1596	3/20/2019 13:58	mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Blue	Cracking	Basement	E12	Negative	1	0	0.02	0.02
1597	3/20/2019 13:58	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Blue	Friction	Basement	E12	Negative	1	0	0.02	0.02
1598	3/20/2019 13:58	mg/cm ²	Door Stop	Wood	B	Deteriorated	Blue	Impact	Basement	E12	Negative	1	0	0.02	0.02
1599	3/20/2019 13:58	mg/cm ²	Door	Metal	B	Deteriorated	Blue	Friction/Impact	Basement	E12	Negative	1	0	0.02	0.02
1600	3/20/2019 13:58	mg/cm ²	Wood On Wall	Wood	A	Intact	White	Friction/Impact	Basement	E12	Negative	1	0	0.02	0.02
1601	3/20/2019 13:59	mg/cm ²	Floor Drain Cover	Metal	-	Deteriorated	Grey	Friction	Basement	E12	Negative	1.3	0.05	0.08	0.13
1602	3/20/2019 14:00	mg/cm ²	Safe Frame	Metal	C	Deteriorated	Black	Friction	Basement	E12	Negative	1.14	0.02	0.05	0.07
1603	3/20/2019 14:00	mg/cm ²	Safe Door	Metal	C	Deteriorated	Black	Friction/Impact	Basement	E12	Negative	1.22	0.4	0.3	0.7
1604	3/20/2019 14:01	mg/cm ²	Work Bench	Wood	C	Deteriorated	Grey	Friction	Basement	E12	Negative	1.32	0.4	0.3	0.7
1605	3/20/2019 14:01	mg/cm ²	Work Bench Frame	Wood	C	Deteriorated	Beige	Chipping	Basement	E12	Negative	1	0	0.02	0.02
1606	3/20/2019 14:01	mg/cm ²	Cabinet Face	Wood	C	Deteriorated	White	Impact	Basement	E12	Negative	4.13	0.08	0.22	0.3
1607	3/20/2019 14:01	mg/cm ²	Cabinet Door	Wood	C	Deteriorated	White	Friction/Impact	Basement	E12	Negative	3.12	0.05	0.15	0.2
1608	3/20/2019 14:01	mg/cm ²	Wall Under Cabinet	Wood	C	Deteriorated	White	Cracking	Basement	E12	Negative	2.74	0.09	0.17	0.26
1609	3/20/2019 14:01	mg/cm ²	Wood Under Windows	Wood	D	Deteriorated	White	Chipping	Basement	E12	Negative	2.59	0.18	0.22	0.4
1610	3/20/2019 14:06	mg/cm ²	Wall	Concrete	C	Deteriorated	White	Cracking	Basement	E11	Negative	4.29	0.28	0.71	0.99
1611	3/20/2019 14:07	mg/cm ²	Wall	Wood	D	Deteriorated	Beige	Cracking	Basement	E11	Negative	1	0.04	0.06	0.1
1612	3/20/2019 14:07	mg/cm ²	Shelf Support	Wood	C	Deteriorated	White	Cracking	Basement	E11	Negative	1	0	0.03	0.03
1613	3/20/2019 14:07	mg/cm ²	Column	Concrete	B	Deteriorated	White	Cracking	Basement	E11	Negative	2.44	0	0	0
1614	3/20/2019 14:07	mg/cm ²	Column	Concrete	B	Deteriorated	Red	Cracking	Basement	E11	Negative	1.2	0.6	0.1	0.7
1615	3/20/2019 14:08	mg/cm ²	Stud Cross Member	Wood	B	Deteriorated	Yellow	Chipping	Basement	E11	Positive	1.61	4.2	2	6.2
1616	3/20/2019 14:10	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	White	Cracking	Basement	E11	Positive	1.62	1.6	0.5	2.1
1617	3/20/2019 14:10	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	Green	Cracking	Basement	E11	Positive	1.33	2.1	0.8	2.9
1618	3/20/2019 14:11	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	Basement	E11	Negative	6.39	0.12	0.28	0.4
1619	3/20/2019 14:16	mg/cm ²	Wall	Wood	A	Deteriorated	White	Cracking	Basement	E10	Positive	3.12	1.1	0.1	1.2

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1620	3/20/2019 14:16	mg/cm ²	Wall	Wood	A	Deteriorated	Green	Cracking	Basement E10	E10	Negative	2.87	0.6	0.1	0.7
1621	3/20/2019 14:17	mg/cm ²	Wall	Wood	B	Deteriorated	White	Cracking	Basement E10	E10	Positive	2.97	0.9	0.1	1
1622	3/20/2019 14:17	mg/cm ²	Wall	Wood	B	Deteriorated	Green	Cracking	Basement E10	E10	Positive	2.49	1.8	0.7	2.5
1623	3/20/2019 14:17	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement E10	E10	Positive	3.76	1.1	0.2	1.3
1624	3/20/2019 14:18	mg/cm ²	Wall	Plaster	C	Deteriorated	Green	Cracking	Basement E10	E10	Positive	3.6	0.8	0.2	1
1625	3/20/2019 14:18	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E10	E10	Positive	4.22	1.3	0.3	1.6
1626	3/20/2019 14:18	mg/cm ²	Wall	Plaster	D	Deteriorated	Green	Cracking	Basement E10	E10	Positive	2.99	1.3	0.3	1.6
1627	3/20/2019 14:19	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Grey	Cracking	Basement E10	E10	Positive	3.69	1.2	0.2	1.4
1628	3/20/2019 14:19	mg/cm ²	Radiator	Metal	All	Deteriorated	Grey	Chipping	Basement E10	E10	Negative	3.35	0.06	0.34	0.4
1629	3/20/2019 14:19	mg/cm ²	Window Sill	Concrete	D	Deteriorated	Brown	Chewable	Basement E10	E10	Negative	1	0.01	0.02	0.03
1630	3/20/2019 14:20	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Stain	Impact	Basement E10	E10	Negative	2.09	0.05	0.11	0.16
1631	3/20/2019 14:20	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Stain	Friction	Basement E10	E10	Negative	1	0.01	0.04	0.05
1632	3/20/2019 14:20	mg/cm ²	Door Stop	Wood	A	Deteriorated	Blue	Impact	Basement E10	E10	Negative	1.15	0.04	0.07	0.11
1633	3/20/2019 14:20	mg/cm ²	Door	Wood	A	Deteriorated	Stain	Friction/Impact	Basement E10	E10	Negative	1.7	0.15	0.16	0.31
1634	3/20/2019 14:22	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement E07 Hall	E07 Hall	Negative	2.13	0.05	0.04	0.09
1635	3/20/2019 14:23	mg/cm ²	Wall	Wood	C	Deteriorated	White	Cracking	Basement E07 Hall	E07 Hall	Negative	1	0.03	0.05	0.08
1636	3/20/2019 14:23	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E07 Hall	E07 Hall	Negative	1.67	0.06	0.03	0.09
1637	3/20/2019 14:23	mg/cm ²	Baseboard	Wood	All	Deteriorated	Grey	Impact	Basement E07 Hall	E07 Hall	Negative	1	0.03	0.08	0.11
1638	3/20/2019 14:23	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Grey	Impact	Basement E07 Hall	E07 Hall	Negative	5.61	0.18	0.39	0.57
1639	3/20/2019 14:24	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement E07 Hall	E07 Hall	Negative	1.88	0.04	0.06	0.1
1640	3/20/2019 14:25	mg/cm ²	Ceiling Wood Support	Wood	-	Deteriorated	White	Chipping	Basement E07 Hall	E07 Hall	Negative	3.06	0.04	0.18	0.22
1641	3/20/2019 14:33	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Positive	6.82	5.4	4.3	9.7
1642	3/20/2019 14:33	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Positive	5.59	3.9	2.1	6
1643	3/20/2019 14:33	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Positive	6.91	10.4	5.8	16.2
1644	3/20/2019 14:33	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Positive	5.96	6.3	4.8	11.1
1645	3/20/2019 14:34	mg/cm ²	Wall	Ceramic	All	Deteriorated	Grey	Cracking	Basement E09 Restroom	E09 Restroom	Negative	1	0	0.02	0.02
1646	3/20/2019 14:34	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Positive	4.71	7.5	6	13.5
1647	3/20/2019 14:34	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement E09 Restroom	E09 Restroom	Positive	2.41	7.7	6.1	13.8
1648	3/20/2019 14:37	mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Negative	2.59	0.08	0.21	0.29
1649	3/20/2019 14:37	mg/cm ²	Window Sill	Ceramic	A	Deteriorated	Beige	Chewable	Basement E09 Restroom	E09 Restroom	Negative	1.78	0.02	0.02	0.04
1650	3/20/2019 14:37	mg/cm ²	Window Casing/Header	Wood	D	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Negative	1.28	0.03	0.09	0.12
1651	3/20/2019 14:37	mg/cm ²	Window Jamb	Wood	D	Deteriorated	Beige	Cracking	Basement E09 Restroom	E09 Restroom	Negative	1.09	0.06	0.08	0.14
1652	3/20/2019 14:37	mg/cm ²	Window Sill	Ceramic	D	Deteriorated	Beige	Chewable	Basement E09 Restroom	E09 Restroom	Negative	1.33	0.02	0.02	0.04
1653	3/20/2019 14:38	mg/cm ²	Pipe	Metal	C	Deteriorated	Grey	Chipping	Basement E09 Restroom	E09 Restroom	Negative	1	0	0.02	0.02
1654	3/20/2019 14:38	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Blue	Friction	Basement E09 Restroom	E09 Restroom	Negative	1.56	0.08	0.11	0.19
1655	3/20/2019 14:39	mg/cm ²	Door Stop	Wood	C	Deteriorated	Blue	Impact	Basement E09 Restroom	E09 Restroom	Negative	2	0.09	0.19	0.28
1656	3/20/2019 14:39	mg/cm ²	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement E09 Restroom	E09 Restroom	Negative	1	0.01	0.04	0.05
1657	3/20/2019 14:45	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement E08	E08	Positive	4.64	0.4	0.6	1
1658	3/20/2019 14:45	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement E08	E08	Negative	4.26	0.14	0.8	0.94
1659	3/20/2019 14:46	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement E08	E08	Negative	10	0.6	0.2	0.8
1660	3/20/2019 14:46	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E08	E08	Positive	2.93	0.9	0.1	1
1661	3/20/2019 14:46	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement E08	E08	Negative	3.3	0.3	0.33	0.63
1662	3/20/2019 14:47	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement E08	E08	Negative	1.02	0.03	0.06	0.09
1663	3/20/2019 14:47	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement E08	E08	Negative	1.13	0.01	0.02	0.03
1664	3/20/2019 14:47	mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	White	Cracking	Basement E08	E08	Negative	2.58	0.06	0.14	0.2
1665	3/20/2019 14:47	mg/cm ²	Window Sill	Ceramic	A	Deteriorated	White	Chewable	Basement E08	E08	Positive	2.16	3.1	1.7	4.8
1666	3/20/2019 14:47	mg/cm ²	Bench Top	Wood	-	Deteriorated	Blue	Friction	Basement E08	E08	Positive	2.29	1.2	0.2	1.4
1667	3/20/2019 14:47	mg/cm ²	Bench Frame	Wood	-	Deteriorated	Blue	Chipping	Basement E08	E08	Positive	1.72	0.9	0.1	1
1668	3/20/2019 14:48	mg/cm ²	Work Bench	Wood	B	Deteriorated	Brown	Friction	Basement E08	E08	Negative	2.6	0.02	0.08	0.1
1669	3/20/2019 14:48	mg/cm ²	Work Bench Frame	Wood	B	Deteriorated	Brown	Chipping	Basement E08	E08	Negative	1.37	0.05	0.08	0.13
1670	3/20/2019 14:48	mg/cm ²	Shelf Frame	Wood	D	Deteriorated	White	Cracking	Basement E08	E08	Positive	2.3	0.7	0.3	1
1671	3/20/2019 14:48	mg/cm ²	Shelf	Wood	D	Deteriorated	White	Friction	Basement E08	E08	Negative	3.34	0.4	0.4	0.8
1672	3/20/2019 14:49	mg/cm ²	Cabinet Face	Wood	C	Deteriorated	White	Impact	Basement E08	E08	Negative	3.29	0.8	0.1	0.9
1673	3/20/2019 14:49	mg/cm ²	Cabinet Door	Wood	C	Deteriorated	White	Friction/Impact	Basement E08	E08	Negative	5.88	0.09	0.73	0.82
1674	3/20/2019 14:49	mg/cm ²	Cabinet Shelf	Wood	C	Deteriorated	Green	Friction	Basement E08	E08	Negative	1.98	0.5	0.3	0.8
1675	3/20/2019 14:50	mg/cm ²	Baseboard	Wood	All	Deteriorated	Blue	Impact	Basement E08	E08	Negative	3.29	0.6	0.3	0.9
1676	3/20/2019 14:50	mg/cm ²	Shoe Molding	Wood	All	Deteriorated	Blue	Impact	Basement E08	E08	Negative	2.67	0.5	0.4	0.9
1677	3/20/2019 14:50	mg/cm ²	Sink	Metal	D	Deteriorated	White	Cracking	Basement E08	E08	Positive	1.91	36.6	32.1	68.7
1678	3/20/2019 14:50	mg/cm ²	Pipe	Metal	-	Deteriorated	Grey	Chipping	Basement E08	E08	Negative	2.34	0.15	0.19	0.34

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1679	3/20/2019 14:50	mg/cm^2	Door Casing/Header	Wood	C	Deteriorated	Blue	Impact	Basement E08	E08	Negative	1	0.02	0.05	0.07
1680	3/20/2019 14:50	mg/cm^2	Door Lamb	Wood	C	Deteriorated	Blue	Friction	Basement E08	E08	Negative	1.36	0.09	0.11	0.2
1681	3/20/2019 14:51	mg/cm^2	Door Stop	Wood	C	Deteriorated	Blue	Impact	Basement E08	E08	Negative	1.72	0.09	0.18	0.27
1682	3/20/2019 14:51	mg/cm^2	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement E08	E08	Negative	1.01	0.08	0.09	0.17
1683	3/20/2019 14:53	mg/cm^2	Cabinet Face	Wood	B	Deteriorated	White	Impact	Basement E08	E08	Positive	2.2	0.8	0.2	1
1684	3/20/2019 14:53	mg/cm^2	Cabinet Door	Wood	B	Deteriorated	White	Friction/Impact	Basement E08	E08	Positive	2.08	1	0.1	1.1
1685	3/20/2019 14:53	mg/cm^2	Cabinet Interior	Wood	B	Deteriorated	Green	Cracking	Basement E08	E08	Negative	1.11	0.5	0.1	0.6
1686	3/20/2019 14:53	mg/cm^2	Cabinet Shelf	Wood	B	Deteriorated	Green	Friction	Basement E08	E08	Negative	1.04	0.5	0.3	0.8
1687	3/20/2019 14:53	mg/cm^2	Cabinet Outer Shelf	Wood	B	Deteriorated	White	Friction	Basement E08	E08	Negative	1.61	0.4	0.3	0.7
1688	3/20/2019 15:00	mg/cm^2	Wall	Plaster	A	Deteriorated	White	Cracking	Basement E006	E006	Negative	5.08	0.09	0.87	0.96
1689	3/20/2019 15:00	mg/cm^2	Wall	Plaster	B	Deteriorated	White	Cracking	Basement E006	E006	Negative	3.92	0	0	0
1690	3/20/2019 15:00	mg/cm^2	Wall	Plaster	C	Deteriorated	White	Cracking	Basement E006	E006	Positive	1.86	1	0.2	1.2
1691	3/20/2019 15:01	mg/cm^2	Wall	Plaster	D	Deteriorated	White	Cracking	Basement E006	E006	Negative	1.86	0.04	0.03	0.17
1692	3/20/2019 15:01	mg/cm^2	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement E006	E006	Negative	1.87	0.07	0.07	0.14
1693	3/20/2019 15:01	mg/cm^2	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement E006	E006	Negative	1.31	0.02	0.06	0.08
1694	3/20/2019 15:02	mg/cm^2	Floor	Concrete	All	Deteriorated	Brown	Friction	Basement E006	E006	Negative	1	0	0.02	0.02
1695	3/20/2019 15:03	mg/cm^2	Window Casing/Header	Wood	A	Deteriorated	White	Cracking	Basement E006	E006	Negative	1.18	0.04	0.07	0.11
1696	3/20/2019 15:03	mg/cm^2	Window Sill	Ceramic	A	Deteriorated	Brown	Chewable	Basement E006	E006	Negative	1.81	0.01	0.02	0.03
1697	3/20/2019 15:03	mg/cm^2	Door Casing/Header	Wood	C	Deteriorated	Stain	Impact	Basement E006	E006	Negative	1	0.05	0.07	0.12
1698	3/20/2019 15:03	mg/cm^2	Door Lamb	Wood	C	Deteriorated	Stain	Friction	Basement E006	E006	Negative	1.58	0.2	0.18	0.38
1699	3/20/2019 15:03	mg/cm^2	Door Stop	Wood	C	Deteriorated	Blue	Impact	Basement E006	E006	Negative	1.4	0.07	0.14	0.21
1700	3/20/2019 15:03	mg/cm^2	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement E006	E006	Negative	1	0.04	0.09	0.13
1701	3/20/2019 15:03	mg/cm^2	Baseboard	Wood	All	Deteriorated	Brown	Impact	Basement E006	E006	Negative	1	0.03	0.06	0.09
1702	3/20/2019 15:03	mg/cm^2	Shoe Molding	Wood	All	Deteriorated	Brown	Impact	Basement E006	E006	Negative	1.96	0.12	0.15	0.27
1703	3/20/2019 15:04	mg/cm^2	Shelf Frame	Wood	D	Deteriorated	White	Cracking	Basement E006	E006	Positive	1.67	0.9	0.3	1.2
1704	3/20/2019 15:04	mg/cm^2	Shelf	Wood	D	Deteriorated	White	Friction	Basement E006	E006	Positive	2.01	1.2	0.2	1.4
1705	3/20/2019 15:04	mg/cm^2	Work Bench	Wood	D	Deteriorated	White	Friction	Basement E006	E006	Negative	1.14	0.02	0.05	0.07
1706	3/20/2019 15:04	mg/cm^2	Work Bench Face	Wood	D	Deteriorated	White	Impact	Basement E006	E006	Positive	1.26	0.7	0.3	1
1707	3/20/2019 15:04	mg/cm^2	Work Bench Door	Wood	D	Deteriorated	Red	Friction/Impact	Basement E006	E006	Negative	1.13	0.5	0.2	0.7
1708	3/20/2019 15:05	mg/cm^2	Work Bench Shelf	Wood	D	Deteriorated	White	Friction	Basement E006	E006	Positive	1.2	0.8	0.2	1
1709	3/20/2019 15:05	mg/cm^2	Hangar Board	Wood	B	Deteriorated	White	Cracking	Basement E006	E006	Positive	3.52	4.3	3.1	7.4
1710	3/20/2019 15:06	mg/cm^2	Wall	Plaster	A	Deteriorated	Brown	Cracking	Basement E005	E005	Negative	2.49	0.19	0.76	0.95
1711	3/20/2019 15:07	mg/cm^2	Wall	Plaster	B	Deteriorated	Brown	Cracking	Basement E005	E005	Positive	2.25	2.1	0.7	2.8
1712	3/20/2019 15:07	mg/cm^2	Wall	Plaster	C	Deteriorated	Brown	Cracking	Basement E005	E005	Positive	1.93	1.6	0.5	2.1
1713	3/20/2019 15:09	mg/cm^2	Wall	Plaster	D	Deteriorated	Brown	Cracking	Basement E005	E005	Negative	2.11	0.2	0.73	0.93
1714	3/20/2019 15:09	mg/cm^2	Ceiling	Plaster	All	Deteriorated	Black	Cracking	Basement E005	E005	Negative	3.38	0.5	0.4	0.9
1715	3/20/2019 15:09	mg/cm^2	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement E005	E005	Negative	1	0	0.02	0.02
1716	3/20/2019 15:10	mg/cm^2	Baseboard	Wood	All	Deteriorated	Brown	Impact	Basement E005	E005	Negative	1	0	0.03	0.03
1717	3/20/2019 15:10	mg/cm^2	Shoe Molding	Wood	C	Deteriorated	Brown	Impact	Basement E005	E005	Negative	1.61	0.03	0.07	0.1
1718	3/20/2019 15:10	mg/cm^2	Door Casing/Header	Wood	C	Deteriorated	Stain	Impact	Basement E005	E005	Negative	1.39	0.01	0.05	0.06
1719	3/20/2019 15:10	mg/cm^2	Door Lamb	Wood	C	Deteriorated	Stain	Friction	Basement E005	E005	Negative	1.05	0.03	0.05	0.08
1720	3/20/2019 15:10	mg/cm^2	Door Stop	Wood	C	Deteriorated	Blue	Impact	Basement E005	E005	Negative	2.09	0.05	0.11	0.16
1721	3/20/2019 15:10	mg/cm^2	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement E005	E005	Negative	1.65	0.08	0.16	0.24
1722	3/20/2019 15:11	mg/cm^2	Work Bench Frame	Wood	D	Deteriorated	Black	Cracking	Basement E005	E005	Negative	1	0	0.02	0.02
1723	3/20/2019 15:11	mg/cm^2	Work Bench Shelf	Wood	D	Deteriorated	Black	Friction	Basement E005	E005	Negative	3.44	0.11	0.22	0.33
1724	3/20/2019 15:12	mg/cm^2	Wall	Concrete	A	Intact	Grey	Friction	Basement E005 Vault	E005 Vault	Negative	1	0	0.02	0.02
1725	3/20/2019 15:12	mg/cm^2	Wall	Concrete	B	Intact	Grey	Friction	Basement E005 Vault	E005 Vault	Negative	1	0	0.02	0.02
1726	3/20/2019 15:13	mg/cm^2	Wall	Concrete	C	Intact	Grey	Friction	Basement E005 Vault	E005 Vault	Negative	1	0	0.02	0.02
1727	3/20/2019 15:13	mg/cm^2	Wall	Concrete	D	Intact	Grey	Friction	Basement E005 Vault	E005 Vault	Negative	1	0	0.02	0.02
1728	3/20/2019 15:13	mg/cm^2	Ceiling	Concrete	All	Intact	Grey	Friction	Basement E005 Vault	E005 Vault	Negative	1	0	0.02	0.02
CAL	3/20/2019 15:27	mg/cm^2										1.2	0.9	0.1	1
CAL	3/20/2019 15:28	mg/cm^2										1.18	0.9	0.1	1
CAL	3/20/2019 15:28	mg/cm^2										1.2	0.9	0.1	1
CAL	3/22/2019 9:30	cps										11.51	0	0	11.51
CAL	3/22/2019 9:32	mg/cm^2										1.19	0.9	0.1	1
CAL	3/22/2019 9:32	mg/cm^2										1.23	0.9	0.1	1
CAL	3/22/2019 9:32	mg/cm^2										1.2	0.9	0.1	1
1729	3/22/2019 9:37	mg/cm^2	Wall	Plaster	A	Deteriorated	White	Cracking	Basement	W Stairway to Front Entry	Negative	1.49	0.4	0.1	0.5
1730	3/22/2019 9:37	mg/cm^2	Wall	Plaster	B	Intact	White	Cracking	Basement	W Stairway to Front Entry	Negative	1.42	0.3	0.05	0.35

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1731	3/22/2019 9:37	mg/cm ²	Wall	Plaster	C	Intact	White		Basement	W Stairway to Front Entry	Negative	1.45	0.05	0.09	0.14
1732	3/22/2019 9:38	mg/cm ²	Wall	Plaster	D	Intact	White		Basement	W Stairway to Front Entry	Negative	1.97	0.3	0.07	0.37
1733	3/22/2019 9:38	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	W Stairway to Front Entry	Negative	2.34	0.3	0.64	0.94
1734	3/22/2019 9:38	mg/cm ²	Stair Tread	Concrete	All	Deteriorated	Grey	Friction	Basement	W Stairway to Front Entry	Negative	1.53	0.05	0.09	0.14
1735	3/22/2019 9:47	mg/cm ²	Stair Riser	Concrete	All	Deteriorated	Grey	Impact	Basement	W Stairway to Front Entry	Negative	1.4	0.07	0.09	0.16
1736	3/22/2019 9:47	mg/cm ²	Stair Stringer	Concrete	All	Deteriorated	Grey	Impact	Basement	W Stairway to Front Entry	Negative	2.39	0.13	0.18	0.31
1737	3/22/2019 9:47	mg/cm ²	Stair Railing	Wood	All	Deteriorated	Stain	Friction	Basement	W Stairway to Front Entry	Negative	1	0.02	0.06	0.08
1738	3/22/2019 9:47	mg/cm ²	Door Casing/Header	Wood	A	Intact	Stain		Basement	W Stairway to Front Entry	Negative	1.13	0.07	0.12	0.19
1739	3/22/2019 9:47	mg/cm ²	Door Jamb	Wood	A	Intact	Stain		Basement	W Stairway to Front Entry	Negative	1.15	0.05	0.08	0.13
1740	3/22/2019 9:47	mg/cm ²	Door Stop	Wood	A	Intact	Stain		Basement	W Stairway to Front Entry	Negative	1.17	0.05	0.11	0.16
1741	3/22/2019 9:47	mg/cm ²	Door	Wood	A	Intact	Stain		Basement	W Stairway to Front Entry	Negative	1	0	0.02	0.02
1742	3/22/2019 9:49	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	W Stairway to Front Entry Storage	Negative	3.37	0.01	0.93	0.94
1743	3/22/2019 9:49	mg/cm ²	Wall	Plaster	C	Intact	White		Basement	W Stairway to Front Entry Storage	Negative	2.37	0.2	0.79	0.99
1744	3/22/2019 9:49	mg/cm ²	Wall	Drywall	D	Intact	White		Basement	W Stairway to Front Entry Storage	Negative	1	0	0.02	0.02
1745	3/22/2019 9:50	mg/cm ²	Ceiling	Plaster	All	Intact	White		Basement	W Stairway to Front Entry Storage	Negative	1.68	0.04	0.05	0.09
1746	3/22/2019 9:50	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement	W Stairway to Front Entry Storage	Negative	1	0.01	0.02	0.03
1747	3/22/2019 9:50	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Blue	Impact	Basement	W Stairway to Front Entry Storage	Negative	1.9	0.1	0.14	0.24
1748	3/22/2019 9:50	mg/cm ²	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement	W Stairway to Front Entry Storage	Negative	2.75	0.17	0.31	0.48
1749	3/22/2019 9:52	mg/cm ²	Ceiling	Plaster	All	Intact	White		Basement	E Stairway to Front Entry	Negative	4.66	0.17	0.82	0.99
1750	3/22/2019 9:54	mg/cm ²	Wall	Plaster	A	Intact	White		Basement	E Stairway to Front Entry	Negative	2.81	0.17	0.08	0.25
1751	3/22/2019 9:55	mg/cm ²	Wall	Plaster	A	Intact	Blue		Basement	E Stairway to Front Entry	Positive	3.27	1.4	0.3	1.7
1752	3/22/2019 9:55	mg/cm ²	Wall	Plaster	B	Intact	White		Basement	E Stairway to Front Entry	Negative	3.14	0.24	0.28	0.52
1753	3/22/2019 9:55	mg/cm ²	Wall	Plaster	B	Intact	Blue		Basement	E Stairway to Front Entry	Positive	2.35	1.1	0.1	1.2
1754	3/22/2019 9:56	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement	E Stairway to Front Entry	Negative	3.18	0.19	0.04	0.23
1755	3/22/2019 9:56	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement	E Stairway to Front Entry	Negative	2.62	0.14	0.19	0.33
1756	3/22/2019 9:57	mg/cm ²	Wall	Plaster	D	Intact	Blue		Basement	E Stairway to Front Entry	Positive	2.5	0.9	0.1	1
1757	3/22/2019 9:57	mg/cm ²	Stair Tread	Concrete	All	Deteriorated	Grey	Friction	Basement	E Stairway to Front Entry	Negative	2.59	0	0	0
1758	3/22/2019 9:57	mg/cm ²	Stair Stringer	Concrete	All	Deteriorated	Blue	Impact	Basement	E Stairway to Front Entry	Negative	1.64	0.1	0.12	0.22
1759	3/22/2019 9:57	mg/cm ²	Stair Railing	Concrete	All	Deteriorated	Blue	Impact	Basement	E Stairway to Front Entry	Negative	4.55	0.16	0.29	0.45
1760	3/22/2019 9:57	mg/cm ²	Stair Railing	Metal	B	Deteriorated	Blue	Friction	Basement	E Stairway to Front Entry	Negative	5.69	0.12	0.33	0.45
1761	3/22/2019 10:04	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement	E01A	Positive	4.58	1.1	0.1	1.2
1762	3/22/2019 10:04	mg/cm ²	Wall	Plaster	A	Deteriorated	Blue	Cracking	Basement	E01A	Positive	4.44	1.4	0.4	1.8
1763	3/22/2019 10:04	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	E01A	Negative	2.95	0	0	0
1764	3/22/2019 10:04	mg/cm ²	Wall	Plaster	B	Deteriorated	Blue	Cracking	Basement	E01A	Negative	2.37	0.03	0.06	0.09
1765	3/22/2019 10:04	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement	E01A	Negative	4.48	0.1	0.14	0.24
1766	3/22/2019 10:05	mg/cm ²	Wall	Plaster	C	Deteriorated	Blue	Cracking	Basement	E01A	Positive	3.72	3.3	1.5	4.8
1767	3/22/2019 10:05	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement	E01A	Negative	2.98	0	0	0
1768	3/22/2019 10:05	mg/cm ²	Wall	Plaster	D	Deteriorated	Blue	Cracking	Basement	E01A	Negative	1.83	0.6	0.1	0.7
1769	3/22/2019 10:06	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	E01A	Negative	3.27	0.28	0.24	0.52
1770	3/22/2019 10:06	mg/cm ²	Radiator	Metal	-	Deteriorated	White	Chipping	Basement	E01A	Negative	2.33	0.07	0.13	0.2
1771	3/22/2019 10:06	mg/cm ²	Pipe	Metal	All	Deteriorated	White	Chipping	Basement	E01A	Negative	2	0.03	0.08	0.11
1772	3/22/2019 10:06	mg/cm ²	Crown Molding	Wood	All	Deteriorated	White	Cracking	Basement	E01A	Negative	1.24	0.04	0.07	0.11
1773	3/22/2019 10:07	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement	E01A	Negative	1.07	0.02	0.03	0.05
1774	3/22/2019 10:07	mg/cm ²	Floor Stripe	Concrete	All	Deteriorated	Yellow	Friction	Basement	E01A	Positive	2.1	3.1	1.7	4.8
1775	3/22/2019 10:07	mg/cm ²	Column	Plaster	All	Deteriorated	White	Cracking	Basement	E01A	Negative	3.59	0.28	0.68	0.96
1776	3/22/2019 10:08	mg/cm ²	Column	Plaster	All	Deteriorated	Blue	Cracking	Basement	E01A	Positive	3.33	1.5	0.5	2
1777	3/22/2019 10:08	mg/cm ²	Baseboard	Wood	All	Deteriorated	Blue	Cracking	Basement	E01A	Negative	1.47	0.03	0.04	0.07
1778	3/22/2019 10:08	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Blue	Cracking	Basement	E01A	Negative	1.67	0.08	0.16	0.24
1779	3/22/2019 10:08	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Blue	Friction	Basement	E01A	Negative	1.18	0.08	0.13	0.21
1780	3/22/2019 10:08	mg/cm ²	Door Stop	Wood	C	Deteriorated	Blue	Impact	Basement	E01A	Negative	2.42	0.16	0.28	0.44
1781	3/22/2019 10:08	mg/cm ²	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement	E01A	Negative	2.76	0.08	0.16	0.24
1782	3/22/2019 10:09	mg/cm ²	Door Threshold	Concrete	C	Deteriorated	Yellow	Friction	Basement	E01A	Negative	1	0	0.02	0.02
1783	3/22/2019 10:09	mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Blue	Impact	Basement	E01A	Negative	1.51	0.05	0.09	0.14
1784	3/22/2019 10:09	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Blue	Friction	Basement	E01A	Negative	4.01	0.22	0.45	0.67
1785	3/22/2019 10:09	mg/cm ²	Door Stop	Wood	B	Deteriorated	Blue	Impact	Basement	E01A	Negative	1.65	0.08	0.16	0.24
1786	3/22/2019 10:09	mg/cm ²	Door	Wood	B	Deteriorated	Blue	Friction/Impact	Basement	E01A	Negative	1	0.03	0.08	0.11
1787	3/22/2019 10:09	mg/cm ²	Door Casing/Header	Wood	B	Deteriorated	Blue	Impact	Basement	E01A	Negative	1.64	0.04	0.09	0.13
1788	3/22/2019 10:10	mg/cm ²	Door Jamb	Wood	B	Deteriorated	Blue	Friction	Basement	E01A	Negative	1.88	0.09	0.14	0.23
1789	3/22/2019 10:10	mg/cm ²	Door Stop	Wood	B	Deteriorated	Blue	Impact	Basement	E01A	Negative	1.03	0.03	0.07	0.1

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1790	3/22/2019 10:10	mg/cm ²	Door	Wood	B	Deteriorated	Blue	Friction/Impact	Basement	E01A	Negative	1	0	0.02	0.02
1791	3/22/2019 10:10	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Blue	Impact	Basement	E01A	Negative	1.58	0.07	0.11	0.18
1792	3/22/2019 10:10	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Blue	Friction	Basement	E01A	Negative	2.33	0.08	0.2	0.28
1793	3/22/2019 10:10	mg/cm ²	Door Stop	Wood	A	Deteriorated	Blue	Impact	Basement	E01A	Negative	1	0.02	0.07	0.09
1794	3/22/2019 10:11	mg/cm ²	Floor Drain	Wood	-	Deteriorated	Yellow	Chipping	Basement	E01A	Positive	1.64	1.5	0.4	1.9
1795	3/22/2019 10:13	mg/cm ²	Cabinet Face	Wood	A	Deteriorated	Blue	Impact	Basement	E01A	Negative	1	0	0.02	0.02
1796	3/22/2019 10:13	mg/cm ²	Cabinet Door	Wood	A	Deteriorated	Blue	Friction/Impact	Basement	E01A	Negative	1	0	0.02	0.02
1797	3/22/2019 10:14	mg/cm ²	Work Bench	Wood	All	Deteriorated	Blue	Friction	Basement	E01A	Negative	1.45	0.05	0.12	0.17
1798	3/22/2019 10:14	mg/cm ²	Work Bench Frame	Wood	All	Deteriorated	Blue	Cracking	Basement	E01A	Positive	2.55	2.9	1.8	4.7
1799	3/22/2019 10:14	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement	E01A	Positive	5.46	4.2	2.3	6.5
1800	3/22/2019 10:14	mg/cm ²	Shelf	Wood	B	Deteriorated	Blue	Friction	Basement	E01A	Negative	1	0	0.02	0.02
1801	3/22/2019 10:14	mg/cm ²	Window Casing/Header	Wood	A	Intact	White		Basement	E01A	Negative	1.89	0.08	0.17	0.25
1802	3/22/2019 10:14	mg/cm ²	Window Sash	Wood	A	Deteriorated	White	Cracking	Basement	E01A	Negative	3.16	0.05	0.14	0.19
1803	3/22/2019 10:15	mg/cm ²	Window Jamb	Wood	A	Deteriorated	White	Cracking	Basement	E01A	Negative	2.51	0.05	0.12	0.17
1804	3/22/2019 10:15	mg/cm ²	Window Inside Stop	Wood	A	Deteriorated	White	Cracking	Basement	E01A	Negative	2.6	0.04	0.11	0.15
1805	3/22/2019 10:15	mg/cm ²	Window Sill	Wood	A	Deteriorated	White	Chewable	Basement	E01A	Negative	4.1	0.12	0.25	0.37
1806	3/22/2019 10:15	mg/cm ²	Work Bench	Wood	All	Deteriorated	Blue	Friction	Basement	E01A	Positive	2.5	1.5	0.4	1.9
1807	3/22/2019 10:16	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	White	Cracking	Basement	E01A	Negative	1	0	0.02	0.02
1808	3/22/2019 10:16	mg/cm ²	Shelf	Wood	A	Deteriorated	White	Friction	Basement	E01A	Negative	3.78	0.02	0.1	0.12
1809	3/22/2019 10:17	mg/cm ²	Shelf Frame	Wood	C	Deteriorated	Blue	Cracking	Basement	E01A	Positive	2.22	1.1	0.1	1.2
1810	3/22/2019 10:17	mg/cm ²	Shelf	Wood	C	Deteriorated	Blue	Friction	Basement	E01A	Negative	2.19	0.11	0.16	0.27
1811	3/22/2019 10:18	mg/cm ²	Wall	Concrete	A	Deteriorated	Brown	Cracking	Basement	E01 Vault	Negative	1.96	0.25	0.08	0.33
1812	3/22/2019 10:18	mg/cm ²	Wall	Concrete	B	Deteriorated	Brown	Cracking	Basement	E01 Vault	Negative	1.8	0.17	0.04	0.21
1813	3/22/2019 10:19	mg/cm ²	Wall	Concrete	C	Deteriorated	Brown	Cracking	Basement	E01 Vault	Negative	1.84	0.2	0.04	0.24
1814	3/22/2019 10:19	mg/cm ²	Wall	Concrete	D	Deteriorated	Brown	Cracking	Basement	E01 Vault	Negative	2.01	0.11	0.84	0.95
1815	3/22/2019 10:20	mg/cm ²	Ceiling	Concrete	All	Deteriorated	Brown	Cracking	Basement	E01 Vault	Positive	1.8	0.5	0.5	1
1816	3/22/2019 10:20	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement	E01 Vault	Negative	1	0.03	0.04	0.07
1817	3/22/2019 10:21	mg/cm ²	Shelf	Wood	All	Deteriorated	Grey	Friction	Basement	E01 Vault	Negative	1.58	0.3	0.23	0.53
1818	3/22/2019 10:21	mg/cm ²	Key Hanger Board	Wood	B	Deteriorated	Grey	Cracking	Basement	E01 Vault	Negative	1.32	0.5	0.3	0.8
1819	3/22/2019 10:21	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Stain	Cracking	Basement	E01 Vault	Negative	1.97	0.27	0.32	0.59
1820	3/22/2019 10:22	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Blue	Friction	Basement	E01 Vault	Negative	5.71	0.21	0.56	0.77
1821	3/22/2019 10:22	mg/cm ²	Door Stop	Wood	A	Deteriorated	Blue	Impact	Basement	E01 Vault	Negative	2.15	0.11	0.16	0.27
1822	3/22/2019 10:22	mg/cm ²	Door	Wood	A	Deteriorated	Blue	Friction/Impact	Basement	E01 Vault	Negative	1.62	0.14	0.15	0.29
1823	3/22/2019 10:24	mg/cm ²	Wall	Plaster	A	Deteriorated	Beige	Cracking	Basement	E01D	Negative	2.3	0.7	0.1	0.8
1824	3/22/2019 10:25	mg/cm ²	Wall	Plaster	A	Deteriorated	Green	Cracking	Basement	E01D	Positive	1.37	0.9	0.1	1
1825	3/22/2019 10:25	mg/cm ²	Wall	Plaster	B	Deteriorated	Beige	Cracking	Basement	E01D	Negative	2.02	0.4	0.3	0.7
1826	3/22/2019 10:27	mg/cm ²	Wall	Plaster	B	Deteriorated	Green	Cracking	Basement	E01D	Negative	1.4	0.6	0.1	0.7
1827	3/22/2019 10:27	mg/cm ²	Wall	Plaster	C	Deteriorated	Beige	Cracking	Basement	E01D	Negative	1.65	0.3	0.23	0.53
1828	3/22/2019 10:27	mg/cm ²	Wall	Plaster	C	Deteriorated	Green	Cracking	Basement	E01D	Positive	1.44	0.9	0.1	1
1829	3/22/2019 10:28	mg/cm ²	Wall	Plaster	D	Deteriorated	Beige	Cracking	Basement	E01D	Negative	1.69	0.29	0.15	0.44
1830	3/22/2019 10:28	mg/cm ²	Wall	Plaster	D	Deteriorated	Green	Cracking	Basement	E01D	Positive	1.32	1.5	0.4	1.9
1831	3/22/2019 10:28	mg/cm ²	Ceiling	Plaster	All	Deteriorated	Beige	Cracking	Basement	E01D	Positive	2.26	0.8	0.4	1.2
1832	3/22/2019 10:30	mg/cm ²	Hanger Board	Wood	All	Deteriorated	Beige	Cracking	Basement	E01D	Positive	2.07	0.8	0.2	1
1833	3/22/2019 10:35	mg/cm ²	Wall	Plaster	A	Deteriorated	Brown	Cracking	Basement	E01C	Positive	7.4	4.9	3.1	8
1834	3/22/2019 10:35	mg/cm ²	Wall	Plaster	B	Deteriorated	Brown	Cracking	Basement	E01C	Positive	8.05	6.7	4.4	11.1
1835	3/22/2019 10:35	mg/cm ²	Wall	Plaster	C	Deteriorated	Brown	Cracking	Basement	E01C	Positive	3.15	2	0.9	2.9
1836	3/22/2019 10:36	mg/cm ²	Wall	Plaster	D	Deteriorated	Brown	Cracking	Basement	E01C	Positive	8.31	6.3	4.6	10.9
1837	3/22/2019 10:36	mg/cm ²	Wainscoting	Ceramic	All	Intact	Grey		Basement	E01C	Negative	1	0	0.02	0.02
1838	3/22/2019 10:36	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	E01C	Positive	9.26	4.8	3.3	8.1
1839	3/22/2019 10:36	mg/cm ²	Radiator	Metal	-	Deteriorated	Grey	Chipping	Basement	E01C	Positive	1.67	2.2	1	3.2
1840	3/22/2019 10:37	mg/cm ²	Floor	Concrete	All	Deteriorated	Grey	Friction	Basement	E01C	Negative	1	0	0.02	0.02
1841	3/22/2019 10:37	mg/cm ²	Window Casing/Header	Wood	A	Deteriorated	Stain	Cracking	Basement	E01C	Negative	1	0.03	0.07	0.1
1842	3/22/2019 10:37	mg/cm ²	Window Jamb	Wood	A	Deteriorated	Beige	Cracking	Basement	E01C	Negative	1.4	0.01	0.04	0.05
1843	3/22/2019 10:37	mg/cm ²	Window Sill	Wood	A	Deteriorated	Beige	Chewable	Basement	E01C	Negative	1	0	0.02	0.02
1844	3/22/2019 10:37	mg/cm ²	Door Casing/Header	Wood	A	Deteriorated	Stain	Impact	Basement	E01C	Negative	2.78	0.03	0.16	0.19
1845	3/22/2019 10:38	mg/cm ²	Door Jamb	Wood	A	Deteriorated	Stain	Friction	Basement	E01C	Negative	1.51	0.03	0.1	0.13
1846	3/22/2019 10:38	mg/cm ²	Door Stop	Wood	A	Deteriorated	Stain	Impact	Basement	E01C	Negative	1	0.01	0.05	0.06
1847	3/22/2019 10:38	mg/cm ²	Door	Wood	A	Deteriorated	Beige	Friction/Impact	Basement	E01C	Negative	3.89	0	0	0
1848	3/22/2019 10:38	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Beige	Impact	Basement	E01C	Negative	1	0	0.02	0.02

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1849	3/22/2019 10:38	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Stain	Friction	Basement	E01C	Negative	1.16	0.02	0.05	0.07
1850	3/22/2019 10:38	mg/cm ²	Door Stop	Wood	C	Deteriorated	Beige	Impact	Basement	E01C	Negative	4.14	0.04	0.15	0.19
1851	3/22/2019 10:38	mg/cm ²	Door	Wood	C	Deteriorated	Beige	Friction/Impact	Basement	E01C	Negative	1	0.01	0.04	0.05
1852	3/22/2019 10:38	mg/cm ²	Sink	Metal	B	Intact	White		Basement	E01C	Positive	1.55	3.8	2.5	6.3
1853	3/22/2019 10:39	mg/cm ²	Pipe	Metal	All	Deteriorated	Grey	Chipping	Basement	E01C	Positive	1.95	13.1	10.8	23.9
1854	3/22/2019 10:41	mg/cm ²	Wall	Brick	A	Intact	Red		Basement	E01B	Negative	1	0.01	0.02	0.03
1855	3/22/2019 10:41	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	E01B	Positive	5	10.9	9.6	20.5
1856	3/22/2019 10:41	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement	E01B	Positive	5.31	9.4	8.2	17.6
1857	3/22/2019 10:41	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement	E01B	Positive	6.82	15.1	11.5	26.6
1858	3/22/2019 10:41	mg/cm ²	Wainscoting	Ceramic	All	Intact	Grey		Basement	E01B	Negative	1	0	0.02	0.02
1859	3/22/2019 10:42	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	E01B	Positive	4.87	9.5	8	17.5
1860	3/22/2019 10:42	mg/cm ²	Radiator	Metal	All	Intact	White		Basement	E01B	Positive	2.57	6.2	3.5	9.7
1861	3/22/2019 10:44	mg/cm ²	Pipe	Metal	All	Deteriorated	White	Chipping	Basement	E01B	Negative	2.27	0.08	0.21	0.29
1862	3/22/2019 10:44	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement	E01B	Negative	1.42	0.4	0.2	0.6
1863	3/22/2019 10:44	mg/cm ²	Shelf	Wood	B	Deteriorated	White	Friction	Basement	E01B	Negative	1.42	0.4	0.3	0.7
1864	3/22/2019 10:47	mg/cm ²	Wall	Concrete	A	Deteriorated	Black	Cracking	Basement	E02B	Negative	1	0	0.02	0.02
1865	3/22/2019 10:48	mg/cm ²	Wall	Concrete	B	Deteriorated	Beige	Cracking	Basement	E02B	Negative	1	0	0.02	0.02
1866	3/22/2019 10:48	mg/cm ²	Wall	Concrete	C	Deteriorated	Beige	Cracking	Basement	E02B	Negative	1	0	0.02	0.02
1867	3/22/2019 10:48	mg/cm ²	Wall	Concrete	D	Deteriorated	Beige	Cracking	Basement	E02B	Negative	1	0	0.02	0.02
1868	3/22/2019 10:49	mg/cm ²	Ceiling	Concrete	All	Deteriorated	Black	Cracking	Basement	E02B	Negative	1	0	0.02	0.02
1869	3/22/2019 10:49	mg/cm ²	Pipe	Metal	-	Deteriorated	Beige	Chipping	Basement	E02B	Negative	1.22	0.09	0.1	0.19
1870	3/22/2019 10:49	mg/cm ²	Shelf Frame	Wood	A	Deteriorated	Grey	Cracking	Basement	E02B	Positive	1.28	1.5	0.4	1.9
1871	3/22/2019 10:49	mg/cm ²	Shelf	Wood	A	Deteriorated	Grey	Friction	Basement	E02B	Positive	1.25	1.2	0.2	1.4
1872	3/22/2019 10:53	mg/cm ²	Wall	Concrete	A	Deteriorated	Beige	Cracking	Basement	E02A	Negative	1.48	0.04	0.05	0.09
1873	3/22/2019 10:53	mg/cm ²	Wall	Concrete	B	Deteriorated	Beige	Cracking	Basement	E02A	Negative	1.92	0.06	0.08	0.14
1874	3/22/2019 10:53	mg/cm ²	Wall	Concrete	C	Deteriorated	Beige	Cracking	Basement	E02A	Negative	5.16	0.04	0.11	0.15
1875	3/22/2019 10:53	mg/cm ²	Wall	Concrete	D	Deteriorated	Beige	Cracking	Basement	E02A	Negative	1	0.02	0.03	0.05
1876	3/22/2019 10:54	mg/cm ²	Ceiling	Concrete	All	Deteriorated	Beige	Cracking	Basement	E02A	Negative	1.01	0.02	0.03	0.05
1877	3/22/2019 10:54	mg/cm ²	Work Bench	Wood	D	Deteriorated	Green	Friction	Basement	E02A	Positive	1.26	0.6	0.4	1
1878	3/22/2019 10:54	mg/cm ²	Work Bench Frame	Wood	D	Deteriorated	Green	Cracking	Basement	E02A	Negative	1.16	0.4	0.3	0.7
1879	3/22/2019 10:54	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement	E02A	Positive	1.29	0.9	0.1	1
1880	3/22/2019 10:54	mg/cm ²	Shelf	Wood	B	Deteriorated	Blue	Friction	Basement	E02A	Negative	1.26	0.26	0.18	0.44
1881	3/22/2019 10:54	mg/cm ²	Shelf Frame	Wood	B	Deteriorated	Blue	Cracking	Basement	E02A	Positive	5.25	5.5	3.4	8.9
1882	3/22/2019 10:55	mg/cm ²	Shelf	Wood	B	Deteriorated	Blue	Friction	Basement	E02A	Negative	4.23	0.5	0.4	0.9
1883	3/22/2019 10:55	mg/cm ²	Cabinet Face	Wood	B	Deteriorated	Blue	Impact	Basement	E02A	Positive	2.02	2.1	1.1	3.2
1884	3/22/2019 10:55	mg/cm ²	Cabinet Door	Wood	B	Deteriorated	Blue	Friction/Impact	Basement	E02A	Positive	1.56	1.1	0.1	1.2
1885	3/22/2019 10:55	mg/cm ²	Cabinet Shelf	Wood	B	Deteriorated	Green	Friction	Basement	E02A	Negative	1.24	0.8	0.1	0.9
1886	3/22/2019 10:55	mg/cm ²	Shelf Frame	Wood	D	Deteriorated	Green	Cracking	Basement	E02A	Negative	1.21	0.5	0.3	0.8
1887	3/22/2019 10:55	mg/cm ²	Door Casing/Header	Wood	C	Deteriorated	Stain	Cracking	Basement	E02A	Negative	1	0.04	0.09	0.13
1888	3/22/2019 10:56	mg/cm ²	Door Jamb	Wood	C	Deteriorated	Stain	Friction	Basement	E02A	Negative	1	0.05	0.09	0.14
1889	3/22/2019 10:56	mg/cm ²	Door Stop	Wood	C	Deteriorated	Stain	Impact	Basement	E02A	Negative	1	0.04	0.09	0.13
1890	3/22/2019 10:56	mg/cm ²	Door	Wood	C	Deteriorated	Blue	Friction/Impact	Basement	E02A	Negative	1	0.03	0.05	0.08
1891	3/22/2019 10:56	mg/cm ²	Door Threshold	Concrete	C	Deteriorated	Yellow	Friction	Basement	E02A	Positive	10	2.3	1.3	3.6
1892	3/22/2019 11:01	mg/cm ²	Wall	Plaster	A	Deteriorated	White	Cracking	Basement	E02	Positive	2.57	0.4	0.6	1
1893	3/22/2019 11:02	mg/cm ²	Wall	Plaster	B	Deteriorated	White	Cracking	Basement	E02	Negative	2.94	0.27	0.07	0.34
1894	3/22/2019 11:02	mg/cm ²	Wall	Plaster	C	Deteriorated	White	Cracking	Basement	E02	Negative	2.45	0	0	0
1895	3/22/2019 11:02	mg/cm ²	Wall	Plaster	D	Deteriorated	White	Cracking	Basement	E02	Negative	1	0.01	0.02	0.03
1896	3/22/2019 11:02	mg/cm ²	Ceiling	Plaster	All	Deteriorated	White	Cracking	Basement	E02	Negative	1.68	0.1	0.04	0.14
1897	3/22/2019 11:03	mg/cm ²	Radiator	Metal	-	Deteriorated	White	Chipping	Basement	E02	Positive	2.75	0.8	0.2	1
1898	3/22/2019 11:03	mg/cm ²	Pipe	Metal	All	Deteriorated	White	Chipping	Basement	E02	Negative	1.39	0.5	0.4	0.9
1899	3/22/2019 11:03	mg/cm ²	Baseboard	Wood	A	Deteriorated	White	Impact	Basement	E02	Negative	4.26	0.4	0.4	0.8
1900	3/22/2019 11:03	mg/cm ²	Steps	Concrete	All	Deteriorated	Yellow	Impact	Basement	E02	Positive	10	2.1	1.1	3.2
1901	3/22/2019 11:03	mg/cm ²	Wall	Wood	All	Deteriorated	White	Cracking	Basement	E02	Negative	1	0	0.02	0.02
1902	3/22/2019 11:04	mg/cm ²	Stair Railing	Metal	B	Deteriorated	Orange	Friction	Basement	E02	Negative	2.03	0.1	0.25	0.35
1903	3/22/2019 11:04	mg/cm ²	Overhead Door Frame	Wood	C	Deteriorated	White	Cracking	Basement	E02	Positive	1.94	0.7	0.3	1
1904	3/22/2019 11:04	mg/cm ²	A/C Unit Casing	Wood	A	Deteriorated	Blue	Chipping	Basement	E02	Positive	1.29	0.6	0.4	1
1905	3/22/2019 11:05	mg/cm ²	A/C Unit Frame	Wood	A	Deteriorated	Green	Chipping	Basement	E02	Negative	1.94	0.17	0.05	0.22
1906	3/22/2019 11:07	mg/cm ²	Cabinet Face	Wood	B	Deteriorated	Green	Impact	Basement	E03	Negative	1.87	0.17	0.18	0.35
1907	3/22/2019 11:07	mg/cm ²	Cabinet Door	Wood	B	Deteriorated	Green	Friction/Impact	Basement	E03	Negative	1.13	0.05	0.08	0.13

Fort Dodge City Hall - Total XRF Results

Reading No	Time	Units	Component	Substrate	Side	Condition	Color	Hazard	Floor	Room	Results	Depth Index	PbC	PbC Error	PbC Total
1908	3/22/2019 11:07	mg/cm ²	Cabinet Shelf	Wood	B	Deteriorated	White	Friction	Basement	E03	Negative	1.68	0.03	0.08	0.11
1909	3/22/2019 11:08	mg/cm ²	Ceiling	Concrete	All	Deteriorated	Beige	Cracking	Basement	E03	Negative	1	0	0.02	0.02
1910	3/22/2019 11:09	mg/cm ²	Wall	Drywall	D	Intact	White		Basement	E03	Negative	1	0	0.02	0.02
1911	3/22/2019 11:10	mg/cm ²	Wall	Drywall	A	Intact	White		Basement	E03A	Negative	1	0	0.02	0.02
1912	3/22/2019 11:10	mg/cm ²	Wall	Drywall	B	Intact	White		Basement	E03A	Negative	1	0	0.02	0.02
1913	3/22/2019 11:10	mg/cm ²	Door Casing/Header	Metal	B	Deteriorated	Brown	Impact	Basement	E03A	Negative	1	0	0.02	0.02
1914	3/22/2019 11:10	mg/cm ²	Door Jamb	Metal	B	Deteriorated	Brown	Friction	Basement	E03A	Negative	1	0	0.02	0.02
1915	3/22/2019 11:10	mg/cm ²	Door Stop	Metal	B	Deteriorated	Brown	Impact	Basement	E03A	Negative	1	0	0.02	0.02
1916	3/22/2019 11:10	mg/cm ²	Door	Metal	B	Deteriorated	Brown	Friction/Impact	Basement	E03A	Negative	2.77	0.01	0.05	0.06
1917	3/22/2019 11:10	mg/cm ²	Wall	Concrete	D	Deteriorated	Brown	Cracking	Basement	E03A	Negative	1	0.02	0.02	0.04
1918	3/22/2019 11:13	mg/cm ²	Wall	Concrete	A	Deteriorated	Blue	Cracking	Basement	E03B	Negative	1.28	0.03	0.02	0.05
1919	3/22/2019 11:13	mg/cm ²	Wall	Concrete	B	Deteriorated	Blue	Cracking	Basement	E03B	Negative	1.24	0.04	0.03	0.07
1920	3/22/2019 11:14	mg/cm ²	Wall	Concrete	C	Deteriorated	Blue	Cracking	Basement	E03B	Positive	1.82	1.4	0.4	1.8
1921	3/22/2019 11:14	mg/cm ²	Wall	Concrete	D	Deteriorated	Blue	Cracking	Basement	E03B	Positive	1.33	1.3	0.3	1.6
1922	3/22/2019 11:14	mg/cm ²	Ceiling	Concrete	All	Deteriorated	White	Cracking	Basement	E03B	Negative	1	0.03	0.08	0.11
1923	3/22/2019 11:14	mg/cm ²	Door Stop	Metal	A	Deteriorated	Grey	Impact	Basement	E03B	Negative	1.76	0.07	0.2	0.27
1924	3/22/2019 11:14	mg/cm ²	Door Jamb	Metal	A	Deteriorated	Grey	Friction	Basement	E03B	Negative	3.62	0.17	0.63	0.8
CAL	3/22/2019 11:16	mg/cm ²									Negative	1.03	0.8	0.2	1
CAL	3/22/2019 11:16	mg/cm ²									Negative	1.16	0.9	0.1	1
CAL	3/22/2019 11:17	mg/cm ²									Negative	1.11	0.8	0.2	1
CAL	3/22/2019 11:18	cps									Negative	13.41	0	0	13.41